ASS REC.EY	RE	cs/smoise	onges/ Av	d3 n2 special hammedian	b.
Surveyor			SMO (Office)	X.	0 7 18@ Apm
OD (TP) WS /		EVA/INV/MV/	Bill to	GRI	00.061
		XB 7128	A motive	Insured GBI	179241
of1}	caki Bukif A	126 #0	1-43 Autok	CMTD1802:	
Policy No Sum Insured:			Excess:		
Make of Veh:		1		03	36/06/2018
CA / REV /	10pm@2/3/18	S Person Contacte	Sikyi	Vehicle IN) OUT
Date/Time	Action/Instruction (- form	nte		
	XB 7128 A - GBD 2586	144			
श्रीहर	Informed Gr	ace pending	workshop "	est via me	rimen
8 8 F1	Adrian Cov Email preli		Pau Loong	est via me Red 18,25	क , त <u>्</u> राभी

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 20 August 2018 9:35 AM

To:

Gnoh, Pau Loong

Cc:

SUR; melvin.ye@sompo.com.sg; Teo, Grace

Subject:

RE: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Attachments:

XB 7128A PRELI ADVISED.pdf

Dear Pau Loong,

Enclosed preliminary revised of vehicle XB 7128A

Date of survey: 3/7/2018 Number of days: 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 26 July 2018 5:02 PM

To: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>

Cc: SUR <sur@lkkauto.com>; 'melvin.ye@sompo.com.sg' <melvin.ye@sompo.com.sg>; Teo, Grace

<grace.teo@sompo.com.sg>

Subject: RE: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Dear Pau Loong,

We refer to your conversation with our surveyor Mr Adrian Ling.

The estimated repair cost is \$8,000/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 5 July 2018 9:58 AM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>

Cc: SUR < sur@lkkauto.com >; 'Gnoh, Pau Loong' < PauLoong.Gnoh@sompo.com.sg >; 'melvin.ye@sompo.com.sg'

<melvin.ye@sompo.com.sg>

Subject: RE: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Dear Grace,

Please be informed that we have inspected the vehicle XB 7128A on 3/7/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Monday, 2 July 2018 4:00 PM

To: admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Admin nht <admin@nhtmotor.com>; Reena <reena@nhtmotor.com>; Gnoh, Pau Loong PauLoong.Gnoh@sompo.com.sg; Ye, Yong Kang Melvin melvin.ye@sompo.com.sg; Subject: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Our Reference: CMTD1802777/GPL

Dear LKK AUTO/ MARCUS,

Please make arrangement to conduct the survey for XB7128A.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Admin nht [mailto:admin@nhtmotor.com] Sent: Monday, July 02, 2018 3:52 PM To: Teo, Grace Cc: Reena; Gnoh, Pau Loong; Ye, Yong Kang Melvin Subject: Re: CMTD1802777/GPL - PRI/ GBD2586T & XB7128A ACC ON 26.06.18

Without Prejudice

Hi Grace

Please arrange for Marcus Chua of LKK Auto.

Sukyi

SM AUTOMOTIVE 1 Kaki Bukit Avenue 6, #01-43 Block C @ Autobay, Singapore 417883 T: 6747 9241 F: 6741 7276

On Mon, Jul 2, 2018 at 3:05 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1802777/GPL

Your Reference: XB7128A

Without Prejudice

Date: 2nd July 2018

Attention:

M/S SM AUTOMOTIVE

Dear Sukyi,

ACCIDENT INVOLVING GBD2586T & XB7128A ON 26.06.2018

We refer to your Notice of Accident dated 02/07/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
_		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
7		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards Grace Teo Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Admin nht [mailto:admin@nhtmotor.com]

Sent: Monday, July 02, 2018 12:20 PM

To: Claims - Motor Survey

Cc: Reena

Subject: XB7128A CLAIMING AGAINST GBD2586T DOA:26.06.18

ithout Prejudice		
i Motor Claim Dept		
lease send us your surveyor list,thanks.		
lease take note this claim under SM Au	tomotive	
Sukyi SM AUTOMOTIVE		
Kaki Bukit Avenue 6, #01-43 Block C @ Autobay, Singapore	417883	
Kaki Bukit Avenue 6, #01-43 Block C @ Autobay, Singapore	417883	
Kaki Bukit Avenue 6, #01-43 Block C @ Autobay, Singapore	417883	



AVG. This email has been checked for viruses by AVG antivirus software.

www.avg.com



Company Registration No. 19960719

51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564

Your ref:

CMTD1802777/GPL

Our ref:

CS/SMO18011988/Avd3

Date: 20/8/2018

The Motor Claims Department M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

XB 7128A

We thank you for your instruction on

2/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle

3/7/2018

at the premises of M

SM AUTOMOTIVE

and have the following to report:-

Workshop Estimate Amount Revised Estimate Amount

: \$\$35,550.00 : S\$7,300.00 (LUMP SUM)

"Check" Items Amount

: S\$

Market Value LTA Reimbursement Value

: S\$: S\$

Nett Value


: S\$

Description of Damage:

The vehicle sustained damages at the

o/s portion

nearside



front

Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI Licensed Appraiser

Veron Chen (LKKAuto)

From: Sent: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>

Thursday, 26 July 2018 5:04 PM

To:

Veron Chen (LKKAuto)

Cc:

SUR; Ye, Yong Kang Melvin; Teo, Grace; Ong, Lay Gim; Han, Bernard

Subject:

RE: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Dear Veron.

Thank you for your email below regarding the third party cost of repair for XB7128A is at \$ 8,000/-.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG





Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Thursday, 26 July, 2018 5:02 PM

To: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>

Cc: SUR <sur@lkkauto.com>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Teo, Grace

<grace.teo@sompo.com.sg>

Subject: RE: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Dear Pau Loong,

We refer to your conversation with our surveyor Mr Adrian Ling.

The estimated repair cost is \$8,000/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 5 July 2018 9:58 AM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>

Cc: SUR <sur@lkkauto.com>; 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'melvin.ye@sompo.com.sg'

<melvin.ye@sompo.com.sg>

Subject: RE: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Dear Grace,

Please be informed that we have inspected the vehicle XB 7128A on 3/7/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Monday, 2 July 2018 4:00 PM

To: admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Admin nht admin@nhtmotor.com; Reena reena@nhtmotor.com; Gnoh, Pau Loong PauLoong.Gnoh@sompo.com.sg; Ye, Yong Kang Melvin melvin.ye@sompo.com.sg>
Subject: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Our Reference: CMTD1802777/GPL

Dear LKK AUTO/ MARCUS,

Please make arrangement to conduct the survey for XB7128A.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Admin nht [mailto:admin@nhtmotor.com]

Sent: Monday, July 02, 2018 3:52 PM

To: Teo, Grace

Cc: Reena; Gnoh, Pau Loong; Ye, Yong Kang Melvin

Subject: Re: CMTD1802777/GPL - PRI/ GBD2586T & XB7128A ACC ON 26.06.18

Without Prejudice

Hi Grace

Please arrange for Marcus Chua of LKK Auto.

Sukyi

SM AUTOMOTIVE 1 Kaki Bukit Avenue 6, #61-43 Block C @ Autobay, Singapore 417883 T : 6747 9241 | F : 6741 7276

On Mon, Jul 2, 2018 at 3:05 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1802777/GPL

Your Reference: XB7128A

Without Prejudice

Date: 2nd July 2018

Attention:

M/S SM AUTOMOTIVE

ACCIDENT INVOLVING GBD2586T & XB7128A ON 26.06.2018

We refer to your Notice of Accident dated 02/07/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
- 1/1		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

想出

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain

confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click <u>here</u> for our Privacy Policy

From: Admin nht [mailto:admin@nhtmotor.com]

Sent: Monday, July 02, 2018 12:20 PM

To: Claims - Motor Survey

Cc: Reena

Subject: XB7128A CLAIMING AGAINST GBD2586T DOA:26.06.18

Without Prejudice

Hi Motor Claim Dept

Please send us your surveyor list, thanks.

Please take note this claim under SM Automotive

Sukyi

SM AUTOMOTIVE

1 Kaki Bukit Avenue 6, #01-43 Block C @ Autobay, Singapore 417883

T: 6747 9241 F: 6741 7276



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 5 July 2018 9:58 AM

To:

'Teo, Grace'

Cc:

SUR; 'Gnoh, Pau Loong'; 'melvin.ye@sompo.com.sg'

Subject:

RE: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Dear Grace,

Please be informed that we have inspected the vehicle XB 7128A on 3/7/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Monday, 2 July 2018 4:00 PM

To: admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Admin nht <admin@nhtmotor.com>; Reena <<u>reena@nhtmotor.com</u>>; Gnoh, Pau Loong <<u>PauLoong.Gnoh@sompo.com.sg</u>>; Ye, Yong Kang Melvin <<u>melvin.ye@sompo.com.sg</u>>
Subject: CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Our Reference: CMTD1802777/GPL

Dear LKK AUTO/ MARCUS,

Please make arrangement to conduct the survey for XB7128A.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Admin nht [mailto:admin@nhtmotor.com]

Sent: Monday, July 02, 2018 3:52 PM

To: Teo, Grace

Cc: Reena; Gnoh, Pau Loong; Ye, Yong Kang Melvin

Subject: Re: CMTD1802777/GPL - PRI/ GBD2586T & XB7128A ACC ON 26.06.18

Without Prejudice

Hi Grace

Please arrange for Marcus Chua of LKK Auto.

Sukyi

Junyi		
SM AUTOMOTIVE		
1 Kaki Bukit Avenue 6, #01-43 Block C @ Autobay.	Singapore 417883	
T: 6747 9241 F: 6741 7276	266	
1.0141.0241.11.0141.12.0		
1		

On Mon, Jul 2, 2018 at 3:05 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1802777/GPL

Your Reference: XB7128A

Without Prejudice

Date: 2nd July 2018

Attention:

M/S SM AUTOMOTIVE

Dear Sukyi,

ACCIDENT INVOLVING GBD2586T & XB7128A ON 26.06.2018

We refer to your Notice of Accident dated 02/07/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.


Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147





Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit

bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click <u>here</u> for our Privacy Policy

From: Admin nht [mailto:admin@nhtmotor.com]
Sent: Monday, July 02, 2018 12:20 PM
To: Claims - Motor Survey
Cc: Reena
Subject: XB7128A CLAIMING AGAINST GBD2586T DOA:26.06.18

Without Prejudice

Please send us your surveyor list, thanks.


Please take note this claim under SM Automotive

Sukyi SM AUTOMOTIVE

Hi Motor Claim Dept

1 Kaki Bukit Avenue 6, #01-43 Block C @ Autobay, Singapore 417883

T : 6747 9241 F: 6741 7276





This email has been checked for viruses by AVG antivirus software. www.avg.com

Nivitha (LKK Auto)

From:

Teo, Grace < grace.teo@sompo.com.sg>

Sent:

Monday, 2 July 2018 4:00 PM

To:

admin-d@lkkauto.com; assignments@lkkauto.com

Cc:

Admin nht; Reena; Gnoh, Pau Loong; Ye, Yong Kang Melvin

Subject:

CMTD1802777/GPL - SUV(LKK)/ GBD2586T & XB7128A ACC ON 26.06.18

Attachments:

XB7128A PRI.PDF

Our Reference: CMTD1802777/GPL

Dear LKK AUTO/ MARCUS,

Please make arrangement to conduct the survey for XB7128A.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Admin nht [mailto:admin@nhtmotor.com]

Sent: Monday, July 02, 2018 3:52 PM

To: Teo, Grace

Cc: Reena; Gnoh, Pau Loong; Ye, Yong Kang Melvin

Subject: Re: CMTD1802777/GPL - PRI/ GBD2586T & XB7128A ACC ON 26.06.18

Without Prejudice

Hi Grace

Please arrange for Marcus Chua of LKK Auto.

Sukyi

SM AUTOMOTIVE

1 Kaki Bukit Avenue 6, #01-43 Block C @ Autobay, Singapore 417883

6747 9241 F : 6741 7276	×	
	(i	

On Mon, Jul 2, 2018 at 3:05 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1802777/GPL

Your Reference: XB7128A

Without Prejudice

Date: 2nd July 2018

Attention:

M/S SM AUTOMOTIVE

Dear Sukyi,

ACCIDENT INVOLVING GBD2586T & XB7128A ON 26.06.2018

We refer to your Notice of Accident dated 02/07/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

	Pre-Repair Survey Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	

3 .	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click https://example.com/hereau/news/least-state/

From: Admin nht [mailto:admin@nhtmotor.com]

Sent: Monday, July 02, 2018 12:20 PM

To: Claims - Motor Survey

Cc: Reena

Subject: XB7128A CLAIMING AGAINST GBD2586T DOA:26.06.18

Without Prejudice

Hi Motor Claim Dept

Please send us your surveyor list, thanks.

Please take note this claim under SM Automotive

Sukyi
SM AUTOMOTIVE

1 Kaki Bukit Avenue 6, #01-43 Block C @ Autobay, Singapore 417883
T: 6747 9241 | F: 6741 7276

SM AUTOMOTIVE

Our Ref

: XB7128A

Your Ref : GBD2586T

Date

: 2/7/2018

1 Kaki Bukit Ave 6

Blk C @ Autobay, #01-43

Singapore 417883

Tel: (65) 6747 9241

Fax: (65) 6741 7276

Sompo Insurance Singapore Pte. Ltd.

BY EMAIL

motorsurvey@sompo.com.sg

Attention:

Motor Claims Department

Dear Sirs,

DATE OF ACCIDENT: 26 JUN 2018 @ 12:55 hours

NOTICE OF INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We act for WOON FONG TRANSPORT SERVICES who has appointed the undermentioned workshop to repair motor vehicle no. XB7128A

Please be informed that the said vehicle can be inspected at :

SM AUTOMOTIVE 1 KAKI BUKIT AVE 6 #01-43 BLK C @ AUTOBAY SINGAPORE 417883

Contact Person: Office @ 6747 9241 (Reena / Sukyi)

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The said workshop will commence repairs thereafter without further reference to you.

Yours Faithfully

SM Automotive

For Surveyor.

Please initial here after compleion of Pre-repair inspection. Thank you

Surveyor Name

& signature

Date&Time

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended De-registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date: Transfer Count:

Actual ARF Paid:

Actual ART Falu.

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 27 Jun 2018

Business

4200C

XB7128A

Yes

27 Jun 2018

SCANIA

P124CB8X4NZ

White

2000

6118787

Y52P8X40001263316

3

\$126,044.00

12 Apr 2001

12 Apr 2001

1

\$6,303.00

No

\$0.00

11 Apr 2021

C - Goods Vehicle & Bus

10

\$30,401.00

\$8,485.00

\$8,485.00

OK

MSME 18082834 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 27/06/2018 12:59 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties,
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report

27/06/2018 12:59

Date Of Accident

26/06/2018 12:55

Exact Location Of Accident

PIE TWDS TUAS ANAK BUKIT FLYOVER

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

XB7128A

Insured/Policyholder

Name Of Registered Owner

WOON FONG TRANSPORT SERVICES

Co Reg No

27954200C

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No.

OFFICE-90999887

Vehicle Particulars

Manufacturer

SCANIA

Model

P124CB8X4NZ

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company

ERGO INSURANCE PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

DMCV18S006573

Cover Note Number

Driver

NRIC No

Name of Driver

LUO WENZI

Date Of Birth

G6519694N 14/11/1973

Occupation

OUTDOOR

Date Of Driving Pass

20/09/2013

Driving Experience

4 YEARS AND 9 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-82825900

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

WET

RAINING

Road Surface

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

and the same

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG PIE TOWARDS TUAS ON THE SECOND LEFT LANE OF 4 LANES. AS I WAS TRAVELLING, ONE M/LORRY (GBD2586T) CAME FROM MY RIGHT, ENCROACHED INTO MY PATH AND COLLIDED ONTO THE RIGHT SIDE OF MY VEHICLE. AFTER THE COLLISION, THE SAID M/LORRY (GBD2586T) LOST CONTROL AND SKIDDED TO THE RIGHT MOST LANE. AFTER THE ACCIDENT, THE DRIVER OF (GBD2586T) INFORMED THAT WHILE HE WAS APPLYING BRAKE, HIS VEHICLE SKIDDED TO THE THIRD LANE (LOST CONTROL) THUS COLLIDED ONTO OUR VEHICLES AND SUBSEQUENTLY, HIT ONTO THE CENTER DIVIDER ON THE RIGHT MOST LANE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD2586T

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose(s).
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (iii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurer's' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/low firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (iii) for complying with requirements under any regulations, laws or court orders.

PolicyKolder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centra Parsonnel's Signature

Name:


NRIC/FIN No.:

SIARVE Sendifferine 75

RM AUTO

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

															TUAS			
श्रेहरका श	ac	Lei	-7	LANC	9	oF	A	LAN	, 29	AS	I	(DAS	TRA	WELLA	og.	ONE	11/100	LORRY
680	دد	285	7	come	7	ADION.	0 0	74	RIG H	7	ENC	ROACH	100	NTO	my f	H7H	400	
Cour	oel) 0	NA	the	c	P.16	h7	8100	0	FM	y L	EHIC	16	AF7CX	THE	coc	cis re	, نده
THE	5 3	QAID.	m	HERE	4 6	380	258	67	. 40	57	Con	10ch	AND	Ski	0000	to	THE	R16H7
Mes	1	LAN	ε.	AF	TER	1	THE	Acc	100	17 .	1	€ D	PIVER	OF	GBD:	382	7 "	VFORM
THE	1	WH	ILE	Н	e .	ons	1	1991	ING	AIS	BA	AKE	, 4119	ve	HICLE	8k1	0000	70
016	74	1180	16	عدوا	(1	037	COA	1700	(۱	th	us	000	coo	an	o ou	7 000	enche	ANI
0.4		,,-0	4				1		an	oe.	n		(40)	THE	DIGH	1 n	1057	MAG.
													407					

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyfiolder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

SM &UTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883 Email: SM_AUTOMOTIVE@HOTMAIL.COM Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

28/06/2018

Blk 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883

TPSompo

Accident date:

Estimated repair cost for vehicle no: XB7128A SCANIA

S/n C	Qty	Items / Special Nett	U/price	Amount
1	1	Rear R/H Plywood Tailgate Cracled)	\$2,000.00
2	5	Rear R/H Plywood Tailgate Hinge 2 pile	s Bed \$280.00	\$1,400.00
3	1	Rear R/H Tyre id		\$750.00
4	1	Rear R/H Tyre Front Mudguard Pish	ld	\$550.00
5	1	Rear R/H Tyre Front Mudguard Bracket	MIN	\$380.00
6	1	Rear R/H Tyre Rear Mudguard 3ex	t	\$550.00
7	1	Rear R/H Body Sticker / / /		\$380.00
8	1	Rear Petrol Tank Zeuted		\$2,650.00
9	1	Rear R/H Tyre Rim		\$750.00
10	1	Rear R/H Lower Arm		\$550.00
11	1	Rear R/H Upper Arm		\$450.00
12	1	Rear R/H Knuckle Arm		\$1,250.00
13	1	Rear R/H Knuckle Arm Bearing 지난 사	ev	\$280.00
14	1	Rear R/H Stabilizer Bar 2 N4		\$220.00
15	1	Rear R/H Shock Absorber		\$380.00

30 SN. 4850

Subtotal :- \$12,540.00

Labour charges

To remove & refit petrol tank

To remove & refit R/H undercarriage

To remove & refit tyre & aluminium

To repair crane, hydraulic pump, housing, pipe, control box,

\$380.00 15.

\$750.00 /50

\$180.00 /50

\$18,000.00

2000-2000

motor, switch & top up hydraulic oil

To check wiring

Panel beating

Spray painting

4300

\$100.00 <

\$1,800.00

\$1,800.00 250

\$23,010.00 Subtotal :-

\$35,550.00 Total:-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey beforefalter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to continuation Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed Supplementary (fem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date;



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internati		
SOMPO INSURANC	E SINGAPORE PL	Ref : CS/SMO18011988/Avd3n2	
50 RAFFLES PLAC #05-01/06 SINGAPORE LAND	E TOWERSINGAPORE 048623	Date: 27-08-2018	
		Code: SMO	
1.		:- THIRD PARTY CLAIM	XB 7128A
Insured Veh.	GBD 2586T	Veh. Inspected	0.00
Policy No.		Coverage (\$)	207.277
Claim No.	CMTD1802777/GPL	Excess (\$)	0.00
Assign From		Assign Date	02/07/2018
2.	Vehicle Par	ticulars & Condition	
Make & Mode	el SCANIA P124	c.c	11705
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	YS2P8X40001263316	Colour	BLUE
Odometer	•	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3.	Cond	itions of Tyres	
	Size	Make	Balance
R/H Front Ty	re 11.00 R20	DOUBLE HAPPINESS	6 mm
L/H Front Ty	re 11.00 R20	DOUBLE HAPPINESS	6 mm
R/H Rear Tyr	re 11.00 R20	DOUBLE HAPPINESS	6 mm
L/H Rear Tyr	e 11.00 R20	DOUBLE HAPPINESS	6 mm
4.	Descrip	tion of Damages	
	SUSTAINED DAMAGES AT THE C	O/S BODY.	
DAMAGES SE	E DETAILS.		
5.		ral Information	
Accident Da	te 26/06/2018	Inspection Date	03/07/2018
Survey held	at SM AUTOMOTIVE		
<u></u>	BLK C, 1 KAKI BUKIT AVENU	E 6 #01-43 SINGAPORE 41	7883
5a.		Remarks	
A)THE INSPE	CTION WAS CONDUCTED ON A"V	VITHOUT PREJUDICE" BASI	S. ED REPAIRS
B)IN ACCORE	DANCE TO YOUR INSTRUCTIONS.	te Days of Repair	ED REPAIRS.

ESTIMATED NORMAL PERIOD FOR REPAIR:

6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XB 7128A

Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS			
REAR R/H TYRE FRONT MUDGUARD BRACKET (SN)	NOT NECESSARY	380.00	12-
REAR R/H TYRE REAR MUDGUARD (SN)	BENT	550.00	550.00
REAR R/H TYRE RIM (SN)	NOT NECESSARY	750.00	
REAR R/H LOWER ARM (SN)	NOT NECESSARY	550.00	19
REAR R/H UPPER ARM (SN)	NOT NECESSARY	450.00	
REAR R/H KNUCKLE ARM (SN)	NOT NECESSARY	1,250.00	
REAR R/H KNUCKLE ARM BEARING (SN)	NOT NECESSARY	280.00	
REAR R/H STABILIZER BAR (SN)	NOT NECESSARY	220.00	
REAR R/H SHOCK ABSORBER (SN)	NOT NECESSARY	380.00	
REAR R/H PLYWOOD TAILGATE (SN)	CRACKED	2,000.00	1,600.00
REAR R/H PLYWOOD TAILGATE HINGE @\$280.00 (SN)	BENT (2 PCS ONLY)	1,400.00	450.00
1 REAR R/H TYRE (SN)	сит	750.00	600.00
REAR R/H TYRE FRONT MUDGUARD (SN)	DISTORTED	550.00	550.00
REAR R/H BODY STICKER (SN)	NECESSARY	380.00	100.00
REAR PETROL TANK (SN)	DENTED	2,650.00	1,000.00
		12,540.00	4,850.00
LABOUR			
TO REMOVE & REFIT PETROL TANK.		380.00	150.00
TO REMOVE & REFIT R/H UNDERCARRIAGE.		750.00	150.00
TO REMOVE & REFIT TYRE & ALUMINIUM.		180.00	150.00
TO REPAIR CRANE, HYDRAULIC PUMP, HOUSING, PIPE, CONTROL BOX, MOTOR, SWITCH & TOP UP HYDRAULIC OIL.		18,000.00	2,000.0
TO CHECK WIRING.	NOT NECESSARY	100.00	
PANEL BEATING.		1,800.00	1,000.00
SPRAY PAINTING.		1,800.00	850.00
		23,010.00	4,300.0
GRAND TOTAL		35,550.00	9,150.00
GRAND TOTAL	POT OF LUMP CUM PERAIDS		

RECOMMENDED COST OF LUMP SUM REPAIRS	7,300.00	
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO18011988/Avd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.