

ASS. REC. BY:

REF: CS3/MSG18011992/D24d3

Special Instruction:

Surveyor: **menmen**

Bryan

ASSIGNMENT (Office)

From (Person):

Lionel fan

of

MSIG

Date/Time:

2/7/18 @ 3:57pm

Estimated Cost:

Bill to:

OD # TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBD 8375X

Insured:

SLW 2541D

at Workshop m/s

Speedy Motor Cycle

Tel:

6 481 5567

of

10 AMK Ind. Park 2A #05-21

Policy No:

B27154205SMP

Claim No:

562811

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/06/2018

03/07/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement

Date/Time:

4:40pm @ 2/7/18

Person Contacted:

Ms Tan

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

FBD 8375X - NBA / MSG18011840 / Y

DOA: 27/6/2018

SLW 2541D - NBA / MSG18011840 / Y

DOA: 27/6/2018

Dismantle: 4/7/18

REF:

Surveyor

ASSIGNMENT

COB Aug 2019

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBD 8375X Yr Regn: 2009 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Spark c.c. 135

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 14631 T/Radio: Insured / Std / NI / NA

Eng/No: 5YPO10799

C/No: 5YPO10799

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 80/90 R17

80/90 R17 90/80 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front R/Bal. 3 mm Rear R/Bal. 3 mm

L/Bal. - mm L/Bal. - mm

D.O.A. 27/06/2018 D.O.I. 03/07/2018

Survey held at Speedy Moto SMK Antiput

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Front y O/S Body y O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSIG. PRS SLW 2541 D
	MV 21C
	LTA 162.10
	HL 1.81C Rep Unit. e 1.8K with 5 days jrn
RECEIVED 20 JUL 2018	

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Report Format: PRS

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jun 2018		02 Jul 2018 15:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	LEE LIAN PENG, ID: S1768694A, Tel: +6581185960								
Main Claimant:	LIM CHEE MIN, ID: S7048535D								
Vehicle Reg. No.:	FBD8375X	Date of Loss:	27/06/2018 16:00 - :59 [106 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 562811	Policy/Cover Note No.:	B27154205SMP (Comprehensive) Coverage: 28/06/2017 - 27/06/2018						
Vehicle Reg. No. (Insured):	SLW2541D	Policy No. (Claimant):							
		Excess:	S\$3,000.00						
Repairer:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/07/2018]								
Driver/Custodian (Insured):	CHOO KANG SIANG (64 / Male), NRIC: S0019130B, Tel: +6582185555								
Adj Asg. Remarks:	on WP, SJE - DISAGREED Please appoint LKK AUTO CONSULTANCY to conduct the survey . Kindly contact MR LIM SEE HEE @ 6481 5567 / 9388 6867 to arrange survey. Liability : NOT CLEAR								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**SINGAPORE
POLICE FORCE**



T/20180628/2142

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3
Report No, T/20180628/2142

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/06/2018 17:13		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: LIM CHEE MIN			Address: 258 ANG MO KIO AVE 4 #04-01 HDB-ANG MO KIO SINGAPORE 560258		
ID Type / ID No.: NRIC NO / S7048535D			Contact No.: Home/Office: Mobile: 93985868		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 48	Date of Birth: 29/05/1970	Type of Informant: Rider		
Race: Chinese		Language:		Institution / School Name:	
Occupation: Painter		Driving Licence Information: Class: 2B		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 27/06/2018 15:00	Type of Location: Straight Road
Location: Along Road 1 JALAN BUKIT MERAH				
SLIP ROAD INTO CTE(PIE)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
FBD8375X	Motorcycle	YAMAHA	SPARK 135 A	Red		0
SLW2541D	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBD8375X	MSIG INSURANCE (SINGAPORE) PTE. LTD.	60784810	26/01/2018	25/01/2019



**SINGAPORE
POLICE FORCE**



T/20180628/2142

2 of 3.

Report No. T/20180628/2142

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	LIM CHEE MIN	ID No.	S7048535D
Related Vehicle	NIL	Contact No.	93985868
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHOO KANG SIANG	ID No.	S0019130B
Related Vehicle	NIL	Contact No.	81185960
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE & LOCATION @ ABOUT 1500HRS,

I WAS RIDING(FBD8375X),WHILE I WAS GOING STRAIGHT,A CAR WAS IN HIGH SPEED,AND HE MOVED TOWARDS MY LANE AND I TRIED TO AVOID.AS I TRIED TO AVOID ,I SKIDDED AND FELL OFF FROM MY BIKE.

AFTER I FELL OFF,ONE OF THE PASSERBY HELPED ME.THE DRIVER CALLED THE AMBULLANCE AND THE AMBULLANCE ARRIVED @ SCENE.

I WAS BROUGHT OVER TO SINGAPORE GENERAL HOSPITAL,

THATS ALL



**SINGAPORE
POLICE FORCE**



T/20180628/2142

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

3 of 3
Report No, T/20180628/2142

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / YOGENDRAN S/O RAJASAKARAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sgt 3 MARIAH BINTE ZAKARIA Contact No.: 65476433

Signature Of Informant: <i>Sam</i>
Date/Time: 28/06/2018 17:13

Classification Of Case:
 SINGAPORE POLICE FORCE
Signature: <i>[Signature]</i>

Authentication Stamp
NP168

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBD8375X		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	SPARK 135 A		
Chassis No. :	5YP010799		
Propellant :	Petrol		
Engine No. :	5YP010799		
Engine Capacity :	135 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	109 kg		
Year Of Manufacture :	2009		
Original Registration Date :	25 Aug 2009		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,053.00		
COE Expiry Date :	24 Aug 2019		
Road Tax Expiry Date :	25 Jan 2019		
Inspection Due Date :	25 Jan 2019		
Intended Transfer Date :	19 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8535D
Vehicle Details	
Vehicle No.:	FBD8375X
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	YAMAHA
Vehicle Model:	SPARK 135 A
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	5YP010799
Chassis No.:	5YP010799
Maximum Power Output:	-
Open Market Value:	\$2,026.00
Original Registration Date:	25 Aug 2009
First Registration Date:	25 Aug 2009
Transfer Count:	4
Actual ARF Paid:	\$304.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2019
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,053.00
COE Rebate Amount:	\$162.00
Total Rebate Amount:	\$162.00

The information contained herein is correct as at 19 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jun 2018		02 Jul 2018 15:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE LIAN PENG , ID: S1768694A, Tel: +6581185960		
Main Claimant:	LIM CHEE MIN , ID: S7048535D		
Vehicle Reg. No.:	FBD8375X	Date of Loss:	27/06/2018 16:00 - :59 [106 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 562811	Policy/Cover Note No.:	B27154205SMP (Comprehensive) Coverage: 28/06/2017 - 27/06/2018
Vehicle Reg. No. (Insured):	SLW2541D	Policy No. (Claimant):	
		Excess:	S\$3,000.00
Repairer:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Imm.Advice due 03/07/2018]		
Driver/Custodian (Insured):	CHOO KANG SIANG (64 / Male), NRIC: S0019130B, Tel: +6582185555		
Adj Asg. Remarks:	on WP. SJE - DISAGREED Please appoint LKK AUTO CONSULTANCY to conduct the survey . Kindly contact MR LIM SEE HEE @ 6481 5567 / 9388 6867 to arrange survey. Liability : NOT CLEAR		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBD8375X (562811)**

[SLW2541D]

TP

LIM CHEE MIN

Jun 27 2018 4:00PM

[LEE LIAN PENG]

Speedy Motor Cycle Service Centre

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▼	
Video			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/07/18 18:56	Video - Accident	1	Load MP4	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/07/18 08:13	Accident Statement From: SC - Reg. No: SLW2541D, Claimant: LEE LIAN PENG	1	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	19/07/18 18:18	General View	1	Load JPG	<input checked="" type="checkbox"/>

Video				<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
31	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
33	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
34	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
35	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
38	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
50	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
51	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
52	19/07/18 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
53	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	19/07/18 18:20	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	19/07/18 18:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Video				
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
77	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
78	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
79	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
80	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
81	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
82	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
83	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
84	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
85	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
86	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
87	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
88	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
89	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
90	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
94	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
95	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
96	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
97	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
98	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
99	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
100	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
101	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
102	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
103	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
104	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
105	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
106	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
107	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
108	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
109	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
110	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
111	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
112	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
113	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
114	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
115	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
116	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
117	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
118	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
119	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
120	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
121	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
122	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
123	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
124	19/07/18 18:20	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Video					✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
125	19/07/18 18:20	Photographs of Damaged Parts		Load JPG	✓
126	19/07/18 18:20	Photographs of Damaged Parts		Load JPG	✓
127	19/07/18 18:20	Photographs of Damaged Parts		Load JPG	✓
128	19/07/18 18:20	Photographs of Damaged Parts		Load JPG	✓
129	19/07/18 18:20	Photographs of Damaged Parts		Load JPG	✓
130	19/07/18 18:20	Photographs of Damaged Parts		Load JPG	✓
Documentation				1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/07/18 08:13	TPD FBD8375X - SURVEY LISTING		Load PDF	
2	02/07/18 08:13	Reject email to TPD Lawyer & appoint LKK AUTO		Load PDF	
3	02/07/18 08:16	TPD FBD8375X - PRI & POLICE REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18011992/DZ4D3S2
Date: 20/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27154205SMP
Claimant Vehicle No :	FBD8375X	Insured Vehicle No :	SLW2541D
Date of Loss:	27/06/2018	Nature of Claim:	TP
		Claim No:	562811

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBD8375X	Engine No:	5YP010799
Make & Model:	YAMAHA SPARK, 135cc	Chassis No:	5YP010799
Reg. Date:	25/08/2009 (Man. Year: 2009)	Odometer:	14631 km
Colour:	Blue		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	80/90R17	Rear Tyre Size:	90/80R17
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/07/2018		
Date Inspected:	03/07/2018	Inspected At:	Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21 Singapore 568047
Estimated Period of Repair:	0.0 days		

Adjuster: BRYAN TANI

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jul 2018)
Parts:	N/A YAMAHA SPARK 135cc (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBD8375X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >