

Surveyor

Tanji

REF: A14

12001 / Tues

(W)

### ASSIGNMENT

From: Date: 16072018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDB 8890L

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Han

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

956K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SDB 8890L

Yr Regn:

2012 Apr.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Bmw 116i

c.c

1890

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

50685

T/Radio:

Insured / Std / NI / NA

Eng/No:

c

C/No:

WKA / A12010.3200784

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

25 / 60K6

R:

~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

16/7/18 @ 1040

Survey held at

PMU

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9382H
<b>Vehicle Details</b>	
Vehicle No.:	SDB8890L
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	116I AT ABS D/AIRBAG 2WD HID 5DR
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	B276J180N13B16A
Chassis No.:	WBA1A12010J200784
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,217.00
Original Registration Date:	30 Apr 2012
First Registration Date:	30 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$27,217.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2022
PARF Rebate Amount:	\$17,691.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$64,201.00
COE Rebate Amount:	\$24,289.00
<b>Total Rebate Amount:</b>	<b>\$41,980.00</b>

The information contained herein is correct as at 17 Jul 2018

OK