

ASS. REC. BY

REF: CS/GAI18012024/R/qd302

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Rachel Tan

of GAI

Date/Time: 3/7/18 @ 9:18am

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBE 1772 T

Insured: FBF 1833B

at Workshop m/s Southern Motor

Tel: 62730369

of BIK 1006, BKf Merah Lane 2 #01-10

Policy No: Claim No: CIMOMVM000000307

Sum Insured: Excess:

Make of Veh: D.O.A. 25/6/18
(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 10:06am @ 3/7/18

Person Contacted: Mr. Lim

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBE 1772 T - X
	FBF 1833B - NBA / MSG18011626/Y
04/7/18 @ 3:50pm	revised to Rachel Tan by email.
08/10/18 @ 5:14pm	checked with Ah Kiat, the motorbike has not send in for repair due to awaiting liability issued.
09/10/18	submit Pres. report.

DOA: 25/6/2018

(08/11/13) • wet

ASS. REC. BY:

REF:

GAI

40126

ASSIGNMENT

From:

Date:

03/07/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBF 1772T

at Workshop m/s

Southern Motor

of

Bik 1006 Bkt March Lane 2 #01-10

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBF 1772T

Yr Regn: 2011 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA FZ16

C.C.

153

Colour

BLACK

A/C:

Insured / Std / NI / NA

Sp. Reading

99999

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ME12165182026812

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/70-17

R:

140/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/06/18

D.O.I.

03/07/18

Survey held at

Southern Motor

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 09 OCT 2018

Date/Time, File Pass to?



Preli. Report

1) 09/10 10:00 AM



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

250

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Nivitha (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Tuesday, 3 July 2018 9:18 AM
To: LKK Assignments
Subject: CLMOMVM000000307 - FBF1833B (GA) v FBE1772T on 25/6/18
Attachments: 03072018091312-0001.pdf

Hi LKK

Please assist on the PRI for above mentioned on a without prejudice basis.
Liability is not clear.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

-----Original Message-----

From: ApeosPort-VI C5571 <SIN.International.Xerox5571-Claims@sg.gaig.com>
Sent: Tuesday, July 3, 2018 9:13 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: Scan Data from FX-110081

Number of Images: 10
Attachment File Type: PDF

Device Name: ApeosPort-VI C5571
Device Location:

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 July 2018 3:50 PM
To: 'Tan, Rachel'; assignments
Cc: SUR
Subject: RE: CLMOMVM000000307 - FBF1833B (GA) v FBE1772T on 25/6/18
Attachments: CSGAI18012024R1qd3.pdf

Dear Rachel,

Enclosed herewith preliminary advice of FBE 1772T.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)
Sent: Tuesday, 3 July 2018 10:08 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CLMOMVM000000307 - FBF1833B (GA) v FBE1772T on 25/6/18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Tuesday, 3 July 2018 9:18 AM
To: LKK Assignments <assignments@lkkauto.com>
Subject: CLMOMVM000000307 - FBF1833B (GA) v FBE1772T on 25/6/18

Hi LKK

Please assist on the PRI for above mentioned on a without prejudice basis.
Liability is not clear.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

-----Original Message-----



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Claim No. : CLMOMVM000000307

Date: 04th July 2018

Our Ref: CS/GAI18012024/R1qd3

The Motor Claims Department
Great American Insurance Company

Attn: Rachel

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. FBE 1772T

We thank you for the instruction on 03/07/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/07/2018 at the premises of M/s SOUTHERN MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$	<u>2,113.30</u>	.
Revised Estimate Amount	: S\$	<u>1,643.30</u>	.
"Check" Items Amount	: S\$	<u>-</u>	.
Market Value	: S\$	<u>-</u>	.
Salvage Value	: S\$	<u>-</u>	.
Nett Value	: S\$	<u>-</u>	.

Description of Damage:
The motorbike sustained damages at the
o/s portion.



Comments/ Present Status:
Damages consistent.
Recommend repair days: 3 days
We have NOT authorise repair.

Yours faithfully

Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2018 16:18
Date Of Accident	25/06/2018 14:15
Exact Location Of Accident	ALONG DUNEARN RD B/F TURNING LEFT TO YARWOOD AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF1772T
Insured/Policyholder	
Name Of Registered Owner	TAN BUCK CHOON
NRIC No	S1624012E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91123345
Alternative Phone No	OTHERS-91123345

Vehicle Particulars

Manufacturer	YAMAHA
Model	FZ16-153CC (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/VMT/18-378138-CA
Cover Note Number	

Driver

Name of Driver	TAN BUCK CHOON
NRIC No	S1624012E
Date Of Birth	28/04/1963
Occupation	OUTDOOR
Date Of Driving Pass	17/10/1987
Driving Experience	30 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91123345
Fax Number	
Contact Number	OTHERS-91123345
Email Address	NOEMAIL

Address	BLK 289E BUKIT BATOK STREET 25 #16-152
Postcode	654289
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ALEXANDRA NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 46-2 COMMONWEALTH DR , POSTCODE: 140462 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4739999 - FAX NO: 64713569
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20180625/2138

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBF1833B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMMAD ASHRAFF BIN RAMLI
NRIC/Passport Number	S9912774J
Contact Number	81281792
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

*Great American Insurance Company
3 Temasek Ave #16-01
Centennial Tower
Singapore 039190
Tel 68047846
Fax 62353354*

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN BUCK CHOON

Approximate Age

Injuries Sustain SLIGHT INJURY

Injured person in which vehicle? FBE1772T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode



SINGAPORE POLICE FORCE



T/20180625/2138

Police Station Of Origin:
Alexandra NPP
46 Tanglin Halt Road #01-328 SINGAPORE
140462
Tel No: 1800-4739999

1 of 3

Report No. T/20180625/2138

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/06/2018 16:37	Vide Report No.:	Station Diary No.: 23
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TAN BUCK CHOON		Address: APT BLK 289E BUKIT BATOK STREET 25 #16-152 SINGAPORE 654289	
ID Type / ID No.: NRIC NO / S1624012E		Contact No.: Home/Office: Mobile: 91123345	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 55	Date of Birth: 28/04/1963	Type of Informant: Rider
Race: Chinese		Language:	Institution / School Name:
Occupation: Painter		Driving Licence Information: Class: 2B,3,4,5 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 25/06/2018 14:15	Type of Location: Straight Road
Location: Along Road 1 DUNEARN ROAD				
Along Dunearn road before turning left into Yarwood Ave, just outside Esso Petrol Kiosk.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF1772T	Motorcycle	YAMAHA	FZ 16	Black	Slightly Damaged	0
FBF1833B	Motorcycle				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBF1772T	MSIG INSURANCE (SINGAPORE) PTE. LTD.	MSDTMT18378138	26/03/2018	25/03/2019



**SINGAPORE
POLICE FORCE**



T/20180625/2138

Police Station Of Origin:
Alexandra NPP
46 Tanglin Halt Road #01-328 SINGAPORE
140462
Tel No: 1800-4739999

2 of 3

Report No. T/20180625/2138

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN BUCK CHOON	ID No.	S1624012E
Related Vehicle	NIL	Contact No.	91123345
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On above mentioned date, time and location, I was riding my bike FBF1772T along Dunearn Road just before turning left into Yarwood Ave, outside Esso Petrol Kiosk. Suddenly I felt an impact from my rear left and my body was thrown forward. I realized it was another motorcycle with plate number FBF 1833B. The rider also fell onto the road. My bike had slight damage on the rear plate area, while the other rider had slight damage to his front area.

We got up and exchanged particulars and decided not to call the police. We agreed to settle through insurance.

I suffered slight abrasion on my left hand and bruises on my left shoulders. I will go and see a doctor after lodging this report

The other rider's particulars are:
Muhammad Ashraff Bin Ramli
S9912774J
HP:81281792



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Alexandra NPP
46 Tanglin Halt Road #01-328 SINGAPORE
140462
Tel No: 1800-4739999



T/20180625/2138

3 of 3

Report No. T/20180625/2138

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /
Sgt 2 TAN TUAN WANG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SSI 2 SITIMARSITA BINTE BOHARI
Contact No.: 65476219

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
25/06/2018 16:37

Classification Of Case:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

26/6/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

26/06/2018
Reshi wong

SKETCH PLAN

ESSO STATION

YARWOOD
AVE

FBF1833B



FBF1772T



DUNKERN ROAD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Q12 REFERR TO POLICE REPORT
T/20180625/2138

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

26/6/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

26/06/2018
Rohit Kumar



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614
Mr Lim

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 2nd July 2018
Motor Claims Department
Great American Insurance Company
3 Temasek Ave #16-01
Centennial Tower
Singapore 039180

RECEIVED
03 JUL 2018

BY:

Dear Sirs

Re: Cost of repairs to Yamaha FZ16 - FBF 17727

1 pc of Head lamp complete	S\$ 195.00
" Head lamp cover	S\$ 50.00
" Handle bar	S\$ 15.00
" Handle grips	S\$ 15.00
" Brake lever	S\$ 10.00
" Mirror	S\$ 45.00
" Front footrest bracket	S\$ 40.00
" Gear lever	S\$ 25.00
" Brake pedal	S\$ 20.00
" Exhaust pipe	S\$ 50.00
" Tail cover	S\$ 10.00
" Rear mudguard	S\$ 60.00
" Rear No plate mudguard	S\$ 40.00
" Rear Signal	S\$ 25.00
	<u>S\$ 1,437.00</u>
	S\$ 143.70
	<u>S\$ 1,293.30</u>

Less 10%

-2 JUL 2018 9:04am

TO CALL BACK
LOOK for Mr Lim
R7.

(LKF)

Yours faithfully,
SOUTHERN MOTOR

Nett	
Transport	S\$ 30.00
Jack rear body	S\$ 110.00
Kappa box	S\$ 20.00
No plate	S\$ 10.00
Labour	S\$ 200.00
	<u>S\$ 370.00</u>
	<u>S\$ 1,663.30</u>

Mr Lim called back -
PRI first
Liability not clear
-R7

Tel 6204 7846
Fax 6235 3374



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 2nd July 2018
Motor Claims Department
Great American Insurance Company
3 Temasek Ave #16-01
Centennial Tower
Singapore 039180

Dear Sirs

Re: Cost of repairs to Yamaha FZ16 - FBF 17727

1 pc of Head lamp complete	195.00	sun
" Head lamp cover	9.00	sun
" Handle bar	15.00	PA
" Handle grips	2.50	cut
" Brake lever	1.00	sun
" Mirror	45.00	sun
" Front footrest bracket	4.00	PA
" Rear lever	35.00	Xsun
" Brake pedal	2.00	sun
" Exhaust pipe	50.00	sun
" Tail cover	1.00	sun
" Rear mudguard	6.00	sun Xsun
" Rear No plate mudguard	4.00	CR
" Rear Signal	2.00	sun
	1,437.00	
	143.70	
	1,293.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Less 10%

Nett

Transport
Teck rear body
Kappa box
No plate
Labour

30.00

~~25.00~~ 100 ~~sun~~

20.00 150 sun

10.00

~~20.00~~ 150

PA 2,113.30

Yours faithfully,
SOUTHERN MOTOR

RASUL

HP 90010068

3 days

4/5

03/07/18 @ 1225

Resurvey after repair

TEL 6204 7846
Fax 6235 3354




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18012024/R1qd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 25-10-2018		
Code : GAI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBF 1833B	Veh. Inspected	FBE 1772T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVM000000307	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA FZ 16	c.c	153	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	ME121C051B2026812	Colour	BLACK	
Odometer	99999	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70-17	BRIDGESTONE	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70-17	BRIDGESTONE	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/06/2018	Inspection Date	03/07/2018	
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 1772T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD LAMP COMPLETE	SCRATCHED	195.00	195.00
1	HEAD LAMP COVER	SCRATCHED	90.00	90.00
1	HANDLE BAR	BENT	55.00	55.00
1	HANDLE GRIPS	CUT	25.00	25.00
1	BRAKE LEVER	SCRATCHED	18.00	18.00
1	MIRROR	SCRATCHED	45.00	45.00
1	FRONT FOOTREST BRACKET	BENT	48.00	48.00
1	GEAR LEVER	SERVICEABLE	35.00	-
1	BRAKE PEDAL	SCRATCHED	28.00	28.00
1	EXHAUST PIPE	SCRATCHED	580.00	580.00
1	TAIL COVER	SCRATCHED	180.00	180.00
1	REAR MUDGUARD	SERVICEABLE	65.00	-
1	REAR NO PLATE MUDGUARD	CRACKED	48.00	48.00
1	REAR SIGNAL	SCRATCHED	25.00	25.00
	LESS 10% DISCOUNT		-143.70	-133.70
			1,293.30	1,203.30
	<u>SPECIAL NETT ITEMS</u>			
1	KAPPA BOX (SN)	SCRATCHED	280.00	150.00
1	NO PLATE (SN)	CRACKED	10.00	10.00
			290.00	160.00
	<u>LABOUR</u>			
	TRANSPORT.		30.00	30.00
	JACK REAR BODY.		250.00	100.00
	LABOUR.		250.00	150.00
			-	-
			-	-
			-	-
			530.00	280.00
	GRAND TOTAL		2,113.30	1,643.30

Report Ref No. CS/GAI18012024/R1qd3e2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			1,643.30
---	--	--	----------

Report Ref No. CS/GAI18012024/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.