

ASS. REC. BY:

REF: CS/MSG18012025 / Ksd3nz Special Instruction

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Jasmine Lok of MSIG Date/Time: 3/7/18 @ 10:07am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJF 2465D Insured: SKP 7394C

at Workshop m/s: Keng Hock Auto Tel: 9657 1534

of Blk 7 Sin Ming Ind. Est C# 01-84

Policy No: B27786878SMP Claim No: 562954

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01/07/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS lup H.O.D. Endorsement: _____

Date/Time: 10:49am @ 3/7/18 Person Contacted: thomas Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 2465D - CS / CAI 3008198 / Uqn DUA: 2/5/2013
	SKP 7394C - X.
<u>04/07/18</u>	<u>@ 17:17 p.m. revised IA to Jasmine Lok via merimer.</u>
<u>12/18</u>	<u>LI Lyn @ 42501 email</u>

ASS. REC. BY:

REF: MS61

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Key Hook

of 7

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 35k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5-6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5123

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: Sark 2465D Yr Regn: 05, 0d
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or M.P.V

Make: Toy wish c.c. 1794

Colour: M. Piber A/C: Insured / Std / NI / NA

Sp. Reading: 189321 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZNE10 . 0404717

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: Maxen

R: Autone 205/50 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 11/7/18

Survey held at _____

Rear R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 3/7/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>4/7</u>	<u>File pass to Cartene Kenneth</u>
<u>12/09/18</u>	<u>Parts Prices checked by Kenneth, pls check parts prices. Confirmed 215 \$ A.250/- @ 6 days with Kenneth (C \$4988/- Red - 54%).</u>

RECEIVED 3 SEP 2018

5/7

Date/Time, File Pass to? 13/09/18
1) Typist
Date/Time, File Return to? _____

: Prell. Report
 : Final Report

Days Of Repair: 6
Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	<u>200</u>
S - RS. SI	<u>10</u>
Fixtios	
Others	
TOTAL	<u>210</u>

Report Format : _____
Lump Sum / I.B.I. (\$) 4,250/- H.S.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2018		03 Jul 2018 10:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SHEN YUHUA, ID: S7087528D, Tel: +6590212405, Email: STELLA.W.SHEN@GMAIL.COM		
Main Claimant:	C & L CAR RENTAL, Co. Reg. No.: 53311266D		
Vehicle Reg. No.:	SJF2465D	Date of Loss:	01/07/2018 09:00 - :59 [121 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 562954	Policy/Cover Note No.:	B27786878SMP (Comprehensive) Coverage: 07/10/2017 - 06/10/2018
Vehicle Reg. No. (Insured):	SKP7394C	Policy No. (Claimant):	
		Excess:	
Repairer:	Keng Hock Auto () BLK 7 SIN MING INDUSTRIAL ESTATE C #01-84, 575642 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/07/2018]		
Driver/Custodian (Insured):	SHEN YUHUA (48 / Female), NRIC: S7087528D, Tel: +6590212405		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP nominated LKK (Mr Kenneth Kong) to be SJE. Liability not clear. Contact : Thomas/ 9657 1534		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 04 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKP7394C	Accident Date	: 01/07/2018
TP Vehicle No	: SJF2465D	Assignment Date	: 03/07/2018
Make	: TOYOTA WISH	Est. Duration of Repair	: 6 days
Date of Inspection	: 03/07/2018		
Inspection At	: Keng Hock Auto BLK 7 SIN MING INDUSTRIAL ESTATE C #01-84 Singapore 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,172.90
Revised Amount	:S\$	5,923.44
Check Items (Estimated)	:S\$	1,234.88
Total	:S\$	7,158.32

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2018 11:25
Date Of Accident	01/07/2018 09:00
Exact Location Of Accident	REFLECTIONS AT KEPPEL BAY, CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF2465D
Insured/Policyholder	
Name Of Registered Owner	C & L CAR RENTAL
Co Reg No	53311266D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93834289
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5099216131
Cover Note Number	
Driver	
Name of Driver	TAN CHEE YONG
NRIC No	S6820785A
Date Of Birth	24/05/1968
Occupation	OUTDOOR
Date Of Driving Pass	05/06/1987
Driving Experience	31 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93834289
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 213 CHOA CHU KANG CENTRAL
 #05-112
 Postcode 680213
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle: -
 -
 -

General information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes against whom?

Circumstances of Accident

REFER ATTACHED


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKP7394C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SHEN YUHUA
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am in the car park at Reflection@Keppel to pick up a passenger @ tower ~~33~~ 33. The vis visibility in the car park is very low. I stop to look for the tower 33 and the car behind driven by Shen Yukun car plate SKP 7394C being on my back back.

DECLARATION

I/we declare that the above particulars are true in every respect.

CAR RENTAL
 BLOCK 7 #01-84
 SIN MING IND. ESTATE SECTOR C
 SINGAPORE 575642
 TEL: 655 1534 FAX: 6458 5588
 Date & Reg No 53311266D

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 2/07/2018

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for compliance with requirements under any regulations, laws or court orders.

C & L CAR RENTAL
 BLOCK 7 #01-84
 SIN MING IND ESTATE SECTOR C
 SINGAPORE 575642
 TEL/HP 9657 1534 FAX: 6458 5539
 Reg No. 53311266D

Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

慶福摩嘜
 KENG HOCK AUTO
 SECTOR C, BLK 7 #01-84
 SIN MING ROAD SINGAPORE 575842
 TEL/FAX: 6458 5589 H/P: 9657 1534

Not Authorized
 61 Sing B4250L
 Resurvey After Paint
 6 days

Date: 3/7/18

Terms:

Quotation

Regn. No:

SJF 2465 D

Vehicle Make:

TOYOTA WISH

Mileage:

Repaired/Labour Charges / Other Services

	Qty	U/Price \$	Amount \$	
Tail gate	1210.15	Bu	1,460.30	✓
Tail Gate emblem (Logo)		Ma	70.10	—
Tail Gate weather strip		Dal/CM	260.40	Solr
Tail Gate inner garnish		MS/CM	350.10	—
Tail Gate lock		DJ	388.70	—
Tail Gate lock latch		R	42.10	X
Tail Gate outer chrome handle	383.85	CM	450.10	✓
Tail Gate door sensor		SM	230.40	X
2 Tail lamp	0.15 MS/CM N/15 CM		960.10	✓
2 Tail plate lamp		SM	60.10	X
Rear bumper	500.30	Bu	1,250.00	✓
1 set Rear bumper clips		Ma	70.10	—
Rear bumper bracket		R	150.80	R
2 Rear bumper side retainer		N/15 Mi	120.10	✓
2 Rear bumper stay		R	140.20	R
Rear end panel		Bu	480.40	R
Rear end panel top garnish		SM	260.10	R
1 set Rear end panel top garnish clips		Ma	35.00	R
Rear bumper reflector		SM	60.00	^
Rear wind screen moulding		Ma	168.10	✓
Tail wiper motor		SM	580.00	R

251

1 set Rear reverse sensor
 Rear number plate
 Rear wind screen sealant

2005N
 Phat 250.00
 Sur 30.00 205N
 Ma 80.00 405N

E & O E

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

慶福摩多
KENG HOCK AUTO
SECTOR C, BLK 7 #01-84
SIN MING ROAD SINGAPORE 575642
TEL/FAX: 6458 5589 H/P: 9657 1634

Date: 3/7/18

Terms:

Quotation

Regn. No: SJF 2465 D

Vehicle Make: TOYOTA WISH

Mileage:

Replaced / Labour Charges / Other Services	Qty	U/Price \$	Amount \$
To Spray anti rust on accident affected panel		601	180 00
To remove both tail lamps, Check wiring system to facilitate repair and refit the same		201	50 00
To remove and refit all fitting to new tail gate to facilitate repair		601	120 00
To redo sealant on gap to facilitate repair		301	100 00
To remove and refit rear wind screen glass to facilitate repair		1201	150 00
To panel beat		6001	1,200 00
To Spray - painting		7001	1,300 00
			-9,238/-
			11077.20

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012025/KSD3N2

Date: 17/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27786878SMP
Claimant Vehicle No :	SJF2465D	Insured Vehicle No :	SKP7394C
Date of Loss:	01/07/2018	Nature of Claim:	TP
		Claim No:	562954

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF2465D	Engine No:	1ZZ3080103
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZNE100404717
Reg. Date:	23/05/2008 (Man. Year: 2008)	Odometer:	189321 km
Colour:	Metallic Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R15	Rear Tyre Size:	205/50 R15
Front Left Side:	Nexen 9 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Nexen 9 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,977.20	3,894.16	4,083.04	51.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,590.00	1,510.00	48.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,077.20	5,484.16	5,593.04	50.49
Approved Total (Overridden) (S\$)		4,250.00		
Nett Amount (S\$)	11,077.20	4,250.00	6,827.20	61.63

INSPECTION

Date of Assignment:	03/07/2018	
Date Inspected:	03/07/2018 Inspected At:	Keng Hock Auto BLK 7 SIN MING INDUSTRIAL ESTATE C #01-84 Singapore 575642
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2018)
Parts: M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF2465D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,460.30 F	*1,210.15 FL
2	1		*TAIL GATE EMBLEM (LOGO)	Necessary	70.10 F	*70.10 FL
3	1		*TAIL GATE INNER GARNISH	Mtg Cracked	380.10 F	*380.10 FL
4	1		*TAIL GATE LOCK	Dented	388.70 F	*388.70 FL
5	1		*TAIL GATE LOCK LATCH	Repair	42.10 F	*- FL
6	1		*TAIL GATE OUTER CHROME HANDLE	Cracked	450.10 F	*383.85 FL
7	1		*TAIL GATE DOOR SENSOR	Serviceable	230.40 F	*- FL
8	2		*TAIL LAMP	O/s Mtg Cracked/N/s Cracked	960.10 F	*960.10 FL
9	2		*TAIL PLATE LAMP	Serviceable	60.10 F	*- FL
10	1		*REAR BUMPER	Buckled	1,250.00 F	*500.30 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	70.10 F	*70.10 FL
12	1		*REAR BUMPER BRACKET	Repair	150.80 F	*- FL
13	1		*REAR BUMPER SIDE RETAINER	N/s Distorted	120.10 F	*60.05 FL
14	2		*REAR BUMPER STAY	Repair	140.20 F	*- FL
15	1		*REAR END PANEL	Bent	480.40 F	*480.40 FL
16	1		*REAR END PANEL TOP GARNISH	Serviceable	260.10 F	*- FL
17	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	35.00 F	*- FL
18	1		*REAR BUMPER REFLECTOR	Serviceable	60.00 F	*- FL
19	1		*REAR WIND SCREEN MOULDING	Necessary	168.10 F	*168.10 FL
20	1		*TAIL WIPER MOTOR	Serviceable	580.00 F	*- FL
21	1		*TAIL GATE WEATHER STRIP (50%)	Dented/Cut	260.40 FS	*130.20 FS
22	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
23	1		*REAR NUMBER PLATE	Scratched	30.00 FS	*20.00 FS
24	1		*REAR WIND SCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,977.20	5,062.15
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,167.99
Total Parts (\$\$)	7,977.20	3,894.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PANEL	New	180.00	60.00
2	TO REDO SEALANT ON GAP TO FACILITATE REPAIR	New	100.00	30.00
3	TO REMOVE BOTH TAIL LAMPS,CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	50.00	20.00
4	TO REMOVE AND REFIT ALL FITTING TO NEW TAIL GATE TO FACILITATE REPAIR	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WIND SCREEN GLASS TO FACILITATE REPAIR	New	150.00	120.00
6	TO PANEL BEAT	New	1,200.00	600.00
7	TO SPRAY PAINTING	New	1,300.00	700.00
Gross Labour Cost (S\$)			3,100.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >