

ASS. REC. BY:

REF: C83 / LPC18012027 / Noob Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Eric Woo of LPC Date/Time: 28062018 11:32am

Estimated Cost: Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 1234A Insured: SJV 8349M

at Workshop m/s Sin Motor Tel: 6453 3908

of Blk 176 Sin Ming Drive #05-07

Policy No: Claim No: 18/18/18/VP05/020701

Sum Insured: Excess:

Make of Veh: D.O.A. 25062018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLM 1234A - X
	SJV 8349M - X
	Submit PRS report
	* check with Lim 91811947

ERIC WOO JUN KIAT

From: ERIC WOO JUN KIAT
Sent: Thursday, 28 June, 2018 11:32 AM
To: 'accident@kscgp.com'
Cc: MT_Claim_SG
Subject: Our Ref: 18/18/18/VP05/020701 Your Ref: SLM1234A/SMR/jp/ja Accident involving SJV8349M & SLM1234A along CTE Balestier on 25/6/2018
Attachments: 28062018112954.pdf

WITHOUT PREJUDICE
SAVE AS TO COST

We refer to your fax of 27 June 2018.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

ERIC WOO JUN KIAT

From: ERIC WOO JUN KIAT
Sent: Thursday, 28 June, 2018 12:12 PM
To: 'accident@kscgp.com'
Cc: MT_Claim_SG; jiapei@kscgp.com; 'assignments@lkkauto.com'
Subject: RE: 2nd Notice to conduct pre-repair inspection/survey. Your Ref:18/18/18/VP05/020701
Our Ref: SLM1234A/SMR/jp/ja Accident involving SJV8349M & SLM1234A along CTE
Balestier on 25/6/2018
Attachments: 2nd PRS.PDF

Dear Jatin,

Thank you for your list of surveyors.

We regret we are not agreeable to your panel of surveyor as listed.

We shall be assigning to LKK Auto Consultants Pte Ltd to conduct the survey on your client's
vehicle No: SLM 1234A.

Dear Catherine / Nivitha,

FYA.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: accident@kscgp.com [<mailto:accident@kscgp.com>]
Sent: Thursday, 28 June, 2018 11:50 AM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG; jiapei@kscgp.com
Subject: RE: 2nd Notice to conduct pre-repair inspection/survey. Your Ref:18/18/18/VP05/020701 Our Ref:
_M1234A/SMR/jp/ja Accident involving SJV8349M & SLM1234A along CTE Balestier on 25/6/2018

Dear Sirs,

Please see enclosed our 2nd Notice to conduct Pre-Repair Survey.

Thank you.

Regards,
Jatin
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and

ERIC WOO JUN KIAT

From: ERIC WOO JUN KIAT
Sent: Thursday, 28 June, 2018 5:25 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: 2nd Notice to conduct pre-repair inspection/survey. Your Ref:18/18/18/VP05/020701
Our Ref: SLM1234A/SMR/jp/ja Accident involving SJV8349M & SLM1234A along CTE
Balestier on 25/6/2018
Attachments: 2nd PRS.PDF

Dear Catherine,

As spoken, resend for your action.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

30 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: ERIC WOO JUN KIAT
Sent: Thursday, 28 June, 2018 12:12 PM
To: 'accident@kscgp.com'
Cc: MT_Claim_SG; jiapei@kscgp.com; 'assignments@lkkauto.com'
Subject: RE: 2nd Notice to conduct pre-repair inspection/survey. Your Ref:18/18/18/VP05/020701 Our Ref:
SLM1234A/SMR/jp/ja Accident involving SJV8349M & SLM1234A along CTE Balestier on 25/6/2018

Dear Jatin,

Thank you for your list of surveyors.

We regret we are not agreeable to your panel of surveyor as listed.

We shall be assigning to LKK Auto Consultants Pte Ltd to conduct the survey on your client's
(Vehicle No: SLM 1234A.

Dear Catherine / Nivitha,

FYA.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: accident@kscgp.com [<mailto:accident@kscgp.com>]
Sent: Thursday, 28 June, 2018 11:50 AM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG; jiapei@kscgp.com
Subject: RE: 2nd Notice to conduct pre-repair inspection/survey. Your Ref:18/18/18/VP05/020701 Our Ref:
SLM1234A/SMR/jp/ja Accident involving SJV8349M & SLM1234A along CTE Balestier on 25/6/2018



LONPAC INSURANCE BHD

Policy / Claim No : 18/18/18/VP05/020701

Insured Veh No : SJV 8349M

Accident Date / Time : 25/6/2018

At / along CTE Balestier

Please select one of the following surveyors to inspect

T/P Veh No. SLM 1234A at workshop TBA

Lonpac's Fax No / Tel : 6296 2706 / 6250 7388

Please select one of the following surveyors:

No	Name of Surveyor	Please tick <input checked="" type="checkbox"/>
1	Bryan Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Kalvin Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Prepare by: Eric Woo

Your Ref : SJV 8349H
Our Ref : SLM 1234A/SMR/jp/ja
Date : 27 June 2018



18/18/18/VPO5/020701

Email: accident@kscgp.com

Lonpac Insurance Berhad

BY FAX 6296 3767 ONLY

DATE OF ACCIDENT: 25 JUNE 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of SLM 1234A to notify you of a road traffic accident on 25 June 2018 at about 11.05am along CTE towards city (near Novena), involving our client's vehicle registration number SLM 1234A and vehicle registration number SJV 8349H which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

F JP

(Main Office)
Enc.
Cc client

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2018 14:23
Date Of Accident	25/06/2018 11:05
Exact Location Of Accident	CTE TWDS CITY (NEAR NOVENA)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM1234A
Insured/Policyholder	
Name Of Registered Owner	CHEW LI BENG
NRIC No	S7537478Z
Email Address	VICKICHEW@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91551696
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	BR2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00465522
Cover Note Number	

Driver

Name of Driver	CHEW LI BENG
NRIC No	S7537478Z
Date Of Birth	12/12/1975
Occupation	INDOOR
Date Of Driving Pass	04/07/1997
Driving Experience	20 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91551696
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	VICKICHEW@HOTMAIL.COM

Address	44 SERAYA CRESCENT
Postcode	575858
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV8349H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YANG YAN
NRIC/Passport Number	S7964193F
Contact Number	84882185 - 91473356
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



Contact us at
 Hotline: (65) 6532 2888
 E-mail: CustomerService@DirectAsia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.	:	MT/00465522
Type of Coverage / Driver Plan	:	Low Mileage Car Comprehensive (Value Plan)
1) Vehicle Registration No.	:	SLM1234A
Chassis No.	:	JF1ZC6K72HG012009
2) Name of Policy Holder	:	Chew, Li Beng
3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	:	23/03/2018 11:17
4) Date/Time of Expiry of Insurance	:	09/03/2019 23:59
5) Persons or Classes of Persons Entitled to Drive		
(a) The Insured		
(b) Any person who is named on the policy who is driving on the Insured's order or with his permission.		
The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.		
6) Limitations as to use*		
Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business.		
*Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.		
Sum Insured	:	Market Value
Own Damage Excess	:	S\$ 1,500.00 (before any applicable GST)
Windscreen Excess	:	S\$ 100.00 (before any applicable GST)
Choice of workshop	:	My Workshop/ My Authorised Distributor Workshop
Finance company / Hire Purchase	:	DBS Bank Ltd
Main driver	:	Chew, Li Beng
Ref		
Named driver (1)	:	OH WEE TAI NICHOLAS
		Named Driver
		Date of Birth
		06/07/1971
Important Note: This policy is on a named driver basis. Any unnamed drivers will not be covered.		

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).


Issued on: 23/03/2018

Direct Asia Insurance (Singapore) Pte. Ltd.

Edip Okur
 Chief Underwriting Officer

Date of accident: 25/6/18 Time: 11:05 Location: CTE (Towards City)
 My Vehicle A: SLM 1234A Vehicle B: SJV 8349H Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along CTE towards city on 25th June 2018 around 11:05am on lane 1. Suddenly I heard and felt a long bang on back of my vehicle (A). I put on hazard light and stopped the car immediately. The car (BMW black) B behind had hit my left rear of A while trying to change to lane 2. B then moved his car in front of my car and we took photos and exchange details and contact numbers. 2 men stopped their car on road shoulder and came up to offer assistance. They then called LTA and EMAS towing as both cars' wheel were damaged in accident. EMAS towed our vehicles to nearest public carpark behind Moulmain road and subsequently owner & driver of B called towing service to tow to his preferred workshop Sin My Autocare # 05-07 and B ~~said~~ informed me to ~~submit~~ insurance. He will pay damages through his insurance.

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: SIN MOTOR
 Email address:
 & myself:
 Email address: vickichew@hotmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle: - SLM 1234A

Policyholder's Signature
 Date & Time: 26/6/18 1:02pm

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: Mee L
 NRIC/FIN No.: 26/06/18





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC18012027/Nrbe2 Date: 16-10-2018 Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJV 8349M	Veh. Inspected	SLM 1234A	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020701	Excess (\$)	0.00	
Assign From	ERIC WOO	Assign Date	28/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU BRZ	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1ZC6K72HG012009	Colour	WHITE	
Odometer	5595 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
5. General Information				
Accident Date	25/06/2018	Inspect Date / Time	02/07/2018 (12:09 PM)	
Survey held at	SIN MOTOR REPAIRS BLK 176 SIN MING DRIVE #05-07 SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC18012027/Nrbe2

Inspected By



MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.