

ASS. REC. BY:

REF. CS/FCI 18012039 / TH 322

Special Instruction:

Surveyor:
CWS

Tauhiah

ASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time:

3/7/18 @ 12.23pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 3310R

Insured:

SHA 44204

at Workshop n/s

Pegasus Engineering

Tel:

6513 7748

of

74 Kiam Teck Road

Policy No:

Claim No:

D18005146MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/06/2018

CA / REV / REP. / REV 24 HRS

(05)

Date/Time:

1.53pm @ 3/7/18

Person Contacted:

Alvin

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 3310R - CS/GAI 17006451 / S/bn2 DOA: 24/3/2017
	SHA 44204 - CC3/AG 11002034 / H/ga 3e3 DOA: 27/01/2011
	lump sum \$22501 - (red: 4977.28, 68%)

(08/11/13) wef

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From:

Date: 04/07/2018

Estimated Cost:

OP/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SLJ 3310R

at Workshop m/s

Pegasus

of

74 Kian Teck Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ3310R

Yr Regn:

2016, December

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

96994

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A8H920443

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60K16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wustlake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/7/180 spin

Survey held at

Pegasus

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 15 JAN 2019

Date/Time, File Pass to?



Preli. Report

1) 15/11/2018



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

150

Transportation:

70

S + RS, SI

50

Photos

20

Others

TOTAL

270

Report Format: TP

Lump Sum / I.B.I. (\$) 2250/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012039/T1td3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4420U	Veh. Inspected	SLJ 3310R
Policy No.		Coverage (\$)	0.00
Claim No.	D18005146MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	03/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	29/06/2018	Inspection Date	03/07/2018
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	02-07-2018	Our Ref No. D18005146MFSH
Accident Date	29-06-2018	Claim Type. Third Party
Insured Vehicle	SHA4420U	Third Party Vehicle. SLJ3310R
Survey Location	74 KIAN TECK ROAD	
Contact Person.	ALVIN LOW	
Contact No.	65137748/ 0	Fax No. 62513161
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241995)



PRI Documents



Close



PRI Header Details

Claim No	D18005146MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	74 KIAN TECK ROAD Mobile: 0 , Phone: 65137748 , Fax: 62513161 EmailId: AR_CLAIMS@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4420U	TP Vehicle No	SLJ3310R
PRI Recieved Date	02-07-2018 09:36:29 PM	Surveyor Appointed Date	03-07-2018 12:22:43 PM	Surveyor Accept Date	03-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	03-07-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>
Sent: Thursday, 22 November 2018 12:42 PM
To: SUR
Cc: Belinda Sim; Lawrence Sim; Lionel Chua <lionelchua@pegasusengrg.com.sg>; josephyeh@vendaengrg.com.sg; Seng Kee Wong
Subject: RE: Finalise For SLJ3310R (DOA 29/06/2018)
Attachments: SLJ3310R (DOA 29.06.18).pdf; resized.zip

Dear Taufikh,

Please find the calculation for your confirmation.

Lump Sum repair \$2,250.00 and 4 days repair.

The attached copies of the documents & after paint photos for your attention.

Thank You

Best Regards,
Vivian Tan
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Office: 65137748
Fax: 62513161

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 15 January 2019 11:01 AM
To: Pegasus Engineering; SUR
Cc: Belinda Sim; Lawrence Sim; Lionel Chua <lionelchua@pegasusengrg.com.sg>; josephyeh@vendaengrg.com.sg; Seng Kee Wong
Subject: RE: Finalise For SLJ3310R (DOA 29/06/2018)

Dear Vivian,

Confirm lump sum at \$2250/-, 4days

Please submit the relevant document to First Capital.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>
Sent: Thursday, 22 November 2018 12:42 PM
To: SUR <sur@lkkauto.com>
Cc: Belinda Sim <belindasim@pegasusengrg.com.sg>; Lawrence Sim <lawrencesim@vendaengrg.com.sg>; Lionel Chua <lionelchua@pegasusengrg.com.sg> <lionelchua@pegasusengrg.com.sg>; josephyeh@vendaengrg.com.sg; Seng Kee Wong <sengkee.wong@pegasusengrg.com.sg>
Subject: RE: Finalise For SLJ3310R (DOA 29/06/2018)

Dear Taufikh,

Please find the calculation for your confirmation.

Lump Sum repair \$2,250.00 and 4 days repair.

The attached copies of the documents & after paint photos for your attention.

Thank You

Best Regards,
Vivian Tan
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Office: 65137748
Fax: 62513161

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/06/2018 20:35
Date Of Accident	29/06/2018 11:50
Exact Location Of Accident	DRIVE WAY 112 KATONG MALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ3310R
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29069766MKF
Cover Note Number	N.A.

Driver

Name of Driver	NG HEE KHENG
NRIC No	S1796557C
Date Of Birth	29/11/1967
Occupation	OUTDOOR
Date Of Driving Pass	19/06/1995
Driving Experience	23 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93894868
Fax Number	
Contact Number	
EMail Address	KHENG2911@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving slowly along drive way at 112 KATONG MALL when suddenly a passenger from taxi SHA4420U open the rear left door & hit onto my SLJ3310R right side mirror. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING FROM DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA4420U
Vehicle Make/Model/Colour	HYUNDAI/ I40/ BLUE
Details Of Properties	NA
Vehicle Category	TAXI
Name of Driver	TONG KWOK LEONG
NRIC/Passport Number	S0209342A
Contact Number	96686382
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


**VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHD FADZLY BIN ISMAIL**

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

I was driving slowly along drive way at 112 KATONG MALL when suddenly a passenger from taxi SHA4420U open the rear left door & hit onto my SLJ3310R right side mirror. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

29 June 2018 3:02 pm

Date/Time:

29 June 2018 3:02 pm

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLJ3310R
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 Jun 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	P520402466
Chassis No.:	JM6BN22A8H0120443
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,091.00
Original Registration Date:	06 Dec 2016
First Registration Date:	06 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$12,091.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Dec 2026
PARF Rebate Amount:	\$9,068.00
Intended COE Rebate Details	
COE Expiry Date:	05 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$40,792.00
Total Rebate Amount:	\$49,860.00

The information contained herein is correct as at 04 Jun 2018

OK



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/06-1357	Quotation Date : 30/06/2018	Terms : 30 DAYS
Vehicle No. : SLJ3310R	Chassis No. : JM6BN22A8H0120443	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 29/06/2018	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEHICLE NO: SHA4420U, DATE OF ACCIDENT: 29.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	O/S FRONT DOOR	1	1,062.0000	bt 1,062.00
2	O/S FRONT DOOR HINGE TOP	1	42.0000	Ry 42.00
3	O/S FRONT DOOR HINGE BOTTOM	1	40.0000	Ry 40.00
4	O/S FRONT DOOR CHECKER/ARRESTOR	1	37.0000	Ry 37.00
5	O/S FRONT DOOR INNER LOCK	1	240.0000	x 240.00
6	O/S FRONT DOOR INNER LOCK STRIKER	1	26.0000	x 26.00
7	O/S FRONT DOOR POWER WINDOW MOTOR	1	142.0000	x 142.00
8	O/S FRONT DOOR REGULATOR	1	120.0000	x 120.00
9	O/S FRONT DOOR INNER TRIM BOARD	1	844.0000	x 844.00
10	O/S FRONT DOOR OUTER HANDLE	1	61.0000	x 61.00
11	O/S FRONT DOOR OUTER HANDLE INNER BASE	1	33.0000	x 33.00
12	O/S FRONT DOOR OUTER HANDLE - EXTENSION GARNISH	1	18.0000	x 18.00
13	O/S FRONT DOOR WINDOW GLASS	1	309.0000	aut 309.00
14	O/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	165.0000	ny x 165.00
15	O/S FRONT DOOR OUTER CHROME WEATHERSTRIP MOULDING	1	77.0000	de 77.00
16	O/S FRONT DOOR SIDE MIRROR - MOTOR ASSY	1	378.0000	bw 378.00
17	O/S FRONT DOOR SIDE MIRROR COVER	1	123.0000	ms 123.00
18	O/S FRONT DOOR SIDE MIRROR INDICATOR LIGHT	1	82.0000	ms 82.00
19	O/S FRONT DOOR SIDE MIRROR GLASS	1	103.0000	ms 103.00
20	O/S FRONT DOOR WEATHERSTRIP	1	107.0000	re 107.00
21	O/S FRONT DOOR WINDOW FRAME MOULDING TOP	1	111.0000	ny x 111.00
22	O/S FRONT DOOR WINDOW FRAME GARNISH REAR	1	64.0000	ny x 64.00
23	O/S FRONT DOOR WINDOW FRAME GARNISH FRONT	1	50.0000	aut 50.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax No. :

Quotation No. : QO18/06-1357	Quotation Date : 30/06/2018	Terms : 30 DAYS
Vehicle No. : SLJ3310R	Chassis No. : JM6BN22A8H0120443	Third Party Insurer :
Model : MAZDA 3		Date of Accident : 29/06/2018
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEHICLE NO: SHA4420U, DATE OF ACCIDENT: 29.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	O/S FRONT DOOR INNER RUBBER STOPPER	2	6.0000	12.00
25	O/S FRONT DOOR CHANNEL WEATHERSTRIP	1	143.0000	143.00
26	DOOR CENTER "B" PILLAR	1	785.0000	785.00
27	DOOR CENTER "B" PILLAR MATT BLACK TAPE	1	31.5000	31.50
28	FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	140.0000	140.00
29	FRONT DOOR OUTER HANDLE BASE	1	151.1000	151.10
30	LESS 20% ITEM (1-29)	1	-1,099.3200	-1,099.32
31	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000	150.00
32	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.	1	240.0000	240.00
33	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00
34	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	180.0000	180.00
35	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECCESARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,000.0000	1,000.00
36	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	1,200.0000	1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

Tan Jiah 9749 5749
"wp"
4/7/18 2:30pm
Resurvey after repair.
4 days.
surp (Muantr.com)

Sub Total 7,227.28
GST(7.00%) 505.91
Total (SGD) 7,733.19



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Attn : Tel : Fax No. :

Quotation No. : QO18/06-1357	Quotation Date : 30/06/2018	Terms : 30 DAYS
Vehicle No. : SLJ3310R	Chassis No. : JM6BN22A8H0120443	Third Party Insurer :
Model : MAZDA 3		Date of Accident : 29/06/2018
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEHICLE NO: SHA4420U, DATE OF ACCIDENT: 29.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	O/S FRONT DOOR	1	1,062.0000	bt 1,062.00
2	O/S FRONT DOOR HINGE TOP	1	42.0000	Ry 42.00
3	O/S FRONT DOOR HINGE BOTTOM	1	40.0000	Ry 40.00
4	O/S FRONT DOOR CHECKER/ARRESTOR	1	37.0000	Ry 37.00
5	O/S FRONT DOOR INNER LOCK	1	240.0000	X 240.00
6	O/S FRONT DOOR INNER LOCK STRIKER	1	26.0000	X 26.00
7	O/S FRONT DOOR POWER WINDOW MOTOR	1	142.0000	X 142.00
8	O/S FRONT DOOR REGULATOR	1	120.0000	X 120.00
9	O/S FRONT DOOR INNER TRIM BOARD	1	844.0000	X 844.00
10	O/S FRONT DOOR OUTER HANDLE	1	61.0000	X 61.00
11	O/S FRONT DOOR OUTER HANDLE INNER BASE	1	33.0000	X 33.00
12	O/S FRONT DOOR OUTER HANDLE - EXTENSION GARNISH	1	18.0000	X 18.00
13	O/S FRONT DOOR WINDOW GLASS	1	309.0000	aut 309.00
14	O/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	1	165.0000	X 165.00
15	O/S FRONT DOOR OUTER CHROME WEATHERSTRIP MOULDING	1	77.0000	de 77.00
16	O/S FRONT DOOR SIDE MIRROR - MOTOR ASSY	1	378.0000	bw 378.00
17	O/S FRONT DOOR SIDE MIRROR COVER	1	123.0000	m/s 123.00
18	O/S FRONT DOOR SIDE MIRROR INDICATOR LIGHT	1	82.0000	m/s 82.00
19	O/S FRONT DOOR SIDE MIRROR GLASS	1	103.0000	m/s 103.00
20	O/S FRONT DOOR WEATHERSTRIP	1	107.0000	re 107.00
21	O/S FRONT DOOR WINDOW FRAME MOULDING TOP	1	111.0000	X 111.00
22	O/S FRONT DOOR WINDOW FRAME GARNISH REAR	1	64.0000	X 64.00
23	O/S FRONT DOOR WINDOW FRAME GARNISH FRONT	1	50.0000	aut 50.00

C/F 0.00

Page 1 of 2



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/06-1357	Quotation Date : 30/06/2018	Terms : 30 DAYS
Vehicle No. : SLJ3310R	Chassis No. : JM6BN22A8H0120443	Third Party Insurer :
Model : MAZDA 3		Date of Accident : 29/06/2018
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEHICLE NO: SHA4420U, DATE OF ACCIDENT: 29.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	O/S FRONT DOOR INNER RUBBER STOPPER	2	6.0000	X 12.00
25	O/S FRONT DOOR CHANNEL WEATHERSTRIP	1	143.0000	K 143.00
26	DOOR CENTER "B" PILLAR	1	785.0000	Ry 785.00
27	DOOR CENTER "B" PILLAR MATT BLACK TAPE	1	31.5000	new 31.50
28	FRONT DOOR OUTER WEATHERSTRIP MOULDING	1	140.0000	X 140.00
29	FRONT DOOR OUTER HANDLE BASE	1	151.1000	x 151.10
30	LESS 20% ITEM (1-29)	1	-1,099.3200	-1,099.32
31	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000	60 150.00
32	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.	1	240.0000	60 240.00
33	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	30 60.00
34	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	180.0000	30 180.00
35	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECCESARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,000.0000	400 1,000.00
36	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	1,200.0000	400 1,200.00

Tan Jiah 9749 5749
"wp"

4/7/18 2:30pm

Resing after repair.

4 days.

sure@kian-teck.com

Sub Total	7,227.28
GST(7.00%)	505.91
Total (SGD)	7,733.19

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

SLJ 3310R - Mazda 3

s/parts	—	\$	2322.50
Less: 20%	—	\$	464.50
		\$	<u>1858.00</u>
Add: Labor	—	\$	980.00
		\$	<u>2838.00</u>




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012039/T1td3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4420U	Veh. Inspected	SLJ 3310R	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005146MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BN22A8H0120443	Colour	SILVER	
Odometer	96994	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/06/2018	Inspection Date	04/07/2018	
Survey held at	74 KIAN TECK ROAD			
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3310R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	O/S FRONT DOOR	BENT	1,062.00	1,062.00
1	O/S FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	42.00	-
1	O/S FRONT DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	40.00	-
1	O/S FRONT DOOR CHECKER / ARRESTOR	TO REPAIR SEE LABOUR	37.00	-
1	O/S FRONT DOOR INNER LOCK	NOT NECESSARY	240.00	-
1	O/S FRONT DOOR INNER LOCK STRIKER	NOT NECESSARY	26.00	-
1	O/S FRONT DOOR POWER WINDOW MOTOR	NOT NECESSARY	142.00	-
1	O/S FRONT DOOR REGULATOR	NOT NECESSARY	120.00	-
1	O/S FRONT DOOR INNER TRIM BOARD	NOT NECESSARY	844.00	-
1	O/S FRONT DOOR OUTER HANDLE	NOT NECESSARY	61.00	-
1	O/S FRONT DOOR OUTER HANDLE INNER BASE	NOT NECESSARY	33.00	-
1	O/S FRONT DOOR OUTER HANDLE - EXTENSION GARNISH	NOT NECESSARY	18.00	-
1	O/S FRONT DOOR WINDOW GLASS	CUT	309.00	309.00
1	O/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	165.00	-
1	O/S FRONT DOOR OUTER CHROME WEATHERSTRIP MOULDING	DEFORMED	77.00	77.00
1	O/S FRONT DOOR SIDE MIRROR - MOTOR ASSY	BROKEN	378.00	378.00
1	O/S FRONT DOOR SIDE MIRROR COVER	MISSING	123.00	123.00
1	O/S FRONT DOOR SIDE MIRROR INDICATOR LIGHT	MISSING	82.00	82.00
1	O/S FRONT DOOR SIDE MIRROR GLASS	MISSING	103.00	103.00
1	O/S FRONT DOOR WEATHERSTRIP	NECESSARY	107.00	107.00
1	O/S FRONT DOOR WINDOW FRAME MOULDING TOP	NOT NECESSARY	111.00	-
1	O/S FRONT DOOR WINDOW FRAME GARNISH REAR	NOT NECESSARY	64.00	-
1	O/S FRONT DOOR WINDOW FRAME GARNISH FRONT	CUT	50.00	50.00
2	O/S FRONT DOOR INNER RUBBER STOPPER @\$6.00	NOT NECESSARY	12.00	-
1	O/S FRONT DOOR CHANNEL WEATHERSTRIP	NOT NECESSARY	143.00	-
1	DOOR CENTER "B" PILLAR	TO REPAIR SEE LABOUR	785.00	-

Report Ref No. CS/FCI18012039/T1td3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR CENTER "B" PILLAR MATT BLACK TAPE	NECESSARY	31.50	31.50
1	FRONT DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	140.00	-
1	FRONT DOOR OUTER HANDLE BASE	NOT NECESSARY	151.10	-
	LESS 20% DISCOUNT		-1,099.32	-464.50
			4,397.28	1,858.00
	LABOUR			
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		150.00	60.00
	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.		240.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	30.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		180.00	30.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF O/S FRONT DOOR HINGE TOP, O/S FRONT DOOR HINGE BOTTOM, O/S FRONT DOOR CHECKER / ARRESTOR AND DOOR CENTER "B" PILLAR.		1,000.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	400.00
			2,830.00	980.00
	GRAND TOTAL		7,227.28	2,838.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00

Report Ref No. CS/FCI18012039/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.