

INSR001

INS. CASE OWNER:

Frankman
KASMI

CC (Asm / AXA1801 2063), R. *Wb3*

LKK
IDAC

Surveyor:

DOE:

ASSIGNMENT

10/10/18

Date / Time:

3/7/18

Registered in Merimen:

Pre-assign / CCU / FTE

YN 705E



Insured Vehicle No.:

Claim No.:

S&MOONIT/54994

Name of Insured:

HM SOON LEE (LIM) HEAVY TRANSPORT PVT

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

GI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SGR 87719



INSRS:
WSP:
Tel:
Liability:
RMKS:

Performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
<i>4/5/18</i>	<i>SGR 87719 - X</i>	Non-Reporting Itr (1st):	
<i>4/5/18</i>	<i>YN 705E - Y</i>	Non-Reporting Itr (2nd):	
<i>4/5/18</i>	<i>YN 705E - Y</i>	Non-Reporting Itr (Final):	
<i>4/5/18</i>	<i>YN 705E - Y</i>	Notification Itr (if non-pickup):	
<i>4/5/18</i>	<i>YN 705E - Y</i>	Call OI:	<i>4/9/18</i>
<i>4/5/18</i>	<i>YN 705E - Y</i>	After call Itr to OE:	<i>4/9/18</i>
<i>20/8/18</i>	<i>YN 705E - Y</i>	Documentation Check List: Handler	Typist
<i>4/9/18</i>	<i>YN 705E - Y</i>	Notification Itr (if non-pickup):	<input type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	After call Itr to OE:	<input checked="" type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Authorisation To Act:	<input checked="" type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Release Voucher:	<input checked="" type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Final Repair Bill:	<input checked="" type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Car Rental Invoice:	<input type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Towing Invoice:	<input type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	LTA / GIA:	<input checked="" type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Medical Bill:	<input type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	PIR:	<input type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	LOD:	<input checked="" type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Payment Breakdown Form:	<input type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Post-Repair Photos:	<input type="checkbox"/>
<i>4/9/18</i>	<i>YN 705E - Y</i>	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: *MFB*

Repair Cost: *PP* \$5,200.97 (6 days) Reduction: 20 % Email Call

FINAL SETTLEMENT Date/Time: 15-04-19 Confirm with: *PRELIM* Email Call

Final Liability: % *100* (Agreed / Assessed) BOLA S/N No.: *13*

Repair Cost: *with* \$5,200.97

Less of Rental (LOR): \$5 - (days)

Less of Use (LOU): \$5 480.00 (540 x 8 days)

Less of Income (LOI): \$5 - (5 x days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search: \$52.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5,282.97 Global Sum SS:

FINAL PAYMENT Date/Time: 15-04-19 Confirm with: *PRELIM* Email Call

Payee 1: \$5,282.97 Name 1: *PERGOL/PHS MORIS Limited*

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COPIED

PASAL

REF: ASM(AXA)

W

2305G

ASSIGNMENT

From: _____ Date: 10.10.2018

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No.: SGR 8779G

at Workshop no/s: Performance

of: 303 - Alexander Rd

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Kevin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 103K

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SGR 8779G Yr Regn: 2016 OCT

Type: Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: B.M.W 216 D C.C. 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp Reading: 55539 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 2B 320 10V 791432

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16
R: _____

BS / DUN / EXNOVA / G / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 05/06/18 D.O.I: 10/10/18

Survey held at: PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S FRF

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	99: 75A21 47 (RBD: 1346 B 2%)

Close Time: File Pass to? PreIL Report

ii Final Report

Close Time: File Return to? _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech Insp (\$ _____)

Weekend (\$ _____)

TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012063/wb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 03-07-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 705E	Veh. Inspected	SGR 8779G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/06/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Revision / part list

W Dealer

Performance Motors Limited

A member of the Sime Darby Group
 Co. Reg. No. 197461599G GST Reg. No. WJ-0020081-X



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 119942
 Tel. 43180100 (Sales & Admin)
 43180111 (AfterSales)
 Fax. 44747773

188, Kangkong Aring Road
 East Coast Centre
 Singapore 434180
 Tel. 43180888 (AfterSales)
 Fax. 43447773

115, Alexandra Road
 Sime Darby Business Centre
 Singapore 119944
 Tel. 43180028 (AfterSales)
 43180033/330 (Motorist)
 Fax. 44746001 (AfterSales)
 44746004 (Motorist)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

02 JUL 2018

Estimate No. : b1 47516	Page No. : 1 of 4
Date Estimated : 02/07/2018	
Prepared By : Kevin Leong Wai Kit	

- ESTIMATE REPAIR FOR - Koh Chai Luan 201 Tanjong Rhu Road #01-13 Singapore 436917	- ACCOUNT - 238 AXA Insurance Pte Ltd 8 Shenton Way #24-01 AXA Tower Singapore 068811
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGR8779G	V791432	17/10/2016	216d CAT	0

DESCRIPTION	VALUE
To replace left wing mirror assembly & wing mirror cover To replace on front bumper, front left side panel, front left door & all attachments cause by accident.	2550 3,400.00 <i>2395</i>
Painting on front bumper, front left side panel, front left door & left wing mirror cover	2,449.00 2,304.10 <i>6 days</i>
To check electrical wiring systems for proper function.	150 177.00 <i>10/10/18 @ 1140</i>
Sundries. <i>Nil</i>	80 150.00 <i>Return by paint</i>
Total Labour 1:	6,176.00

DESCRIPTION	QTY	PRIC	VALUE
LH COVER MIRROR BASE <i>new</i>	1	56.10	56.10 56.10 <i>25.62</i>
LH OUTSIDE MIRROR COVER CAP PRIMED	1	116.10	116.10 116.10 <i>30.29</i>
LH SUPPORTING RING	1	51.85	51.85 51.85 <i>25.23</i>
LH LOWER HOUSING SECTION	1	23.95	23.95 23.95 <i>41.25</i>
LH EXTERIOR MIRROR W/O MOUNTING PAR	1	481.70	481.70 481.70 <i>53.98</i>
LH ADDITIONAL TURN INDICATOR LAMP	1	61.80	61.80 61.80
Total Parts :			791.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey *after* spray painting
- To display damaged part(s) during resurvey
- Parts whose availability is confirmed

• Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Receiver
 Signature:
 Date:

Labour 1	:	6,176.00
Parts	:	791.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	487.73
Grand Total	:	7,455.23

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg No. 197401559W, GST Reg No. M2-002001-K



FINAL REPORT

Estimate No. : b1 47516
Date Estimated : 02/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Koh Chai Luan
201 Tanjong Rhu Road
#01-13

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Singapore 436917

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SGRB779G	V791432	17/10/2016	216d CAT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace LH wingmirror assembly and attachments include making good the front bumper, front LH fender, front LH door and knocking out dents caused by the accident	2550.00 ✓	10.00	2,295.00	
To spray paint front bumper, front LH fender, front LH door and LH wing mirror cover	2449.00 ✓	10.00	2,204.10	
To check electrical wiring systems at the front section for proper function	150.00 ✓	10.00	135.00	
Sundries	80.00 ✓	0.00	80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
LH OUTSIDE MIRROR COVER CAP PRIMED	116.10 ✓	1.00	3.00	112.62
LH SUPPORTING RING	51.85 ✓	1.00	3.00	50.29
LH LOWER HOUSING SECTION	23.95 ✓	1.00	3.00	23.23
LH EXTERIOR MIRROR W/O MOUNTING PAR	481.70 ✓	1.00	3.00	467.25
LH ADDITIONAL TURN INDICATOR LAMP	55.65 ✓	1.00	3.00	53.98

SUPPLEMENTARY ITEMS

Total Labour :	4,714.10
Total Parts :	707.37
Total Labour & Parts :	5,421.47
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,421.47
GST @7%:	379.50
Grand Total :	5,800.97

Performance Motors Limited

A member of the Fine Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



103, Alexandra Road
Fine Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Fine Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

02 JUL 2018

Estimate No. : b1 47516
Date Estimated : 02/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Koh Chai Luan
201 Tanjong Rhu Road
#01-13

Singapore 436917

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGR8779G	V791432	17/10/2016	216d CAT	0

DESCRIPTION

To replace left wing mirror assembly & wing mirror cover
To replace on front bumper, front left side panel, front left door & all attachments cause by accident.

Painting on front bumper, front left side panel, front left door & left wing mirror cover

To check electrical wiring systems for proper function.

Sundries.

Rasul
Hp 90000088
6 days
10/10/18 @ 1140
Resurvey by paint

DESCRIPTION	VALUE
To replace left wing mirror assembly & wing mirror cover	3,408.00
To replace on front bumper, front left side panel, front left door & all attachments cause by accident.	2,449.00
Painting on front bumper, front left side panel, front left door & left wing mirror cover	177.00
To check electrical wiring systems for proper function.	150.00
Sundries.	?
Total Labour 1:	6,176.00

DESCRIPTION

LH COVER MIRROR BASE
LH OUTSIDE MIRROR COVER CAP PRIMED
LH SUPPORTING RING
LH LOWER HOUSING SECTION
LH EXTERIOR MIRROR W/O MOUNTING PAR
LH ADDITIONAL TURN INDICATOR LAMP

QTY	PRIC	VALUE
1	58.10	? 58.10
1	116.10	CR 116.10
1	51.85	? 51.85
1	23.95	scr 23.95
1	481.70	? 481.70
1	61.80	CR 61.80

Total Parts : 791.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,176.00
Parts	:	791.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	487.73
Grand Total	:	7,455.23

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

◀ MANDATE IA (S8M00N17)

Type

🔔 Question

Message

Liability: Insured changed lane and hit third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost w/GST : \$5,800.97 Loss of Use: \$480.00 (8days x \$60) LTA Search: \$2.00 Total: \$6,282.97 Immediate Advice with Mandate and revert document uploaded for your easy referance. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (29/03/2019)

Reply

◀ Re:MANDATE IA (S8M00N17)

Type

📍 Question

Message

PLS PROCEED AS PROPOSED

Reply

RE: [OFFER SETTLEMENT] Re: FOR DIRECT SETTLEMENT - SGR8779G & YN705E ON 5 JUNE 2018

Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>

Mon 4/8/2019 4:23 PM

to: PBSP <pml-pbsp@simedarby.com.sg>;

cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>;

Dear All,

Customer accept with \$ 60 x 8 day = \$ 480.00

Thank you

Regards,

Kevin Leong

Customer Service Advisor | Body and Paint

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Hp: (+65) 9116 5600 | Fax (+65) 6479 4601

Kevin.leong.waikit@simedarby.com.sg

From: PBSP

Sent: Monday, April 08, 2019 3:00 PM

To: Kevin Leong Wai Kit

Cc: Asher Sng (LKKAuto)

Subject: Re: [OFFER SETTLEMENT] Re: FOR DIRECT SETTLEMENT - SGR8779G & YN705E ON 5 JUNE 2018

Dear Kevin

You have submitted loss of use at \$80 x 8 days for customer.

Please confirm customer's acceptance of \$60 x 8. Customer's case is a BMW 2 series.

Thank you.

Regards,

Caroline

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Sent: Saturday, 6 April 2019 2:18:36 PM

To: PBSP

Subject: [OFFER SETTLEMENT] Re: FOR DIRECT SETTLEMENT - SGR8779G & YN705E ON 5 JUNE 2018

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 5,800.97
2. Loss of Use (8 days x \$60)	\$ 480.00
3. LTA/GIA search fee	\$ 2.00
TOTAL	<u>\$ 6,282.97</u>

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Tuesday, September 4, 2018 1:49 PM

To: Admin-D (LKKAuto); Vivian Lau (LKKAuto)

Cc: Admin A; Thin Thin (LKKAuto)

Subject: Re: FOR DIRECT SETTLEMENT - SGR8779G & YN705E ON 5 JUNE 2018

Dear Vivian

Have you reviewed the video?

Please reply on liability.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Sent: Tuesday, 3 July 2018 1:10:16 PM

To: PBSP

Cc: 甯瑤 ©; 'assignments'

Subject: RE: FOR DIRECT SETTLEMENT - SGR8779G & YN705E ON 5 JUNE 2018

Dear Caroline,

Noted with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Tuesday, 3 July, 2018 12:10 PM

To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Subject: Re: FOR DIRECT SETTLEMENT - SGR8779G & YN705E ON 5 JUNE 2018

Dear Catherine

Vehicle not in. Please arrange your colleagues to advise on liability.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Sent: Tuesday, 3 July 2018 11:05:38 AM

To: PBSP

Subject: FOR DIRECT SETTLEMENT - SGR8779G & YN705E ON 5 JUNE 2018

Dear Caroline,

Kindly check the vehicle currently got in the workshop?

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD16V14372 /NPC2 /R00
Form	MX1
Date of Issue	03-NOV-2016
1.Index Mark and Registration No. of Vehicle:	SGR8779G
2.Chassis number of Vehicle:	WBA2B32010V791432
3.Name of Policyholder:	KOH CHAI LUAN
4.Effective date of Commencement of insurance for the purposes of the Act:	17-OCT-2016 00:00 AM
5.Date of Expiry of Insurance:	16-OCT-2018 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	
A) The Policyholder.	
B) Any other person who is driving on the Policyholder's order or with his permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
7.Limitations as to use*:	
Use only for social, domestic and pleasure purposes and for the Policyholder's business.	
8.The Policy does not cover:	
A) Use for hire or reward.	
B) Use for racing, pace-making, reliability trials or speed-testing.	
C) Use for the carriage of goods (other than samples) in connection with any trade or business.	
D) Use for any purpose in connection with the Motor Trade.	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
<p>For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers</p>  <hr style="width: 20%; margin-left: auto; margin-right: 0;"/> <p>Authorised Signature</p>	
For Information only:	
COVERAGE :	Comprehensive,Unlimited Windscreen,Ncd Protection
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS
EXCESS:	Section I S\$400,Additional Excess For Young & Inexperienced Drivers S\$2500,Windscreen Excess S\$0
FINANCE COMPANY:	DBS BANK LTD
PRODUCER NAME:	SIME DARBY SINGAPORE LIMITED


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIFICATION

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

24 Jul 1989

NP 428A



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1772305G

Name:

KOH CHAI LUAN

Birth Date: 27 May 1966

Issue Date: 20 Jun 2003



◀ Service Request Details

Claim

S8M00N17

Reference

None ✎

Loss Date

June 5, 2018

Request Date

July 3, 2018

Due Date

July 10, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGR8779G

Make

TPVD BMW

03/07/2018 @ 11:06am
Caroline veh not in.

Model

Service Address

...

Primary Contact/Insured

KIM SOON LEE (LIM) HEAVY TRANSPORT PTE LTD
200 BEDOK SOUTH AVE 1, 469331, Singapore
65674755

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions
NON-REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



Auto
Consultants
Pte Ltd

31 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

03 JULY 2018

**KIM SOON LEE (LIM) HEAVY TRANSPORT PTE LTD
200 BEDOK SOUTH AVE 1
Singapore 469331**

Dear Sir,

**OUR REF : CC4/ASM18012063/wb3
YOUR REF : YN 705E**

**ACCIDENT INVOLVING YN 705E & SGR 8779G ALONG FORT ROAD ON
05/06/2018**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to vivianlau@lkkauto.com or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6841 8625 if you have any further enquiries.

Yours sincerely,
Claim department

This is a computer generated letter and no signature is required.

CC: AXA INSURANCE PTE LTD



(-A)

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

“Without Prejudice”

Your Ref :

Our Ref :

Date :

06 March 2019

Subject :

ACCIDENT INVOLVING VEHICLES SGR8779G & YN705E ON 05.06.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of Repair	:	S\$	5800.97
Loss of use	:	S\$	640.00 (S\$80.00 x 8 days)
GIA search fee	:	S\$	2.00
Total	:	S\$	6442.97

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Insurance of Certificate
4. Copy of Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Performance Motors
Limited
1800-Call-BMW
(1800-2255-268)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel Aftersales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel Aftersales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel Aftersales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401539W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

07 September 2018

Kim Soon Lee (LIM) Heavy Transport Pte Ltd
200 Bedok South Ave 1
Singapore 469331

Dear Sir/ Mdm

OUR REF : CC4/ASM18012063/wb3
YOUR REF : YN 705E

ACCIDENT INVOLVING YN 705E & SGR 8779G ALONG FORT RD ON 05/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Performance Motors Limited** acting on behalf of the owner of SGR 8779G against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd
(Motor Claims Dept)

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SGR 8779G & YN 705E ON 5/6/18

I, Koh Chai Luan owner of Vehicle Registration No. SGR 8779G hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Name: KOH CHAI LUAN (Date) 02/07/2018
NRIC No.: S1772305G

In the presence of:

Name: _____ (Date) 02/07/2018
NRIC No.: _____



redefining insurance

CLAIM REF : SSM00N17
INSURED : KIM SOON LEE (LIM) HEAVEY TRANSPORT PTE LTD

DISCHARGE VOUCHER

We/I (KOH CHAI LUAN , NRIC NO. S1772305G) hereby agree to accept the sum of dollars [SIX THOUSAND TWO HUNDRED EIGHTY TWO AND CENTS NINETY SEVEN ONLY] (S\$ 6,282.97) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [YN 705E] as a result of an accident along [FORT RD] on [05/08/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SGR 8779G].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said insurer, owner and/or driver of vehicle no. [YN 705E] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [YN 705E].

Dated this 15 day of APRIL 2019

Claimant's Signature

[Signature]

NRIC no./ Company Stamp

: S1772305G

Occupation/ Business

: _____

Address

: 201 TANJONG RHU RD #01-13

Telephone No.

: _____

Witness's Name

: Kevin Leong

Witness's Signature

: _____

Witness's NRIC No.

: _____

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1305852	Page No. : 1 of 2
Date IN : 10/10/2018	Invoice Number : 2070965 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 28/02/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mdm Koh Chai Luan
201 Tanjong Rhu Road
#01-13

Singapore 436917

- INVOICE TO - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO. SGR8779G	CHASSIS NO. V791432	REGN. DATE 17/10/2016	MODEL 216D CAT	MILEAGE 55539
------------------------------	-------------------------------	---------------------------------	--------------------------	-------------------------

- - - - LABOUR 1 - - - -

	Retail Price	DISC%	NETT
To replace left wing mirror assembly including to make good the front bumper, front left fender, front left door and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	2,550.00	10.00	2,295.00
To respray front bumper, front left fender, front left door and left wing mirror cover etc	2,449.00	10.00	2,204.10
To check electrical wiring systems at the left section for proper function.	150.00	10.00	135.00
Sundries.	80.00	0.00	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00	0.00	0.00
DATE OF ACCIDENT : 5.6.2018. 3RD PARTY CAR : YN705E.			
YOUR REF NO : NIL.			
VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 10.10.2018 AT 11.40 AM. AUTHORISED REPAIR BY MS VIVIAN LAU FROM LKK ON 4.9.2018 VIA E-MAIL.			
PROPOSE LOSS OF USE = \$80x8. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00	0.00	0.00
GIA SEARCH FEE = \$2.00.	0.00	0.00	0.00
Total Labour 1:			4,714.10

- - - - PARTS - - - -

	Qty	Retail Price	DISC%	NETT
LH OUTSIDE MIRROR COVER CAP PRIMED	1	116.10	3.00	112.62
LH LOWER HOUSING SECTION	1	23.95	3.00	23.23
LH ADDITIONAL TURN INDICATOR LAMP	1	55.65	3.00	53.98
LH EXTERIOR MIRROR W/O MOUNTING PAR	1	481.70	3.00	467.25
LH SUPPORTING RING	1	51.85	3.00	50.29
Total Parts :				707.37

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020061-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1305852	Page No. : 2 of 2
Date IN : 10/10/2018	Invoice Number : 2070965 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 28/02/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges : 4,634.10	Total Labour & Parts Charges : S\$ 5,421.47
Parts Charges : 707.37	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 5,421.47
	GST @ 7% : S\$ 379.50
	Invoice Total Amount Include GST : S\$ 5,800.97

Computer generated invoice. No signature is required.	Amount Payable Include GST : S\$ 5,800.97
---	--

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-100439

Date of Request: 02/07/2018

Your Ref No:

Online Purchase

Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Dear Sir/Madam,

Enquiry Date 02/07/2018
 Enquiry By Caroline Tan Shirui
 TP Vehicle No. YN705E
 Accident Date 05/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YN705E	AXA Insurance Pte Ltd	21/10/2017-20/10/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-100439

Date of Request: 02/07/2018

Your Ref No:

Online Purchase

 Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Dear Sir/Madam,

 Enquiry Date 02/07/2018
 Enquiry By Caroline Tan Shirui
 TP Vehicle No. YN705E
 Accident Date 05/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18012063/R1eb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 24-04-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 705E	Veh. Inspected	SGR 8779G
Policy No.	VCA/P2009402	Coverage (\$)	0.00
Claim No.	S8M00N17	Excess (\$)	0.00
Assign From		Assign Date	03/07/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 216D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA2B32010V791432	Colour	RED
Odometer	55539	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	GOODYEAR	6 mm
L/H Front Tyre	205/60 R16	GOODYEAR	6 mm
R/H Rear Tyre	205/60 R16	GOODYEAR	6 mm
L/H Rear Tyre	205/60 R16	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/06/2018	Inspection Date	10/10/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 8779G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	80.00
1	LH COVER MIRROR BASE (SN) (CONSISTENT)	SERVICEABLE	56.10	-
1	LH OUTSIDE MIRROR COVER CAP PRIMED (SN) (CONSISTENT)	CRACKED	116.10	112.62
1	LH SUPPORTING RING (SN) (CONSISTENT)	NECESSARY	51.85	50.29
1	LH LOWER HOUSING SECTION (SN) (CONSISTENT)	SCRATCHED	23.95	23.23
1	LH EXTERIOR MIRROR W/O MOUNTING PAR (SN) (CONSISTENT)	CRACKED	481.70	467.25
1	LH ADDITIONAL TURN INDICATOR LAMP (SN) (CONSISTENT)	CRACKED	61.80	53.98
			941.50	787.37
LABOUR				
TO REPLACE LEFT WING MIRROR ASSEMBLY & WING MIRROR COVER TO REPLACE ON FRONT BUMPER,FRONT LEFT SIDE PANEL,FRONT LEFT DOOR & ALL ATTACHMENTS CAUSE BY ACCIDENT.			3,400.00	2,295.00
PAINTING ON FRONT BUMPER ,FRONT LEFT SIDE PANEL,FRONT LEFT DOOR & LEFT WING MIRROR COVER.			2,449.00	2,204.10
TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION.			177.00	135.00
			6,026.00	4,634.10
GRAND TOTAL			6,967.50	5,421.47
RECOMMENDED COST OF REPAIRS				5,421.47

Report Ref No. CC4/ASM18012063/R1eb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9400H17
Reference	CC4/ASM18012062/181eb3a2 
Loss Date	5 June 2018
Report Date	3 Jul 2018 9:14:17 AM
Request Date	3 July 2018
Due Date	
Vendor Name	LAK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SGR8779G
Make	TRVD BMW
Model	
Service Address	

Primary Contact/Insured	
MIM SOON LEE (MIM) HEAVY TRANSPORT PTE LTD 200 BEDOK SOUTH AVE 1, 469331, Singapore 65674755	

Claim Handler	
CHAN Kuan Chuan 6568804269 kianchuan.chan@lax.com.sg	

Additional Instructions: NON-REPORTED

[Messages](#)
[Invoices](#)
[History](#)
[Documents](#)
[Assessment](#)
[Metrics](#)
[Notes](#)
Document Type:

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

 Accident Statement

Reports & Statement

Mainmen

 LAKInvoice1 (5).pdf

Invoice

Surveyor/ Assessor
expense

LAK AUTO CONSULTANTS PTE LTD (TP)

26 April 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
payment breakdown.pdf	Forms / Claim Documents	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
LCD.pdf	Forms / Claim Documents	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
LKKInjunction (5).pdf	Forms / Claim Documents	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
LKKAdjustment1a (7).pdf	Forms / Claim Documents	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
GIA_SEARCH.pdf	Forms / Claim Documents	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
WORKSHOP INVOICE.pdf	Invoice	Receipt	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK-AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
LTA PAIR COE Relate Details.pdf	Reports & Statement	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	29 March 2019
LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	29 March 2019
LKK Survey Photo.pdf	Reports & Statement	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	29 March 2019
Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK-AUTO CONSULTANTS PTE LTD (TP)	29 March 2019
TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK-AUTO CONSULTANTS PTE LTD (TP)	17 October 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SGR 8779 G.m04	Evidence	Video	LXX AUTO CONSULTANTS PTE LTD (TP)	4 September 2018
EMAIL FROM WORKSHOP WITH TP SGR8779G GIA.mtg	Forms / Claim Documents	Others	KUMAR Shalendra	3 July 2018
Non reporting letter.pdf	Letters and Correspondence	Policy Holders / Insured	LXX AUTO CONSULTANTS PTE LTD (TP)	3 July 2018