,	wss. 1050, BY	Kennika ASSIGNMENT (Office)
-	www.men	Irune tay CT1 Determe 3/7/160 4-40pm
	OD TP/WS	
	To Inspect Ve	hicle No. 3KV 7197Z insured:
	at Workshop r	
	of Policy No.	19 Lovory 8 toa pay 8 h SMPCSN 15439 11702 Claim No: SNM18 DO 2535CO 1
	Sum Insured	Excess \$ 750.00
	Make of Vehr (Client's Record	D.O.A. 19/05 2018 04/07/2018 Offer 10am 11.O.D. Endorsement
		2.55pm@3/7/18 Person Contacted Danie Vehicle IN)OUT
	Date/Time	Action/Instruction () Estimate SKV71977-X
		Kenneth said \$60K (MV)
	4/7/18	Revert thm mennen
	2/1/18	Mandate approve
	5/7/18	Inform Daniel to proceed repour.

(08/11/13) wef REF: C	11 05/0	CTL18012066/Krd3		
ASS. REC. BY:		SCHOOL STATE		
(438)		SKV 719;	77 Yr Reon OP	1 =
From: Date: OA	8105/50/	VEH NO.	D III. Togin	15
Estimated Cost:		Type M.Car / M.Cycle / Bus / Van / L	orry / Laxi / Prime Mover /	
TP / WS / TP RES / OD RES / EVA / INV / MV		Truck / Trailer or	1 //	00
To Inspect Vehicle No: SKV 7193	72	Make: Suhan	organi i	
et Workshop m/s Motor Ima	ge	Colour A. P. White	A/C: Insured / Std / NI /	
19 Lorong 8 to a payo	h	Sp.Reading 53374	T/Radio: Insured / Std / NI	/ NA
Insured:		Eng/No:		
Policy No.			1656606400	2
Claims No.		Gen. Cond: Fair / Poor / Burn		
Sum Insured: Excess:	\$750·00	Steering: Inorder Jammed / Leaker		
(Client's Record) after 10 am		Brake: Ingrder / Jammed / Leaker	d / Burnt or	
Make of Veh:		Modi: Nil / 8/Rim / STD A/Rim	_	
		Tyre Size: F:	205/55RI6	
(Policy Condition)		R:		
Remark: The veh had commenced its	N/S O/S	BS DUN / EXNOVA / GY / FS / LIZ	A / MIC / OHTSU / PIR / SUMI /	
repair at the time of inspection.		TOYO / YOKO or		
Bal. or Market Value: 860k		Front	Rear	
IDAC Accident Rport: Consistent? : You	es or No	R/Bal. 9 mm	R/Bal. 5	mm
GIA / PR Seen: Consistent? : Y		L/Bal. 9 mm	L/Bal. 9	mm
Est Repairs: 03 days Res.: Yo		D.O.A. 18/5/18	D.O.I. 4/7/	18
Lum Sum: % 3 Val.: Ye		Survey held at		-
Lunisum		Des. of Damages : Frt / Rear / O/S	S / N/S / U/C / Rooftop or	***
CA / REV / REP. / 24 HRS	Vehicle: IN / OUT	NIS IM		
Date: Person Contacted:	TOTAL TOTAL	The U/C / Chassis frame / Bo	dy Structure affected due to co	Ilision
Lon firm \$ 2004. RECEIV	56 , 3 day			
Date/Time, File Pass to? : Preli. Report	•	Days Of Repair: 3		
1) typist : Final Report		Resurvey No. of Trip:	Survey Fee:	
Date/Time, File Return to?			Transportation:	
2)	Add Fee)S+RS,SI	
	743	: Interview (\$) Photos	
Report Format : OD		: Tech. Invs (\$) Others	
Lump Sum / I.B.I: (\$ >204.56)	: Weekend (\$		
		A	TOTAL 23	0

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authled	Status
Main	21 Jun 2018		02 Jul 2018 16:40 Assign				New Assignment Cancel Case

Ma	nin [Reference		laim Details	U_	Documents		Show Al
CLAIM SUBI	FOLDER DETAIL	S	Annual States and an	No. of the last of	[Created	by insurer]		
Insured:	LIM SWEE TEC	K, ID: S7236243H,	Tel: +6581180580	, Email: SWEE	TECHKLIM@	HOTMAIL.COM		
Vehicle Reg. No.:	SKV7197Z			SKV7197Z Date of Loss: 19/05/2018 10:00 - :59				
Claim Type:			Policy/Cover Note No.:				ve)	
				Excess:	S\$750,00			
Repairer:	Motorimage En	otorimage Enterprises Pte Ltd (HQ) 19 LORONG 8, TOA PAYOH, 319255 Toa Payoh - Tel: 64730333 /62222311 / 65063848						
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Irene Tay Hui Ping - 638986192]						
Adjuster:	LKK Auto Cons	ultants Pte Ltd (HQ) - Tel: 6256-3561 .	[Final Rpt	due 11/07	7/2018]		
Driver/Custo dian:	LIM SWEE TECK	(45 / Male), NRIC:	S7236243H, Tel:	+6581180580				
Adj Asg. Remarks:	PLEASE SURVEY	AND REVERT						
ASSOCIATE	D MAIL RECEIV	ED				V	iew All	Compose Case
There are no	mail for this case.							
ALL ASSOC	IATED TASKS				View All	Search Tasks	Create I	New Task Comp
	Priority Ty	pe Task Group	Subject Hand	iler Assign	ned By	Completed On	Cn	eated On Do



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

SE SKV 7197Z 0.00 750.00 03/07/2018
SKV 7197Z 0.00 750.00 03/07/2018
SKV 7197Z 0.00 750.00 03/07/2018
SKV 7197Z 0.00 750.00 03/07/2018
750.00 03/07/2018
03/07/2018
we was a supplied to the control of
0
0
Balance
mm
mm
mm
mm

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Irene Tay Hui Ping

Date:

04 Jul 2018

Preliminary Advice

Vehicle No

: SKV7197Z

Accident Date

: 19/05/2018

Make

Policy No.

: DMPCSN1543911702

: SUBARU IMPREZA 5D

Assignment Date

: 02/07/2018

Excess

: S\$750.00

Date of Inspection

: 04/07/2018

Est. Duration of Repair

: 3.00

Inspection At

: MOTORIMAGE ENTERPRISES PTE LTD (HQ)

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

:S\$	8,058.32
:S\$	2,204.56
:S\$	875.20
:S\$	3,079.76
	:S\$:S\$

Lump Sum Repair

:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	48,622.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,378.00

Remarks

(X)		usted amount.	We have also confirmed	excess and policy	coverage.	Kindly
		let us have your authorisation.					

)	The vehicle is uneconomical to be	repaired,	you are adv	vised to	invite	tender	for	the	wrec	k.
---	-----------------------------------	-----------	-------------	----------	--------	--------	-----	-----	------	----

Other comments:

Print Received Message

This mail is associated with:

*SKV7197Z (SNM18D02535C01)

OD

May 19 2018 10:00AM [LIM SWEE TECK] Motorimage Enterprises Pte Ltd

From

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 05/07/2018 10:38 AM.

To Subject LKK_HQ

Alert - Adj Mandate Approved (S\$3079.76) - SKV7197Z - Claim Handler: Irene Tay Hui Ping

Approved:3079.76.	
T. P. P. T. T. P. T.	

Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Thursday, July 05, 2018 2:30 PM

To:

daniellim@motorimage.net

Cc:

SUR

Subject:

SKV 7197Z CTI OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SKV 7197Z (excess \$750/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Yelliele	
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	6243H	
Vehicle No.:	SKV7197Z	
Vehicle to be Exported:	No	
Intended De-registration Date:	04 Jul 2018	
Vehicle Make:	SUBARU	
Vehicle Model:	IMPREZA 5D 1.6I-S AWD CVT	
Primary Colour:	White	
Manufacturing Year:	2015	
Engine No.:	FB161619856	
Chassis No.:	JF1GP3KC5EG064002	
Maximum Power Output:	84.0 kW (112 bhp)	
Open Market Value:	\$11,381.00	
Original Registration Date:	30 Sep 2015	
First Registration Date:	30 Sep 2015	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$11,381.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	29 Sep 2025	
PARF Rebate Amount: Intended COE Rebate Details	\$8,535.00	
COE Expiry Date:	29 Sep 2025	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$55,399.00	
COE Rebate Amount:	\$40,087.00	
Total Rebate Amount:	\$48,622.00	

The information contained herein is correct as at 04 Jul 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCID	ENIT	CTAT	CH.	ENT	ī
ACCID		DIA	9		ı

Date Of Report

21/05/2018 18:27

Date Of Accident

19/05/2018 10:45

Exact Location Of Accident

BLK 1 BEACH ROAD OPEN SPACE CARPARK

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKV7197Z

Insured/Policyholder

Name Of Registered Owner

LIM SWEE TECK

NRIC No

S7236243H

Email Address

SWEETECHKLIM@HOTMAIL.COM

Mobile Phone No

(LOCAL) +65-81180580

Alternative Phone No.

OTHERS-93623364

Vehicle Particulars

Manufacturer

SUBARU

Model

IMPREZA 5D-1.6 I-S AWD CVT (A)

Exact Purpose for which vehicle was being used at

time of accident

PARKED

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

DMPCSN1543911702

Cover Note Number

Driver

Name of Driver

LIM SWEE TECK

NRIC No

S7236243H

Date Of Birth

04/10/1972

Occupation

INDOOR

Date Of Driving Pass

17/08/2006

Driving Experience

11 YEARS AND 9 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-81180580

Fax Number

Contact Number

OTHERS-93623364

EMail Address

SWEETECHKLIM@HOTMAIL.COM

Address

APT BLK 166B PUNGGOL CENTRAL #08-139

Postcode

822166

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

Vehicle

General Information of the Accident

COLLIDED INTO PARKED VEHICLE

Type Of Accident Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

KAMPONG GLAM NEIGHBOURHOOD POLICE POST

ROAD: 17A BEACH ROAD , POSTCODE: 199596 , COUNTRY: Police Station Address

SINGAPORE

Police Station Contact

TEL NO: 1800-2989999 - FAX NO: 62936498

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS PER ATTACHED SKETCH PLAN AND POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. 'Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the malling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

2115/21870-

Driver's Signature (If driver is not the policyholder) Date & Time:

NRIC/FIN No.:

Reporting Centre Personnel's Signature

GIARMC SketchPlanForm_V3

Sketch Plan #2 Pg. 1

								A:	SIN	AR.
										HA.
					77			13:	MUK	Mour
										井
#								H		
				13	1 19	A		Ш		
其						My Can		H		
#					+11			118	2	
					HH			1	411	
			THE ACCIDENT						0	
As	Per	POLICE	Ropor	€ T	12018	10519	1213	9	A	
			1		N)					
			11111						1 000. 10	
	المسد.									
_										
					THE STATE OF THE S					
FCLAR	ATION									
		egoing particula	rs are true in ev	ery respect.						
	are the for	1	rs are true in ev	ery respect.						
	are the for	egoing particula	rs are true in ev	ery respect.						
SA	are the for	5/2018	Driver's Sign				oorting Cent	tre Perso	onnel's Sign	nature

GIARRAC Sketch PlanForm_V3

Page 5 of 22

MOTORIMAGE ENTERPRISES PTE. LTD. 19 LORONG 8, TOA PAYOH SINGAPORE 319255

ESTIMATE

: ACCIDENT/BODY REPAIRS

WORKSHOP

: TOA PAYOH

CONTACT NO : 64730333

REFERENCE : INS/IC/CHI/0802/2018

DATE : 07-JUN-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#15-00 SPRINGLEAF TOMER

SINGAPORE S(079909)

TEL : 6389 6111

FAX: 6222 1033

OWNER'S NAME : LIM SWEE TECK (LIN RUIDE)

ADDRESS

: APT BLK 166B PUNGGOL CENTRAL

#08-139

\$(822166)

TELEPHONE NO : 8118 0580

TYPE OF CLAIM : COMPREHENSIVE CLAIM

POLICY NO : DMPCSN1543911702

VEHICLE NO : SKV7197Z

MODEL CODE : GP3CK2C

MODEL/YEAR : IMPREZA 1.61-S AWD CVT 5D

ENGINE NO : FB161619856

CHASSIS NO : JF1GP3RC5EG064002(*)

MILEAGE : 1 KM
DATE IN : 07/06/2018
LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 19/05/2018

Print Date : 07/06/2018

Print Time

: 18:27:30

MOTORIMAGE ENTERPRISES PTE. LTD. 19 LORONG 8, TOA PAYOH SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV7197Z

1 ODCLAIM CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM) 2 ZZ/001 CONDUCT OD CLAIM CHINA TAIPING DATE:19/05/2018 LOCATION:BLK 1 BEACH RD CARPARK TIME:1045HRS 3 ZZ/002 REPAIR/REPLACE FRONT BUMPER, FRONT LHS FENDER, HOOD AND PANEL 4 ZZ/003 RESPRAY FRONT BUMPER, FRONT LHS FENDER, HOOD AND PANEL 5 ZZ/004 TO CONDUCT FRONT LIGHTING TEST 6 ZZ/005 TO SUPPLY/INSTALL FRONT SENSOR-4 EYES 7 ZZ/006 SUNDRIES 100.00 Zol / No	s/No	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
LOCATION: BLK 1 BEACH RD CARPARK TIME: 1045HRS 3 ZZ/002 REPAIR/REPLACE FRONT BUMPER, FRONT LHS FENDER, 2800.00 5601 / HOOD AND PANEL 4 ZZ/003 RESPRAY FRONT BUMPER, FRONT LHS FENDER, HOOD AND PANEL 5 ZZ/004 TO CONDUCT FRONT LIGHTING TEST 50.00 301 / HOUSE SUPPLY/INSTABL FRONT SENSOR-4 EYES 400.00 7 × 500 / NO.000 201 / NO.0000 201 / NO.00000 201 / NO.000000 201 / NO.000000 201 / NO.00000000 201 / NO.000000000000000000000000000000000000	1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
HOOD AND PANEL 4 ZZ/003 RESPRAY FRONT BUMPER, FRONT LHS FENDER, HOOD 2100.00 860/ AND PANEL 5 ZZ/004 TO CONDUCT FRONT LIGHTING TEST 50.00 30/ 6 ZZ/005 TO SUPPLY/INSTALL FRONT SENSOR-4 EYES 400.00 7 × 5/ 7 ZZ/006 SUNDRIES 100.00 20/ N	2	ZZ/001			
AND PANEL 5 ZZ/004 TO CONDUCT FRONT LIGHTING TEST 50.00 301 / 6 ZZ/005 TO SUTTLY/INSTALL FRONT SENSOR-4 EYES 400.00 7 × 5 × 7 ZZ/006 SUNDRIES 100.00 201 / N	3	ZZ/002		2800.00	5601/
6 ZZ/005 TO SUPPLY/INSTALL FRONT SENSOR-4 EYES 400.00 7 × SV 7 ZZ/006 SUNDRIES 100.00 201 / N	4	ZZ/003		2100.00	8601
6 ZZ/005 TO SUPPLY/INSTALL FRONT SENSOR-4 EYES 400.00 7 × SV 7 ZZ/006 SUNDRIES 100.00 201 / N	5	ZZ/004	TO CONDUCT FRONT LIGHTING TEST	50.00	301/
	6	5 ZZ/005	TO SUPPLY/INSTALL FRONT SENSOR-4 EYES	400.00	7 × SVL
		7 22/006	SUNDRIES	100.00	201 / nec
TOTAL LABOUR CHARGES 5450.00				ARREST COLUMN	
			TOTAL LABOUR CHARGES		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV7197Z

		DAMAGEI	D PARTS & PRI	CES	
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT			S/LIST REMARKS
1 FENDER COMPLETE-FRONT, LEFT	57120FJ0419P	N 270.00	Χ		
2 HOOD COMPLETE-FRONT	57229FJ0009P	1 540.00 €	X		
3 BUMPER FACE F 1.61MP	57704FJ003	594.00	18		
4 ENERGY ABSORBER-FRT	57705FJ000	∫ 79.20	X		
5 BRKT CORNER F RH	57707FJ001	∫ 43.20	X		
6 BRKT FLH BUMP CORN	57707FJ011	·P/ 43.20	_		
7 BRKT-FR BMPR SD RH	57707FJ020	f⊷ 8.70	X		
8 BRKT-FRT BMPR SD LH	57707FJ030	8.70	7 SV C		
9 BACK BEAM COMPL-FRONT EU	57711FJ0019P	N 259.20	×		
10 COVER FOG F STD LH	57731FJ010	S ₂ 32.40	X		
11 LAMP ASSY HEAD HJL	84001FJ170	(M) 900.00	~/		
12 FRONT GRILLE-BASE	91122FJ000	رم 140.80	X		
13 MOLDING-FRONT GRILLE RIGHT	91123FJ000	J. 112.70	×		
14 MOLDING-FRONT GRILLE LEFT	91123FJ010	∫₄ 112.70	×		
15 BRET-CRILLE	91165FJ000	∫ ₁ 28.80	×		
16 SEAL	91171FJ000	∫~ 1.80	<		
17 ORNAMENT F SIX	93013FJ040	S 85.00	X		
SUB TOTAL		3260.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		652.08		0.00	0.00
GRAND TOTAL		2608.32		0.00	0.00
OVERALL TOTAL		2608.32			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD. 19 LORONG 8, TOA PAYOH SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKV7197Z

TOTAL LABOUR CHARGES

5450.00

TOTAL SPARE PARTS CHARGES

2608.32

GRAND TOTAL

8058.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

1 0.00 : 0.00

LIABILITY

REMARKS

Not Nothorn

Beauty Bypany

Ex 8750h

3day,

Fax 62564315

Kenneth (CKK)

PLS NOTE: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE EMTERPRISES PTE. LTD. 19 LORONG 8, TOA PAYON SINGAPORE 319255



LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SEV7197Z

s/No	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM CHINA TAIPING DATE:19/05/2018 LOCATION:BLK 1 BEACH RD CARPARK TIME:1045HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER, FRONT LHS FENDER, HOOD AND PANEL	2800.00	560.00 /
4	22/003	RESPRAY FRONT BUMPER, FRONT LES FENDER, BOOD AND PANEL	2100.00	840.00
5	22/004	TO CONDUCT FROMT LIGHTING TEST	50.00	30.00 /
6	22/005	TO SUPPLY/INSTALL FRONT SENSOR-4 EYES	400.00	.00 X
7	22/006	SUNDRIES	100.00	20.00/

		TOTAL LABOUR CHARGES	5450.00	1450.00

KDS SAT

MOTORIMAGE ENTERPRISES PIE. LTD. 19 LORONG 8, TOA PAYOH SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE RECN NO SKV7197Z

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER		LIST	S/NETT	S/LIST	REMARKS
1 FENDER COMPLETE-PRONT, LEFT	57120FJ0419P	270.00				χ
2 HOOD COMPLETE-FRONT	57229FJ0009P	540.00				X
3 BUMPER FACE F 1.6 DMP	57704FJ003	594.00			n	X
4 ENERGY ABSORBER-FRT	57705FJ000	79.20				X
5 BRET CORNER F RE	57707FJ001	43.20				X
6 BRRT FLE BUMP CORN	57707 F J011	43.20				OK/
7 BRRT-FR EMPR SD RH	57707FJ020	8.70				X
8 BRRT-FRT BMPR SD LH	57707FJ030	8.70			Sn	X
9 BACK BEAM COMPL-FRONT EU	57711FJ0019P	259.20				X
10 COVER FOG F STD LH	57731FJ010	32,40				x
11 LAMP ASSY HEAD HJL	84001FJ170	900.00				OR /
12 FRONT GRILLE-BASE	91122FJ000	140.80				X
13 MOLDING-FRONT GRILLE RIGHT	91123FJ000	112.70				X
14 MOLDING-FRONT GRILLE LEFT	91123FJ010	112.70				X
15 BRET-GRILLE	91165FJ000	28.80				x
16 SEAL	91171FJ000	1.80				X
17 ORNAMENT F SIX	93013FJ040	85.00				X
SUB TOTAL		943.20	0.00		0.00	
LESS DISCOUNT (NETT-20 %)		188.64	0.00	0.00	0.00	
GRAND TOTAL		754.56	0.00	0.00	0.00	
OVERALL TOTAL		754.56				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORINAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKV7197Z

943.20	
-188.64	
754.56	
0.00	
0.00	
0.00	
0.00	
0.00	
0.00	
0.00	
1450.00	
754.56	
	/ok
2204.56	, ,,,
750.00	
1454.56	
101.82	
1556.38	
	-188.64 754.56 0.00 0.00 0.00 0.00 0.00 0.00 0.00 1450.00 754.56 750.00 1454.56 101.82

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909

Our File No:

Odometer:

CS/CTI18012066/KRD3N2

Date:

03/09/2018

REFERENCE

Date of Loss:

Insured/Claimant:

LIM SWEE TECK

19/05/2018

Policy No: Nature of Claim: DMPCSN1543911702

Claim No: SNM18D02535C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKV7197Z

Make & Model:

SUBARU IMPREZA 5D, 1.6 I-S AWD CVT (A)

Reg. Date:

30/09/2015 (Man. Year: 2015)

Engine No: Chassis No:

FB161619856 JF1GP3KC5EG064002

Colour:

Metallic Pearl White

1600 cc

53374 km

Engine Capacity:

Market Value/New Car Price:

S\$60,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Pre-accident Condition: No

Front Tyre Size: Front Left Side:

205/55R16 Bridgestone 9 mm Rear Tyre Size: Rear Left Side:

205/55R16 Bridgestone 9 mm

Front Right Side:

Bridgestone 9 mm

Rear Right Side:

Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 3,108.32 0.00	Adjuster's 774.56 0.00	Difference 2,333.76 0.00	Diff % 75.08
Labour Paintwork Labour	4,950.00 0.00	1,430.00 0.00	3,520.00 0.00	71.11
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) - Excess (S\$)	8,058.32 750.00	2,204.56 750.00	5,853.76 0.00	72.64 0.00
(S\$)	7,308.32	1,454.56	5,853.76	80.10
+ GST 7.00/7.00% (S\$)	511.58	101.82	409.76	80.10
Nett Amount (S\$)	7,819.90	1,556.38	6,263.52	80.10

INSPECTION

Date of Assignment:

02/07/2018

Date Inspected:

04/07/2018 Inspected At:

Motorimage Enterprises Pte Ltd (HQ) 19 LORONG 8, TOA PAYOH

Singapore 319255

Estimated Period of Repair:

3.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 03 Sep 2018)

Parts:

143

SUBARU IMPREZA 5D 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV7197Z)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

		Part No.	ed Parts Particulars	Condition	Repairer's	Amount
		5.43.5.5.5.5			270.00 FN	*-FN
1	1		*FENDER COMPLETE-FRONT, LEFT	Repair		*-FN
2	1		*HOOD COMPLETE-FRONT	Repair	540.00 FN	
3	1		*BUMPER FACE F 1.6TMP	Repair	594.00 FN	*-FN
4	1		*ENERGY ABSORBER-FRT	Serviceable	79.20 FN	*-FN
5	1		*BRKT CORNER F RH	Serviceable	43.20 FN	*-FN
6	1		*BRKT FLH BUMP CORN	Distorted	43.20 FN	*43.20 FN
7	1		*BRKT-FR BMPR SD RH	Serviceable	8.70 FN	*-FN
8	1		*BRKT-FR BMPR SD LH	Serviceable	8.70 FN	*- FN
9	1		*BACK BEAM COMPL-FRONT EU	Repair	259.20 FN	*- FN
10	1		*COVER FOG F STD LH	Serviceable	32.40 FN	*-FN
11	1		*LAMP ASSY HEAD HJL	Cracked	900.00 FN	*900.00 FN
12	4		*FRONT GRILLE-BASE	Serviceable	140.80 FN	*- FN
13	-		*MOLDING-FRONT GRILLE RIGHT	Serviceable	112.70 FN	*- FN
14	4		*MOLDING-FRONT GRILLE LEFT	Serviceable	112.70 FN	*-FN
			*BRKT-GRILLE	Serviceable	28.80 FN	*- FN
15	1		*SEAL	Serviceable	1.80 FN	*- FN
16	3		*ORNAMENT F SIX	Serviceable	85.00 FN	*- FN
17	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
18 19	1		*FRONT SENSOR-4 EYES	Serviceable	400.00 FS	*- FS
		nart SESncN	lett. N=NettItemDisc.	-	0 8775(40)30(1)73	
1-11	ancinoc	part o-open		Sub Total (S\$)	3,760.40	963.20
			- Nett Item Discount on N Ite	이 전에서 열어져 되면 가장이 되지 않아 아니라 하다 가장이다.	652.08	188.64
				Total Parts (S\$)	3,108.32	774.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	l abour
Recommended	Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items		000000000000000000000000000000000000000	500.00
1	REPAIR/REPLACE FRONT BUMPER,FRONT LHS FENDER,HOOD AND PANEL	New	2,800.00	560.00
2	RESPRAY FRONT BUMPER, FRONT LHS FENDER, HOOD AND PANEL	New	2,100.00	840.00
3	TO CONDUCT FRONT LIGHTING TEST	New	50.00	30.00
	Gross Labou	r Cost (S\$)	4,950.00	1,430.00
	Report was unsubmitted during	ng this print-out.		

< END OF ESTIMATES >