

Your Ref: 17/18/18/VC00/020549

Date: 13<sup>th</sup> July 2018

Our Ref: CS1/LPC18012093/Kqbs2

**M/s Lonpac Insurance Bhd**  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:**  
**SLA 7126C**  
**INSURED VEHICLE: JSL 9**  
**ACCIDENT DATE: 17/02/2018**

We thank you for your instruction on 03/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLA 7126C from M/s New Auto Spec Appraisal.
- b) Colour damaged vehicle photographs of SLA 7126C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLA 7126C
Make & Model	: Honda Vezel 1.5X A
Year of Registration	: 2016
Chassis Number	: RU11111855
Engine Capacity	: 1496 cc
2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.