

2/03/2012

ASS. REC. BY:

REF: CS/MSG18012128 / Gsbm2 Special Instruction:

Surveyor

Melimen

Gyo Disney

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSH

Date/Time:

03072018 4:51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 683Z

Insured:

SJS 9234P

at Workshop m/s

Sun Fatt Motors

Tel:

6741 8535

of

Blk 1 Kaki Bukit Ave 6 #01-47

Policy No:

804420896mx

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

05072018 @ morning

H.O.D. Endorsement:

Date/Time:

04072018 10:06am

Person Contacted:

Vehicle-IN/OUT

Date/Time

Action/Instruction (✓) Estimate

YP 683Z-x

SJS 9234P-x

0607/18

@ 14:41 p.m. revised IA to Jasmine Lok v's merimen.

(08/11/13) wef

ASS. REC. BY:

REF:

MSIG

C 24798

ASSIGNMENT

From: Date: 5/7/2018

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YP683Z

at Workshop m/s Sun Fatt Motors
of 81K1, Kaki Bukit Ave 6 # 01-47

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 26 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

YP683Z

Yr Regn:

08 Jan 2016

Type: M.Car / M.Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Atlas 3.0 c.c 2453

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

64869

T/Radio: Insured / Std / NI / NA

Eng/No:

582F24060281

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ NI / S/Rim / STD A/Rim or

Tyre Size:

F: 195 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Rear

Firemax (Frt)

Front

Rear

R/Bal.

5

mm

R/Bal.

5/5

mm

L/Bal.

5

mm

L/Bal.

5/5

mm

D.O.A.

D.O.I.

05-07-18

Survey held at

w/s

5pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

part price check already. - X6Q.

17/8 finalized \$2667.56

(\$888.77 Red - 25%)

RECEIVED 20 AUG 2018

Date/Time, File Pass to?

1) 20/03/13
Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

150

10

Photos

Others

TOTAL

160

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 2667.56 p/p)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jun 2018		03 Jul 2018 16:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	DIONG CHAY YIN, ID: S7389529D, Tel: +6582876122		
Main Claimant:	LIGHT ON ELECTRICAL SERVICES PTE LTD, Co. Reg. No.: 21012479Z		
Vehicle Reg. No.:	YP683Z	Date of Loss:	27/06/2018 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	80442089QMX (Comprehensive) Coverage: 15/09/2017 - 14/09/2018
Vehicle Reg. No. (Insured):	SJS9234P	Policy No. (Claimant):	
		Excess:	
Repairer:	SUN FATT MOTORS (HQ) Blk 1 Kaki Bukit Avenue 6 #01-47 Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwel - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/07/2018]		
Driver/Custodian (Insured):	DIONG CHAY YIN (45 / Male), NRIC: S7389529D, Tel: +6582876122		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP nominated LKK to be SJE. Liability : 100% Contact : M/s Sun Fatt Motors @ 6741 8535		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18012128/Gsb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 04-07-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 9234P	Veh. Inspected	YP 683Z	
Policy No.	10527582QMX	Coverage (\$)	0.00	
Claim No.	563220	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/06/2018	Inspection Date		
Survey held at	SUN FATT MOTORS 1 KAKI BUKIT AVE 6 AUTOBAY@ KAKI BUKIT #01-47 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 06 Jul 2018

Preliminary Advice

Insured Vehicle No	: SJS9234P	Accident Date	: 27/06/2018
TP Vehicle No	: YP683Z	Assignment Date	: 03/07/2018
Make	: NISSAN ATLAS	Est. Duration of Repair	: 4 days
Date of Inspection	: 05/07/2018		
Inspection At	: SUN FATT MOTORS (HQ) Blk 1 Kaki Bukit Avenue 6 #01-47 Autobay Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,556.33
Revised Amount	:S\$	1,281.20
Check Items (Estimated)	:S\$	1,386.36
Total	:S\$	2,667.56

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Light Vehicle Registration Details

Owner Particulars	
NRIC/Passport/Company Cert No.:	201012479Z
Owner ID Type:	Company
Owner Name:	LIGHT ON ELECTRICAL SERVICES PTE LTD
Registered Address:	3025 UBI ROAD 3 #04-119 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408653
Mailing Address:	-
Birth Date:	-
Vehicle Particulars	
Vehicle No.:	YP683Z
Previous Vehicle No.:	-
Effective Date of Ownership:	08 Jan 2016
Original Regn Date:	08 Jan 2016
Registration Date:	08 Jan 2016
Year of Manufacture:	2015
Vehicle Type:	Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Scheme:	-
Vehicle Attachment 1:	With Hood
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	NISSAN
Vehicle Model:	ATLAS 3.0 5M/T 2WD SINGLE CAB
Primary Colour:	Silver
Secondary Colour:	-
Passenger Capacity:	2
Chassis No.:	SZ2F24060281
Engine No.:	ZD30003205N
Engine Capacity / Power Rating:	2953 cc / -
Maximum Power Output:	-
Propellant:	Diesel
Max Unladen Weight:	1960 kg
Maximum Laden Weight:	3525 kg
Open Market Value:	\$30,746.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
Minimum PARF Benefit:	-
No. of Transfers:	0
IU Label No.:	1510893729
COE No.:	2016010805000659H
COE Expiry Date:	07 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Registration Category:	C - Goods Vehicle & Bus
Quota Premium (QP) / Prevailing Quota Premium:	- / \$45,166.00
PQP Paid:	\$19,183.00
QP (Regn Cat):	--
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$0.00
Additional Registration Fee Rate:	5.00 %
Actual ARF Paid:	\$1,538.00
Vehicle Lifespan Expiry Date:	07 Jan 2036
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	The vehicle is registered under Early Turnover Scheme.

OK

Save as PDF

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2479Z
Vehicle Details	
Vehicle No.:	YP683Z
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jul 2018
Vehicle Make:	NISSAN
Vehicle Model:	ATLAS 3.0 5M/T 2WD SINGLE CAB
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	ZD30003205N
Chassis No.:	SZ2F24060281
Maximum Power Output:	-
Open Market Value:	\$30,746.00
Original Registration Date:	08 Jan 2016
First Registration Date:	08 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$1,538.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,183.00
COE Rebate Amount:	\$14,392.00
Total Rebate Amount:	\$14,392.00

The information contained herein is correct as at 06 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/06/2018 15:06
Date Of Accident	27/06/2018 19:30
Exact Location Of Accident	ALONG SEMBAWANG ROAD TOWARDS WOODLAND
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP683Z
Insured/Policyholder	
Name Of Registered Owner	LIGHT ON ELECTRICAL SERVICES PTE LTD
Co Reg No	201012479Z
Email Address	LIGHTON29@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96102288
Alternative Phone No	OFFICE-96102288

Vehicle Particulars

Manufacturer	NISSAN
Model	ATLAS-3.0 D F24 (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076969282-02
Cover Note Number	

Driver

Name of Driver	CHINNADURAI SANTHOSH
Passport No/FIN	G6634651Q
Date Of Birth	16/05/1990
Occupation	OUTDOOR
Date Of Driving Pass	22/09/2017
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92423242
Fax Number	
Contact Number	OFFICE-96102288
Email Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : SURESH
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJS9234P
 Vehicle Make/Model/Colour NA
 Details Of Properties NA
 Vehicle Category PRIVATE CAR
 Name of Driver DIONG CHAY YIN
 NRIC/Passport Number S7389529D
 Contact Number 82876122
 Address NA
 NA
 Postcode
 Insurance Company Name
 Nature Of Damage NA
 No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

LEAD IN FIELD

P. 1 VP 8-12
P. 2 VP 9-12

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/06/2018, I was driving along Sembawang Road towards Woodlands. As I came near the pedestrian light, traffic was heavy and I slow down my vehicle. I noticed the vehicle B got flashing towards my vehicle and hit the rear of my vehicle.

DECLARATION

I HEREBY DECLARE THAT:

1. The reporting centre personnel has explained the above statement & sketch plan to me.
2. I fully understand and agree with the above statement.
3. The information given is true and correct to best of my/our knowledge and belief.

Name, Signature & Company
(to be printed)

DECLARATION

立安电业服务社
LIGHT ON ELECTRICAL SERVICES PTE LTD
81K 3025 Ubi Road 3 #04-119
Singapore 405553
Tel: 6749 6711 Fax: 6749 1125
Email: lighton25@gmail.com

Printed Name, Signature & Company
(to be printed)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

立安电业服务社
LIGHT ON ELECTRICAL SERVICES PTE LTD
Blk 3025 Ubi Road 3 #04-119
Singapore 408653
Tel: 6749 6711 Fax: 6749 1125
Email: lighton29@gmail.com

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SUN FATT MOTORS

1 Kaki bukit Avenue 6 Auto Bay @ Kaki Bukit #01-47
Singapore 417883

Tel: 67418535 Fax: 64815149

Your Ref: Estimates cost of repair: YP 683 Z

date: 3.7.18.

Nett items:

1pc	rear bumper	BT	\$	1,046.80	
2pcs	tail lamp	CRA		493.60	
1pc	tail lamp bracket lh	BT		115.30	
2pcs	rear reflector	Cut		96.40	
1pc	tail gate rubber lh	Cut		56.30	
1pc	front side mirror lh	X NN		165.30	X
			\$	1,973.70	1808.4
				197.37	
				1,776.33	1627.56
1pc	rear number plate and frame	CRA		80.00	40.

To repair rear end panel, remove and replace above mention
Damaged parts,

800.00 500

To spray painting

800.00 500 X

To spray anti rust

100.00 X NN

\$ 3,556.33

2667.56

4 Days.

part by part.

before paint photo.

After repair photos.

Guo Qian - 8288 0282

05/7/18.

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012128/GSBN2

Date: 20/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	10527582QMX
Claimant Vehicle No :	YP683Z	Insured Vehicle No :	SJS9234P
Date of Loss:	27/06/2018	Nature of Claim:	TP
		Claim No:	563220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP683Z	Engine No:	ZD30003205N
Make & Model:	NISSAN ATLAS, 3.0 D F24 (M)	Chassis No:	SZ2F24060281
Reg. Date:	08/01/2016 (Man. Year: 2015)	Odometer:	64869 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D)
Front Left Side:	Firemax 5 mm	Rear Left Side:	Yokohama 5/5 mm
Front Right Side:	Firemax 5 mm	Rear Right Side:	Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,856.33	1,667.56	188.77	10.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,000.00	700.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,556.33	2,667.56	888.77	24.99

INSPECTION

Date of Assignment:	03/07/2018	
Date Inspected:	05/07/2018 Inspected At:	SUN FATT MOTORS (HQ) Blk 1 Kaki Bukit Avenue 6 #01-47 Autobay Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Aug 2018)	
Parts:	N/A	NISSAN ATLAS 3.0 D F24 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP683Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,046.80 FN	*1,046.80 FN
2	2		*TAIL LAMP	Cracked	493.60 FN	*493.60 FN
3	1		*TAIL LAMP BRACKET LH	Bent	115.30 FN	*115.30 FN
4	2		*REAR REFLECTOR	Cut	96.40 FN	*96.40 FN
5	1		*TAIL GATE RUBBER LH	Cut	56.30 FN	*56.30 FN
6	1		*FRONT SIDE MIRROR LH	Not Necessary	165.30 FN	*- FN
7	1		*REAR NUMBER PLATE AND FRAME	Cracked	80.00 FS	*40.00 FS
					Sub Total (S\$)	2,053.70
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	197.37
					Total Parts (S\$)	1,856.33
						1,667.56

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR END PANEL,REMOVE AND REPLACE ABOVE MENTION DAMAGED PARTS	New	800.00	500.00
2	TO SPRAY PAINTING	New	800.00	500.00
3	TO SPRAY ANTI RUST	New	100.00	-
Gross Labour Cost (\$\$)			1,700.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >