

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 73E90646at Workshop m/s Levi

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 4500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: u Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 73E90646 Yr Regn: 27/10 10Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PIAGGIO GILERA c.c. 198Colour: Black A/C: Insured / Std / NI / NASp. Reading: 30806 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2APM4640100005306Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 120/70-14R: 140/60-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 23/6/14 D.O.I. 6/7/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear. N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 3893 yrs. 4 mths.Ltd \$4,000.00CRAB: \$4,421.00 (52%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$ _____) S + RS, SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____) TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Survey Fee:

Transportation:

Photos

Others

TOTAL

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 4 July 2018 10:48 AM
To: Catherine Chong (LKK Auto)
Cc: MT_Claim_SG
Subject: PRE-REPAIR SURVEY OF FBE9064G
Attachments: 04072018104347.pdf

11:20 am @ 4/7/2018
vehicle in
person @ Irene
Sur @ Marus

Our ref : 18/18/18/VP05/020707

Dear Catherine,

We attached a copy of fax from M/s Kivile Enterprise for your attention.

Please proceed to survey the vehicle.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 12 July, 2018 12:22 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; Vic (LKKAUTO)
Subject: RE: PRE-REPAIR SURVEY OF FBE9064G
Attachments: INSD 'S REPORT.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

Attached insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 12 July, 2018 11:54 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; ONG LI LI; ericwoo; Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: PRE-REPAIR SURVEY OF FBE9064G

WITHOUT PREJUDICE

LPC ref: 18/18/18/VP05/020707
LKK REF: CC4/LPC18012135/Uha3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: FBE 9064G

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.



吉维利企业 KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBE9064G model :piaggio runner 200

Handle Bar
Balance
Brake Lever LH
Mirror Set
Meter Cover
Wind Screen
Wind Screen Holder
Top
Front Fairing
Front Fairing Cover
Head Lamp Set
Front Fairing Protector
Front Signal Light RH
Side Fairing Small
Front Fairing Stay
Front Fairing Inner Garnish Top
Front Fairing Inner Garnish Lower
Front Fork Set
Fork Triple Clamp
Staying Cone Set
Front Mudguard
Front Disc
Front Rim
Front Brake Caliper
Front Wheel Shaft
Fairing Garnish Top
Fairing Garnish Centre
Lower Fairing
Radiator
Front Footrest Base LH
Centre Footrest Base LH
Side Cover LH
Clutch Cover
Clutch Cover Garnish
Oil Stick
Main Stand
Side Stand
Side Stand Bracket
Side Stand Bracket Accessories
Box
Body Frame Repair

Seat	160	—
SEN	38	✓
ent	58	—
SW	85	—
11	120	X
SW	120	—
701	40	—
CM	190	—
KW	190	—
SW	145	✓
SW	330	—
SW	90	—
SW	65	✓
SW	135	—
SW	85	—
CM	165	—
CM	165	—
	650	?
	220	?
15	130	?
SW	95	—
11	230	X
	550	?
12	380	X
	85	?
CM	190	—
CM	155	—
CM	155	—
11	450	X
CM	75	—
CM	75	—
CM	125	—
M.S	65	—
	65	?
CM	35	—
12	180	X
NZ	130	X
11	55	?
	95	?
CM	165	150 S.N
	350	280

Not Allowed
N/A
S/L
6/7/18
Tampub. Attye

102

Body Frame Respray
 Number Plate Front
 Fairing Screw Set
 Fairing Crip Set
 IU
 Transport
 Labour

	750	600
nu	30	105.2
nu	90	50
1pc	100	50
cu	165	✓
	50	38
	350	300
	8421	

ATTN: off floor Incharge,

Pls arrange survey to inspect my FBE 9064 G.



5/7/18

Thks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before later spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-3131

2817.9

1540

4357.9



吉维利企业

KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBE9064G model :piaggio runner 200

Handle Bar
Balance
Brake Lever LH
Mirror Set
Meter Cover
Wind Screen
Wind Screen Holder
Top
Front Fairing
Front Fairing Cover
Head Lamp Set
Front Fairing Protector
Front Signal Light RH
Side Fairing Small
Front Fairing Stay
Front Fairing Inner Garnish Top
Front Fairing Inner Garnish Lower
Front Fork Set
Fork Triple Clamp
Staying Cone Set
Front Mudguard
Front Disc
Front Rim
Front Brake Caliper
Front Wheel Shaft
Fairing Garnish Top
Fairing Garnish Centre
Lower Fairing
Radiator
Front Footrest Base LH
Centre Footrest Base LH
Side Cover LH
Clutch Cover
Clutch Cover Garnish
Oil Stick
Main Stand
Side Stand
Side Stand Bracket
Side Stand Bracket Accessories
Box
Body Frame Repair

Seat 160 —
Scr 38 —
Seat 58 —
Seat 85 —
11 120 X
Seat 120 —
Twr 40 —
Cm 190 —
KAW 190 —
Seat 145 —
Seat 330 —
Seat 90 —
Seat 165 —
Seat 135 —
Seat 85 —
Cm 165 —
Seat 165 —
Seat 650 —
Seat 220 —
Seat 130 —
Seat 95 —
11 230 X
2 550 X
2 380 X
11 85 X
Cm 190 —
Cm 155 —
Cm 155 —
11 450 X
Cm 75 —
Cm 75 —
Cm 125 —
11 65 —
11 65 X
11 35 —
2 180 X
11 130 X
11 55 X
11 95 X
Cm 165 1505.2
350 280

Not Allowed
N/A
1/59 4000/2
521
6/7/18
Talephat Atege

102

Body Frame Respray
 Number Plate Front
 Fairing Screw Set
 Fairing Crip Set
 IU
 Transport
 Labour

	750	600
nu	30	105.2
nu	90	505.2
nc	100	505.2
cu	165	5.2
	50	35
	350	300
	<u>8421</u>	

ATTN: officer Incharge,

Pls arrange survey to inspect my FBE 9064G.



P4031

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before final spray painting
- To supply damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair work should be allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

P-3117
 2817.9
 1440
 4187.9

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 8661J

Vehicle Details

Vehicle No.: FBE9064G

Vehicle to be Exported: No

Intended De-registration Date: 06 Jul 2018

Vehicle Make: PIAGGIO

Vehicle Model: GILERA RUNNER ST 200

Primary Colour: Black

Manufacturing Year: 2010

Engine No.: M464M0008686

Chassis No.: ZAPM4640100005306

Maximum Power Output: -

Open Market Value: \$3,373.00

Original Registration Date: 27 Oct 2010

First Registration Date: 27 Oct 2010

Transfer Count: 5

Actual ARF Paid: \$506.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2020

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$1,689.00

COE Rebate Amount: \$389.00

Total Rebate Amount: \$389.00

The information contained herein is correct as at 06 Jul 2018

OK

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/PIAGGIO-PIAGGIO-X8-200/7363/)

Piaggio X10 350 (/listing/usedbike/piaggio-piaggio-x10-350/8303/)



(/listing/usedbike/piaggio-piaggio-x10-350/8303/)

SGD\$9300

Reg : 11/03/2013

Type: Scooters

330cc

Visit United Cycles Now! Trade In/Loan Available! Price Nego For Sincere Buyers! Call Now!

Posted on : 23/06/2018

★ PAID AD

★ DEALER AD

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/PIAGGIO-PIAGGIO-X10-350/8303/)

Piaggio X8 400 (/listing/usedbike/piaggio-piaggio-x8-400/8305/)



(/listing/usedbike/piaggio-piaggio-x8-400/8305/)

SGD\$4500

Reg : 14/09/2010

Type: Scooters

399cc

Visit United Cycles! Trade In/Loan Available! Price Nego For Sincere Buyers! Call Now!

Posted on : 23/06/2018

★ PAID AD

★ DEALER AD

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/PIAGGIO-PIAGGIO-X8-400/8305/)

10 Sin Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

Our ref 0709170501N001871313

07 Sep 2017

KIVILE ENTERPRISE
3007 UBI ROAD 1
#01-408
KAMPONG UBI INDUSTRIAL ESTATE
SINGAPORE 408701

000090



Dear Sir/Madam

NOTIFICATION ON TRANSFER OF OWNERSHIP FOR VEHICLE NO. FBB6373A

We are pleased to inform you that your application to transfer ownership of the above-mentioned vehicle has been approved. You are no longer the registered owner of the vehicle with effect from 07 Sep 2017. The details are as follows:

Vehicle No.	: FBB6373A
Application Date	: 07 Sep 2017
Effective Transfer of Ownership Date	: 07 Sep 2017
Vehicle Make	: YAMAHA
Vehicle Model	: SPARK135 M
Chassis No./Trailer Chassis No.	: 5YP205694 / -
Engine No./Motor No.	: 5YP205694 / -

- Please contact our customer service officers at tel: 1800-CALL LTA (1800-2255 582) should you require further assistance.
- Thank you.

Yours sincerely

NG LAY CHOO (MS)
DEPUTY DIRECTOR, VRL SERVICE OPERATIONS
VEHICLE SERVICES GROUP
LAND TRANSPORT AUTHORITY

(This is a computer-generated notice that requires no signature.)

From 15 February 2017, you do not need to display road tax disc on the windscreen of your vehicle. LTA has stopped issuing physical road tax discs as part of our efforts to streamline our processes. Please ensure that your original motor insurance certificate is readily available in your vehicle at all times. If you are driving into Malaysia, you are advised to carry printed proof of the validity of your road tax in your vehicle.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18012135/Uha3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 31-10-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGH 5622Y	Veh. Inspected	FBE 9064G
Policy No.	Z18VP05018648	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020707	Excess (\$)	0.00
Assign From	GERALD	Assign Date	04/07/2018

2. Vehicle Particulars & Condition

Make & Model	PIAGGIO GILERA	c.c	198
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	ZAPM4640100005306	Colour	BLACK
Odometer	30806	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70-14	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/60-13	PIRELLI	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/06/2018	Inspection Date	06/07/2018
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 9064G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	160.00	160.00
1	BALANCE	SCRATCHED	38.00	38.00
1	BRAKE LEVER LH	BENT	58.00	58.00
1	SET MIRROR	BROKEN	85.00	85.00
1	METER COVER	NOT NECESSARY	120.00	-
1	WIND SCREEN	BROKEN	120.00	120.00
1	WIND SCREEN HOLDER	TWISTED	40.00	40.00
1	TOP	CRACKED	190.00	190.00
1	FRONT FAIRING	BROKEN	190.00	190.00
1	FRONT FAIRING COVER	BROKEN	145.00	145.00
1	SET HEAD LAMP	BROKEN	330.00	330.00
1	FRONT FAIRING PROTECTOR	BROKEN	90.00	90.00
1	FRONT SIGNAL LIGHT RH	BROKEN	65.00	65.00
1	SIDE FAIRING SMALL	BROKEN	135.00	135.00
1	FRONT FAIRING STAY	BENT	85.00	85.00
1	FRONT FAIRING INNER GARNISH TOP	CRACKED	165.00	165.00
1	FRONT FAIRING INNER GARNISH LOWER	CRACKED	165.00	165.00
1	SET FRONT FORK	BENT / TWISTED	650.00	650.00
1	FORK TRIPLE CLAMP	BENT	220.00	220.00
1	SET STAYING CONE	NECESSARY	130.00	130.00
1	FRONT MUDGUARD	BROKEN	95.00	95.00
1	FRONT DISC	NOT NECESSARY	230.00	-
1	FRONT RIM	TO REPAIR SEE LABOUR	550.00	-
1	FRONT BRAKE CALIPER	TO REPAIR SEE LABOUR	380.00	-
1	FRONT WHEEL SHAFT	NOT NECESSARY	85.00	-
1	FAIRING GARNISH TOP	CRACKED	190.00	190.00
1	FAIRING GARNISH CENTRE	CRACKED	155.00	155.00
1	LOWER FAIRING	CRACKED	155.00	155.00
1	RADIATOR	NOT NECESSARY	450.00	-

Report Ref No. CC4/LPC18012135/Uha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FOOTREST BASE LH	CUT	75.00	75.00
1	CENTRE FOOTREST BASE LH	CUT	75.00	75.00
1	SIDE COVER LH	CRACKED	125.00	125.00
1	CLUTCH COVER	MISSING	65.00	65.00
1	CLUTCH COVER GARNISH	NOT NECESSARY	65.00	-
1	OIL STICK	CUT	35.00	35.00
1	MAIN STAND	TO REPAIR SEE LABOUR	180.00	-
1	SIDE STAND	NOT FITTED	130.00	-
1	SIDE STAND BRACKET	NOT NECESSARY	55.00	-
1	SIDE STAND BRACKET ACCESSORIES	NOT NECESSARY	95.00	-
	LESS 10% DISCOUNT		-	-403.10
			6,371.00	3,627.90
	<u>SPECIAL NETT ITEMS</u>			
1	BOX (SN)	CUT	165.00	150.00
1	NUMBER PLATE FRONT (SN)	NECESSARY	30.00	10.00
1	SET FAIRING SCREW (SN)	NECESSARY	90.00	50.00
1	SET FAIRING CRIP (SN)	NECESSARY	100.00	50.00
1	IU (SN)	CUT	165.00	165.00
			550.00	425.00
	<u>LABOUR</u>			
	BODY FRAME REPAIR .		350.00	280.00
	BODY FRAME RESPRAY .		750.00	600.00
	TRANSPORT.		50.00	35.00
	LABOUR.INCLUSIVE OF THE REPAIR OF FRONT BRAKE CALIPER ,FRONT RIM AND MAIN STAND.		350.00	300.00
	-		-	-
	-		-	-
	-		-	-
			1,500.00	1,215.00
	GRAND TOTAL		8,421.00	5,267.90

Report Ref No. CC4/LPC18012135/Uha3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	----------

Report Ref No. CC4/LPC18012135/Uha3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.