

ASS. REC. BY:

REF: CS/FCI18012141/T1sd3ⁿ² Special Instruction:Surveyor
cwsTaufik
May chua

ASSIGNMENT (Office)

From (Person):

of

FCI

Date/Time: 3/7/18 @ 5.44pm

Estimated Cost:

Bill to:

OD / (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 3705L

Insured:

SHD 6940 G

at Workshop m/s

Cycle & Carriage Automotive
209 Pandan Gardens

Tel:

81680997

Policy No:

Claim No:

D18005143MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A

29/6/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9.55am @ 1/7/18

Person Contacted:

Mr. Tan

Vehicle IN / (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLX 3705L - X
	SHD 6940 G - CC3/AIG16020799/Hlyg3q2 DOA: 30/10/2016
23/07/18	@ 13:45 pm. revised PA to May Chua via email.
26/09/18	Confirmed P/P \$3,296.00 @ 3 days with Taufik (\$3,324.00 Red - 46%)

(08/11/13) wef

ASS. REC. BY:

REF:

F.C.I

ASSIGNMENT

From:

Date:

18/07/18

Estimated Cost:

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLX 3705L Yr Regn: 2018 1 March

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Eclipse Cross c.c 1499

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

1833

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SUMAXTGK1WJ200666

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

7 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19/7/18 9320pa.

Survey held at

CSC Pandan Gdn

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 26 SEP 2018

Date/Time, File Pass to?

26/09/18

1)

Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

150

50

50

41

291

Report Format :

Lump Sum / I.B.I: (\$ 3,896.00 p/p)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012141/T1sd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6940G	Veh. Inspected	SLX 3705L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005143MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/06/2018	Inspection Date		
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005143MFSH

Date: 23 July 2018

Our Ref: CS/FCI18012141/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 3705L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/07/2018 at the premises of M/s Cycle & Carriage Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,303.00</u> .
Revised Estimate Amount	: S\$ <u>2,460.00</u> .
"Check" Items Amount	: S\$ <u>1,793.00</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	02-07-2018	Our Ref No. D18005143MFSH
Accident Date	29-06-2018	Claim Type. Third Party
Insured Vehicle	SHD6940G	Third Party Vehicle. SLX3705L
Survey Location	209 PANDAN GARDENS	
Contact Person.	TAY JIAN YE	
Contact No.	65684501/ 81680997	Fax No. 65651240
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241992)



PRI Documents



Close X

PRI Header Details

Claim No	D18005143MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CYCLE & (LTD
Workshop Name	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (Contact Person : TAY JIAN YE)	Survey Location & Contact Details	209 PANDAN GARDENS Mobile: 81680997 , Phone: 65684501 , Fax: 65651241 EmailId: JIANYE.TAY@CYCLECARRIAGE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6940G	TP Vehicle No	SLX3705L
PRI Recieved Date	03-07-2018 11:55:23 AM	Surveyor Appointed Date	03-07-2018 05:43:09 PM	Surveyor Accept Date	04-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 26 September 2018 11:03 AM
To: 'Lauro Araos Songcuan Jr'
Cc: 'Tay Jian Ye'; 'Yusof Bin Hashim'; 'Cheng Jo Jo'; 'Loi Ai Ting'; 'Andre Chow En De'; Admin A; Admin-D (LKKAuto); Taufikh (LKKAuto)
Subject: RE: SLX3705L (MIT) - FINALIZE

Dear Larry,

Confirmed finalised P/P amount \$ 3,896.00 and 3 repair days.

Final invoice and all supporting documents sent over to **First Capital Ins Ltd.**

Thank you,

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Shir@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Monday, 20 August 2018 9:01 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: SLX3705L (MIT) - FINALIZE

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lauro Araos Songcuan Jr <lauro.songcuan@cyclecarriage.com.sg>
Sent: Thursday, 16 August 2018 5:35 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Yusof Bin Hashim <yusof.hashim@cyclecarriage.com.sg>; Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>
Subject: RE: SLX3705L (MIT) - FINALIZE

Additional photos

From: Lauro Araos Songcuan Jr
Sent: 16 August 2018 17:32

To: Taufikh (LKKAUTO); Admin A
Cc: Andre Chow En De; Loi Ai Ting; Cheng Jo Jo; Yusof Bin Hashim; Tay Jian Ye
Subject: SLX3705L (MIT) - FINALIZE

Dear Sir/Madam,

Pls. refer to attached files and photos.

Kindly confirm finalized amount of **\$ 3,896.00** before Gst for SLX3705L.

Thank you so much.

Best regards,

Larry Songcuan
Customer Service



Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4658 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 23 July 2018 1:45 PM
To: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: ASSIGNMENTS@LKKAUTO.COM; sur@lkkauto.com; 'Nivitha (LKK Auto)'
Subject: RE: SURVEY ASSESSMENT - D18005143MFSH/1
Attachments: SLX 3705L - Preli Advise.pdf

Dear May Chua,

Enclosed herewith preliminary advice of SLX 3705L.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 4 July 2018 9:58 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18005143MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 3 July 2018 5:44 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005143MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : MICHAEL JOHN OLIVER
 Period of Insurance : 26 Mar 2018 To 25 Mar 2020
 Engine No. : 4B40DA2325
 Chassis No. : JMAXTGK1WJZ001066

Vehicle No. : SLX3705L
 Policy No. : 1800029116
 Endorsement No. :
 Issued Date : 04 Apr 2018

ABOUT THE COVER

Make/Model : MITSUBISHI Eclipse Cross 1.5
 Engine Capacity/Tonnage : 1,499.00 CC Sum Insured : Market Value First Year of Registration : 2018
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

MICHAEL JOHN OLIVER - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Customer Service Centres (For windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
 2. Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
 3. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504620218

C&CMICP2 - LUKAS
 239 ALEXANDRA ROAD
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

S8CASB

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2726849H



Name

MICHAEL JOHN OLIVER

Race

CAUCASIAN

Date of birth

09-07-1948 M

Country of birth

UNITED KINGDOM

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S2726849H

Name

MICHAEL JOHN OLIVER

Birth Date: 09 Jul 1948

Issue Date: 26 Sep 2007



FOR C&C USE ONLY

8651613



NRIC No. S2726849H



FOR C&C USE ONLY

Nationality

BRITISH

Date of issue

24-09-2004

308 JALAN AMPANG
SINGAPORE 258618
NRIC No: S2726849H


Date: 11-12-2005 No: 531089G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2B	Motorcycles < 200 cc	04 Jan 2002
Class 2A	Motorcycles between 201 cc and 400 cc	04 Jan 2002
Class 2	Motorcycles > 400 cc	04 Jan 2002
Class 3	Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg	04 Jan 2002

FOR C&C USE ONLY



Licence No: S2726849H

NP 428A



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
MR MICHAEL JOHN OLIVER 30B JALAN AMPANG SINGAPORE 268616 Contact No	Cust No/Name	KCV08274/Mr Michael John Oliver
	Reg No/Reg Date	SLX3705L / 26/03/201
	Date In/Mileage	/ 0
	Chassis No	JMAXTGK1WJZ001066
	Engine No	4B40DA2325
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C 2WD (T07)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV08274	CRDVCH	19/07/2018/ 10:18		465 / Tay Jian Ye	27901		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							550 1650.00
TO RENEW REAR BUMPER AND REPAIR END PANEL							✓ 60.00
E PNT88000							420 1260.00
TO TRANSFER REAR PARKING SENSOR TO NEW PART							30 50.00
E PNT98000							✓ 200.00
PAINT WORK SPRAY REAR BUMPER AND END PANEL							nn X 60.00
A 54900099							20 50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							✓ 200.00
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							20 50.00
TO APPLY ANTI COROSSION							✓ 200.00
M SUNDRY							
SUNDRIES							
M SUNDRY							
TO APPLY ZENTNA ON THE DAMAGE PART							
M REINFORCEMENT,RR BUMPER				1.00	489.00	00.00	? 489.00
M BRKT,R/BMPR FACE SIDE,LH				1.00	25.00	00.00	rec 25.00
M BRKT,R/BMPR FACE SIDE,RH				1.00	25.00	00.00	rec 25.00
M FACE,RR BUMPER				1.00	548.00	00.00	de 548.00
M EXTENSION,RR BUMPER				1.00	150.00	00.00	de 150.00
M COVER,RR BUMPER,LH				1.00	116.00	00.00	ant 116.00
M COVER,RR BUMPER,RH				1.00	116.00	00.00	ant 116.00
M SENSOR,BACK DISTANCE WARN				1.00	326.00	00.00	326.00
M SENSOR,BACK DISTANCE WARN				1.00	326.00	00.00	326.00
M SENSOR,CORNER CLEARANCE LH				1.00	326.00	00.00	326.00
M SENSOR,CORNER CLEARANCE RH				1.00	326.00	00.00	326.00

Estimate

Surveyor Name: Tay Jian Ye 97495749

Surveyor Signature: [Signature]

Date: 19/7/18 1520

Remarks: Repair before paint
02 days

* sales agreement

✓ 200.00

? 489.00

rec 25.00

rec 25.00

de 548.00

de 150.00

ant 116.00

ant 116.00

326.00

326.00

326.00

326.00

SURVEYOR NAME: *Tay Jian Ye*SURVEYOR SIGNATURE: *Tay Jian Ye*

DATE: 19/7/18

REMARKS: Resurvey before paint

Confirm & Accepted By: *Tay Jian Ye*

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on 6303.00

Nett 6,303.00

441.21

Total Payable 6,744.21

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Michael John Oliver	Cust No/Name KCV08274/Mr Michael John Oliver
30B Jalan Ampang	Reg No/Reg Date SLX3705L / 26/03/2018
Singapore 268616	Date In/Mileage 20/07/2018/ 1833
Contact No Mobile: 96621975	Chassis/Package JMAXTGKIWJZ001066 /DC17S3C
20/07/	Engine No 4B40DA2325
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD (T07)
	Colour/Trim X04 BLACK / BK BLACK


Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	16/08/2018/ 16:29	TLT	884 / Lauro Songcuan	27901

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER				550.00 ✓
E PNT88000 TRANSFER REAR PARKING SENSOR TO NEW PART				60.00 ✓
E PNT98000 SPRAY PAINT REAR BUMPER				420.00 ✓
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
M SUNDRY APPLY ZERTONA PAINT PROTECTION				200.00 ✓
A 15900099 RENEW EXHAUST REAR MUFFLER → <i>supp.</i>				ali ✓ 150.00
X REINFORCEMENT,RR BUMPER ✓	1.00	489.00	00.00	489.00 ✓
X BRKT,R/BMPR FACE SIDE,LH ✓	1.00	25.00	00.00	25.00 ✓
X BRKT,R/BMPR FACE SIDE,RH ✓	1.00	25.00	00.00	25.00 ✓
X FACE,RR BUMPER ✓	1.00	548.00	00.00	548.00 ✓
X EXTENSION,RR BUMPER ✓	1.00	150.00	00.00	150.00 ✓
X COVER,RR BUMPER,LH ✓	1.00	116.00	00.00	116.00 ✓
X COVER,RR BUMPER,RH ✓	1.00	116.00	00.00	116.00 ✓
X MUFFLER,EXHAUST MAIN	1.00	591.00	00.00	del ✓ 591.00
X BUZZER,KEYLESS OPERATIO,RR	1.00	90.00	00.00	car ✓ 90.00
X LAMP ASSY,BACKUP,LH } <i>supp.</i>	1.00	116.00	00.00	cut ✓ 116.00

"Guarantee your warranty, maintain with Cycle & Carriage."

Parts	2,266.00			
Labour	1,410.00			
Standard Menu	0.00	7% GST on	3896.00	272.72
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	220.00			
Total (w/o GST)	3,896.00		Total Payable	4,168.72

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO.: FIRST CAPITAL

Supplementary For Registration No.: SLX 3705 L

<u>Materials</u>		<u>Cost (\$)</u>
1	Muffler, Exhaust Main	591.00 dd
2	Buzzer, Keyless Operatio, RR	90.00 cra
3	Lamp Assy, Backup, LH	116.00 cut
		<u>797.00</u>
<u>Labour</u>		
1	Renew Exhaust Rear Muffler	150.00 /
		<u>947.00</u>
7% Gst		<u>66.29</u>
Total		<u>1,013.29</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LARRY SONGCUANG
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CYCLE & CARRIAGE

LKK
Taufikh

VEHICLE NO : SLX 3705L

MODEL : MIT/ECLIPSE CROSS 1.5 T/C

WIP : 27901

Material	: \$	<u>2,266.00</u>
Labour	: \$	<u>1,630.00</u>
Sub-Total	: \$	<u>3,896.00</u>
Less 2% Disc	: \$	<u>-</u>
Less Excess	: \$	<u>-</u>
Total	: \$	<u>3,896.00</u>
GST 7%	: \$	<u>272.72</u>
Grand Total	: \$	<u>4,168.72</u>
Finalise By/Date : <u>LARRY ON 16/08/18</u>		

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS

* TP vehicle no: SHD69406

* claim loss of RENTAL.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012141/T1sd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6940G	Veh. Inspected	SLX 3705L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005143MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ECLIPSE CROSS	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JMAXTGK1WJZ001066	Colour	BLACK	
Odometer	1833	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	YOKOHAMA	6 mm	
L/H Front Tyre	225/55 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/06/2018	Inspection Date	19/07/2018	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 3705L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REINFORCEMENT,RR BUMPER (SN)	BENT	489.00	489.00
1	BRKT,R/BMPR FACE SIDE,LH (SN)	NECESSARY	25.00	25.00
1	BRKT,R/BMPR FACE SIDE,RH (SN)	NECESSARY	25.00	25.00
1	FACE,RR BUMPER (SN)	DEFORMED	548.00	548.00
1	EXTENSION,RR BUMPER (SN)	DEFORMED	150.00	150.00
1	COVER,RR BUMPER,LH (SN)	CUT	116.00	116.00
1	COVER,RR BUMPER,RH (SN)	CUT	116.00	116.00
1	SENSOR,BACK DISTANCE WARN (SN)	NOT NECESSARY	326.00	-
1	SENSOR,BACK DISTANCE WARN (SN)	NOT NECESSARY	326.00	-
1	SENSOR,CORNER CLEARANCE LH (SN)	NOT NECESSARY	326.00	-
1	SENSOR,CORNER CLEARANCE RH (SN)	NOT NECESSARY	326.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	MUFFLER,EXHAUST MAIN (SN)(ADDITIONAL)	DENTED	591.00	591.00
1	BUZZER,KEYLESS OPERATIO,RR (SN)(ADDITIONAL)	CRACKED	90.00	90.00
1	LAMP ASSY,BACKUP,LH (SN)(ADDITIONAL)	CUT	116.00	116.00
			3,620.00	2,286.00
LABOUR				
	TO RENEW REAR BUMPER AND REPAIR END PANEL.		1,650.00	550.00
	TO TRANSFER REAR PARKING SENSOR TO NEW PART.		60.00	60.00
	PAINT WORK SPRAY REAR BUMPER AND END PANEL.		1,260.00	420.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	TO APPLY ANTI COROSSION.	NOT NECESSARY	60.00	-
	TO APPLY ZENTNA ON THE DAMAGE PART.		200.00	200.00
	RENEW EXHAUST REAR MUFFLER. (ADDITIONAL).		150.00	150.00
			3,630.00	1,610.00
GRAND TOTAL			7,250.00	3,896.00
RECOMMENDED COST OF REPAIRS				3,896.00

Report Ref No. CS/FC118012141/T1sd3n2



Report Ref No. CS/FCI18012141/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.