

1242/11 was - (w)

SDK 61884

Veh No: [Signature] Yr Regn: 2014 / Oct

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: BMW 218I C.C. 1499

Colour: white A/C: Insured / Std / Ni / NA

Sp. Reading T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WSA 2A 320206Z48971

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 50 R 17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 19/7/18

Survey held at pwt

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

☐: Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$

☐ Interview (\$

5) $S + RS \rightarrow SI$

Photos

TOTAL