

2/10/2018

ASS. REC. BY:

REF

CS/FCI18012145/Kqd3n2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

aws

From (Person):

Lurene Jaw

of

FCI

Date/Time:

4/7/18 @ 6:45pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.:

SLU 966K

Insured:

SHC 0837S

at Workshop n/s:

City Auto

Tel:

64531235

of

Blk 160, Sin Ming Drive # 05-01

Policy No.:

D-18088937MFSH

Claim No.:

D18005153MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/07/2018

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

9:23am @ 4/7/18

Person Contacted:

Vronica

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLU 966K -X

SHC 0837S - CS/MSG 17013273/K/rbk2

D.O.A: 6/7/2017

05/7/18 @ 11:43pm revised to wrong by email.

2018

L1 Imp @ 275d Ca form (Red @ 1026.10, 27%)

(08/11/23) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From:

Date: 04/07/2018

Veh No:

SLU 966K Yr Regn: 07 10

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /ON ☒ WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SLU 966K

Make:

Mr S300L c.c. 2997

at Workshop m/s

city auto

Colour

M. Gray

A/C: Insured / Std / NI / NA

of BIK 8, Sin Ming Ind. Est #01-60/62

Sp. Reading

171045

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

WDD 2211542A 317298

Policy No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Claims No.

Steering: ☒ In order / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

Brake: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

after 10:30am

Modi: Nil / S/Rim / STD A/Rim or

Make of Veh:

Tyre Size:

F:

R:

255/45R18

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

S 75K

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

1/7/18

D.O.I.

4/7/18

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S down mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/7 File pass to Customer

RECEIVED 7 11 AUG 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 20/8 14:54

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

7P

Lump Sum / I.B.I. (\$

2750

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

130

50

50

19

249



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005153MFSH

Date: 05 July 2018

Our Ref: CS/FCI18012145/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 966K

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/07/2018 at the premises of M/s CITY AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,776.10</u>
Revised Estimate Amount	: S\$ <u>2,475.00</u>
"Check" Items Amount	: S\$ <u>971.10</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the front o/s door mirror.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	03-07-2018	Our Ref No.	D18005153MFSH
Accident Date	01-07-2018	Claim Type.	Third Party
Insured Vehicle	SHC0837S	Third Party Vehicle.	SLU966K
Survey Location	BLK 160, SIN MING DRIVE, SIN MING AUTO CITY #05-01		
Contact Person.	VRONICA LAW		
Contact No.	64531235/ 0	Fax No.	64537944
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242005)



PRI Documents



Close



PRI Header Details

Claim No	D18005153MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CITY AUTO
Workshop Name	CITY AUTO PTE LTD (Contact Person : VRONICA LAW)	Survey Location & Contact Details	BLK 160, SIN MING DRIVE, SIN MING AUTO CITY #05-C Mobile: 0 , Phone: 64531235 , Fax: 64537944 EmailId: CITYAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0837S	TP Vehicle No	SLU966K
PRI Recieved Date	03-07-2018 06:24:47 PM	Surveyor Appointed Date	03-07-2018 06:44:16 PM	Surveyor Accept Date	04-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 5 July 2018 1:43 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005153MFSH/1
Attachments: CSFC18012145Kqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLU 966K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 4 July 2018 9:25 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005153MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 3 July 2018 6:45 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005153MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000030(00)

Date : 03/07/2018

Vehicle No : SLU966K

Make/Model : MERCEDES BENZ S300L

Mileage (km) : 0

Chassis No : WDD2211542A317298

Accident Date : 01/07/2018 00:00:00

Claim No : SHC837S

Reference : SLU966K

Policy No : S 28987588 SMF

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Attention: Chan Hiang H'ng

Contact : 96793628

Fax No. : 6507 3849

*Not Authorized
Resurvey by pain
1.3.1
1 day*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Side mirror motor - RH	1.0	717.00	717.00 <i>Ja</i>
2	Side mirror cover	1.0	362.00	362.00 <i>mgm</i>
3	Side mirror indicator lamp	1.0	112.00	112.00 <i>cat</i>
4	Side mirror glass	1.0	1,482.00	1,482.00 <i>cm</i>
5	Door glass - RH	1.0	856.00	856.00 <i>cu</i>
List Total :				3,529.00
10% Discount S\$				352.90
				3,176.10
LABOUR :				
	- Spray painting on affected & replace parts	1.0	350.00	350.00 <i>150</i>
	- To remove and re-install above parts	1.0	250.00	250.00 <i>120</i>
				600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

Total S\$: 3,776.10

GST 7% S\$: 264.33

Amount Due S\$: 4,040.43

MA

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012145/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 837S	Veh. Inspected	SLU 966K	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005153MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES S300L (A)	c.c	2997	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2211542A317298	Colour	METALLIC GREY	
Odometer	171045	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/45 R18	CONTINENTAL	8 mm	
L/H Front Tyre	255/45 R18	CONTINENTAL	8 mm	
R/H Rear Tyre	255/45 R18	CONTINENTAL	8 mm	
L/H Rear Tyre	255/45 R18	CONTINENTAL	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/07/2018	Inspection Date	04/07/2018	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 966K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE MIRROR MOTOR-RH	JAMMED	717.00	717.00
1	SIDE MIRROR COVER	MTG CRACKED	362.00	362.00
1	SIDE MIRROR INDICATOR LAMP	CRACKED	112.00	112.00
1	SIDE MIRROR GLASS	CRACKED	1,482.00	1,482.00
1	DOOR GLASS-RH	CUT	856.00	856.00
	LESS 10% DISCOUNT		-352.90	-352.90
			3,176.10	3,176.10
	LABOUR			
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		350.00	150.00
	TO REMOVE AND RE-INSTALL ABOVE PARTS.		250.00	120.00
			600.00	270.00
	GRAND TOTAL		3,776.10	3,446.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,750.00

Report Ref No. CS/FCI18012145/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.