

15/9/2019

INS. CASE OWNER:

Kitty.
Lepetua.CCU ASM
QBE1801

2158, 1/1/18

LKK:

IDAC:

Surveyor:

MARCUS

DOE:

ASSIGNMENT

10/07/18

Date / Time:

4/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLU 6076J

Name of Insured:

HO TET

Insured Tel No.:

HP:

907947

Excess Sec II :\$

D.O.A:

1/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8moomyl 5890

Policy No.:

VPA/D2040014

Make / Model:

MUMDAR

Place of Accident:

TRAFFIC JUNCTION SIMS WAY
& Geylang Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SLE 3987A

INSRS:
WSP:
Tel:
Liability:
RMKS:Kah
motorINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

Date/ Time	STAGE	DATE / PIC
5/7/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
05/07/18	Documentation Check List: Handler	Typist
06/07/18	Notification ltr (if non-pickup)	
06/07/18	After call ltr to OI:	
06/07/18	Authorisation To Act:	
06/07/18	Release Voucher:	
06/07/18	Final Repair Bill:	
06/07/18	Car Rental Invoice:	
06/07/18	Towing Invoice:	
06/07/18	LTA / GIA:	
06/07/18	Medical Bill:	
06/07/18	PIR:	
06/07/18	Mandate/Reject Instruction:	
06/07/18	LOD	
06/07/18	Payment Breakdown Form:	
06/07/18	Post-Repair Photos:	
06/07/18	Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	% 50	(Agreed / Assessed) BOLA S/N No.:	19.
Repair Cost:	\$		
Loss of Rental (LOR):	\$	(days)	
Loss of Use (LOU):	\$	(\$ x days)	
Loss of Income (LOI):	\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐		(Tick only one)	
GIA/LTA Search	\$		
Medical:	\$		
Disbursement:	\$	(e.g. Tow/ Independent)	
Legal Cost	\$		
Total:	\$	Global Sum \$:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$	Name 1:	
Payee 2: (Strike if N.A.)	\$	Name 2:	
Payee 3: (Strike if N.A.)	\$	Name 3:	

REF: ASM(AXA)

ASSIGNMENT

From Date 18072018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SLE 3983A
at Workshop m/s Kuh Motor

of 15ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Wew

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 01151

IDAC Accident Report: Consistent? : Yes or No

BIA / PR Seen: 4 Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No. SLE 3983A Yr Regn 7 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda Odyssey C.C. 2356

Colour: maroon A/C Insured / Std / NI / NA

Sp. Reading 04675-3 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMR C18806C 205072

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17
R:BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front 6 mm Rear 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/7/18 D.O.I. 18/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Lf.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SLE 3983A

PIP \$2710.02 (Red = \$3865.71 / 59%)
? Item \$3085.71

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + PS \$

) Pkcs

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) Add Fee:

☐ Site Insp. (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012158/hb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 04-07-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 6026J	Veh. Inspected	SLE 3983A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/07/2018	Inspection Date		
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

18/7/18
@
1600pm
Survey

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLE3983A
Chassis No : JHMRC1880GC205072
Model : ODYSSEY 2.4 EX-S 16YM
Owner's Name : YAP KOK BOON
Ins Policy No. :
Date of Accident : 1/7/2018

Document No. : SQT18002715
Date : 3. Jul 2018
Customer No. : WZA006
Svc Advisor : LIEW THYE WEI
Engine No : K24W72012260
Date | Time : 3. Jul 2018 9:53:38 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: YAP KOK BOON						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 01/07/18						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SLU6026J						
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT	1	180.00		180.00	12.60	192.60
	Sum Ext. Service				180.00	12.60	192.60
60260-T6A-300ZZ	FENDER COMPL.FR.	1	537.80	25	403.35	28.23	431.58
74150-T6A-000	FENDER ASSYL.FR INNER	1	118.30	25	88.72	6.21	94.93
91512-SX0-003	CLIPINNER FENDER	5	3.50	25	13.12	0.92	14.04
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
04711-T6A-000ZZ	FACE.FR.BUMPER	1	677.60	25	508.20	35.57	543.77
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71109-T6A-003	GARNISHL.FR.BUMPER	1	40.90	25	30.67	2.15	32.82
33150-T6A-Q01	HEADLIGHT ASSY,L.	1	886.20	25	664.65	46.53	711.18
42700-T6A-Q81	DISKALUMINIUM WHEEL 17X7J	1	897.00	25	672.75	47.09	719.84
44300-T6A-J51	BEARING ASSYFR.HUB	1	135.50	25	101.62	7.11	108.73
51215-T6A-000	KNUCKLE COMPL.FR.	1	292.60	25	219.45	15.36	234.81
51360-T6A-N00	LOWER ARM ASSY,L.FR.	1	623.80	25	467.85	32.75	500.60
	Sum Item				3225.73	225.80	3451.53
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00		80.00	5.60	85.60
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)	1	840.00		840.00	58.80	898.80

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLE3983A
Chassis No : JHMRC1880GC205072
Model : ODYSSEY 2.4 EX-S 16YM
Owner's Name : YAP KOK BOON
Ins Policy No. :
Date of Accident : 1/7/2018

Document No. : SQT18002715
Date : 3. Jul 2018
Customer No. : WZA006
Svc Advisor : LIEW THYE WEI
Engine No : K24W72012260
Date | Time : 3. Jul 2018 9:53:38 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKFE11R	REMOVE & RENEW FR L FENDER & FRONT BUMPER.	1	1120.00	560	1120.00	78.40	1198.40
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1100.00	900	1100.00	77.00	1177.00
Sum Labor					3170.00	221.90	3,391.90

Survey By

Date & Time

Excess

Status

Signature

Total Amount 6,575.73 460.30 7,036.03

Total (Inclusive of GST) 7,036.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 3/7/2018 11:26:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0619J
Vehicle Details	
Vehicle No.:	SLE3983A
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-S CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	K24W72012260
Chassis No.:	JHMRC1880GC205072
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$28,006.00
Original Registration Date:	20 Jul 2016
First Registration Date:	20 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$31,209.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jul 2026
PARF Rebate Amount:	\$23,406.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$40,808.00
Total Rebate Amount:	\$64,214.00

The information contained herein is correct as at 19 Jul 2018

OK



**WIDE RANGE OF PRE-OWNED
TOYOTA AND OTHER MAKES
AVAILABLE**

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRES

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years COE Renewal Honda Stream 1.8A.



\$2500 Down Payment Monthly
From \$688 Onwards.Lowest
3.68%P.A@GV Cars Fin
GV Credit Pte Ltd StarAd

ABWIN



Browse by Category ▼

« Back (1 2) Next »

Sort b

35 vehicles

Honda Odyssey

Advant

Make Model Price Depreciation Reg Date Eng Cap Mil

Search Selection

Honda Odyssey

Any

Any

2016

Any



Honda Odyssey 2.4A EXV-S

\$125,800

\$13,180 /yr

08-Sep-2016

2,356 cc

41

1 Car Lover Owner, Vehicle Parked Under Shelter Most Of The Time, Full Agent Maintained By Kah Motor, Agent Warrant Spacious Interior And Flawless Leather, High Loan And High...

Posted: 18-Jul-2018

Tags: 2016 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A EXV-S

\$130,800

\$13,240 /yr

21-Dec-2016

2,356 cc

16

Kah Motor Unit With Full Servicing Record. 5 Years Warranty And 3 Years Free Kah Motors Servicing Included. New Car (Mileage, Non-smoker Driver, 100% Accident Free. Just Comple...

Autotruster Traders Pte Ltd

Posted: 17-Jul-2018

Tags: 2016 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A EX-S

\$116,800

\$12,030 /yr

07-Dec-2016

2,356 cc

15

Single Owner, Very Well Maintained And Still Under Warranty! Owner Selling Due To Relocation. Popular Luxury MPV To Travel In Comfort! Bank Loans And Trade In Available, Call ...

Mayfair Motoring

Posted: 16-Jul-2018

Tags: 2016 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda



Honda Odyssey 2.4A EXV-S

\$125,800

\$12,980 /yr

18-Oct-2016

2,356 cc

20

Accredited Company! Super Low Mileage At Only 20K Km. Fully Serviced By KAH Motor With Records And 5 Years Warra Beautiful Paintwork With Spick And Span Interior. Ceramic C...

Fu Yiap Motor Trading

Posted: 16-Jul-2018

Tags: 2016 Honda Odyssey, Honda Odyssey, Honda, Odyssey, Used Honda

Car Buying

Car Selling

Car Ownership

Compare

On The Move

Lifestyle



Service Request Details

Claim

S8M00MYL

Reference

None 

Loss Date

July 1, 2018

Request Date

July 3, 2018

Due Date

July 10, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Bot 2018 @ 3:31 pm
Mr. Liew veh not in.
email liability

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLE3983A

Make

TPVD HONDA

Model

RED

Service Address

...

Primary Contact/Insured

HO TET

BLK 972 HOUGANG STREET 91, #12-194, 530972, Singapore

90229297

matthewht195@gmail.com

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

 RE: Re:RE: PROCEED DS

Type

 Question

Message

Hi, TP repairer inform that their client convert OD claim. We will proceed to submit WP report and close the case as survey has been done. Thanks - CCL 25/03/2020

[Reply](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012158/Uga3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KITTY TEO		Date : 30-03-2020 Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 6026J	Veh. Inspected	SLE 3983A	
Policy No.	VPA/P2040014	Coverage (\$)	0.00	
Claim No.	S8M00MYL	Excess (\$)	0.00	
Assign From	KITTY TEO	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY (A)	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHMRC1880GC205072	Colour	MAROON	
Odometer	046753	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	DUNLOP	6 mm	
L/H Front Tyre	215/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/07/2018	Inspection Date	18/07/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 3983A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER COMPL.FR. (SN) (CONSISTENT)	BENT	403.35	403.35
1	FENDER ASSYL.FR INNER. (SN) (CONSISTENT)	* CHECK	88.72	-
5	CLIPINNER FENDER (SN) (CONSISTENT)	NECESSARY	13.12	13.12
14	CLIPBUMPER (SN) (CONSISTENT)	NECESSARY	21.00	21.00
1	FACE, FR.BUMPER (SN) (CONSISTENT)	DISTORTED	508.20	508.20
1	SPACERL.FR.BUMPER SIDE (SN) (CONSISTENT)	BENT	8.70	8.70
1	BEAM.FR.BUMPER UPPER (SN) (CONSISTENT)	BENT	25.65	25.65
1	GARNISH.FR.BUMPER (SN) (CONSISTENT)	* CHECK	30.67	-
1	HEADLIGHT ASSY,L. (SN) (CONSISTENT)	* CHECK	664.65	-
1	DISKALUMINIUM WHEEL 17X7J (SN) (CONSISTENT)	* CHECK	672.75	-
1	BEARING ASSYFR.HUB (SN) (CONSISTENT)	* CHECK	101.62	-
1	KNUCKLE COMPL.FR. (SN) (CONSISTENT)	* CHECK	219.45	-
1	LOWER ARM ASSY,L.FR. (SN) (CONSISTENT)	* CHECK	467.85	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	30.00	10.00
			3,255.73	990.02
LABOUR				
	INSPECT FR LIGHTING MECHANISM & FOCUS.		80.00	80.00
	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.	* CHECK	840.00	-
	REMOVE & RENEW FR L FENDER & FRONT BUMPER.		1,120.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,100.00	900.00
	WHEEL ALIGNMENT.		180.00	180.00
			3,320.00	1,720.00
GRAND TOTAL			6,575.73	2,710.02
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3,085.71 NETT)				2,710.02

Report Ref No. CC4/ASM18012158/Uga3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.