

INS. CASE OWNER:

DOWYN

CC 3, CT1 180

12/72, Nha 3n2

LKK:

IDAC:

Vic

## ASSIGNMENT

NA 2

FOI:

2/7/18

Date / Time:

7/2/18

Registered in Merimen:

Pre-assign / CCU / FTE

GBD 5660S



Insured Vehicle No.:

Name of Insured:

CHIEF LOON Renovation Contractor

Claim No.:

SNM1600328802

Policy No.:

PMERSN308379002

Insured Tel No.:

HP:

Make / Model:

FIAT DOBLO

Excess Sec II :SS

D.O.A: 29/6/18

Place of Accident:

PE (TNGS)

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

My Puan Guan

Driver Tel No.:

9185-8344

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

PC 54476

GBD 5660S

SHA 3862J



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

6/7

SHA3862J. NO. 1 MIXED 1583/Y. PRA. 6/9/15

GBD5660S. NA(TH)12007124. PRA. 29/1/18

PINKUERO.

12/07/18 @ 2PM

SPONSOR TO OIL. HE CONFIRMED ACCEPTANCE  
DETAILS & WAS INVOLVED IN A 3 VEH. C.O.  
IN THE 2ND CAT. INFORMED TP  
CLAIM, AGREED TO OFFER & WERE NOT  
LEADS. SEND LETTER TO OI.

ORIGINAL TP LOG IN.

BELOW FOR MANDATE

RECEIVED 10 AUG 2018

07/08/18

NO FORDSTAR FROM OI. SEND 1ST  
OFFER TO TP.

10/08/18

ORIG. IN IN. TP RECEIVED OFFER.  
Let POS IN OFFER.  
TO CLOSE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

6/7

Sent By:

[Signature]

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L16

SS

760.00

( 2 days)

Reduction:

10

%

Email

Call

FINAL SETTLEMENT

Date/Time:

07/08/18

Confirm with:

WILLIAM

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

20

Repair Cost:

(W160)

SS

802.60

Loss of Rental (LOR):

SS

47.45

( 3.5 days)

X 4119.28

Loss of Use (LOU):

SS

75.00

(\$ 50 x 3.5 days)

Loss of Income (LOI):

SS

—

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7.19

Medical:

SS

—

Disbursement:

SS

—

Legal Cost

SS

—

(e.g. Tow/Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 400.00

Total:

SS

1,402.47

Global Sum SS:

1,400.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1,400.00

Name 1:

COMFORTPOLERO ENGINEERING PTB LTD

Payee 2: (Strike if N.A.)

SS

—

Name 2:

—

Payee 3: (Strike if N.A.)

SS

—

Name 3:

—



## Mei Kwan (LKKAUTO)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Thursday, 5 July, 2018 2:16 PM  
**To:** Mei Kwan (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving GBD5660S (OI : CTI - SNM18D03288C02) and SHA3862J (TP : LKK REF - CC3/CTI18012172/Nha3) on 29/06/2018  
**Attachments:** leeSZ\_SNM18D03288C01-GBD5660S-LKKDirectSettlementAccidentLtr\_CLCR95.848.pdf; MNA118085363-GBD5660S.pdf  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Jowyn Tay

Lucas Lee  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6181  
Fax (65) 6222 7175/6224 7478  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



**Disclaimer :**

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Wednesday, 4 July, 2018 6:47 PM  
**To:** Claims Dept of CTI  
**Cc:** Jowyn Tay; Angie Foo; Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving GBD5660S (OI : CTI - TBA) and SHA3862J (TP : LKK REF - CC3/CTI18012172/Nha3) on 29/06/2018

**WITHOUT PREJUDICE**



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Tel: 6389 6111 Fax: 6222 1033  
Website: www.sg.chinataiping.com  
Co. Reg. No. 200208384E

Our Reference: **SNM18D03288/C01/0**

Date : **05 JULY 2018**

via Ordinary & Registered Mail

**CHIET LOON RENOVATION CONTRACTOR  
61 ALMOND CRESCENT**

**SINGAPORE 677815**

Dear Sir / Madam

**ACCIDENT INVOLVING GBD5660S AND SHA3862J ON 29 JUNE 2018  
ALONG PIE TUAS AFTER KPE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHA3862J**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,  
Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd

Attn : VIC  
Ref : CC3/CTI18012172/NHA3  
Contact No : 68412096  
via Email : VIC@LKKAUTO.COM

CC : Agent - (AN0101A) - I TRUST PTE LTD

F01/LKKDS-2013

# COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road, Singapore 579701  
 Mobile: + 65 8383 8280, Fax: + 65 8380 9735

### Workshops

59 Lorong Drive, Singapore 536965  
 383 Sin Ming Drive, Singapore 575717  
 45 Pandan Road, Singapore 609288  
 320 Upper Road, Singapore 309499

24 Serangoon Loop, Singapore 156156  
 7 Sungei Kadut Way, Singapore 728791  
 8 Geylang Road, Singapore 399537

Date/Time: 30.06.2018 11:38 Page : 1

Team: ARC Repair TP(CLSO)1

### JOB CARD

Sales Order:

JC NO.: 305181694

OWNER

AS COMFORT TRANSPORTATION PTE LTD  
 7010045  
 OWNER NO. 383 SIN MING DRIVE  
 ADDRESS Singapore SINGAPORE 575717  
 65508755 (R) (O)  
 (P)

OUNT CARD NO.

|              |                   |                      |
|--------------|-------------------|----------------------|
| REGN NO:     | SHA3862J          | MILEAGE              |
| MAKE:        | HYUNDAI           | FUEL                 |
| MODEL        | I-40              | E.....1/2.....F      |
| YR OF MANU.  | 30.12.2014        | DATE/TIME IN         |
| CHASSIS CODE | KMHLB41UMEU061502 | 30.06.2018 08:55     |
|              |                   | TARGET DATE          |
|              |                   | COMPLETION DATE/TIME |

### JOB DESCRIPTION

Accident Date: 29.06.2018  
 NATURE: 3P 29.06.18

S/NO LABOR CODE DESCRIPTION

RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Recognition Slip

Exit Pass

No.: SHA3862J LIMITS

Vehicle No.: SHA3862J

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection.

To be kept by Security Guard

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHA 3862J

MAKE :

MODEL : HYUNDAI i40

China Taiping  
CP(P)

DATE 6/30/2018

(Sat)

LKK -

| Qty | Parts Description/ Labour   | Type | Unit Price | Amount           |
|-----|-----------------------------|------|------------|------------------|
|     | <b>Labour Charge</b>        |      |            |                  |
|     | Panel Beating               |      |            | \$ 350.00        |
|     | Spray Painting Charge       |      |            | \$ 250.00        |
|     | Wiring Charge               |      |            | \$ 30.00         |
|     | Remove/Refix Reverse Sensor |      |            | \$ 120.00        |
|     | <b>+ SUPP PARTS</b>         |      |            |                  |
|     | <b>TOTAL LABOUR</b>         |      |            | <b>\$ 750.00</b> |
|     | <b>ESTIMATE TOTAL</b>       |      |            | <b>\$ 750.00</b> |
|     |                             |      |            | <b>1,250.48</b>  |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

|         |           |               |          |
|---------|-----------|---------------|----------|
| VEHICLE | SHA3862J  | TYPE OF CLAIM | TP       |
| MODEL   | I-40      | SURVEY BY     | LKK-NAZ  |
| JOB NO  | 305181694 | DATE          | 03/07/18 |

[illegible]

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305181694

Date : 04/07/18

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHA3862J

Date of Accident : 29-Jun-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBD5660S

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$750.00

**Final Lumpsum Repair cost \$750.00**

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : NAZ

Date : 12/7/18

## For Official Use Only

| Item                                                 | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        | NO                          |                        |         |
| 3. Survey Fees                                       | -----  |                             |                        |         |
| 4. LTA Search Fee                                    | \$7.49 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun                                           |        |                             |                        |         |

Remarks:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                          |                              |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|------------------------------|-------------------------------------------------------------------------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                          | Ref : CC3/CTI18012172/Nha3n2 |                                                                                     |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909                                                                                 |                                                                          | Date : 13-08-2018            |  |
|                                                                                                                                           |                                                                          | Code : CTI                   |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                          |                              |                                                                                     |
| Insured Veh.                                                                                                                              | GBD 5660S                                                                | Veh. Inspected               | SHA 3862J                                                                           |
| Policy No.                                                                                                                                | DMCVSN3085191702                                                         | Coverage (\$)                | 0.00                                                                                |
| Claim No.                                                                                                                                 | SNM18D03288/C01/0                                                        | Excess (\$)                  | 0.00                                                                                |
| Assign From                                                                                                                               |                                                                          | Assign Date                  | 02/07/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                          |                              |                                                                                     |
| Make & Model                                                                                                                              | HYUNDAI I40                                                              | c.c                          | 1685                                                                                |
| Engine No.                                                                                                                                | HIDDEN                                                                   | Year of Reg.                 | 2014                                                                                |
| Chassis No.                                                                                                                               | KMHLB41UMEU061502                                                        | Colour                       | BLUE                                                                                |
| Odometer                                                                                                                                  | 488076                                                                   | Steering                     | IN ORDER                                                                            |
| Brakes                                                                                                                                    | IN ORDER                                                                 | Modification                 | STANDARD ALLOY RIM                                                                  |
| General                                                                                                                                   | GOOD                                                                     |                              |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                          |                              |                                                                                     |
|                                                                                                                                           | Size                                                                     | Make                         | Balance                                                                             |
| R/H Front Tyre                                                                                                                            | 205/60 R16                                                               | HANKOOK                      | 5 mm                                                                                |
| L/H Front Tyre                                                                                                                            | 205/60 R16                                                               | HANKOOK                      | 5 mm                                                                                |
| R/H Rear Tyre                                                                                                                             | 205/60 R16                                                               | HANKOOK                      | 5 mm                                                                                |
| L/H Rear Tyre                                                                                                                             | 205/60 R16                                                               | HANKOOK                      | 5 mm                                                                                |
| <b>4. Description of Damages</b>                                                                                                          |                                                                          |                              |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS.                                                            |                                                                          |                              |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                          |                              |                                                                                     |
| Accident Date                                                                                                                             | 29/06/2018                                                               | Inspection Date              | 02/07/2018                                                                          |
| Survey held at                                                                                                                            | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                              |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                          |                              |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                              |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                        |                                                                          |                              |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                       |                                                                          | 2 Working Days               |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3862J

| Qty | Description of Parts                                                        | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                                                 |           |                           |                   |
| 1   | REAR BUMPER (ADDITIONAL)                                                    | DENTED    | 603.60                    | 603.60            |
| 10  | REAR BUMPER CLIPS @\$2.20 (ADDITIONAL)                                      | NECESSARY | 22.00                     | 22.00             |
|     | LESS 20% DISCOUNT                                                           |           | -125.12                   | -125.12           |
|     |                                                                             |           | 500.48                    | 500.48            |
|     | <b>LABOUR</b>                                                               |           |                           |                   |
|     | PANEL BEATING .                                                             |           | 350.00                    | 200.00            |
|     | SPRAY PAINTING CHARGE.                                                      |           | 250.00                    | 200.00            |
|     | WIRING CHARGE.                                                              |           | 30.00                     | 20.00             |
|     | REMOVE/REFIX REVERSE SENSOPR .                                              |           | 120.00                    | 20.00             |
|     |                                                                             |           | 750.00                    | 440.00            |
|     | <b>GRAND TOTAL</b>                                                          |           | <b>1,250.48</b>           | <b>940.48</b>     |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |           |                           | <b>750.00</b>     |

Report Ref No. CC3/CT118012172/Nha3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.