

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. SHC 86225 Page. 17/03/2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make. HYUNDAI 140 1685
 Colour BLUE AC Insured / Std / NI / NA
 Sp. Reading 307,521 (not start) Insured / Std / NI / NA

Eng. No:

C. No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAK

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 27/6/18 D.O.I. 27/18

Survey held at EDGE LOYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AGT PTP

Date/Time File Pass to:

☐ : Preli. Report

☐ : Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

_____ - _____

Photos

Notes

Add Fee: ☐ : Site Insp : \$

☐ : Inter. Insp : \$

☐ : Tech. Insp : \$

☐ : Measure : \$

Report Format :

Lump Sum / I.B.B. : \$



Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3835497

JC NO.: 305181045

TOMER

MS

TOMER NO

RESS

(R)

(P)

OUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD

7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

REGN NO:

SHC8622S

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

27.06.2018 19:15

YR OF MANU

17.03.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU085744

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 27.06.2018

NATURE: 3P 27.06.18/B

S/NO

LABOR CODE

DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SHC8622S

FZ NTUC LKK

Vehicle No.:

SHC8622S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard