ASS. REC. B	7	REF C FC118	8012179/A	cd302	d festivation:
CMZ		ASSIG	NMENT (Office)	
From (Perso	Screne Ler	of	FCI	Da	ete/Time 4/7/18 3 4:17p
ESSENTIAL CEC	OSC:		Bill to:		
To Inspect V	VS/TP RES/OD RI /chicle No:	SLCgo	147	Insured:	SH 7929H
at Workshop	m/s	SK Auton	nobile	Tel:	6789 5155
-	23 Kaki B	ukit Ave -	1 # 03-01		
Policy No:_		•	Claim No:	D1800	5192MFSH
Sum Insured			Excess:		, , , , , , , , , , , , , , , , , , , ,
Make of Vel (Client's Recor					0.A 19/06/2018
CA / REV	/ REP. / REV 24 H	rrs (wp)			5/07/2018
Date/Time:	4.22pm @ 4/7/18	Person Contact	ed Huey		H.O.D. Endorsement:
Date/Time	Action/Instruction	() Estim	ate		
	SLC994		u net		
			8000954	Nubni) [] [] [] [] [] [] [] [] [] [
		10/11/01	0003937	Z NIVOII-	DOA: 12/02/2018

	ASSIGNMENT
From: Date: 5 7 20	Veh No: SLC994Z Yr Regn: 2007 , No
Estimated Cost:	Type: M.Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLC 994Z	Make: Harda Civic c.c 1998
	Colour White A/C: Insured / Std / NI / NA
at Workshop m/s SK Automobile	
of 23 kaki bulcit Ave 4 # 03-01	
Insured:	Eng/No: THMF0254075201571
Policy No.	0/10.
Claims No.	Gen. Cond: Good/Fair/Poor/Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim) / STD A/Rim or
	Tyre Size: F: 275/45/217.
(Policy Condition)	R: 225/+5R17.
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Continental.
Bal. or Market Value:	Front OG Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. mm R/Bal. mr
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mr
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. QS/07/18
Lum Sum: % 3 Val.: Yes or No	Survey held at S-K
CA / REV / REP. / 24 HRS (4)	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle:	10.000000000000000000000000000000000000
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	WE Expiry : 06/11/22 -
	all marine (10 A to account TT 2)
10/12 Adrian confirmed 15 & 2900-	with repairer. (Red. 10, see, 48, 772)
MV 30V - MV. 30,000	RECEIVED 1 1 DEC 2018.
PV 217K LTB:21,753	KEUEIVLU
Net: 8.51C Net: 8,247	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee: 170+45
Date/Time, File Return to?	Transportation: 50
2)	dd Fee: : Site Insp (\$) _s+Rssi 50
	: Interview (\$) Photos 21
Report Format: TP	: Tech. Invs (\$) Others
Lump &um / I.B.I: (\$ 2900)	: Weekend (\$
(3 100)	21
	TOTAL



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. MZ-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

03-07-2018

Our Ref No. D18005192MFSH

Accident Date

19-06-2018

Claim Type. Third Party

Insured Vehicle

SH7929H

Third Party Vehicle. SLC994Z

Survey Location

23 KAKI BUKIT AVE 4 #03-01 VICOM INSPECTION CENTRE(SOUTH WING)

Contact Person.

XIONG

Contact No.

67895155/81210478

Fax No. 67835155

Survey Type

WITHOUT PREJUDICE: NO EST. PROVIDED

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

SK AUTOMOBILE PTE

Attention. NIL

Cc: TP Solicitor

LTD NA

TP Solicitor Fax No. NA

Officer Incharge

SERENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

· ·					
Job Sheet (/	ClaimWS/Surveyor/JobSheet,	/242052) 🚣 P	RI Documents (2) Close		
			PRI Header Details		
Claim No	D18005192MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & SK AUTOI
Workshop Name	SK AUTOMOBILE PTE LTD (Contact Person : XIONG)	Survey Location & Contact Details	23 KAKI BUKIT AVE 4 #03 Mobile: 81210478 , Phon EmailId: ADMIN@SKAUTO	e: 67895155	SPECTION CENT Fax: 6783515
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO	EST. PROVIDE	ED .
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7929H	TP Vehicle No	SLC994Z
PRI Recieved Date	03-07-2018 10:48:59 PM	Surveyor Appointed Date	04-07-2018 04:16:20 PM	Surveyor Accept Date	
		2	Survey Report Upload		
Surveyor Inspection Date *:	mE6	Surveyor Report Date	04-07-2018	Upload Survey Report *:	Choose File
			Vehicle Particulars	1	
Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year *
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple Do	cuments Upload				
File Name		Upload Multiple	Documents	Action	
Surveyor Jo	b Remarks				
Remarks				Save	

3 Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Singapore NRIC	100
Owner ID:	0018E	
Vehicle Details		CITAL CO.
Vehicle No.:	SLC994Z	
Vehicle to be Exported:	Yes	
Intended De-registration Date:	05 Jul 2018	
Vehicle Make:	HONDA	
Vehicle Model:	CIVIC 2.0L M	
Primary Colour:	White	
Manufacturing Year:	2007	
Engine No.:	K20Z22501571	
Chassis No.:	JHMFD25407S201571	
Maximum Power Output:	114.0 kW (152 bhp)	
Open Market Value:	\$19,922.00	
Original Registration Date:	07 Nov 2007	_
First Registration Date:	07 Nov 2007	
Transfer Count:	4	
Actual ARF Paid:	\$21,915.00	
Intended PARF Rebate Details	\$21,715.00	
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:		
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details		No. Ed
COE Expiry Date:	06 Nov 2022	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	5	
PQP Paid:	\$25,084.00	
COE Rebate Amount:	\$21,753.00	
Total Rebate Amount:	\$21,753.00	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Jul 2018

Compare [3]



Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW, There are plinity of cars for sale, from vans, trucks, section cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carperk rates & car insurance. Find buy used honda civic, honda civic, singapore, used honda civic, used vehicles Singapore or even buy used honda civic singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com












About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.



Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 03/07/2018 12:12

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2, This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies,
- 5. Any false reporting may be referred to the Police for investigation,
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fea, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT				
Date Of Report	03/07/2018 11:59		9)		
Date Of Accident	19/06/2018 08:00				
Exact Locallon Of Accident	232 YISHUN ST 21				
Country/State of Loss	SINGAPORE				
	DETAILS OF OWN VEHICLE	o day			
Vehicle Registration Number	SLC994Z				
Insured/Policyholder		¥1 21	ĕ	N 0. 3	
Name Of Registered Owner	TEE HUI PING				
NRIC No	S8610018E				
Email Address	NOEMAIL				

Mobile Phone No (LOCAL) +65-85005617

Alternative Phone No OTHERS-85005617

Vehicle Particulars

Manufacturer HONDA

Model CIVIC-2.0 (M)

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA311412/1

Cover Note Number

Driver

 Name of Driver
 TEE QIAN JIANG

 NRIC No
 \$9221903H

 Date Of Birth
 21/06/1992

Occupation INDOOR
Date Of Driving Pass 16/06/2012

Driving Experience 6 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-85005617

Fax Number

Contact Number

EMail Address NOEMAIL

Address

748 YISHUN STREET 72 #03-222 SPORE 760748

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SIBLING

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

Vehicle

enicie

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?
Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Statlon

Police Station Name

Police Station Address

YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE

ROAD: 31 YISHUN CENTRAL, POSTCODE: 768827, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-8529999 - FAX NO: 68522299

Was notice of Intended Prosecution given?

is notice of interiode (resources)

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SH7929H

Vehicle Make/Model/Colour

HYUNDAI 140 1.7 CRDI F/L AT ABS AIRBAG 4DR

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

29. Jun. 2018 19:05

No. 0909 P. 2

SKETCHPLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process,
- 2. This form must be complated by the Policyholder and/or the Authorlied Driver.
- a. Information provided inust he as truthful and accurate as possible. Any willul interpresentation of willyholding of material facts may allow insurance companies to repudiate nelley liebility.
- A. The Issue and acceptance of this Form by insurence companies is not an admission of policy flability on the part of the insurance companies.
- 5. Any falso renorthing may be releared to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centra established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ledgment of this report to the insurers, you hereby consent to the eighlying of this report of the centre and to copies of the report being made available ploresaid.
- 8. Consent under the Personal Date Protection Ast (PDPA)

Lunderstand, acknowledge, ogree and consont that

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information and out in this ((grm) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) throughout in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured to as the "insurers"), the insurers lawyers/law (Irrus, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of s
 - (i) processing, handling and/or dealing with my claims including the settlement of the cisims and any necessary investigations relating to the cisims;
 - (II) Investigating the accident and/or my claims;
 - (III) corrying out and/or dooting with my instructions or responding to any enquiries by me;
 - ((v) administering my claims (including the mailing of correspondence, statements, invokes, reports or notices to me, which could involve disdosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law (trins, may/ere permitted to collect, use, disclose and/or process my Personal information for one or inote of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurars and/or GIA to their third party service providers of agentalincluding their lawyers/law imms), which may be slied outside of Singapore, for one or more of the above Purposes.
- (d) my Personal infortaction will also be collected and used to compile claims history for the purpose of fraud detection, investigation and inanagement in present and all future claims.
- (e) the information so callected under (d) shove may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist to evaluating knostleating controlling or managing fraud, regulators, low enforcement and government agencies as reasonably required for the purposes states, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signaturo

Dilver's Signature

(If driver is not the policyholder)

Date & Tinier

Reporting Confre Personnel's Signature


Name: Safair

NRICFIN NO. SPUYUUD 24

Sketch Plan #2

29. Jun. 2018 19:05

No. 0909 P. 3



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	Refor	Yoke Report	T /20180619	2057	
		, ,			
		No.			
	1 1 1				
					•
-			~~		-
	N-KIC				
			the state of the s		
	. (6)	······································			
					_
					_
-					-
					_
	1 10				
	0, 0		N 101		
		405		2 2	
					

INVe declare the foregoing particulars are true in every respect,

Policyholder's Signature Date & Time:

Dilver's Signature

(if driver is not the pokcyliolder)

Dalo & Tima:

Reporting Centre Personnel's Signature Name: State . Mr.

NAICHHNO: 57- FUTTIN

MILALIF TLANSPORTER OF

Police Report

2. Jul. 2018 11:28

TUNGLOK HO

No. 3560 P. 1



SINGAPORE POLICE FORCE



Police Station Of Origin: Yishun North N.P.C 31-Yishun Gentral-SINGAPURE-700827 Tel No: 1800-8528989

Report No. T/20180010/2057 7 344 ------

REPORT	DF A TRAFFI	VCCIPENA		
	no Roport N 218 12:21	fade:	Vide Report No.:	Station Diary No.:
in al.				
Name o	I Informent		Address:	ET 72 #03-222 SINGAPORE
	/ (D No.) 0 / 892219	D9H	Contact No.: Home/Office:	Mobile: 65005617
National SINGAL	IIV: ORE CITIZ	EN	Empli:	
Sex; Malo	Age:	Date of Birth: 21/08/1902	Type of informant: Vehicle Owner	
Race: Chinese			Language: English	Institution / School Name;
Occupat NAVY R	lon: ÈGULAR C	FFICER	Driving Licence Information: Class: 28,2A,2,3,4,5	Date of Explry:

Type of Accident:	Non-Injury Hit and Run	Drink Drive; No	Date/Time of Accident: 18/09/2018 08:00	Type of Location Cer Perk
Localion: Nong Road 1 YISHUN STR Block 232 Yis Wealher Raining	EET 21	rk Y-15, parked at lot r Road Surface: Wet	umber; 204A)	oad Speed Limit:
Traffic Flow: Two Way		Traffic Control:	Tr	affic Volume:
Typo of Collis I III & Run	lon:			yone conveyed by ibulance:

3. 3	A Contract of the Contract of	Charles The	14400		The State No.	
8LC9942	Çar	HONDA	CIVIC 2, OL	While	Slightly	0

Police Report





Police Station Of Origin: Yishun North N.P.C 31 Yishun Contral SINGAPORE 768827 Tel No: 1000-8529999 2 of 9 Rapad No. T/20189019/2067

CONTINUATION OF REPORT

Brief Details.

On the 19 June 2010 at 2.30am, I parked my family vehicle registration number: SLC994Z at the corpork (Y-16) at fillock 232 Yishun Stroot 21 at carpork tot number: 204A., All was in order before I left for home. On the 19 June 2018 at about 0.00am, when I returned back to the vehicle, I discovered the front right lower bumper was damage and there was some scratch marks at the same damage area which had blue coloured paints marks on it.

Upon checking the in-car camers, it showed a blue coloured vehicle (blue coloured comfort text

Upon checking the in-car camera, it showed a blue coloured vehicle (blue coloured comfort text vehicle) had reversed and the rear right of this vehicle had collided on the front right lower bumper of my family vehicle. I would like to state the in-car camera image is not very clear and the registration number of the said comfort vehicle cannot be seen clearly.

of the said comfed vehicle cannot be seen clearly.

I have made a check with Housing Development Board carpark department to assist me to check the gantry of vehicle exitentry, however I was informed to lodge a Road Traffic Accident first, as such I am lodging this report to forward to them for easistence to release the comfort text vehicle number in order to claim insurance.

At this juncture, I have not sent the vehicle to the workshop for repair and as such I am not sure of the repair damage.

Police Report

2. Jul. 2018 11:28

TUNGLOK HO



No. 3560

SINGAPORE POLICE FORCE

Police Station Of Origin: Ylehun North N.P.C

3 of A

Report No. T/20160010/2057

31-Yiahun Central BINGAPORE / 60827

Tel No: 1800-8529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please allach a copy of your vehicle's insurance Certificate to this report, if you don't have the certificate with you now, please fax a copy to 85474885 staling the report number as reference.

Signature Of Officer Recording F / BSI ANDY LUCAS	The Report: Signature Of Informant:
Signature Of Interpreter	Date/Time: 19/06/2016 12:21
Officer in Charge Of Caso: TP / HRT / 68I GOH GEOK LYE Contact No.: 66476146	Classification Of Case;
Authentication Stamp	11, en /0.00 /2

SK Automobile Pte Ltd (Co Reg. No. 201500047H) 23 Kaki Bukit Ave 4, #03-01 Vicom Inspection Centre (S415933)

Tel: 6789 5155 Fax: 6783 5155

TO

: FIRST CAPITAL

DATE

: 30-Jun-18

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

ESTIMATE REPORT

OWNER'S PARTICULAR

VEHICLE DETAILS

NAME

Janice

VEHICLE NO : SLC994Z

ADDRESS

MODEL

: HONDA CIVIC

TEL. NO.

CHASSIS NO :

JHMFD254075201571

ACCIDENT DETAILS

DATE :

TIME :

THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TO	PRICE	
1	BONNET NEW	1	\$1,028.00	\$	1,028.00	+
2	BONNET LOCK NO V	1	\$85.14	\$	85.14	+ 0-0
3	HEADLAMP RH Cut	1	\$1,184.00	\$	1,184.00	1 952
4	HEADLAMP LOWER BRACKET RH	1	\$29.14	\$	29.14	4
5	FRONT SUPPORT PANEL ALL	1	\$884.00	\$	884.00	4
6	FRONT SUPPORT PANEL TOP GARNISH	1	\$298.60	\$	298.60	+
7	FRONT BUMPER Deled	1	\$759.60	\$	759.60	-638.
8	FRONT BUMPER FOG LAMP RH Couled	1	\$398.60	\$	398.60	\$ 250.20
9	FRONT BUMPER FOG LAMP COVER RH	1	\$125.40	\$	125.40	+
10	FRONT BUMPER REINFORCEMENT 34	1	\$544.00	\$	544,00	\$ 268.
11	FRONT BUMPER SIDE RETAINER	1	\$11.70	\$	11.70	_
12	FRONT BUMPER LOWER COVER	1	\$298.60	\$	298.60	+
13	WIPER WASHER TANK H ~	1	\$321.20	\$	321.20	+
14	AIR CON CONDENSOR	1	\$729.40	\$	729.40	+
15	AIR CON CONDENSOR BRACKET	1	\$12.04	\$	12.04	4
16	AIR CON SUCTION PIPE	1	\$324.20	\$	324.20	X.

17 RADIATOR Not M	1	\$1,507.44	\$ 1,507.44
18 FRONT FENDER RH	1	\$488.00	\$ 488.00
19 FRONT FENDER INNER COWLING RHZ ME	1	\$198.30	\$ 198.30
20 FRONT FENDER TOP GARNSIH	1	\$25.74	\$ 25.74

1695 82

TOTAL PRICE LESS 20% SUB TOTAL PRICE

9,253.10 \$ 1,850.62 7,402.48

S/N	DESCRIPTION	QTY	UN	IIT S/NETT	тот	AL S/NETT	
1	FRONT NUMBER PLATE	1	\$	50.00	\$	50.00	x
2	FRONT BUMPER CLIP	10	\$	6.00	\$	60.00	30
3	FRONT BUMPER LOWER LIP (BODYKIT)	1	\$	1,800.00	\$	1,800.00	-680
4	FRONT GRILLE could	1	\$	1,000.00	\$	1,000.00	4 30
5	FRONT GRILLE CLIP X50 AM	5	\$	6.00	\$	30.00	+
6	FRONT SUPPORT PANEL TOP GARNISH CLIP	8	\$	6.00	\$	48.00	x
7	FRONT FENDER COWLING CLIP	12	\$	6.00	\$	72.00	+
8	FRONT FENDER TOP GARNSIH CLIP	4	\$	6.00	\$	24.00	4
9	RADIATOR COOLANT	1	\$	80.00	\$	80.00	7.

TOTAL

3,164.00

CLAIM DETAILS: LABOUR AND SPRAY DAINTING (EPONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,200.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,000.00	500	
3	WIRING CHECK	\$50,00	30"	
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$120.00	×	
5	RENEW AND REFEX FRONT BUMPER THE LOWER LIP Repairer of the following:	\$150.00	x	
6	To display damaged part(s) during resurvey REMOVE AND REFIX BADIATOR AND CONDUCTARRESSURE, IEST Without Prejudice 1	Dasis \$80.00	×	

No illegal modification(s) is allowe[€].

· Copplementary item(s) must be resurveyed and lect to final approval from Insurance Company

\$2,600.00

ESTIMATE REPORT

TOTAL PARTS COST : \$

10,566.48

Adria Lj tolul. 363552 45 05/07/18-4/5: 2.5/C

1010.

TOTAL LABOUR COST : \$ 2,600.00 13,166.48

APPROVED DETAILS

EXCESS NO. OF DAYS **RE-SURVEY** PART BY PART OR LUMP SUM : DATE & TIME OF SURVEY SURVEYED BY

CONTACT NUMBER

FAX NUMBER



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inter	nationale Des Experts En Auton	nobile
FIRST CAPITAL IN		Ref : CS/FCI1801217	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 18-12-2018 Code: FCI2	
	Policy Particul	ars :- THIRD PARTY CLA	IM
Insured Veh.	SH 7929H	Veh. Inspected	SLC 994Z
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18005192MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	04/07/2018
	Vehicle P	articulars & Condition	
Make & Model	HONDA CIVIC	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMFD25407S201571	Colour	WHITE
Odometer	127324	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
	Cor	nditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
	Descr	ription of Damages	
		FRONT O/S PORTION.	
DAMAGES SEE D		noval Information	Manda and Albania
Assident Date			05/07/2018
Fit he had all all a control and the fit			00/01/2010
Survey neid at			
	23 MANI BONTI AVE 4 # 03		
B)THE INSPECTIO	ON WAS CONDUCTED ON A	PORT. "WITHOUT PREJUDICE" BAS	
Estimate Days of Repair			
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date Survey held at	Policy Particul Insured Veh. SH 7929H Policy No. D-18088936MFSH Claim No. D18005192MFSH Assign From SERENE LER Vehicle P Make & Model HONDA CIVIC Engine No. HIDDEN Chassis No. JHMFD25407S201571 Odometer 127324 Brakes IN ORDER General GOOD Cor Size R/H Front Tyre 225/45 R17 L/H Front Tyre 225/45 R17 L/H Rear Tyre 225/45 R17 L/H Rear Tyre 225/45 R17 L/H Rear Tyre 225/45 R17 Chassis No. Descr The Vehicle Sustained Damages at the DAMages SEE DETAILS. Gen Accident Date 19/06/2018 Survey held at SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03- A)DAMAGES CONSISTENT TO ACCIDENT RE B)THE INSPECTION WAS CONDUCTED ON ACC)IN ACCORDANCE TO YOUR INSTRUCTION	COBINSON ROAD O1 CITY HOUSESINGAPORE 068877 Code: FCI2 Policy Particulars: -THIRD PARTY CLAI Insured Veh. SH 7929H Veh. Inspected Policy No. D-18088936MFSH Coverage (\$) Claim No. D18005192MFSH Excess (\$) Assign From SERENE LER Assign Date Vehicle Particulars & Condition Make & Model HONDA CIVIC C.C Engine No. HIDDEN Year of Reg. Chassis No. JHMFD25407S201571 Colour Odometer 127324 Steering Brakes IN ORDER Modification General GOOD Conditions of Tyres KH Front Tyre 225/45 R17 CONTINENTAL L'H Front Tyre 225/45 R17 CONTINENTAL L'H Rear Tyre 225/45 R17 CONTINENTAL CONTINENTAL Sescription of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS. General Information Accident Date 19/06/2018 Inspection Date Survey held at SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933 Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BAS C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISE

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 994Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
1	BONNET	NOT NECESSARY	1,028.00	-	
1	BONNET LOCK	NOT NECESSARY	85.14		
1	HEADLAMP RH	CUT	1,184.00	952.00	
1	HEADLAMP LOWER BRACKET RH	BENT	29.14	29.14	
1	FRONT SUPPORT PANEL	NOT NECESSARY	884.00		
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	298.60	-	
1	FRONT BUMPER	DEFORMED	759.60	638.00	
1	FRONT BUMPER FOG LAMP RH	CRACKED	398.60	250.20	
1	FRONT BUMPER FOG LAMP COVER RH	NOT NECESSARY	125.40		
1	FRONT BUMPER REINFORCEMENT	BENT	544.00	268.00	
1	FRONT BUMPER SIDE RETAINER	NECESSARY	11.70	11.70	
1	FRONT BUMPER LOWER COVER	NOT NECESSARY	298.60		
1	WIPER WASHER TANK	NOT NECESSARY	321.20		
1	AIR CON CONDENSOR	NOT NECESSARY	729.40		
1	AIR CON CONDENSOR BRACKET	NOT NECESSARY	12.04		
1	AIR CON SUCTION PIPE	NOT NECESSARY	324.20		
1	RADIATOR	NOT NECESSARY	1,507.44		
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	488.00		
1	FRONT FENDER INNER COWLING RH	NOT NECESSARY	198.30		
1	FRONT FENDER TOP GARNISH	NOT NECESSARY	25.74		
	LESS 20% DISCOUNT		-1,850.62	-429.81	
			7,402.48	1,719.23	
	SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00		
10	FRONT BUMPER CLIP @\$6.00 (SN)	NECESSARY	60.00	30.00	
	FRONT BUMPER LOWER LIP (BODYKIT) (SN)	CRACKED	1,800.00	680.00	
	FRONT GRILLE (SN)	CRACKED	1,000.00	300.00	
	FRONT GRILLE CLIP @\$6.00 (SN)	NOT NECESSARY	30.00		
8	FRONT SUPPORT PANEL TOP GARNISH CLIP @\$6.00 (SN)	NOT NECESSARY	48.00	-	

Report Ref No. CS/FCI18012179/Acd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
12	FRONT FENDER COWLING CLIP @\$6.00 (SN)	NOT NECESSARY	72.00	
4	FRONT FENDER TOP GARNISH CLIP @\$6.00 (SN)	NOT NECESSARY	24.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	
			3,164.00	1,010.00
	LABOUR			
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		1,200.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	500.00
	WIRING CHECK.		50.00	30.00
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS.	NOT NECESSARY	120.00	-
	RENEW AND REFIX FRONT BUMPER LOWER LIP.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	80.00	-
			2,600.00	930.00
	GRAND TOTAL		13,166.48	3,659.23

RECOMMENDED COST OF LUMP SUM REPAIRS	2,900.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI18012179/Acd3e2

MARKET VALUE: \$30,000.00(EST)-LTA REIMBURSEMENT VALUE: \$21,753.00=NETT VALUE: \$8,247.00



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.