

INS. CASE OWNER:

ccp/pc 1801 n97, Ti h6704 LKK: IDAC:

Surveyor: TAUMIKH DOI: 16/07/18 Date / Time: 4/9/18 Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No. : SES 4570P
Name of Insured : LOH KWOK FONG
Insured Tel No. : _____ HP: _____
Excess Sec II :SS _____ D.O.A : no/6/18
Is driver the owner? (YES / NO) Nature of Accident : _____
If NO, Driver Name / Age : LOH JIA WEN KETHA
Driver Tel No. : _____ (V/L: YES / NO)

Claim No. : 18/18/18/UP05/020729
Policy No. : 318VP06018216
Make / Model : REUGROT
Place of Accident : PLE TWDS TWDS MARK ADAMS RD EXIT
OI GIA REPORT: YES NO ; TP GIA REPORT: YES / NO
Insured Liability : % Final ? Yes / No

SMH 7897J



INSRS: _____
WSP: cke
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
<u>5/7/18</u>	Non-Reporting ltr (1st):	
<u>vic</u>	Non-Reporting ltr (2nd):	
<u>06/07/18</u>	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
<u>18/02/19</u>	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 11/07/18 Sent By: bs

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: PIP \$S 3,068.00 (4 days) Reduction: 47 % Email Call

FINAL SETTLEMENT Date/Time: 13/06/19 Confirm with: AT TING Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27 If NO or B 28, Ass. Lia : COLO KATH - ENDED TP

Repair Cost: (w/acc) \$S 3,282.76

Loss of Rental (LOR): (w/acc) \$S 642.00 (6 days) X \$100

Loss of Use (LOU): \$S - (S x days)

Loss of Income (LOI): \$S - (S x days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search \$S -

Medical: \$S -

Disbursement: \$S - (e.g. Tow/ Independent)

Legal Cost \$S -

Total: \$S 3,924.76 Global Sum \$S: -

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 3,924.76 Name 1: OCUS 4 CARWASH KIA PTE LTD

Payee 2: (Strike if N.A.) \$S - Name 2: -

Payee 3: (Strike if N.A.) \$S - Name 3: -

COPY SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format: _____
3) Survey fee: \$450.00

Tanpin

REF: LPC

ASSIGNMENT

From: Date: 16032018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMA 7893J
at Workshop n/s: Cycle & Carriage
of: 209 Pandan Garden

Insured

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh: Don.

(Policy Condition)

2:30pm
owner waiting

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMA 7893J Yr Regn: 2018 June.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Kia Forte. c.c. 1591

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 1741 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

145/65R15
R R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

D.O.I. 16/7/18 e1445

Survey held at

C&C Pandan Garden

Des. of Damages: Frt / (Rear) / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

P/P \$3,068.00
CRBD: \$2,719.09 (47%)

Date/Time: File Pass to?

: Preli. Report
 : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) S+RS \$

2) Photo

3) Other

4)

TOTAL

1)

Date/Time: File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: Site Insp. (\$

Interview (\$

Tech Invs (\$

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18012197/hb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 04-07-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKS 4570P	Veh. Inspected	SMA 7893J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/06/2018	Inspection Date	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18012197/T1hb3

Date: 17.07.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SMA7893J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.07.2018 at the premises of M/s Cycle & Carriage KIA Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	<u>5,787.00</u>
Revised Estimate Amount	: S\$	<u>3,068.00</u>
"Check" Items Amount	: S\$	<u>854.00</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3-4 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

KIA AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : WONG QI XUAN
Period of Insurance : 14 Jun 2018 to 13 Jun 2019
Engine No. : G4FGHH692494
Chassis No. : KNAFJ411MJ5762313



Vehicle No. :
Cover Note No. : 1800069405
Endorsement No. :
Issued Date : 13 Jun 2018

PNM78235



ABOUT THE COVER

Make/Model : KIA FORTE K3 1.6 A EX
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
 a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
 WONG, QI XUAN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 606339 65684501
 - Cycle & Carriage Authorised Service Centre Add: 241 Alexandra Road Singapore 159931 64278800
 - Cycle & Carriage Authorised Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
- For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
 We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0500709237
 CYCLE & CARRIAGE - DPHANG(KIA)
 239 ALEXANDRA ROAD
 SINGAPORE 159930 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

Jeanine Lin

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8829368A**

Name: **WONG QI XUAN**

Birth Date: **19 Aug 1988**

Issue Date: **30 Jun 2008**

001620739A



FOR C&C USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8829368A**

Name: **WONG QI XUAN**

黄 麒 轩

Race: **CHINESE**

Date of Birth: **19-08-1988** Sex: **M**

Country of Birth: **SINGAPORE**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE: **30 Jun 2008**

Class 3 Motor Cars =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

NP 428A

Licence No: **S8829368A**

FOR C&C USE

AB048385

S8829368A

NPIC No: **S8829368A**

Blood Group: _____ Date of issue: **19-08-2003**

Address: **APT BLK 411 BUKIT BATOK WEST AVENUE 4 #04-188 SINGAPORE 650411**






CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for Wong Qi Xuan and vehicle LCV05917/WONG QI XUAN.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00081, Cash, 11/07/2018/ 18:55, QUD, 247 / DonBong, 31306.

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like RENEW COVER-RR BUMPER CTR, PAINT WORK SPRAY REAR BUMPER FACE, etc.

Estimate

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

INSURVEYOR NAME: Tanj... 97495719
INSURVEYOR SIGNATURE: [Signature]
DATE: 6/7/18 1445


Confirm & accepted by

REMARKS: Resurvey before paint
3-4 days
sure thank you.

Nett 5,787.00
7% GST on 5787.00 405.99
Total Payable 6,192.09

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
WONG QI XUAN BLK 411 BUKIT BATOK WEST AVENUE #04-18B SINGAPORE 650411 Contact No Mobile: 85184389	Cust No/Name LCV05917/WONG QI XUAN Reg No/Reg Date SMA7893J / 20/06/201 Date In/Mileage / 0 Chassis No KNAFJ411MJ5762313 Engine No G4FGHH692494 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	02/07/2018/ 18:25	QUD	247 / DonBong	31306			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW COVER-RR BUMPER CTR, REAR BUMPER FACE REPAIR REAR END PANEL								2200.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER FACE, REAR END PANEL AND AFFECTED PORTION								1260.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								50.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST								80.00
M SUNDRY SUPPLY PARKING SENSOR								280.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								200.00
M SUNDRY SUNDRIES								50.00
M COVER-RR BUMPER,CTR					1.00	347.00	00.00	347.00
M BRACKET-RR BUMPER SIDE MTG,LH					1.00	29.00	00.00	29.00
M BRACKET-RR BUMPER SIDE MTG,RH					1.00	29.00	00.00	29.00
M STAY-RR BUMPER LH					1.00	120.00	00.00	120.00
M STAY-RR BUMPER RH					1.00	120.00	00.00	120.00
M BEAM-RR BUMPER					1.00	318.00	00.00	318.00
M BRACKET-RR BEAM UPR MTG					1.00	3.00	00.00	3.00
M BRACKET-RR BEAM UPR MTG,RH					1.00	3.00	00.00	3.00
M BRACKET-RR BEAM LWR MTG					1.00	5.00	00.00	5.00
M BRACKET-RR BEAM LWR,CTR					1.00	5.00	00.00	5.00
M COVER-RR BUMPER					1.00	688.00	00.00	688.00
SURVEYOR NAME : _____								
SURVEYOR SIGNATURE : _____								
DATE : _____								
REMARKS :								

Confirm & accepted by _____

7% GST on	Nett 5787.00	5,787.00
	Total Payable	6,192.09

Authorized signatory and company stamp _____

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
WONG QI XUAN BLK 411 BUKIT BATOK WEST AVENUE #04-188 SINGAPORE 650411 Contact No Mobile: 85184389	Cust No/Name LCV05917/WONG QI XUAN Reg No/Reg Date SMA7893J / 20/06/201 Date In/Mileage / 0 Chassis No KNAFJ411MJ5762313 Engine No G4FGHH692494 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	02/07/2018/ 18:25	QUD	247 / DonBong	31306

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW COVER-RR BUMPER CTR, REAR BUMPER FACE REPAIR REAR END PANEL				2200.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER FACE, REAR END PANEL AND AFFECTED PORTION				1260.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				50.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				80.00
M SUNDRY SUPPLY PARKING SENSOR				280.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY SUNDRIES				50.00
M COVER-RR BUMPER,CTR	1.00	347.00	00.00	347.00
M BRACKET-RR BUMPER SIDE MTG,LH	1.00	29.00	00.00	29.00
M BRACKET-RR BUMPER SIDE MTG,RH	1.00	29.00	00.00	29.00
M STAY-RR BUMPER LH	1.00	120.00	00.00	120.00
M STAY-RR BUMPER RH	1.00	120.00	00.00	120.00
M BEAM-RR BUMPER	1.00	318.00	00.00	318.00
M BRACKET-RR BEAM UPR MTG	1.00	3.00	00.00	3.00
M BRACKET-RR BEAM UPR MTG,RH	1.00	3.00	00.00	3.00
M BRACKET-RR BEAM LWR MTG	1.00	5.00	00.00	5.00
M BRACKET-RR BEAM LWR,CTR	1.00	5.00	00.00	5.00
M COVER-RR BUMPER	1.00	688.00	00.00	688.00
SURVEYOR NAME : _____				
SURVEYOR SIGNATURE : _____				
DATE : _____				
REMARKS :				

Confirm & accepted by _____

7% GST on	5787.00	Nett	5,787.00
			405.09
		Total Payable	6,192.09

Authorized signatory and company stamp _____

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
 PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
WONG QI XUAN	Cust No/Name LCV05917/WONG QI XUAN
BLK 411 BUKIT BATOK WEST AVENUE	Reg No/Reg Date SMA7893J / 20/06/2018
#04-188	Date In/Mileage 01/09/2018/ 4788
SINGAPORE 650411	Chassis/Package KNAFJ411MJ5762313 /1F17
Contact No Mobile: 85184389	Engine No G4FGHH692494
01/09/	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	11/01/2019/ 13:30	TLD	260 / AiTing	31306

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR REAR END PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 825.00
E PNT98000 RESPRAY ON REAR BUMPER, REAR END PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 840.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST TO FACILITATE REPAIR				✓ 60.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 200.00
M SUNDRY SUNDRIES				✓ 20.00
X COVER-RR BUMPER,CTR	1.00	✓ 347.00	00.00	347.00
X BRACKET-RR BUMPER SIDE MTG,LH	1.00	✓ 29.00	00.00	29.00
X BRACKET-RR BUMPER SIDE MTG,RH	1.00	✓ 29.00	00.00	29.00
X COVER-RR BUMPER	1.00	✓ 29.00	00.00	29.00
Z TEXT	1.00	✓ 688.00	00.00	688.00
TP CLAIM LONPAC SKS4570P				
DOA : 30.06.18				
SURVEYOR TAUFIKH (LKK) 16.07.18				
4 REPAIR DAYS				

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	1,093.00			
Labour	1,955.00			
Standard Menu	0.00	7% GST on	3068.00	214.76
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	20.00			
Total (w/o GST)	3,068.00			
			Total Payable	3,282.76

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

Surveyor : TAUFIKH - LKK
Company : TP LONPAC
Emailed : 11/01/19, 1.20pm

VEHICLE NO : SMA7893J
MODEL : KIA FORTE K3 1.6 A
WIP : 31306

Material	: \$	<u>1,093.00</u>
Labour	: \$	<u>1,975.00</u>
Sub-Total	: \$	<u>3,068.00</u>
		<u>-</u>
Less Excess	: \$	<u>-</u>
Total	: \$	<u>3,068.00</u>
GST 7%	: \$	<u>214.76</u>
Grand Total	: \$	<u>3,282.76</u>
Finalise By/Date	: <u>LOI / 11/01/19</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 4 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 6

TP claim SKS4570P

Claim GIA / LTA fee _____

Claim Loss of Use / Rental

Claim Medical Fee / Others _____

Third Party Report - _____

GERALD POH WEE BIN

From: GERALD POH WEE BIN
Sent: Tuesday, 3 July, 2018 8:59 AM
To: assignments@lkkauto.com
Cc: 'mt_claim@lonpac.com'; 'Don Bong Kiong Hua'
Subject: FW: TP LONPAC CLAIM SMA7893J AGAINST SKS4570P DOA 30.06.2018
Attachments: GIA REPORT & ESTIMATE SMA7893J.pdf; WhatsApp Image 2018-07-02 at 9.17.52 AM.jpeg; WhatsApp Image 2018-07-02 at 9.17.53 AM.jpeg

Importance: High

1:02pm @ 3/7/2018
person Don Bong
vehicle not in

Our Ref : 18/18/18/VP05/020729

Dear Nivitha,

Kindly proceed to conduct the survey and revert to them on direct settlement.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Don Bong Kiong Hua [mailto:kionghua.bong@cyclecarriage.com.sg]
Sent: Monday, 2 July, 2018 6:39 PM
To: MT_Claim_SG
Cc: Andre Chow En De; Coco Lu Ting; Edwin Abcede Caina; Tay Jian Ye
Subject: RE: TP LONPAC CLAIM SMA7893J AGAINST SKS4570P DOA 30.06.2018
Importance: High

Attn : Motor Claim Department

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number **SMA7893J**), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number **SKD4570P**) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

Do let me know the liability at the soonest possible.

Regards,

Don Bong
Claim Division Operations
209 Pandan Gardens
Singapore 609339



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

21st June 2019

LKK Ref: CC4/LPC18012197/T1hb3

Mr Vic Alpeh (Motor Claims Department)
LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
#02-25 Ubi Avenue 1
Singapore 408933

Dear Sir,


Discharge Voucher for Accident Involving Vehicles SMA7893J and SKS4570P on
30/06/2018

Attached is the Discharge Voucher duly signed by claimant.

Kindly process for payment to, Cycle & Carriage Kia Pte Ltd, the soonest possible.

Appreciate your assistance.

Yours Sincerely,



Loi Ai Ting
Customer Service Advisor



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18012197/T1hb3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 02-07-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 4570P	Veh. Inspected	SMA 7893J
Policy No.	Z18VP05018216	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020729	Excess (\$)	0.00
Assign From	GERALD	Assign Date	04/07/2018

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAFJ411MJ5762313	Colour	WHITE
Odometer	1741	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	KUMHO	6 mm
L/H Front Tyre	195/65 R15	KUMHO	6 mm
R/H Rear Tyre	195/65 R15	KUMHO	6 mm
L/H Rear Tyre	195/65 R15	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/06/2018	Inspection Date	16/07/2018
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 7893J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	COVER-RR BUMPER ,CTR (SN)	DEFORMED	347.00	347.00
1	BRACKET -RR BUMPER SIDE MTG ,LH (SN)	NECESSARY	29.00	29.00
1	BRACKET -RR BUMPER SIDE MTG ,RH (SN)	NECESSARY	29.00	29.00
1	STAY-RR BUMPER LH (SN)	NOT NECESSARY	120.00	-
1	STAY -RR BUMPER RH (SN)	NOT NECESSARY	120.00	-
1	BEAM-RR BUMPER (SN)	NOT NECESSARY	318.00	-
1	BRACKET -RR BEAM UPR MTG (SN)	NOT NECESSARY	3.00	-
1	BRACKET -RR BEAM UPR MTG,RH (SN)	NOT NECESSARY	3.00	-
1	BRACKET -RR BEAM LWR MTG (SN)	NOT NECESSARY	5.00	-
1	BRACKET -RR BEAM LWR CTR (SN)	NOT NECESSARY	5.00	-
1	COVER -RR BUMPER (SN)	DEFORMED	688.00	688.00
			1,717.00	1,113.00
LABOUR				
	RENEW COVER-RR BUMPER CTR,REAR BUMPER FACE REPAIR REAR END PANEL.		2,200.00	825.00
	PAINT WORK SPRAY REAR BUMPER FACE,REAR END PANEL AND AFFECTED PORTION .		1,260.00	840.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	30.00
	REMOVE AND INSTALL PARKING ASSIST.		80.00	60.00
	SUPPLY PARKING SENSOR .	NOT NECESSARY	280.00	-
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
			4,070.00	1,955.00
GRAND TOTAL			5,787.00	3,068.00
RECOMMENDED COST OF REPAIRS				3,068.00

Report Ref No. CC4/LPC18012197/T1hb3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.