



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for WONG QI XUAN, vehicle registration SMA7893J, and chassis/engine information.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00081, Cash, 11/07/2018/ 18:55, QUD, 247 / DonBong, 31306

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like bumper repairs, painting, and electrical checks with handwritten quantities and prices.

Estimate

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SURVEYOR NAME : Taufiq 97495719

SURVEYOR SIGNATURE : [Signature]

DATE : 16/7/2018

Confirm & accepted by

REMARKS : Resurvey before paint
3 - 4 days
sure in handson.

Nett 5,787.00
7% GST on 405.09
Total Payable 6,192.09

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.