

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its
repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**GIA / PR Seen: _____ Consistent? : **Yes** or **No**Est. Repairs: _____ days Res.: **Yes** or **No**Lum Sum: _____ % 3 Val.: **Yes** or **No****CA / REV / REP. / 24 HRS**Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SCR234SL Yr Regn: 2016 / Oct.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 35752 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru11206906 *Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS: BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____

D.O.I. 31/07/18Survey held at ModeruDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP ALG.

Date/Time, File Pass to?

☐: **Preli. Report**

1)

☐: **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____