

Surveyor

Manus

ASSIGNMENT (Office)

From (Person)

Gabriel Wee

of

III

Date/Time:

4/7/18 @ 5.13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 9690U

Insured:

SHA 2093T

at Workshop n/s:

Yew Hock Auto

Tel:

8285 7623

of

1 Kaki Bukit Ave 6 #02-11

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

03/07/2018

CA / REV / REP. / REV 24 HRS

(wp)

05/07/2018

H.O.D. Endorsement:

Date/Time:

5.54pm @ 4/7/18

Person Contacted:

Ah hock

Vehicle:

IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKJ 9690U-X

SHA 2093T-NBA / MSG 17020923/Y

D.O.A: 31/10/2017

## ASSIGNMENT

From: Date: 5/7/18

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKJ 9690 R

at Workshop m/s Yew Hok Auto

of 1 Kaki Bukit Ave 6 #02-11

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GA / PR-Seen: Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKJ 9690 R Yr Regn: 7116

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota Corolla C.C. 1986

Colour: Purple A/C: Insured / Std / NI / NA

Sp. Reading: 19811 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 254 6000 72916

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Brim / STD A/Rim or

Tyre Size: F: 235/55 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 31/7/18 D.O.I. 5/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

quoting Estimate.

20/7/18 2/5 @ 5800 confirmed with AM hock (Red: 6032) 50%

RECEIVED 25 JUL 2018

Date/Time, File Pass to?

1) 25/7 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I.: (\$ 5800 )

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$ )☐ Interview (\$ )☐ Tech. Invs (\$ )☐ Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

350

10

360



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III18012208/Utd3

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 04-07-2018



Code : III2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2093T	Veh. Inspected	SKJ 9690R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	04/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	03/07/2018	Inspection Date
Survey held at	YEW HOK AUTO SERVICES 1 KAKI BUKIT AVE 6 #02-11 AUTOBAY SINGAPORE 417883	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 4 July 2018 5:13 PM  
**To:** Kuru & Co; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Sundari Nagarajan - III  
**Subject:** RE: PRE-REPAIR INSPECTION NOTIFICATION - III ref: SHA 2093T // AXA ref: SGU 9628L // Our ref: L.18.0985.It(jt)  
**Attachments:** SKJ9690R\_03072018.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle **SKJ9690U** and let us have your report urgently.

This claim will be handled by **Ms Sundari**.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

---

**From:** Kuru & Co [mailto:kurulegal@yahoo.com.sg]  
**Sent:** 04 July, 2018 3:34 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>; AXA SGP - Motor Survey <motor.survey@axa.com.sg>  
**Cc:** raghav.dhakal@axa.com.sg; mary.chia@axa.com.sg  
**Subject:** Re: PRE-REPAIR INSPECTION NOTIFICATION - III ref: SHA 2093T // AXA ref: SGU 9628L // Our ref: L.18.0985.It(jt)

Dear Gabriel,

We refer to your email of even date.

Our client is agreeable to the following surveyor(s) as the SJE: **LKK Auto Consultants Pte Ltd.**

Please arrange for your surveyor to survey our client's vehicle at the following address:

**YEW HOK AUTO SERVICES**

1 Kaki Bukit Avenue 6

#02-11 Autobay@Kaki Bukit

Singapore 417883

Contact: Ah Hok: **8285 7623**

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards,

Judy Tan  
Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

---

**From:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>  
**To:** Kuru & Co <[kurulegal@yahoo.com.sg](mailto:kurulegal@yahoo.com.sg)>; AXA SGP - Motor Survey <[motor.survey@axa.com.sg](mailto:motor.survey@axa.com.sg)>  
**Sent:** Wednesday, 4 July 2018, 14:35  
**Subject:** RE: PRE-REPAIR INSPECTION NOTIFICATION - III ref: SHA 2093T // AXA ref: SGU 9628L // Our ref: L.18.0985.It(jt)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]  
**Sent:** 04 July, 2018 10:19 AM  
**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>; AXA SGP - Motor Survey <[motor.survey@axa.com.sg](mailto:motor.survey@axa.com.sg)>  
**Subject:** PRE-REPAIR INSPECTION NOTIFICATION - III ref: SHA 2093T // AXA ref: SGU 9628L // Our ref: L.18.0985.It(jt)

Dear Sirs,

**ACCIDENT INVOLVING SKJ 9690U, SHA 2093T AND SGU 9628L ON 03.07.18  
AT/ALONG JALAN BUKIT MERAH  
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **Loh Kim Boon (Liu Jinwen)**, whose vehicle registration number **SKJ 9690U** was damaged in the above accident.

A copy of the **Police & SAS Report** filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thanks / Rgds,  
Lena  
Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.  
It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/07/2018 08:37
Date Of Accident	03/07/2018 12:30
Exact Location Of Accident	JALAN BUKIT MERAH (AFTER BUS STOP TOWARDS CTE)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ9690R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOH KIM BOON (LU JINWEN)
NRIC No	S7324481A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93360299
Alternative Phone No	OTHERS-93360299
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	7VPCB1722810 (COMP)
Cover Note Number	
<b>Driver</b>	
Name of Driver	LOH KIM BOON (LU JINWEN)
NRIC No	S7324481A
Date Of Birth	02/07/1973
Occupation	INDOOR
Date Of Driving Pass	08/01/1999
Driving Experience	19 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93360299
Fax Number	
Contact Number	OTHERS-93360299
EMail Address	NOEMAIL



Address BLK 621 HOUGANG AVE 8 #03-302  
 Postcode 530621  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 3  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : PETER YEO  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TAMPINES NORTH NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 461 TAMPINES STREET 44 #01-56 , POSTCODE: 520461 ,  
 COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-7818999 - FAX NO: 67838603  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA2093T  
 Vehicle Make/Model/Colour HYUNDAI SONATA NF 2.0 CRDI  
 Details Of Properties  
 Vehicle Category TAXI  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SGU9628L  
Vehicle Make/Model/Colour MITSUBISHI LANCER 1.6 A  
Details Of Properties  
Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name LOH KIM BOON (LU JINWEN)  
Approximate Age 45  
Injuries Sustain  
Injured person in which vehicle? SKJ9690R  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders


  
 Policyholder's Signature  
 Date & Time: - 4 JUL 2018

  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time: - 4 JUL 2018

**IDAC KAKI BUKIT (P) LTD.**  
 23 Kaki Bukit Ave 4  
 Singapore 41593  
 Tel: 67416697 Fax: 67416698  
 Email: [yackb@singnet.com.sg](mailto:yackb@singnet.com.sg)  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



Vehicle A: SKJ 9690R.

Vehicle B: SHA 2093T.

Vehicle C: SGU 9628L.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report NO: 1/20180703/2091

yhlee@outlook.sg

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

- 4 JUL 2018

Driver's Signature

(if driver is not the policyholder)

Date & Time:

- 4 JUL 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Reporting Centre Personnel's Signature

Email: vacb@singapore.gov.sg

NRIC/FIN No.:



SINGAPORE  
POLICE FORCE



T/20180703/2091

1 of 4

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

Report No: T/20180703/2091

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/07/2018 15:43	Vide Report No.:	Station Diary No. 26
--	------------------	-------------------------

## Informant's Particulars

Name of Informant: LOH KIM BOON			Address: APT BLK 621 HOUGANG AVENUE 8 #03-302 SINGAPORE 530621	
ID Type / ID No.: NRIC NO / S7324481A			Contact No.: Home/Office: Mobile: 93360299	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 45	Date of Birth: 02/07/1973	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Self-Employed			Driving Licence Information: Class: 3,4,5 Date of Expiry:	

## General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 03/07/2018 12:30	Type of Location: Straight Road
Location:  JALAN BUKIT MERAH				
Along Jalan Bukit Merah after bus stop towards CTE				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Traffic Light - Working		Traffic Volume: Moderate	
Type of Collision: Chain-collision	Anyone conveyed by ambulance: No			

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGU9628L	Car	MITSUBISHI	LANCER 1.6 A	Silver		0
SHA2093T	Car	HYUNDAI	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO	Blue		0

## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



SINGAPORE  
POLICE FORCE



T/20180703/2091

2 of 4

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
S20461  
Tel No: 1800-7818999

Report No: T/20180703/2091

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKJ9690R	Car	TOYOTA	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD	Black		1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKJ9690R	MSIG INSURANCE (SINGAPORE) PTE. LTD.	7VPCB1722810	12/07/2017	11/07/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SEE SI SIEN	ID No.	F1443941L
Related Vehicle	SGU9628L (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHAN THIAN KWEE	ID No.	S1694558G
Related Vehicle	SHA2093T (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



SINGAPORE  
POLICE FORCE



1/20180703/2091

3 of 4

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

Report No.: 1/20180703/2091

CONTINUATION OF REPORT

<b>Driver</b>			
Name	LOH KIM BOON	ID No.	S7324481A
Related Vehicle	SKJ9690R (Car)	Contact No.	93360299
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	03/07/2018	Date Discharge	03/07/2018
No. of Days granted Medical Leave	05	Degree of Injury	NIL

**Brief Details.**

On 03/07/2018 at about 1230hrs, I was driving my car (SKJ9690R) on lane 3 along Jalan Bukit Merah after bus stop towards CTE with one passenger on board.

Out of sudden, I felt impact coming from the rear of my car. I realised my car was involved in a chain-collision which resulted to the rear of my car to be damage. My car was the first vehicle out of three vehicles involved in the collision. The second vehicle is a taxi (SHA2093T) and the third vehicle is a car (SGU9628L).

No one was injured at that point of time including my passenger. We alighted and exchanged particulars with one another. I took photos of the accident scene using my mobile phone. My car is not install with in-car CCTV.

After the accident, I felt unwell thus seek medical treatment at a private clinic and was given 5 days of MC from 03/07/2018 to 07/07/2018.





SINGAPORE  
POLICE FORCE



T/20180703/2091

4 of 4

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-53 SINGAPORE  
520461  
Tel No: 1800-7818999

Report No. T/20180703/2091

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Sgt 2 MUHAMMAD ISA BIN MD RASHID

Signature Of Informant

Signature Of Interpreter:  
Not applicable

Date/Time:  
03/07/2018 15:43

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt TANG SIEW PING  
Contact No.: 65476430

Classification Of Case:



SINGAPORE  
POLICE FORCE

Authentication Stamp  
NP168

SIGNATURE

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 4481A

**Vehicle Details**

Vehicle No.: SKJ9690R

Vehicle to be Exported: No

Intended De-registration Date: 05 Jul 2018

Vehicle Make: TOYOTA

Vehicle Model: HARRIER 2.0 ELEGANCE AT ABS  
D/AIRBAG 2WD

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: 3ZRB733023

Chassis No.: ZSU600072916

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$28,846.00

Original Registration Date: 12 Jul 2016

First Registration Date: 12 Jul 2016

Transfer Count: 0

Actual ARF Paid: \$27,385.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Jul 2026

PARF Rebate Amount: \$20,538.00

**Intended COE Rebate Details**

COE Expiry Date: 11 Jul 2026

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$56,089.00

COE Rebate Amount: \$44,961.00

**Total Rebate Amount: \$65,499.00**

The information contained herein is correct as at 05 Jul 2018

OK

# YEW HOK AUTO SERVICES

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

H/P: 8285 7623

TEL: 6636 5355

FAX: 6252 4129

Email: yhlee@outlook.sg

Not Afford  
like  
1/5 \$5800  
5th.

Vehicle number: SKJ9690R

Vehicle Made & Model: TOYOTA HARRIER

Qty	List Items	Amount \$
1	Tailgate	1,662.50
1 set	Tailgate glass moulding	297.54
1	Tailgate emblem "HARRIER"	81.50
2	Tailgate lamps - L/R @ 390.60	781.20
1	Tailgate outer garnish	541.60
10	Tailgate outer garnish clips @ 4.50	45.00
1	Tailgate inner lock	591.66
1	Tailgate inner board	481.60
15	Tailgate inner board clips @ 4.50	67.50
1	Tailgate w/strip	341.62
2	Tailgate dampers - R/L @ 291.60	583.20
1	Rear bumper	1,381.65
1	Rear bumper difusser	419.70
2	Rear bumper reflectors - L/R @ 101.60	203.20
1	Rear bumper foam	180.63
2	Rear bumper side retainers - L/R @ 101.20	202.40
10	Rear bumper clips @ 4.50	45.00
2	Rear bumper splash shields - L/R @ 142.60	285.20
1	Rear end panel	792.96
1	Rear end panel garnish	360.89
1	Rear exhaust silencer	892.62
2	Rear taillamps - L/R @ 491.75	983.50
Sub-total		11,222.67
Less 25%		2,805.67
Total List		8,417.00

6561.25  
4920.93

Vehicle number: SKJ9690R

Vehicle Make & Model: TOYOTA HARRIER

**Special Nett Items**

1 set Tailgate glass sealant	RM	80.00	40
1 set Tailgate glass foam tape	RM	65.00	40
1 set Rear reverse sensor	shw	280.00	200
<b>Total Special Nett</b>		425.00	

**Labour charges**

To remove, refix tailgate glass	180.00	120
To check rear electrical wiring	50.00	30
To remove, refix rear reverse sensor/camera	80.00	50
To respray undercoating	100.00	80
To reinstall tailgate electrical & mechaical part to new tailgate	180.00	80
To respray painting and etc	1,200.00	800
Panel beating, cut, weld remove & replacing above parts	1,200.00	900
	<u>2,990.00</u>	
<b>Total Labour</b>		7260.93

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 11,832.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18012208/UTD3N2

Date: 01/08/2018

## REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant:	SKJ9690R	Insured Vehicle No :	SHA2093T
Vehicle No :		Nature of Claim:	TP
Date of Loss:	03/07/2018	Claim No:	N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKJ9690R	Engine No:	3ZRB733023
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Chassis No:	ZSU600072916
Reg. Date:	12/07/2016 (Man. Year: 2015)	Odometer:	19811 km
Colour:	Purple		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,842.00	5,200.94	3,641.06	41.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	2,060.00	930.00	31.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,832.00</b>	<b>7,260.94</b>	<b>4,571.06</b>	<b>38.63</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,832.00</b>	<b>5,800.00</b>	<b>6,032.00</b>	<b>50.98</b>

## INSPECTION

Date of Assignment:	04/07/2018	
Date Inspected:	05/07/2018 Inspected At:	Yew Hok Auto Services (HQ) 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 01 Aug 2018)	
<b>Parts:</b>	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKJ9690R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,662.50 FL	*1,662.50 FL
2	1		*SET TAILGATE GLASS MOULDING	Necessary	297.54 FL	*297.54 FL
3	1		*TAILGATE EMBLEM HARRIER	Necessary	81.50 FL	*81.50 FL
4	2		*TAILGATE LAMPS-L/R	Not Necessary	781.20 FL	*- FL
5	1		*TAILGATE OUTER GARNISH	Not Necessary	541.60 FL	*- FL
6	10		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	45.00 FL	*- FL
7	1		*TAILGATE INNER LOCK	Dented/Shorted	591.66 FL	*591.66 FL
8	1		*TAILGATE INNER BOARD	Not Necessary	481.60 FL	*- FL
9	15		*TAILGATE INNER BOARD CLIPS	Not Necessary	67.50 FL	*- FL
10	1		*TAILGATE W/STRIP	Twisted	341.62 FL	*341.62 FL
11	2		*TAILGATE DAMPERS-R/L	Not Necessary	583.20 FL	*- FL
12	1		*REAR BUMPER	Dented/Deformed	1,381.65 FL	*1,381.65 FL
13	1		*REAR BUMPER DIFUSSER	Cracked	419.70 FL	*419.70 FL
14	2		*REAR BUMPER REFLECTORS-L/R	Cracked	203.20 FL	*203.20 FL
15	1		*REAR BUMPER FOAM	Torn	180.63 FL	*180.63 FL
16	2		*REAR BUMPER SIDE RETAINERS-L/R	Bent	202.40 FL	*202.40 FL
17	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
18	2		*REAR BUMPER SPLASH SHIELDS-L/R	Not Necessary	285.20 FL	*- FL
19	1		*REAR END PANEL	Dented	792.96 FL	*792.96 FL
20	1		*REAR END PANEL GARNISH	Twisted	360.89 FL	*360.89 FL
21	1		*REAR EXHAUST SILENCER	Not Necessary	892.62 FL	*- FL
22	2		*REAR TAILLAMPS-L/R	Not Necessary	983.50 FL	*- FL
23	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
24	1		*SET TAILGATE GLASS FOAM TAPE	Necessary	65.00 FS	*40.00 FS
25	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,647.67</b>	<b>6,841.25</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,805.67</b>	<b>1,640.31</b>
<b>Total Parts (\$\$)</b>	<b>8,842.00</b>	<b>5,200.94</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
2	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
3	TO REMOVE,REFIX REAR REVERSE SENSOR/CAMERA	New	80.00	50.00
4	TO RESPRAY UNDERCOATING	New	100.00	80.00
5	TO REINSTALL TAILGATE ELECTRICAL & MECHAICAL PART TO NEW TAILGATE	New	180.00	80.00
6	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
7	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	900.00
Gross Labour Cost (\$\$)			2,990.00	2,060.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;