SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
03/07/2018 16:52	
02/07/2018 22:50	
MARINA BOULEVARD	
SINGAPORE	
DETAILS OF OWN VEHICLE	
	03/07/2018 16:52 02/07/2018 22:50 MARINA BOULEVARD SINGAPORE

Vehicle Registration Number	SHB8468B

Insur	ed/Poli	cynoia	er	

PREMIER TAXIS PTE LTD Name Of Registered Owner

200304975H Co Reg No NOEMAIL Email Address

Mobile Phone No

Alternative Phone No OFFICE-62148880

Vehicle Particulars

KIA Manufacturer

OPTIMA-1.7 D (A) Model

Exact Purpose for which vehicle was being used at

time of accident

HIRED & REWARDS

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

THIRD PARTY Type Of Coverage

Fleet Policy YES

5095103893 Policy Number

Cover Note Number

Driver

NG GHAN CHAI TERENCE Name of Driver

S1612749C NRIC No 04/09/1963 Date Of Birth OUTDOOR Occupation 10/07/1984 Date Of Driving Pass

33 YEARS AND 11 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-96801204 Mobile Number

Fax Number

Contact Number

NOEMAIL EMail Address

. Address

56 OXLEY ROAD

Postcode

238641

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - SUPER RELIEF - REDHILL

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance,

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

VEH. A - NO PAX VEH. B - 1 PAX

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHA4127S

Vehicle Make/Model/Colour

COMFORT TAXI

Details Of Properties

VEH, B TAXI

Vehicle Category

JEFFREY

Name of Driver

NRIC/Passport Number

Contact Number

96913118

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims,
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:


Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Sketch Plan Pg. 2



Page 4 of 11

Sketch Plan Pg. 3

Describe Circumstance of the Accident.

ON 02/07/2018 @ 2250HRS, I WAS DRIVING MY TAXI (SHB 8468 B) TRAVELLING ALONG MARINA BOULEVARD IN LANE 2.

AFTER CHECKING FOR CLEARANCE FROM MY LEFT, I THEN FILTERED INTO LANE 3 WITH MY LEFT INDICATOR AND WHEN MY TAXI WAS FULLY IN LANE 3, SUDDENLY VEHICLE B (SHA 4127 S - COMFORT TAXI) WHICH WAS FROM MY LEFT - ENCROACHED & COLLIDED ONTO THE FRONT LEFT PORTION OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE FRONT LEFT PORTION AND VEHICLE B HAD DAMAGES ON THE RIGHT PORTION.

NO INJURY INVOLVED. NO PASSENGERS ONBOARD MY TAXI. VEHICLE B HAD A PASSENGER ONBOARD.

*VIDEO FOOTAGE CAPTURED.

