

REF CS/FCI 18012210/ Nvd3 ⁿ² _{per d instruction}
ASS. REC BY: N192
SWI Veyor: CWS
From Person: Joanne Yong of FCI Date/Time: 4/7/18 @ 5:30pm

Estimated Cost: OD TP WS/TP RES/OD RES/EVA/INV/MV/CS
To Inspect Vehicle No: SHB 8468B Insured: SHA 4127S
at Workshop m/s: Premier Automotive Tel: 65446682
of: 23 Changi South Ave 2 # 03-02

Policy No: D18005196MFSH Claim No: D18005196MFSH
Sum Insured: Excess:
Make of Veh: D.O.A. 02/07/2018
(Client's Record) 05/07/2018
CA / REV / REP. / REV 24 HRS ^{up} H.O.D. Endorsement:
Date/Time: 5:47pm @ 4/7/18 Person Contacted: Goh wee dek Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 8468B - CC3/III 16014397/H1eb3q2 DOA: 29/7/2016
	SHA 4127S - CS3/FCI 16024709/Sqh 3s2 DOA: 24/11/2016
6/7/18	Email preli revised to FCI

NAZ

REF

FCI

ASSIGNMENT

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop no.

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Sp. Reading

Eng. No:

C. No.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or HANKOOK

Front

Rear

R. Bal.

R. Bal.

L. Bal.

L. Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/17/18

FINALIZED LUMP SUM REPAIR \$1150 / 3 DAYS

(Red 1415.90, 55%)

RECEIVED 1 JUL 2018

Date/Time File Pass to

☐

: Preli. Report

☐

: Final Report

Date/Time File Return to

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Fuel

Tools

Others

Add Fee:

☐

: Site Insp : \$

☐

: Inter. : \$

☐

: Tech. : \$

☐

: Material : \$

Report Format:

Lump Sum / L.B. : CWS LS \$1150p

110
50
50
18

228



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012210/Nvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 4127S	Veh. Inspected	SHB 8468B
Policy No.		Coverage (\$)	0.00
Claim No.	D18005196MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	04/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/07/2018	Inspection Date	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005196MFSH
Our ref: CS/FCI18012210/Nvd3

Date: 6/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8468B


We thank for your instruction on 4/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 5/7/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES P L and have the following to report:-

Workshop Estimate Amount	: S\$2,565.90
Revised Estimate Amount	: S\$1,489.90
"Check" Items Amount	: S\$150.40
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Muhd Nazril
Technical Investigator

MOTOR SURVEY ASSIGNMENT

Date	04-07-2018	Our Ref No. D18005196MFSH
Accident Date	02-07-2018	Claim Type. Third Party
Insured Vehicle	SHA4127S	Third Party Vehicle. SHB8468B
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242071)



PRI Documents



Close



PRI Header Details

Claim No	D18005196MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GOH WEE DEK)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446682 , Phone: 62148880 , Fax: 6214151: EmailId: WEEDEK.GOH@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE;		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4127S	TP Vehicle No	SHB8468B
PRI Recieved Date	04-07-2018 04:52:47 PM	Surveyor Appointed Date	04-07-2018 05:28:59 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Naz (LKKAuto)
Sent: Monday, 9 July 2018 4:15 PM
To: Goh Wee Dek
Cc: Gary Shi; SUR
Subject: Re: SHB8468B- FINALIZE

Dear Mr Goh,

Confirmed Lump Sum Repair \$1,150 / 3 Days.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Saturday, 7 July 2018 9:27:18 AM
To: Naz (LKKAuto)
Cc: Gary Shi; SUR
Subject: SHB8468B- FINALIZE

Dear Naz

Please confirm l/sum \$1,150, 3days.

No check items.

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.



Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 6 July 2018 12:35 PM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005196MFSH/1, SHB 8468B
Attachments: SHB 8468B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHB 8468B
Date of survey: 5/7/2018
Number of days :3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 4 July 2018 5:50 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005196MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 4 July 2018 5:29 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005196MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Enquire Transaction History

Transaction History Details

Log Date/Time:	09 Oct 2013 / 09:08:52	Receipt No.:	AACCK001-AX239-131009-000005
Asset Type:	Vehicle	Transaction Amount:	\$73,954.00
Asset ID:	SHB8468B	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131009090852698528		

Vehicle No.:	SHB8468B
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	09 Oct 2013
Original Registration Date:	09 Oct 2013
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5446879
Engine No.:	D4FDDH308147
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,990.00
Minimum PARF Benefit:	\$7,494.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	09 Oct 2013 09:08:52
COE No.:	2013100901000732D
COE Expiry Date:	08 Oct 2021
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$61,324.00
Lifespan Expiry Date:	08 Oct 2021
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

3-Jul-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8468 B

1 pc	Front bumper	\$	531.00	DT
1 pc	Front bumper n/s side retainer	\$	16.00	X 07
1 pc	Front bumper emblem @ \$44.00	\$	44.00	acc
1 pc	Front n/s wheel cover	\$	116.00	DT
1 pc	Front n/s fender	\$	384.00	X 07 R
1 pc	Front n/s fender inner shield	\$	120.00	X 07
		\$	1,211.00	691
		Less 10%	\$	121.10 621.9
			\$	1,089.90

S/NETT

1 set	Front bumper clips	\$	48.00	acc
1 set	Front n/s fender inner shield clips	\$	28.00	X 07
Sundry		\$	50.00	nn
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	50 X 07
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.		\$	500.00	360
To putty and spray painting on front bumper, front n/s fender		\$	550.00	360
To apply rustproofing on the repaired and replaced panels.		\$	120.00	30
		\$	2,565.90	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKK

5/7/18 1430

L/S

3 days

After repair photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damage 2 part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental claim(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012210/Nvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-07-2018	
				
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4127S	Veh. Inspected	SHB 8468B	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005196MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5446879	Colour	SILVER	
Odometer	464708	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	6 mm	
L/H Front Tyre	205/65 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/07/2018	Inspection Date	05/07/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8468B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED	531.00	531.00
1	FRONT BUMPER N/S SIDE RETAINER	NOT NECESSARY	16.00	-
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT N/S WHEEL COVER	DENTED	116.00	116.00
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	384.00	-
1	FRONT N/S FENDER INNER SHIELD	NOT NECESSARY	120.00	-
	LESS 10% DISCOUNT		-121.10	-69.10
			1,089.90	621.90
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			126.00	48.00
LABOUR				
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME. ETC. INCLUSIVE OF THE REPAIR OF FRONT N/S FENDER.		500.00	360.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT N/S FENDER.		550.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	50.00
	-		-	-
	-		-	-
	-		-	-
			1,350.00	770.00
GRAND TOTAL			2,565.90	1,439.90



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,150.00
---	--	--	----------

Report Ref No. CS/FCI18012210/Nvd3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.