

(08/11/13) wef

REF: AXA

ASS. REC. BY: Xhe.

ASSIGNMENT

From:

Date:

11/7/18

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SJZ 2031S

at Workshop m/s

TTS Eurocars

of

383 Sin Ming Drive

Insured:

Wilson - 9640 4178

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


after 11.30am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJZ 2031S

Yr Regn:

29 Sep 2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 320i M c.c 1998

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

14570

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAJA520 10WA34585

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40 R19

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

11-07-18

Survey held at

w/s

4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/7

Double check with AXA how much per day for labour. because w/s ask for \$520 per day.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$