

NATIONAL Assessment Centre Services

[wef 1 Jan'05] MHA118086617

Date In: 5/7/18-13:00	Job description	Date & Time Completed	Done by
Ref No: NA/INC18012258/C24	SAS e-filing		
Veh No: 5N93317	E-mail (within 3hrs, AIC 2hrs)		
D.O.A : 4/7/18-13:10	i-Motor Claim Form	MT/1001775-001	5/7/18 14:40
OD / TP / Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: SKX141J	INC () / Non-INC ()
Owner / Driver: (	Tel:	
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date:	Time:
Insured/Driver Liability: (	% [Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:
() Walk-In Customer : Customer's information strictly Confidential & Strictly NO refer of repairer.
() Total Loss Case : to e-mail Insurer URGENTLY.
Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks: (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury : _____

Date/Time	Actions

NA1804292	Invoice Preparation Checklist	Ant (\$) Est Bill	Ant (\$) Add Bill
Claimant's Particulars:	1) AR: Accident Reporting (\$30);		
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$80)		
Contact No:	3) TF: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
	5) FT: Follow-Through Survey (Resurvey) \$30		
	For claiming against INC Only (wef 10 Jan 2005)		
	6) TR: Re-inspection \$75		
	7) N1: Idac DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
QC Checked by (Engr-In-Charge):	ON*		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
Auditors' Comments:-	TP (N11): TP (Non INC) against INC \$20		
Dat 1:	9) N12: Idac Mobile 30		
Dat 2 / 3:	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/07/2018 13:00
Date Of Accident	04/07/2018 13:10
Exact Location Of Accident	ALONG LOR 32 GEYLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN9331T
Insured/Policyholder	
Name Of Registered Owner	HE CHUNTIE
Passport No/FIN	G6450786P
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90590728
Alternative Phone No	OFFICE-90590728

Vehicle Particulars

Manufacturer	HYUNDAI
Model	HD AVANTE 1.6 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084829831-01
Cover Note Number	

Driver

Name of Driver	HE CHUNTIE
Passport No/FIN	G6450786P
Date Of Birth	11/03/1957
Occupation	INDOOR
Date Of Driving Pass	16/12/2010
Driving Experience	7 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90590728
Fax Number	
Contact Number	OFFICE-90590728
Email Address	NOEMAIL

Address	574 GEYLANG ROAD
Postcode	389517
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, I WAS COMING OUT FROM MINOR RD, VEHICLE B WAS TRAVELLING ALONG MAIN ROAD, I ACCIDENTALLY HIT ONTO VEHICLE B FRONT RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX1411J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: ;
	GENDER: ;

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Lor 32
 Geylang

A: SJN93317
 B: SKX1411J

refer to statement.

A blue diagonal line is drawn across the page, starting from the lower-left quadrant and extending towards the upper-right quadrant. It appears to be a stray mark or a placeholder for a diagram.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ENTREPASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Company
YU ZHAO YUAN PTE. LTD.

Name
HE CHUNTIE

Occupation
MANAGING DIRECTOR

FIN
G6450786P

Date of Application
22-06-2017

Date of Issue
02-07-2017

Date of Expiry
01-07-2018

L8166135

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **G6450786P**

Name
HE CHUNTIE

Birth Date: **11 Mar 1957**

Issue Date: **06 Nov 2015**

Valid Till **15/12/2020**

002490754G

SG 50

VISIT PASS
Immigration Regulations

Name
HE CHUNTIE

Date of Birth: **11-03-1957** Sex: **M** Nationality: **CHINESE**

FIN: **G6450786P** Date of Issue: **27-07-2017** Date of Expiry: **01-07-2018**

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg **16 Dec 2010**

Licence No: G6450786P

NP 428A

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	04/07/2018 13:10						
Vehicle No. (For Motor)	SJN9331T								
Search									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5084829831-01	HE CHUNTIE	G26593519	GPC	drive CLASSIC	SJN9331T	SJN9331T	07/10/2017	06/10/2018
Continue									

 Policy Information


Policy No.	5084829831-01	Policyholder Name	HE CHUNTIE	Policyholder NRIC	G26593519
Address	574 GEYLANG ROAD SINGAPORE 389517				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy issue Date	25/09/2017	Effective Date	07/10/2017 00:00	Expiry Date	06/10/2018 23:59
Excess Type		All Claim Excess			
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0	Young/Inexperience Driver Excess	
Agent	THONG LEE TRADING PTE LTD	Agent Tel.	62569655	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

 Policyholder Mailing Address

Address 1	574 GEYLANG ROAD LOR 34	Address 2	SINGAPORE 389517	Address 3	
Address 4		Address Type	Singapore address	Post Code	389517
Unit No.		Related Policy Number	5084829831-01		

 Insured Object: SJN9331T

 Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
 				

Claim Handling

Exit

Accident MT/1001775

Policy No.	5084829831-01	Vehicle No.	SIN9331T	GST Registration No.	
Policyholder Name	HE CHUNTIE			Policyholder NRIC	G26593519
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	90590728	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	No
KPK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No
Accident Details					
Report Date	05/07/2018 14:37	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Major/Minor Road
Date of Accident	04/07/2018	Time of Accident hh:mm	13:10	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	ALONG LOR 32 GEYLANG				
Benefits					
Excess					
Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
GST Registered Information					
GST Registered	No	GST Registration Date			
GST Registration No.		GST Status Verified	Yes		
Modification History					

Policyholder Mailing Address

Address 1	574 GEYLANG ROAD LOR 34	Address 2	SINGAPORE 389517	Address 3	
Address 4		Address Type	Singapore address	Post Code	389517
Unit No.		Related Policy Number	5084829831-01		

OI Driver Info

Driver Name	HE CHUNTIE	Driver Type	Main Driver	Driver DOB	11/03/1957
Unnamed driver Name		Driver NRIC	G6490786P	Driving Experience	7
Register Date of Driver License	16/12/2010	Driver Age	61	Contact No.(Home)	0
Contact No.(Mobile)	90590728	Contact No.(Office)	0	Address 3	
Address 1	574 GEYLANG ROAD	Address 2	SINGAPORE 389517	Post Code	389517
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	
Declaration					
Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No		

Modification History

Claim 001

New

Claim Type *	OD-MD	Insured Name	HE CHUNTIE	Insured NRIC	G26593519
Contact No.(Mobile)	83023786	Contact No.(Home)		Contact No.(Office)	
Email Address		DI Vehicle Number	SIN9331T	TP Vehicle Number	SKK14111
Claim Description	SIN9331T / SKK14111 ON 4 Jul 2018				
Preferred Workshop Contact No.	81383333	Insured Liability *	Fully at Fault	Name of Preferred Workshop	YEW TEE AUTOMOBILE TECH P
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	GIA report	Received
Date Registered	05/07/2018 14:40	Claim Close Date		Date Received	05/07/2018 00:00
Report Taken By	Jackson				

Print AK letter

Save Submit

Attachment

Accident No.	MT/1001775	Claim No.	001																																			
Last Doc. Received	☒ Yes ☐ No	Upload Date	05/07/2018 14:45																																			
<table border="0"> <thead> <tr> <th>Part *</th> <th>Category *</th> <th>Confidential</th> <th>Urgency *</th> <th>Description *</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>				Part *	Category *	Confidential	Urgency *	Description *																														
Part *	Category *	Confidential	Urgency *	Description *																																		
Resend Email Send Message Upload																																						

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description	Msg Sent? (CO)	Action
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:45	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:45	SAS	Normal	SAS 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:44	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:43	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:43	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:43	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:43	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:43	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5		Edit

	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:42	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 05 Jul 2018 14:41	Photos	Normal	Photos 2018-7-5	Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
		Display in New Window	Scan and uploading	

ASS. REC. BY:

REF:

Assessor:
Mobile: YES / NO

ASSIGNMENT (IDAC)

By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle: ()
a) Motorcar ()
b) M/cycle ()
c) Bicycle ()
- 2) Vehicle hit ?? ()
a) Pedestrian ()
b) Animal ()
- 3) Vehicle hit Road Side Objects: ()
a) Govn Property ()
(Eg. signboard, barrier, tree etc)
b) Road Work Object ()
c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God: ()
a) Fallen Object ()
b) Flood ()
c) Other: _____
- 6) Parked & Found Damaged: ()
a) Vandalism ()
b) Hit by Moving Object ()
- 7) Theft Case ()
a) Stolen ()
b) Damage found when recovered ()
- 8) Fire ()
a) Whilst driving ()
b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SJN 9331 T Yr Regn: 5 Mar / 2009

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / M/T
/ Truck / Trailer or

Make & Model: Hyundai Avante 1.6A c.c. 1591

Colour: Grey Transmission Type: (Auto) / Manual

Eng/No: _____ Sp. Reading: 169225

C/No: KMHDU41BR9U707607

Gen. Cond: Good / (Fair) / Poor / Burnt or

Steering: (Order) / Jammed / Leaked / Burnt or

Brake: (Order) / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 215/45R17 - Hankook
R: Nexen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or As above

Front	Rear
R/Bal. <u>3</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>3</u> mm	L/Bal. <u>5</u> mm

Parallel Import: Yes (No) Towed-In: Yes / No

Repair Type: (LS) / I.B.I Towing Required: (Yes) / No

No of Repair Days: 7 Vehicle in Idac: (Yes) / No

D.O.I. 5/7/2018 Time: 4.05 pm

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
e. Animal () f. Govn Object () g. Road Work Object ()
h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	DD	-	
1002	991887	Frt Number Plate Base	BR	-	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR	-	
1005	992341	Frt Bumper Clips	NEC	-	6
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS	-	2
1008	991433	Frt Bumper Reinforcement	BT	-	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA	-	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRA	-	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	INT	-	
1018	991355	Frt RH Bumper Fog Lamp Cover	INT	-	
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA	-	
1022	991328	Frt Grille Emblem	NEC	-	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BR	-	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel	BT	-	
1029	995153	Frt LH Headlamp Assy	CRA	-	
1030	991821	Frt RH Headlamp Assy	CRA	-	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BUC	-	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	BT	-	
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge	BT	-	2
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	BT	-	
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator	DD	-	
1053	992738	Radiator Cowling	CRA	-	
1054	992742	Radiator Fan Assy	INT	-	
1055	992745	Radiator Fan Clutch	INT	-	
1056	992758	Radiator Hose Top	DD	-	
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct	CRA	-	
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose	CRA	-	
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: STN 93217

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Emblem			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Emblem			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sucker			
		Head Lamp Lower Support			
		Frt RH Door			

Sticker
Headlamp Lower Support BT
RH RH Door SCR R

Claim Handling

Task Transfer Exit

Accident MT/1001775

LOG SAVE SUB

Policy No.	S084829831-01	Vehicle No.	SIN9331T	GST Registration No.	
Policyholder Name	HE CHUNTIE			Policyholder NRIC	G26993519
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	90590728	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	05/07/2018 14:37	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Major/Minor Road
Date of Accident	04/07/2018	Time of Accident hh:mm	13:10	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	ALONG LOR 32 GEYLANG				

Benefits

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	574 GEYLANG ROAD LOR 34	Address 2	SINGAPORE 389517	Address 3	
Address 4		Address Type	Singapore address	Post Code	389517
Unit No.		Related Policy Number	S084829831-01		

DI Driver Info

Driver Name	HE CHUNTIE	Driver Type	Main Driver	Driver DOB	11/03/1957
Unnamed driver Name		Driver NRIC	G6450786P	Driving Experience	7
Register Date of Driver License	16/12/2010	Driver Age	61	Contact No.(Home)	0
Contact No.(Mobile)	90590728	Contact No.(Office)	0	Address 3	
Address 1	574 GEYLANG ROAD	Address 2	SINGAPORE 389517	Post Code	389517
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any Injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Ng Hak Joo

LOG SAVE SUB

Claim Type	OD-MD	Insured Name	HE CHUNTIE	Insured NRIC	G26993519
Contact No.(Mobile)	83023786	Contact No.(Home)		Contact No.(Office)	
Email Address		OT Vehicle Number	SIN9331T	TP Vehicle Number	SKX14113
Claim Description	SIN9331T / SKX14113 ON 4 Jul 2018			Name of Preferred Workshop	YEW TEE AUTOMOBILE TECH PT
Preferred Workshop Contact No.	81383333	Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	GIA report	Received
Date Registered	05/07/2018 14:47	Claim Close Date		Date Received	05/07/2018 20:00
Report Taken By	Jackson	Workshop Repairer		Total Loss but Repaired	
☒ Print Ack letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval		Reason	
Remarks			

damage assessment Attachment

Vehicle Info

Vehicle Make	HYUNDAI	Vehicle Model	AVANTE	Engine Capacity	
Date of Registration	05/03/2009	Classis No.	KMHDDU41BR9U707607	Parallel Import *	☐ Yes ☒ No
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Survey Current Status	
Type of Tender *	Own Damage	Assessor Name *	SIMON		
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	

Remark:

REMARK: NO OF REPAIR DAY: 7 DAYS. 1 X AIR CON SUCTION PIPE (LOW PRESSURE) - UNCONFIRM. 1 X AIR CON DISCHARGE PIPE (HIGH PRESSURE) - UNCONFIRM. 1 X AIR CON LIQUID PIPE - UNCONFIRM. 1 X AIR DUCT - REPLACE. 1 X AIR CLEANER ASSY - UNCONFIRM. 1 X ENGINE UNDER COVER - REPLACE. 1 X FRT LH FENDER EMBLEM - REPLACE. 1 X FRT RH FENDER EMBLEM - REPLACE. 2 X HEADLAMP LOWER SUPPORT - REPLACE.

Damage Listing

Find a Part

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
Not Applicable	1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
ABS	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace	X
ABSORBER	3	16000101	BUMPER (FRONT)	1	Replace	X
ACCELERATOR	4	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
ACTUATOR	5	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
ADVERTISMENT STICKER	6	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
AIR BAG	7	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace	X
AIR BLOWER	8	16005901	BUMPER SPONGE (FRONT)	1	Replace	X
AIR BOX	9	16003201	BUMPER GRILLE (FRONT)	1	Replace	X
AIR CHAMBER BOX	10	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Replace	X
AIR CLEANER	11	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace	X
AIR COMPRESSOR	12	27100101	GRILLE (FRONT)	1	Replace	X
AIR CON	13	27100801	GRILLE EMBLEM (FRONT)	1	Replace	X
AIR CON (VAN)	14	41300101	SUPPORT PANEL (FRONT)	1	Replace	X
AIR COOLER	15	28500101	HORN (LEFT)	1	Unconfirm	X
AIR DISTRIBUTOR	16	15600101	BRACE PANEL (FRONT)	1	Replace	X
AIR FILTER	17	27700101	HEAD LAMP (LEFT)	1	Replace	X
AIR FLOW	18	27700102	HEAD LAMP (RIGHT)	1	Replace	X
AIR GRILLE	19	149001	BONNET	1	Replace	X
AIR HORN	20	14903401	BONNET LOCK (LOWER)	1	Replace	X
AIR INTAKE	21	149029	BONNET INSULATOR	1	Unconfirm	X
AIR RESONATOR BOX	22	14902201	BONNET HINGE (LEFT)	1	Replace	X
AIR THROTTLE BODY AND SENSOR	23	14902202	BONNET HINGE (RIGHT)	1	Replace	X
ALARM	24	112023	AIR CON CONDENSER	1	Replace	X
ALTERNATOR	25	344001	RADIATOR	1	Replace	X
ALUMINIUM PANEL- SIDE	26	344005	RADIATOR COWLING	1	Replace	X
AMPLIFIER	27	344008	RADIATOR FAN	1	Replace	X
ANTENNA	28	344011	RADIATOR FAN CLUTCH	1	Replace	X
ANTI ROLL	29	34402802	RADIATOR HOSE (TOP)	1	Replace	X
APRON	30	34402801	RADIATOR HOSE (BOTTOM)	1	Unconfirm	X
ARCH	31	11001302	AIR CLEANER HOSE (CENTRE)	1	Replace	X
ARM REST	32	141001	BATTERY	1	Unconfirm	X
ASH TRAY	33	141007	BATTERY TRAY	1	Unconfirm	X
AUTO CLUTCH	34	26600102	FUSE BOX (CENTRE)	1	Replace	X
AUTO COOLER PIPE	35	454012	WIPER WASHER TANK	1	Replace	X
AUTO CRUISE MOTOR	36	454014	WIPER WASHER TANK MOTOR	1	Replace	X
AUTO TRANSMISSION	37	25400102	FENDER (FRONT LEFT)	1	Repair	X
AXLE	38	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
BACK REST (MC)	39	25400103	FENDER (FRONT RIGHT)	1	Repair	X
BACK SEAT	40	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
BALANCER	41	454009	WIPER PANEL GARNISH	1	Replace	X
BATTERY	42	23300202	DOOR (FRONT RIGHT)	1	Repair	X

Save Submit

LKK Paya Ubi

From: Ng Hak Joo <hakjoo.ng@income.com.sg>
Sent: Friday, 6 July 2018 5:34 PM
To: LEE SHENG AUTO P.L
Cc: LKK Paya Ubi
Subject: FW: SJN9331T UNDER OD CLAIM: MT/1001775

Importance: High

Dear Ms Lee of LEE Sheng

We spoke, please tow this vehicle from Idac and contact owner Mr HE Chuntie at 90590728 when the repair is done, excess \$642.

Our Ref: MT/CA/OD/051/1001775-001/NHJ

06 Jul 2018

LEE SHENG AUTO PTE. LTD.

1 KAKI BUKIT AVENUE 6

BLK C #01-58 AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

Dear Sir

CLAIM NUMBER: MT/1001775-001

REPAIR OF VEHICLE NUMBER: SJN9331T

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 06 Jul 2018

Make: HYUNDAI

Model: AVANTE

Estimated Repair Days: 7

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Ng Hak Joo at 64307890 or email us at motor@income.com.sg.

Yours sincerely

Low Choo Mee

Senior Manager

Motor Insurance

Ng Hak Joo

Claims Executive, Motor Insurance

T +65 6430 7890

www.income.com.sg

 income
made different



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SJN 9331T Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Lee Sheng Auto

Collection Date: 7/7/18 Time: 11:18 pm with Keys: Yes / No

Tow Truck No: AN 82 Tow Man: AN 82 NRIC: 69209307

Signature: [Signature]

For office use

Attended by: Shan Hui

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In
Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____