15/5/2010

INS. CASE OWNER: CC 3/EQI1801 nk4, Nubb | LKK: IDAC:

ASSIGNMENT

Surveyor: NKZ DOI: 4/7/18 Date / Time : 4/7/18

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No. : YP 794L Claim No. :

Name of Insured : Policy No. :

Insured Tel No. : HP: Make / Model :

Excess Sec II :S$ D.O.A : 7/7/18 Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If **NO**, Driver Name / Age : OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % **Final ? Yes / No**

SHD 6617K → → →

INSRS:
WSP: COPIE
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	SHD 6617K-Y YP 794L-Y	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	**Handler** / **Typist**
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S$		
Loss of Rental (LOR):	S$	(days)	
Loss of Use (LOU):	S$	($ x days)	
Loss of Income (LOI):	S$	($ x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐	LOR + LO ☐ **[Tick only one]**	
GIA/LTA Search	S$		
Medical:	S$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S$		3) Survey fee:
Total:	**S$**	**Global Sum S$:**	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

NA2 REF: EQ

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop / s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

	N/S	O/S
X		

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHD 6617R Regn: 9 APR 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HYUNDAI I40 CC: 1685

Colour: BLUE A/C: Insured / Std / NI / NA

Sp.Reading: 554,973 Radio: Insured / Std / NI / NA

Eng No:

Ch No: KMHLB41UMFU067920

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or WESTLAKE

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	3/7/18	D.O.I.	4/7/18

Survey held at CDGE LOYANG

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	EQ L/S

Date/Time File Passed: : Preli. Report : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee

Transportation

Date/Time File Returned:

Add Fee: : Site Insp $: Interpret $: Tech Fee $: Weekend $

Photos

Others

Report Format :

Lump Sum / I.B.I: $

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
6 Defu Avenue 1 Singapore 539537

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305183056

ISTOMER R/MS COMFORT TRANSPORTATION PTE LTD ISTOMER NO. 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 L. (R) 65508755 (O) (P) SCOUNT CARD NO.	REGN NO.: SHD6617R MAKE : HYUNDAI MODEL I-40 YR OF MANU. 09.04.2015 CHASSIS CODE KMHLB41UMFU067920	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 03.07.2018 12:20 TARGET DATE COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 03.07.2018
NATURE: 3P 03.07.2018

S/NO	LABOR CODE	DESCRIPTION

ECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

owledgement Slip

e:
lo.:
cle No.: SHD6617R CHIANG

e of Service Advisor

Signature/Date

e returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHD6617R

Name of Service Advisor

Date

To be kept by Security Guard