


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB8033M  
 Ref. No : BUS/06/18/5056  
 Reg. Date : 01/01/1900  
 Vehicle Type : BUS -17M  
 Make : MAN  
 Model : MAN A24  
 Name of Driver : Ten Yok Sooi  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 27/06/2018 07:35:00 AM  
 Accident Reported Date / Time : 04/07/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : EQ Ins Co Ltd  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC,if any :  
 TP: SLJ448Y (EQ INSURANCE)  
 BUS RIGHT REAR PORTION DAMAGED  
 Prepared Date : 04/07/2018 03:47:41 PM



Sathya Sai  
5/7/2018

2 days

- Part by Part

- Photo before paint

- LKK Auto Cons** (to be filled by the Repairer)
- To resurvey before the repair starts
  - To display damaged parts during survey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modifications allowed
  - Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0  
Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	2,120.00	0.00
Total Spray Painting Charges :	1,900.00	0.00
Total Material Charges :	0.00	0.00
Other Charges :	0.00	0.00
<b>TOTAL :</b>	<b>4,020.00</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>0.00</b>	<b>0.00</b>
No. of Repair Days :	5.00	<del>0.00</del> 2 day
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	04/07/2018 05:10:43 PM	01/01/1900 12:00:00 AM




Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/07/2018 05:10:43 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :



**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR RHS PORTION	2,120.00	<del>0.00</del> 1060
<b>Total Labour</b>	<b>2,120.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,900.00	<del>0.00</del> 1060
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,900.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
<b>TOTAL MATERIALS</b>										
<b>TOTAL MATERIALS(Discounted)</b>							<b>0.00</b>	<b>0.00</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									