

22/03/2001

ASS. REC. BY:

REF: CS3/MSG18012271/G24d302

Special Instruction: ✓

Surveyor:
menmen

GW Bieng

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

17/18 @ 3-47pm

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 432 K

Insured:

SLE 2773 X

at Workshop in/s:

Alpha Car Services

Tel:

8229 7328

of

B1K C Kaki Bukit Ave 6 # 01-59

Policy No:

B28967530QMY

Claim No:

563207

Sum Insured:

Excess:

11/07/2018

ASS. REC. BY:

REF: CS3/MSG18012271/G24d3e2 Special Instruction: ✓

Surveyor
menimen

Guo Bing

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

1/7/18 @ 3:47pm

Estimated Cost:

Bill to:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJK 432 K

Insured:

SLE 2773 X

at Workshop n/s:

Alpha Car Services

Tel:

8229 7328

of

B1K C Kaki Bukit Ave 6 # 01-59

Policy No.:

B28967530QMY

Claim No.:

563207

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/07/2018

CA / REV / REP. / REV 24 HRS

lup)

H.O.D. Endorsement:

Date/Time:

5/7/18 @

Person Contacted:

Cailing

Vehicle: IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJK 432K - CS3/A1G14010099/A 1r/b3w2

D.O.A: 28/5/2014

SLE 2773X - X

(OB#1/13) wef

PRS

REF: MSIG

B 5389 w

ASS. REC. BY: X62

ASSIGNMENT

(-2018)

From: Date: 5/7/18

Veh No: SJK432K Yr Regn: 02 Oct 2008

Estimated Cost:

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SJK 432K

Make: Toyota Altis 1.6 c.c 1598

at Workshop m/s Alpha Car Services

Colour: Blue A/C: Insured / Std / NI / NA

of Blk C, Kaki Bukit Ave 6 # 01-59

Sp. Reading: 237194 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: MR053 ZEE 106/19265

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)

Tyre Size: F: 195/65 R15

R: "

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Bal. or Market Value: \$13K

Front R/Bal. 6 mm Rear R/Bal. 6 mm

IDAC Accident Rport: Consistent?: Yes or No

L/Bal. 6 mm D.O.A. 05-07-18

GIA / PR Seen: Consistent?: Yes or No

L/Bal. 6 mm D.O.I. 05-07-18

Est. Repairs: 4 days Res.: Yes or No

Survey held at w/s 5:15pm

Lum Sum: 20 % 3 Val.: Yes or No

Des. of Damages: Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS (up) Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date: Person Contacted:

Date / Time Action / Instruction

\$2000 - \$3000

7/7/18 Submit PRS report.

RECEIVED 09 JUL 2018

Date/Time, File Pass to?

: Preli. Report

Days Of Repair:

1)

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

120
50
10
180

Report Format :

Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Submitter	Adj Submitted	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2018		04 Jul 2018 15:00 Asst				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All
CLAIM SUBFOLDER TRACKING								
Insured:	EURKY RICKY, ID: S74278888			[Created by insurer]				
Main Claimant:	AIG AUTO, Co. Reg. No.: 50101210			Tel: +65 6256 2888, Email: eurcky@yahoo.com.sg				
Vehicle Reg. No.:	SJK1221			Date of Loss:	01/07/2018 11:00 - :59 [116 Months and 29 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP 563207			Policy/Cover No.:	B28967530QMY (Comprehensive) Coverage: 15/07/2017 - 14/07/2018			
Vehicle Reg. No. (Insured):				Policy No. (Insured):				
Repairer:	Alpha Services Pte Ltd (HQ)			Kaki Bukit Ave 5, #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258				
Handling Insurer:	Meriman Insurance (Singapore) Pte Ltd			Tel: 65 6256 2888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]				
Adjuster:	Lombard Associates Pte Ltd			Tel: 6256-3561 ... [Advice due 05/07/2018]				
Driver/Custodian (Insured):	EURKY RICKY (43 / Male)			S74278888 - Tel: 6597931649				
Adj Asg. Remarks:	Lombard Contact : Ms Cailin			328				
ASSOCIATED TASKS								
There are no associated tasks.								
View All Compose Case Mail								
ALL ASSOCIATED TASKS								
Due Date	Type	Task Group	Object	Assigned By	Completed On	Created On	Done?	
No results.								
View All Search Tasks Create New Task Complete								



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18012271/Gz4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 05-07-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLE 2773X	Veh. Inspected	SJK 432K
Policy No.	B28967530QMY	Coverage (\$)	0.00
Claim No.	563207	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	05/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/07/2018	Inspection Date	05/07/2018
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/07/2018 12:47
Date Of Accident	01/07/2018 11:45
Exact Location Of Accident	312A SUMANG WALK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK432K
Insured/Policyholder	
Name Of Registered Owner	AIRVEH AUTO
Co Reg No	53355389W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5101262823
Cover Note Number	

Driver

Name of Driver	OH EUNICE
NRIC No	S8814655G
Date Of Birth	30/04/1988
Occupation	OUTDOOR
Date Of Driving Pass	02/11/2006
Driving Experience	11 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91111177
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 181 #04-255 BISHAN STREET 13
Postcode	570181
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE2773X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RICKY EU KOK KEONG
NRIC/Passport Number	S7427888D
Contact Number	97931649
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

2. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms; the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: _____


Driver's Signature
(If driver is not the policyholder)
Date & Time: _____


Reporting Centre Personnel's Signature
Name: Quayyapoo 11/01/11
NRIC/IN No.: 751 878 6607
Phone: 6734 1234
E-mail: report@accident.gov.sg

SKETCH PLAN



312A Sumang Walk.

vehicle A: SJK 432K

vehicle B: SLE 277BK

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stopping stationary and all of a sudden a car on my right just reverse and hit into me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:



[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

ANVEH AUTO (M) Sdn Bhd

Reporting Centre Personnel's Signature

Name

NRIC/HR No.:

ANVEH AUTO (M) Sdn Bhd
100-01-412105

100-01-412105

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License



> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5389W
Vehicle Details	
Vehicle No.:	SJK432K
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	3ZZ4796384
Chassis No.:	MR053ZEE106119265
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	02 Oct 2008
First Registration Date:	02 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$16,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Oct 2018
PARF Rebate Amount:	\$8,042.00
Intended COE Rebate Details	
COE Expiry Date:	01 Oct 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$9,501.00
COE Rebate Amount:	\$224.00
Total Rebate Amount:	\$8,266.00

The information contained herein is correct as at 06 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2018		04 Jul 2018 15:47 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	EU KOK KEONG RICKY, ID: S7427888D, Tel: +6597931649, Email: eurcky@yahoo.com.sg		
Main Claimant:	AIRVEH AUTO, Co. Reg. No.: 53355389W		
Vehicle Reg. No.:	SJK432K	Date of Loss:	01/07/2018 11:00 - :59 [116 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 563207	Policy/Cover Note No.:	B28967530QMY (Comprehensive) Coverage: 15/07/2017 - 14/07/2018
Vehicle Reg. No. (Insured):	SLE2773X	Policy No. (Claimant):	
		Excess:	
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 05/07/2018]		
Driver/Custodian (Insured):	EU KOK KEONG RICKY (43 / Male), NRIC: S7427888D, Tel: +6597931649		
Adj Asg. Remarks:	Liability 50/50 Contact : Ms Cailing at 8229 7328		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SJK432K (563207)**
[SLE2773X]
TP
AIRVEH AUTO
Jul 1 2018 11:00AM
[EU KOK KEONG RICKY]
Alpha Car Services Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser		
Assessment Reports		1 per page v <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/07/18 10:28	Accident Statement <small>From: SC - Reg. No: SLE2773X, Claimant: EU KOK KEONG RICKY</small>	1 Load HTM	<input type="checkbox"/>
Photos/Images		3 per page v <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
2	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
3	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
4	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
5	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
6	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
7	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
8	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
9	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
10	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
11	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
12	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
13	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
14	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
15	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
16	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
17	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
18	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
19	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
20	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
21	07/07/18 11:00	General View	1 Load JPG	<input checked="" type="checkbox"/>
Documentation		1 per page v <input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/07/18 10:28	SJK432K E-FILE REPORT <small>From: SC - Reg. No: SLE2773X, Claimant: EU KOK KEONG RICKY</small>	1 Load PDF	<input type="checkbox"/>
2	04/07/18 11:14	PRI from Chia S Arul LLC	1 Load PDF	<input type="checkbox"/>
3	04/07/18 11:14	Survey Disagree on SJE - assign AIS	1 Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012271/GZ4D3E2

Date: 09/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28967530QMY
Claimant Vehicle No : SJK432K **Insured Vehicle No :** SLE2773X
 Date of Loss: 01/07/2018 Nature of Claim: TP Claim No: 563207

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK432K**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4796384
 Reg. Date: 02/10/2008 (Man. Year: 2008) Chassis No: MR053ZEE106119265
 Colour: Blue Odometer: 237194 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/07/2018
 Date Inspected: 05/07/2018 Inspected At: Alpha Car Services Pte Ltd (HQ)
 Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit
 Autobay
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK432K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >