

23/03/2002

ASS. REC. BY:

REF:

CS/EOI18012278/Bqd302

Special Instruction:

Surveyor: T.G. Lim

ASSIGNMENT (Office)

From (Person): Joel Goh

of

EOI

Date/Time:

5/7/18 @ 9:02am

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SG2 7036G

Insured:

SJR 9797L

at Workshop m/s

KGC workshop

Tel:

8189 2986

of Blk 176, Sin Ming Drive #02-04

Policy No:

Claim No:

DM18H001680-JG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 02/07/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 9:36am @ 5/7/18

Person Contacted:

Joyce

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SG2 7036G - NA/INC 08030329/pl
	SJR 9797L - X.
	Mr Lim finalised with Joyce LS B5300, 8 days.
	(Red @ 5777.75, 52%)

DOA: 13/11/2008

(08/11/13) wef

ASS. REC. BY:

REF: EQI

## ASSIGNMENT

From: Date: 05/07/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGZ 7036 G

at Workshop m/s KGC Workshop

of Blk 176, Sin Ming Drive #02-04

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record) Joyce: 81892986

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGZ 7036 G Yr Regn: 14 NOV 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios c.c. 1497

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 200852 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053HY9305031547

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45R16

R: 205/45R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 02/07/18 D.O.I. 05/07/18

Survey held at KGC Workshop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 JUL 2018

RECEIVED 27 JUL 2018

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: 8

1) 15/7 tympor

☐: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee: 230

2)

Add Fee: ☐: Site Insp (\$ )

Transportation: \$ + RS. \$ SI

Report Format: TP

Lump Sum / I.B.I: (\$ 5300 )

☐: Interview (\$ )

Photos

☐: Tech. Invs (\$ )

Others

☐: Weekend (\$ )

TOTAL

230



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQ118012278/Bqd3

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 05-07-2018



Code : EQI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 9797L	Veh. Inspected	SGZ 7036G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	05/07/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	02/07/2018	Inspection Date	05/07/2018
Survey held at	KGC WORKSHOP PTE LTD 176 SIN MING DRIVE, SIN MING AUTOCARE #02-04 SINGAPORE 575721		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Nivitha (LKK Auto)

---

**From:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Sent:** Thursday, 5 July 2018 9:02 AM  
**To:** assignments  
**Subject:** FW: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SJR9797L(EQ) // Our ref: L.18.1015.It(jt)  
**Attachments:** SGZ7036G.pdf; SJR9797L.pdf

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joel Goh [mailto:[joel.goh@eqinsurance.com.sg](mailto:joel.goh@eqinsurance.com.sg)]  
**Sent:** Thursday, 5 July, 2018 8:52 AM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SJR9797L(EQ) // Our ref: L.18.1015.It(jt)

Dear LKK

attached both parties accident report for your attention.

Best Regards,

**Joel Goh**

Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify*

---

**From:** Joel Goh  
**Sent:** Thursday, July 5, 2018 8:51 AM  
**To:** 'Kuru & Co'  
**Cc:** Admin A  
**Subject:** RE: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SJR9797L(EQ) // Our ref: L.18.1015.It(jt)

**Without Prejudice**

Dear Irene

Thank you for your confirmation.

Dear LKK

Please assist on this PRS.

Best Regards,

**Joel Goh**

Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify*

---

**From:** Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]

**Sent:** Wednesday, July 4, 2018 4:53 PM

**To:** Joel Goh

**Subject:** Re: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SJR9797L(EQ) // Our ref: L.18.1015.lt(jt)

Hi Joel

We refer to your fax of 04.07.2018.

Our client is agreeable to the following surveyor(s) as the SJE: LKK - T G LIM

Please arrange for your surveyor to survey our client's vehicle at the following address:

**KGC WORKSHOP PTE LTD**

Blk 176 Sin Ming Drive #02-04 Sin Ming Autocare

Singapore 575721

Tel: Joyce 81892986

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

On Wednesday, 4 July 2018, 4:03:58 PM SGT, Joel Goh <[joel.goh@eqinsurance.com.sg](mailto:joel.goh@eqinsurance.com.sg)> wrote:

### Without Prejudice

Dear Lena

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.




Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

<b>1) AJAX Inspection Services Pte Ltd</b>  Tel: 6255 0808  Fax: 6849 9155  Contact person : Joey/Joseh	<b>2) Automobile Inspection Services Pte Ltd</b>  Tel: 6286 0155  Fax: 6284 1539  Contact Person: Sophia
<b>3) LBS Automotive Appraisal Pte Ltd</b>  L.B.S. Auto Consultants Pte Ltd  Tel: 6281 6690 / 62832866  Fax: 6281 8748  Contact Person: Amy/ Grace	<b>4) Priority Services</b>  Tel: 62934822  Fax: 62963283  Contact Person: Sharon Kho
<b>5) RT Appraisal Pte Ltd</b>	<b>6) LKK Auto Consultants Pte Ltd</b>

Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	Tel: 6256-3561 Fax: 6741-4108
<b>7) Kelvin Automotive Appraising Services</b> Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	<b>8) Automotive Appraiser &amp; Surveying Services</b> Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
<b>9) JP Knights Pte Ltd</b> Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,	
<b>Joel Goh</b>	
Executive   Claims	
	
<b>EQ Insurance Company Limited</b>	
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	
did 65 6500 6772   tel 65 6223 9433 ext 772   fax 65 6223 4190	
<a href="http://www.eqinsurance.com.sg">www.eqinsurance.com.sg</a>	
 A Member of Citystate	
<i>Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify i</i>	

---

**From:** Kuru & Co [mailto:kurulegal@yahoo.com.sg]

**Sent:** Wednesday, July 4, 2018 9:05 AM

**To:** EQI PRS

**Subject:** PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SJR 9797L // Our ref: L.18.1015.lt(jt)

Dear Sirs,

**ACCIDENT INVOLVING SGZ 7036G AND SJR 9797L ON 02.07.18**

**AT/ALONG MOULMEIN ROAD - INFRONT OF VELOCITY**

**NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **Ng Beng Sian, Almen**, whose vehicle registration number **SGZ 7036G** was damaged in the above accident.

A copy of the **Police report** filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thanks / Rgds,

Lena

Kuru & Co  
150 South Bridge Road  
#04-06 Fook Hai Building  
Singapore 058727  
Tel: 6532 2009  
Fax: 6532 2007



## Shiau Chan (LKKAUTO)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Thursday, 19 July 2018 5:55 PM  
**To:** Shiau Chan (LKKAUTO); assignments  
**Cc:** SUR  
**Subject:** RE: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SJR9797L(EQ) // Our ref: L.18.1015.lt(jt)

Dear Shiau Chan

Our reference: DM18H001680-JG

Best Regards,

Joel Goh  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]  
**Sent:** Thursday, July 19, 2018 5:41 PM  
**To:** Joel Goh; assignments  
**Cc:** SUR  
**Subject:** RE: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SJR9797L(EQ) // Our ref: L.18.1015.lt(jt)

Dear Joel,

Kindly provide us the claim number of above mentioned.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, 5 July 2018 9:41 AM  
**To:** 'Joel Goh' <joel.goh@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: SJR9797L(EQ) // Our ref: L.18.1015.lt(jt)

## Shiau Chan (LKKAuto)

---

**From:** joyce@kgcworkshop.com.sg  
**Sent:** Friday, 27 July 2018 4:37 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: FINALISE OF VEHICLE SGZ 7036G (DOA: 02/07/2018)

Hi Shiau Chan,

Offer accepted.

Thank you

Thank you

Regards,

**Joyce**

*Claims Executive*

**KGC WORKSHOP PTE LTD**

(Headquarter) 176 Sin Ming Drive, Sin Ming Autocare, #02-04 (Singapore 575721)

Tel (65) 6453 6279 | F (65) 6456 5410 | M (65) 8189 2986

E [joyce@kgcworkshop.com.sg](mailto:joyce@kgcworkshop.com.sg)



*Like our Facebook page today!*

[www.facebook.com/kgcworkshop](http://www.facebook.com/kgcworkshop)

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Friday, 27 July 2018 3:38 PM  
**To:** joyce@kgcworkshop.com.sg  
**Subject:** FINALISE OF VEHICLE SGZ 7036G (DOA: 02/07/2018)

Dear Joyce,

WITHOUT PREJUDISE

Please find the attached.

Offer Lump Sum \$5,300.00 and 8 repair days.

Kindly confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1673A
Vehicle Details	
Vehicle No.:	SGZ7036G
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1NZX634878
Chassis No.:	MR053HY9305031547
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,466.00
Original Registration Date:	14 Nov 2007
First Registration Date:	14 Nov 2007
Transfer Count:	5
Actual ARF Paid:	\$13,713.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$18,279.00
Total Rebate Amount:	\$18,279.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Jul 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/07/2018 13:30
Date Of Accident	02/07/2018 18:30
Exact Location Of Accident	MOULMEIN RD (IN FRONT OF VELOCITY)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGZ7036G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG BENG SIANG, ALMEN
NRIC No	S8221673A
Email Address	ALMEN_NG82@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90095042
Alternative Phone No	OFFICE-90095042

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-005648
Cover Note Number	

### Driver

Name of Driver	NG BENG SIANG, ALMEN
NRIC No	S8221673A
Date Of Birth	01/07/1982
Occupation	INDOOR
Date Of Driving Pass	23/04/2003
Driving Experience	15 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90095042
Fax Number	
Contact Number	OFFICE-90095042
EEmail Address	ALMEN_NG82@HOTMAIL.COM

Address	BLK 712 JURONG WEST ST 71 #07-167
Postcode	640712
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 391 NEW BRIDGE ROAD POLICE CANTONMENT COMPLEX BLOCK A , POSTCODE: 088762 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2369999 - FAX NO: 62268438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR9797L
Vehicle Make/Model/Colour	FIAT PUNTO/BRAVO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GERALD GOH QI WEN
NRIC/Passport Number	S8916122C
Contact Number	94897809
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name NG BENG SIANG, ALMEN

Approximate Age

Injuries Sustain BACK PAIN

Injured person in which vehicle? SGZ7036G

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode


**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time: 3/7/18  
u50lm

  
Driver's Signature  
(If driver is not the policyholder)

Date & Time: 1150lm  
3/7/18


  
Reporting Centre Personnel's Signature

Name: 3/7/2018 CA  
NRIC/FIN No.: 11Am



### Sketch Plan Pg. 2

### SKETCH PLAN



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Please refer to the police report

\* Repair at other workshop.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_  
Company Chop (if applicable) \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Shuman  
Reporting Centre Personnel's Signature  
Name: 3/7/19  
NRIC/FIN No.: 11A





**SINGAPORE  
POLICE FORCE**



T/20180703/2006

1 of 3

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

Report No. T/20180703/2006

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 03/07/2018 02:40		Vide Report No.:		Station Diary No.: 9	
<b>Informant's Particulars</b>					
Name of Informant: NG BENG SIANG, ALMEN			Address: APT BLK 712 JURONG WEST STREET 71 #07-167 SINGAPORE 640712		
ID Type / ID No.: NRIC NO / S8221673A			Contact No.: Home/Office: Mobile: 90095042		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 36	Date of Birth: 01/07/1982	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: SALES AND MARKETING EXEC			Driving Licence Information: Class: Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/07/2018 18:30	Type of Location: X-Junction
Location: Along Road 1 MOULMEIN ROAD  cross junction				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGZ7036G	Car	TOYOTA	VIOS E AUTO	Silver	Seriously Damaged	0
SJR9797L	Car				Slightly Damaged	0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGZ7036G	EQ INSURANCE COMPANY LTD.	DMPPHQ17-005648	25/10/2017	13/11/2018



**SINGAPORE  
POLICE FORCE**



T/20180703/2006

2 of 3

Report No. T/20180703/2006

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

**CONTINUATION OF REPORT**

**Brief Details.**

On the above mentioned date, time and location, I was driving my vehicle SGZ7036G along Moulmein Rd. At the cross junction, upon making a left turn, I stopped as to let pedestrian crossing, however a vehicle behind me had hit onto my rear bumper. Both me and the other driver parked our vehicle to one side so as not to caused any obstruction. We then exchanged particulars. My rear bumper dropped off due to the impact. Both myself and the other driver did not sustain any visible injuries however due to the impact, my back hurts and I had it checked at Singapore General Hospital and was given 4 days of medical leave.



**SINGAPORE  
POLICE FORCE**



T/20180703/2006

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

3 of 3

Report No. T/20180703/2006

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
A /  
Sr Staff Sgt NORIYANTI BINTE MUHAMAD

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
03/07/2018 02:40

Officer In Charge Of Case:  
TP / AEIT /  
SSI 2 SITIMARSITA BINTE BOHARI  
Contact No.: 65476219

Classification Of Case:

Authentication Stamp  
NP168



# KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

Co.Reg.No.: 201719986M

Ng Bemg Siang, Almen  
176 Sin Ming Drive, Sin Ming Autocare  
# 02-04  
Singapore 575721

TP 180704  
Date 03-07-18  
No of Page : 1/3

Registraion No : SGZ 7036 G

Model : Toyota Vios

Accident Date : 02-Jul-18

Chassis No: MR053HY9305031547

Our Ref: TP 180704

Engine Capacity : -

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Boot	\$ 628.00	\$ <del>RCR</del> 628.00 ✓
2	1	Rear Boot 'Vios' Emblem	\$ 55.00	\$ <del>REC</del> 55.00 ✓
3	1	Rear Boot Toyota Emblem	\$ 59.00	\$ <del>REC</del> 59.00 ✓
4	1	Rear Boot Garnish (Long)	\$ 290.00	\$ <del>NN</del> 290.00 X
5	2	Rear Boot No. Plate Lamp	\$ 65.00	\$ <del>NN BRO</del> 130.00 X
6	2	Rear Boot Hinge	\$ 95.00	\$ <del>BT</del> 190.00 ✓
7	1	Rear Boot Lock	\$ 150.00	\$ <del>BT</del> 150.00 ✓
8	1	Rear Boot Weatherstrip	\$ 220.00	\$ <del>Cut</del> 220.00 ✓
9	1	End Panel Garnish	\$ 255.00	\$ <del>Cut</del> 255.00 ✓
10	1	End Panel	\$ 689.00	\$ <del>BT</del> 689.00 ✓
11	1	Rear Bumper	\$ 488.00	\$ <del>CRU</del> 488.00 ✓
12	2	Rear Bumper Reflector	\$ 95.00	\$ <del>BRO</del> 190.00 ✓
13	2	Rear Bumper Retainer	\$ 100.00	\$ <del>BRO</del> 200.00 ✓
14	1	RHS Tail Lamp	\$ 380.00	\$ <del>BRO</del> 380.00 ✓
15	1	LHS Tail Lamp	\$ 380.00	\$ <del>BRO</del> 380.00 ✓
16	1	Spare Tyre Tank	\$ 688.00	\$ <del>CRU</del> 688.00 ✓
17	1	Floor Board	\$ 175.00	\$ <del>TN</del> 175.00 ✓
18	1	Rear Boot Inner Trim	\$ 265.00	\$ <del>NW</del> 265.00 X
19	1	RHS Rear Fender	\$ 910.00	\$ <del>DT</del> 910.00 R
20	1	LHS Rear Fender	\$ 910.00	\$ <del>DT</del> 910.00 R
21	1	LHS Rear Fender Shield	\$ 75.00	\$ <del>TN</del> 75.00 ✓
22	1	RHS Rear Fender Shield	\$ 75.00	\$ <del>TN</del> 75.00 ✓
23	1	Exhaust Tip	\$ 635.00	\$ <del>NN</del> 635.00 X
				\$ <del>4209.00</del> 8,037.00
			-25%	\$ <del>1052.25</del> 2,009.25
			<b>Total for spare parts</b>	\$ <del>3156.75</del> 6,027.75

KGC Workshop Pte Ltd

176 Sin Ming Drive, Sin Ming Autocare #02-04 (575721)

Office : 6453 6279 Fax : 6456 5410

Ng Bemg Siang, Almen  
176 Sin Ming Drive, Sin Ming Autocare  
# 02-04  
Singapore 575721

TP 180704  
Date 03-07-18  
No of Page : 2/3

Registraion No : SGZ 7036 G  
Accident Date : 02-Jul-18  
Our Ref : TP 180704

Model : Toyota Vios  
Chassis No: MR053HY9305031547  
Engine Capacity : -

S/No	Qty	Items	Unit Price	Amount
------	-----	-------	------------	--------

<b>Special Nett</b>				
1	10	Rear Bumper Clips	\$ 4.00	\$ <del>MRC 40.00</del> 30 ✓
2	20	LHS/RHS Rear Fender Garnish Clips	\$ 4.00	\$ <del>NOC 80.00</del> 60 ✓
3	10	End Panel Garnish Clips	\$ 4.00	\$ <del>NOC 40.00</del> 30 ✓
4	1	Windscreen Sealant	\$ 25.00	\$ <del>NOC 25.00</del> ✓
<b>Total for SP</b>			\$	<del>-185.00</del> 145.0
<b>Sub-Total for Parts :</b>			\$	<del>6,212.75</del> 3301.7

#### Labour & Spray Painting :

- To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- 1400.00 ~~2,000.00~~ 1600.00
- To putty and spray paint on all accident damage parts and other accident affected areas 1200.00 ~~1,800.00~~ 800.00
- To realign exhaust pipe 140.00 ~~50.00~~
- To remove and replace exhaust pipe to faciliate repair 80.00 ~~120.00~~
- To conduct test NN 80.00
- Remove and refit rear windscreen NN 150.00

3170

Ng Bemg Siang, Almen  
176 Sin Ming Drive, Sin Ming Autocare  
# 02-04  
Singapore 575721

TP 180704  
Date 03-07-18  
No of Page : 3/3

Registraion No : SGZ 7036 G  
Accident Date : 02-Jul-18  
Our Ref : TP 180704

Model : Toyota Vios  
Chassis No: MR053HY9305031547  
Engine Capacity : -

**Labour & Spray Painting :**

- |  |                  |
|--|------------------|
| 7 To check wiring system to facilitate repair and refit the same | 30.00 50.00 ✓    |
| 8 Apply rust proofing on the adjacent panels                     | 100.00 400.00 ✓  |
| 9 To remove and replace bumper sensors                           | 50.00 60.00 ✓    |
| 10 Wheel Alignment   | NN 60.00 65.00 ✓ |
| 11 To wheel balance  | NN 80.00 X       |

**TOTAL AMOUNT :** 4,865.00 3350.00  
**OVERALL COST :** 11,077.75 6651.75

TG Lim  
5/7/18 w/o  
L/s repair  
After paint photos

*[Handwritten signature]*  
5/7/18

L/S 5,300/2

8 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CS/EQI18012278/Bqd3e2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 03-08-2018	
			Code : EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJR 9797L	Veh. Inspected	SGZ 7036G	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM18HO01680-JG	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	05/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053HY9305031547	Colour	SILVER	
Odometer	200852	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/45 R16	KUMHO	6 mm	
L/H Front Tyre	205/45 R16	KUMHO	6 mm	
R/H Rear Tyre	205/45 R16	KUMHO	6 mm	
L/H Rear Tyre	205/45 R16	KUMHO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/07/2018	Inspection Date	05/07/2018	
Survey held at	KGC WORKSHOP PTE LTD 176 SIN MING DRIVE, SIN MING AUTOCARE #02-04 SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 7036G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT	CRUSHED	628.00	628.00
1	REAR BOOT 'VIOS' EMBLEM	NECESSARY	55.00	55.00
1	REAR BOOT TOYOTA EMBLEM	NECESSARY	59.00	59.00
1	REAR BOOT GARNISH (LONG)	NOT NECESSARY	290.00	-
2	REAR BOOT NO. PLATE LAMP @\$65.00	NOT NECESSARY	130.00	-
2	REAR BOOT HINGE @\$95.00	BENT	190.00	190.00
1	REAR BOOT LOCK	BENT	150.00	150.00
1	REAR BOOT WEATHERSTRIP	CUT	220.00	220.00
1	END PANEL GARNISH	CUT	255.00	255.00
1	END PANEL	BENT	689.00	689.00
1	REAR BUMPER	CRUSHED	488.00	488.00
2	REAR BUMPER REFLECTOR @\$95.00	BROKEN	190.00	190.00
2	REAR BUMPER RETAINER @\$100.00	BROKEN	200.00	200.00
1	RHS TAIL LAMP	BROKEN	380.00	380.00
1	LHS TAIL LAMP	BROKEN	380.00	380.00
1	SPARE TYRE TANK	CRUSHED	688.00	688.00
1	FLOOR BOARD	TORN	175.00	175.00
1	REAR BOOT INNER TRIM	NOT NECESSARY	265.00	-
1	RHS REAR FENDER	TO REPAIR SEE LABOUR	910.00	-
1	LHS REAR FENDER	TO REPAIR SEE LABOUR	910.00	-
1	LHS REAR FENDER SHIELD	TORN	75.00	75.00
1	RHS REAR FENDER SHIELD	TORN	75.00	75.00
1	EXHAUST TIP	NOT NECESSARY	635.00	-
	LESS 25% DISCOUNT		-2,009.25	-1,224.25
			6,027.75	3,672.75
<b><u>SPECIAL NETT ITEMS</u></b>				
10	REAR BUMPER CLIPS @\$4.00 (SN)	NECESSARY	40.00	30.00
20	LHS/RHS REAR FENDER GARNISH CLIPS @\$4.00 (SN)	NECESSARY	80.00	60.00
10	END PANEL GARNISH CLIPS (SN)	NECESSARY	40.00	30.00

Report Ref No. CS/EQ18012278/Bqd3e2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSCREEN SEALANT (SN)	NECESSARY	25.00	25.00
			185.00	145.00
	<b>LABOUR</b>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS- INCLUSIVE OF THE REPAIR OF RHS REAR FENDER AND LHS REAR FENDER.		2,000.00	1,400.00
	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS.		1,800.00	1,200.00
	TO REALIGN EXHAUST PIPE.		60.00	40.00
	TO REMOVE AND REPLACE EXHAUST PIPE TO FACILITATE REPIAR.		120.00	80.00
	TO CONDUCT TEST.	NOT NECESSARY	80.00	-
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME.		50.00	30.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		400.00	100.00
	TO REMOVE AND REPLACE BUMPER SENSORS.		60.00	50.00
	WHEEL ALIGNMENT.	NOT NECESSARY	65.00	-
	TO WHEEL BALANCE.	NOT NECESSARY	80.00	-
			4,865.00	2,900.00
<b>GRAND TOTAL</b>			<b>11,077.75</b>	<b>6,717.75</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,300.00</b>

Report Ref No. CS/EQ118012278/Bqd3e2

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.