

ASS. REC. BY:

REF CS3/CTI18012287/1724d302

and instructions

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time

4/7/18 @ 4.21pm

Estimated Cost:

Bill to:

OD (TI) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBK 868G

Insured:

SJF 7397J

at Workshop n/s:

SKM Garage &amp; Trading

Tel:

9640 7853

of

10 Kaki Bukit Rd 2 #03-31 First East Centre

Policy No:

DMPCSN3048011701

Claim No:

SNM18D02549C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/05/2018

CA / REV / REP. / REV 24 HRS

(up)

6/7/18 @ afternoon

H.O.D. Endorsement:

Date/Time:

5/7/18 @ 10:31 am

Person Contacted:

Ms. Yoke

Vehicle IN

(OUT)

Date/Time

Action/Instruction

(X) Estimate

SBK 8686G - X

SJF 7397J - NA / CTI18009228/21

DOA: 20/5/2018

9/7/18

Dismantled.

## ASSIGNMENT

From: \_\_\_\_\_ Date: 6/7/18

Estimated Cost: \_\_\_\_\_

On ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBK 868G

at Workshop m/s SKM Garage &amp; Trading

of 10kaki Bkt Rd 2 #03-31

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record) afternoon

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>lump</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time Action / Instruction

\$ 4000 - \$ 5000

11/7/18 Submit PRS report

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Veh No: SBK 868G Yr Regn: 1001 / 2008

Type: ☒ M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c. - 1998

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 74699 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: FD214 00 127

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 235/45 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fire 89

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 06-07-18

Survey held at w/s 2:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Tot

The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jul 2018		04 Jul 2018 16:21 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ONG BOON TIN MRS MOH-ONG BOON TIN, ID: S7607872F		
Main Claimant:	BERNARD WU KWENG MUN		
Vehicle Reg. No.:	SBK868G	Date of Loss:	20/05/2018 02:00 - :59
Claim Type:	TP / SNM18D02549C02	Policy/Cover Note No.:	DMPCSN3048011701 (Comprehensive)
Vehicle Reg. No. (Insured):	SJF7397J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	SKM GARAGE & TRADING LLP (HQ) 10 Kaki Bukit Road 2, #03-22 First East Centre, 417868 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/07/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Lucas Lee**

---

**From:** Ong & Shan LLC <ongshanllc@gmail.com>  
**Sent:** Wednesday, 4 July, 2018 4:12 PM  
**To:** Lucas Lee; SKM  
**Subject:** Re: PRI For SBK868G (CTI REF: SNM18D02549C02) (YrRef: SRSTP.7155.18.AY)

Dear Lucas,

We refer to the above matter and your email on the even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

- |                  |                             |
|------------------|-----------------------------|
| 1. Alan Cheong   | 2. Willy Goh                |
| 3. B J Loi       | 4. Marc                     |
| 5. Oh Han Cheong | 6. TT Rajan                 |
| 7. Andrew How    | 8. Teo Hoon Tong            |
| 9. Lee Kok Weng  | 10. Lim Yong Tian Sebastian |

Please be informed that the said vehicle can be inspected at:-

Name of workshop : M/s SKM Garage & Trading LLP  
Address : 10 Kaki Bukit Road 2  
#03-31 First East Centre  
Singapore 417868  
Contact person : Ms. Yoke Peng  
Telephone no : 9640 7853  
Fax no : 6443 0198

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "Single Joint Expert".

We will accordingly inform you who the "Single Joint Expert" is to facilitate your conduct of a pre-repair survey.

If you object to our list of motor surveyors, we will accordingly inform the claimant to instruct his choice of motor surveyors to conduct the pre-repair survey.

Warmest Regards,

CM Chen

M/s Ong & Shan LLC

Block 184 Toa Payoh Central

#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261

Email: [ongshanllc@gmail.com](mailto:ongshanllc@gmail.com)

On Wed, Jul 4, 2018 at 4:03 PM, Lucas Lee <[lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)> wrote:

**Without Prejudice**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/05/2018 16:00
Date Of Accident	20/05/2018 01:55
Exact Location Of Accident	JUNCTION OF TOH GUAN RD & JURONG GATEWAY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBK868G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BERNARD WU KWENG MUN (BERNARD HU JIONGMIN)
NRIC No	S7232578H
Email Address	BERNARDWUKM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83220011
Alternative Phone No	OFFICE-83220011

### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-2.0 TYPE-R (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA274066
Cover Note Number	

### Driver

Name of Driver	BERNARD WU KWENG MUN (BERNARD HU JIONGMIN)
NRIC No	S7232578H
Date Of Birth	12/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	08/12/1994
Driving Experience	23 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83220011
Fax Number	
Contact Number	OFFICE-83220011
Email Address	BERNARDWUKM@GMAIL.COM

Address	BLK203 BUKIT BATOK ST 21 #25-40 SINGAPORE
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DAMP

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : ANNAKYN WU GENDER: : FEMALE
Passenger 2	NAME: : CHOO LAY BOON GENDER: : FEMALE
Passenger 3	NAME: : ANNAVRIL WU GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN AND POLICE REPORT. ACCIDENT LOCATION: JUNCTION OF TOH GUAN ROAD & JURONG GATEWAY ROAD (AT THE X-JUNCTION OF TOH GUAN ROAD AND JURONG GATEWAY ROAD NEXT TO IMM BUILDING).

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF7397J
Vehicle Make/Model/Colour	TOYOTA RUSH
Details Of Properties	

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

21/05/2018

1617 HRS

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Toh Khar Kian



# Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SBK0686

PLEASE REFER TO ATTACHED POLICE REPORT NUMBER T/20180521/2087

KEY POINTS :

- THE OTHER PARTY WAS DRIVING WITHOUT HEADLIGHTS SWITCHED ON
- INSISTED THAT STREET LAMPS ARE BRIGHT ENOUGH TO WARRANT HER NOT TO SWITCH ON THE HEADLIGHTS
- INSISTED THAT THE X-JUNCTION IS AN ILLEGAL U-TURN LOCATION I MADE AT.
- REFUSED TO FURNISH HER PARTICULARS AS THERE ISN'T ANY NECESSITY FOR HER TO DO SO.


## Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.


- Reporting Only
- Claim OD
- Claim TP
- Claim OD ☒ TP at other workshop

## DECLARATION

I/WE declare the foregoing particulars are true in every respect.

  
21/05/2018 1617 HRS  
Policyholder's signature  
Date & Time

Driver's Signature  
(if driver not the policyholder)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name: Toh Khar Kian  
Nric/Fin No.



**SINGAPORE  
POLICE FORCE**



T/20180521/2087

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

1 of 4

Report No. T/20180521/2087

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 21/05/2018 13:38		Vide Report No.:		Station Diary No.: 63	
<b>Informant's Particulars</b>					
Name of Informant: BERNARD WU KWENG MUN			Address: APT BLK 203 BUKIT BATOK STREET 21 #25-40 SINGAPORE 650203		
ID Type / ID No.: NRIC NO / S7232578H			Contact No.: Home/Office: Mobile: 83220011		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 12/09/1972	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: PRIVATE HIRER			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 20/05/2018 01:55	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 TOH GUAN ROAD JURONG GATEWAY ROAD At the X-junction of Toh Guan Road and Jurong Gateway Road next to IMM Building				
Weather: Foggy		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SBK868G	Car	HONDA	CIVIC TYPE-R 2.0 M	Silver	Slightly Damaged	3
SJF7397J	Car				Slightly Damaged	2

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SBK868G	AXA INSURANCE SINGAPORE PTE LTD	GA274066	17/10/2017	16/10/2018



**SINGAPORE  
POLICE FORCE**



T/20180521/2087

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

2 of 4

Report No. T/20180521/2087

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	ANNAKYN WU	ID No.	T1229059F
Related Vehicle	SBK868G (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	BERNARD WU KWENG MUN	ID No.	S7232578H
Related Vehicle	SBK868G (Car)	Contact No.	83220011
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	CHOO LAY BOON	ID No.	S8037653G
Related Vehicle	SBK868G (Car)	Contact No.	82826065
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE  
POLICE FORCE**



T/20180521/2087

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

3 of 4

Report No. T/20180521/2087

## CONTINUATION OF REPORT

<b>Passenger</b>			
Name	ANNAVRIL WU		ID No. T0813009J
Related Vehicle	SBK868G (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 20/05/2018, at about 0155hrs, I was driving V1) SBK868G along Toh Guan Road on the right most lane after exiting PIE, approaching the traffic junction just outside of IMM Building. It was foggy after the rain.

Nearing the traffic junction, I checked the opposite direction for oncoming traffic, ensuring it was clear before executing the U-turn at the said junction.

However, while entering the opposing direction of Toh Guan Road after the U-turn, I saw an oncoming car (V2) without its headlights turned on. However, it was too near to me for me to make an evasive maneuver. I believe the car had also drove through the amber lights at the junction. Before I could do anything, I felt an impact from the left side of V1.

I immediately stopped V1 and exited the car to make a check. True enough, V2's headlights were switched off, and this is the reason why I hadn't noticed the vehicle upon making the U-turn. I have video footage of the accident that had happened. V2 is a red Toyota SJF397J.

I tried to exchange particulars with the other driver, a Chinese female in her 20s however she indicated that since we are not settling the matter by ourselves, there is no need to exchange particulars. I asked her why did she not switch on her headlamps to which she stated that with the bright street lamps in Singapore, it is unnecessary to switch on the headlights and that I was blind not to notice her car.

The damages on V1 was a dented front left fender, scratches and paint chipped off on the passenger side door, scratch on left side mirror, scratches on front left tyre rim and scratched left sideskirt. Neither myself nor my family members are injured. I hope that TP can investigate into this matter and actions taken against V2's driver for driving without switching on the headlights.



**SINGAPORE  
POLICE FORCE**



T/20180521/2087

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

4 of 4

Report No. T/20180521/2087

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 3 MUHAMMAD NURSYAZWAN BIN RASID

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

21/05/2018 13:38

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No.: 65476430

SN 114

Classification Of Case:

Authentication Stamp

NP168



Signature :

Singapore Police Force



Traffic Police  
AMENDMENT

Traffic Police Department  
Charge Office  
10 Ubi Avenue 3  
Singapore 408865

NP168 No: T/20180521/2087 Name: BERNARD WU KWENG MUN  
Accident Date/Time: 20/05/2018 / 0155 HRS Address: APT BLK 203 BUKIT BATOK  
STREET 21 #25-40 SINGAPORE  
650203  
Vehicle(s) Involved : SBK868G  
SJF7397J  
NRIC No: S7232578H  
Tel No : 83220011  
Date : 21/05/2018


Dear Sir / Madam

I wish to amend as follows:

With reference to the traffic accident report reference, T/20180521/2087, I wish to amend on the following details:

In the report brief details, instead of "V2 is a red Toyota SJF397J", it was supposed to be "V2 is a red Toyota SJF7397J".

That is all.

  
Yours faithfully

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SBK868G		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	CIVIC TYPE-R 2.0 M		
Chassis No. :	FD21400127		
Propellant :	Petrol		
Engine No. :	K20A5820128		
Engine Capacity :	1998 cc		
Maximum Power Output :	165.0 kW ( 221 bhp )		
Maximum Laden Weight :	1490 kg		
Unladen Weight :	1270 kg		
Year Of Manufacture :	2007		
Original Registration Date :	17 Oct 2008		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$14,858.00		
COE Expiry Date :	16 Oct 2018		
Road Tax Expiry Date :	16 Oct 2018		
PARF Eligibility Expiry Date :	16 Oct 2018		
Inspection Due Date :	16 Oct 2019		
Intended Transfer Date :	12 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK      Print

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2018		04 Jul 2018 16:21 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>ONG BOON TIN MRS MOH-ONG BOON TIN</b> , ID: S7607872F								
Main Claimant:	<b>BERNARD WU KWENG MUN</b>								
Vehicle Reg. No.:	<b>SBK868G</b>	Date of Loss:	20/05/2018 02:00 - :59 [115 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D02549C02</b>	Policy/Cover Note No.:	DMPCSN3048011701 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SJF7397J</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>SKM GARAGE &amp; TRADING LLP (HQ)</b> 10 Kaki Bukit Road 2, #03-22 First East Centre, 417868 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 13/07/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SBK868G (SNM18D02549C02)**  
**[SJF7397J]**

TP

**BERNARD WU KWENG MUN**

**May 20 2018 2:00AM**

**[ONG BOON TIN MRS MOH-ONG BOON TIN]**  
**SKM GARAGE & TRADING LLP**

[Upload Documents](#) | 
 [Upload Photos](#) | 
 [Compose New Letter](#)

**View** View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/05/18 14:09	<b>Accident Statement</b>	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	21/05/18 14:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/07/18 16:21	<b>PRS</b>	Load PDF	
2	04/07/18 16:21	<b>OI GIA</b>	Load PDF	

No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/05/18 14:01	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	21/05/18 14:01	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/07/18 19:35	<b>LKKPhotosIn6-1.pdf</b>	Load PDF	
2	11/07/18 19:35	<b>LKKPhotosIn6-2.pdf</b>	Load PDF	










## Linked Accident Report Documents

**View** View in Browser



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/05/18 14:09	<b>Accident Statement</b>	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/05/18 14:01	<b>Accident Photo</b>	Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
					<input checked="" type="checkbox"/>
2	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	21/05/18 14:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	21/05/18 14:01	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	21/05/18 14:01	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div> <div></div> <div> ^ v </div> </div> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18012287/GZ4D3E2

Date: 13/07/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3048011701

Claimant Vehicle  
No : SBK868GInsured Vehicle  
No : SJF7397J

Date of Loss: 20/05/2018

Nature of Claim: TP

Claim  
No: SNM18D02549C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SBK868G**

Make &amp; Model: HONDA CIVIC, 2.0 TYPE-R (M)

Engine No: K20A5820128

Reg. Date: 17/10/2008 (Man. Year: 2007)

Chassis No: FD21400127

Colour: Silver

Odometer: 74699 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 04/07/2018

Date Inspected: 06/07/2018 Inspected At:

SKM GARAGE & TRADING LLP (HQ)  
10 Kaki Bukit Road 2, #03-22 First East  
Centre  
Singapore 417868

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2018)
<b>Parts:</b> 144	HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBK868G)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >