

7/10/2003

ASS. REC. BY:

REF:

CS3/EGT18 012994/R124d3

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

5/7/18 @ 10:17am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FY 4199G

Insured:

YN 3767G

at Workshop m/s

All wheel Motoring

Tel:

8510 2102

of

BIK 5032 AMK Ind. Park 2 # 01-307

Policy No:

Claim No:

18-AR3-9505

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/06/2018

(Client's Record)

06/07/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS lup

Date/Time:

11:10am @ 5/7/18

Person Contacted:

Ah Seng

Vehicle:

IN OUT

Date/Time

Action/Instruction (X) Estimate

FY 4199G-x

YN 3767G-CS/AWA 15020776 / Fqbc2

DOA: 21/2/2015

TGLi m

Range 3000/- - 3800/-

lin

Repair days 4

31/7/18

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS3/EGI18012294/R1z4d3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 05-07-2018



Code : EGI

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YN 3767G	Veh. Inspected	FY 4199G
Policy No.		Coverage (\$)	0.00
Claim No.	18-A83-9505	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	05/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	23/06/2018	Inspection Date
Survey held at	ALL WHEEL MOTORING 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933	

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Thursday, 5 July 2018 10:17 AM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** 'ASSIGNMENTS@LKKAUTO.COM'  
**Subject:** OI : YN3767G / TP : FY4199G/LKK / DOA : 23/06/2018  
**Attachments:** YN3767G - SAS.pdf; RE: Accident Involving FY 4199G Our Ref:18-A83-9505 (28.8 KB)

Dear Catherine/Nivitha,

We have rejected to their PRS list, please assist to conduct this survey from **LEGAL OPTIONS LLC**.

ADDRESS : **ALL WHEEL MOTORING**  
BLK 5032 ANG MO KIO INDUSTRIAL PARK 2  
#01-307  
SINGAPORE 569535

PERSON TO CONTACT : AH SENG @ 8510 2102

ERGO OFFICER-IN-CHARGE : STEVE LIM

*Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Try to obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.*

Please update the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached is insured's SAS (note: reports not to be released to any Third Party). No estimates was provided.

**Kindly acknowledge receipt of this email.**

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Date of Accident : 23/06/2018 Accident Time: 14:00 (24-HR-Format)  
 Accident Place : Along Vishnu St 22 \* Infront of BIK 2A3  
 Vehicle Reg. No. (Car Plate No.) : FY 4199G  
 Vehicle Make/Model : Honda CB400 SP2JM  
 Insurance Company : Allied World Policy No. AVMCJB0013181703  
 Owner or Company Name /IC No. : Lin Shiqi, Wendy S8506592J  
 Owner or Company Contact No. : 9005 7888 Owner's Hp \_\_\_\_\_ Company Tel \_\_\_\_\_  
 DRIVER'S Name / IC No. : Lin Shiqi, Wendy S8506592J  
 DRIVER'S Date Of Birth : 06/03/1985 DRIVER'S License Pass Date 03 April 2004  
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Self  
 DRIVER'S Address : BK 397 Vishnu Ave 6 #09-115 2 S (760397)  
 DRIVER'S Contact No. / Alt No. : 1) 9005 7888 2) \_\_\_\_\_  
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
 Email Address : \_\_\_\_\_  
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
 Number of Passengers (Including Driver): \_\_\_\_\_

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident Private use \ Work purpose

Other Party Driver's Particular (if any)

Vehicle Reg. No: YN 3767G

Vehicle Reg. No: \_\_\_\_\_

Vehicle Make/Model: \_\_\_\_\_

Vehicle Make/Model: \_\_\_\_\_

Name Driver: Arif

Name Driver: \_\_\_\_\_

IC No. Driver: G8397769N

IC No. Driver: \_\_\_\_\_

Driver's Contact & Add: \_\_\_\_\_

Driver's Contact & Add: \_\_\_\_\_

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten text in the description area:

POLICE REPORT

PET

AJ

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:



**SINGAPORE  
POLICE FORCE**



T/20180623/2126

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

1 of 3

Report No. T/20180623/2126

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/06/2018 18:41		Vide Report No.: F/20180623/0196		Station Diary No.: 97	
<b>Informant's Particulars</b>					
Name of Informant: LIN SHIQI, WENDY			Address: APT BLK 397 YISHUN AVENUE 6 #09-1152 SINGAPORE 760397		
ID Type / ID No.: NRIC NO / S8506592J			Contact No.: Home/Office: Mobile: 90057888		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 33	Date of Birth: 06/03/1985	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: DELIVERY RIDER			Driving Licence Information: Class: 2B,2A		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/06/2018 14:00	Type of Location: Straight Road
Location: Along Road 1 YISHUN STREET 22 Infront of Blk 293				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FY4199G	Motorcycle	HONDA	CB400 SF2J M	Green	Slightly Damaged	0
YN3767G	Lorry	HINO	XZU700R 4.0L MANUAL TURBO ABS 5T	White	No Damage	1





**SINGAPORE  
POLICE FORCE**



T/20180623/2126

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

2 of 3

Report No. T/20180623/2126

## CONTINUATION OF REPORT

Details of Vehicle Involved				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FY4199G	ALLIED WORLD ASSURANCE COMPANY, LTD (SINGAPORE BRANCH)	AVMCSB00131817 03	03/10/2017	02/10/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	LIN SHIQI, WENDY	ID No.	S8506592J
Related Vehicle	FY4199G (Motorcycle)	Contact No.	90057888
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A Date of Expiry: NIL
Date Treatment	23/06/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On the above mentioned date, time and location, I was riding my motorcycle (Greenish-blue coloured Honda CB400 vehicle number: FY4199G) along Yishun St 22 towards Yishun Ave 7 when I spotted a stationary lorry (White coloured Hino XZU700R vehicle number: YN3767G) as it seems to be stationary for quite awhile therefore, I tried to ride along the lorry in a slow pace. However, when I was about half way past the said lorry, the passenger side door suddenly opened. As it was too sudden I was not able to swerve past it or avoid it, causing the door to scrape on the back of my motorcycle, when the door rammed into my motorcycle, I was thrown to the side of the pavement.

Shortly after the ambulance arrived to assist me as I have sustained injuries due to this accident. After about 15 minutes traffic police also arrived due to the accident. I was then conveyed to Khoo Teck Puat Hospital for further assessment.

I am lodging this report as I was advised to make a report in the earliest convenience regarding the accident.



**SINGAPORE  
POLICE FORCE**



T/20180623/2126

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

3 of 3

Report No. T/20180623/2126

**CONTINUATION OF REPORT****Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 GERALDINE QUEK JIE YI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

23/06/2018 18:41

Officer In Charge Of Case:

TP / GIT /

SI NORASHIKIN BINTE DAUD

Contact No.: 65476439

Classification Of Case:

Authentication Stamp

NP168

Signature:

Singapore Police Force

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6592J
<b>Vehicle Details</b>	
Vehicle No.:	FY4199G
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400 SF2J M
Primary Colour:	Black
Manufacturing Year:	2004
Engine No.:	NC23E2062876
Chassis No.:	NC391052870
Maximum Power Output:	-
Open Market Value:	\$8,601.00
Original Registration Date:	15 Sep 2004
First Registration Date:	15 Sep 2004
Transfer Count:	4
Actual ARF Paid:	\$1,291.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Sep 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$4,157.00
COE Rebate Amount:	\$2,561.00
<b>Total Rebate Amount:</b>	<b>\$2,561.00</b>

The information contained herein is correct as at 16 Jul 2018

OK

6. Sep. 2017 13:26

BHH Office

No. 7269 P. 1

MOTOR CYCLE

**CERTIFICATE OF INSURANCE**

MY3

N 58

25935D0

Cov. Type: F

KERTISSH

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 109) OF THE REPUBLIC OF SINGAPORE  
 THE ROAD TRANSPORT ACT 1987 OF MALAYSIA  
 THE AGREEMENT BETWEEN THE MINISTER FOR FINANCE (SINGAPORE) AND THE MOTOR INSURERS BUREAU OF SINGAPORE DATED 22 FEBRUARY 1975  
 THE AGREEMENT BETWEEN THE MINISTER OF TRANSPORT (MALAYSIA) AND THE MOTOR INSURERS BUREAU OF WEST MALAYSIA DATED 15 JANUARY 1966  
 ANY SUBSEQUENT REVISIONS TO THE ABOVE ACTS AND AGREEMENTS

CERTIFICATE No.

AVMCSB0013101703

ChaNo: NC391052670

1. Index Mark and Registration  
Number of Vehicle

FY 4199 G

2. Name of Policyholder

LIN SHIQI WENDY

3. Effective Date of Commencement of Insurance  
for the purposes of the Ordinance

03 October 2017

4. Date of Expiry of Insurance

02 October 2018

5. Persons or Classes of Persons entitled to drive\* (For certificate references MX1 and MX4, see overleaf)

- A. THE POLICYHOLDER.  
 B. ZHOU LANGSI

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use\* (For certificate reference MX1, see overleaf)

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND BY THE POLICYHOLDER IN PERSON IN CONNECTION WITH HIS BUSINESS OR PROFESSION.

THE POLICY DOES NOT COVER :-

1. USE FOR HIRE OR REWARD.
2. USE FOR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING.
3. USE FOR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS.
4. USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

Estimated Value : MARKET VALUE WITH COE/PAAP

Hire Purchase Owner : YEN HENG CREDIT ENTERPRISE PTE LTD

Type of Cover : Third Party, Fire & Theft

\* Limitations rendered inoperative by Section 79 of the Road Traffic Ordinance 1958 (Malaysia) or Section 7 of the Motor Vehicle (Third-Party Risks and Compensation) Ordinance 1960 (Republic of Singapore) are not to be included under the headings.

I/WE HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and The Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 109) (Republic of Singapore)

**ALLIED WORLD**

Approved Insurers

Examined By



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8506592J



Name

LIN SHIQI, WENDY

林詩琪

Race

CHINESE

Date of birth

08-03-1988

Sex

F

S8506592J

Country/Place of birth  
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

08-Mar-2006  
03-Apr-2006

081179626D

5543270



NRIC No. S8506592J



Date of issue

23-12-2015

Address

APT BLK 397 YISHUN AVENUE 6  
#09-1152  
SINGAPORE 760397

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2B Motorcycles up to 200 CC

Class 2A Motorcycles between 201 CC and 400 CC

03 Apr 2006

05 Dec 2014

S8506592J

S/No. 9000208951

NP 428A



Licence No: S8506592J

Condition (CON)

(01) Best (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

FOR MOTORCYCLE

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)  
4. Not Consistent (NC)

May 2005

Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	135.00	BUC ✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH			
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever	58.00	CUT ✓	
3035	992293	Hand Brake Lever			
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing	135.00	CUT ✓	
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			

Vehicle No: FY 4199G

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar L/R 75/2	SCR ✓		2
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy			
1055	993719	Rear LH Shock Absorber			
1056	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1057	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box	250.00	SCR ✓	
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1036	990247	Sticker			
		Engine camshaft			
		collet 110/2	CRU ✓		1
		Handle bar ends			
		@ 30.00 L/R	CUT ✓		2

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

ORIGINAL COPY




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18012294/R1z4d3s2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date:	01-08-2018	
FIVESINGAPORE 038985		Code: EGI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YN 3767G	Veh. Inspected	FY 4199G	
Policy No.		Coverage (\$)	0.00	
Claim No.	18-A83-9505	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	05/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400 SF2J M	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	NC391052870	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60ZR17	PIRELLI	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60ZR17	PIRELLI	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5. General Information				
Accident Date	23/06/2018	Inspect Date / Time	06/07/2018 ( 12:22 PM )	
Survey held at	BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-307			
Repairer	ALL WHEEL MOTORING			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000- \$3,800				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/EGI18012294/R1z4d3s2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.