

ASS. REC. PT. REF CS/FCI18012297/Kqd3n4 Special Instruction:
 Surveyor Kenneth
 CWS Lurene jaw ASSIGNMENT (Office)
 From (Person) of FCI Date/Time 5/7/18 @ 8:22pm
 Estimated Cost Bill to
 OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No. XD 3086C Insured SHC 722 6J
 at Workshop n/r Cheong Cheong Tel 618 14152
 of BLK 5032 AMK Ind. Park 2 # 01-293
 Policy No. D-18088937MFSH Claim No. D18005167MFSH
 Sum Insured Excess
 Make of Veh. D.O.A. 30/06/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS (bs) H.O.D. Endorsement
 Date/Time 11:04am 5/7/18 Person Contacted Angela Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	XD 3086C - x
06/7/18 @ 11pm	SHC 722 6J - CC3 / FCI 13007798 / Kyn DoA 27/09/2012 revised to Lurene by email.

28/8 11 Lurene @ 30,000 email to centreline (had to redo, 25%)
 16/10/18 re-open ref for amend report - vehicle details. Close 16/10/18.
 1st close date 6/9/18.
 17/10/18 re-open ref only.

RECEIVED 17 OCT 2018

ASS. REC. BY:

REF: FC21Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

07 days

Res.: Yes or No

Lump Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

6/7 File pass to Customer

RECEIVED 10 MAR 2018

Veh No: XO 3086CYr Regn: 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HitC.C. 12882Colour: White

Insured / Std / NI / NA

Sp. Reading 73237P

T/Radio: Insured / Std / NI / NA

Eng No: _____

C.No: 1EV51JJA00355Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII LS/Rlm / STD A/Rlm orTyre Size: F: 2P5/80R225

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

R/Bal. 7 mm

Rear

R/Bal. 66 mmL/Bal. 7 mmL/Bal. 66 mmD.O.A. 30/6/18D.O.A. 5/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

30/8/18

: Prel. Report



: Final Report

Date/Time, File Return to?

7

Days Of Repair: 7Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format: TPLump Sum / L.B.I. (\$ 30000)

29x15=435

1705 435

50

50

18

723



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012297/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7226J	Veh. Inspected	XD 3086C
Policy No.		Coverage (\$)	0.00
Claim No.	D18005167MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	05/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/06/2018	Inspection Date	05/07/2018
Survey held at	CHEONG CHEONG MOTOR SERVICE PL BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005167MFSH

Date: 06 July 2018

Our Ref: CS/FC118012297/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. XD 3086C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/07/2018 at the premises of M/s CHEONG CHEONG, and have the following to report:-

Workshop Estimate Amount	: S\$ 39,850.00
Revised Estimate Amount	: S\$ 39,500.00
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7040E

Vehicle Details

Vehicle No.: XD3086C

Vehicle to be Exported: No

Intended De-registration Date: 06 Jul 2018

Vehicle Make: MITSUBISHI

Vehicle Model: FV51JJD4RDEA

Primary Colour: White

Manufacturing Year: 2008

Engine No.: 6M70421988

Chassis No.: FV51JJA00355

Maximum Power Output: -

Open Market Value: \$83,388.00

Original Registration Date: 19 Sep 2008

First Registration Date: 19 Sep 2008

Transfer Count: 2

Actual ARF Paid: \$4,170.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Jul 2022

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$17,035.00

COE Rebate Amount: \$13,856.00

Total Rebate Amount: \$13,856.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 06 Jul 2018

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012297/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7226J	Veh. Inspected	XD 3086C	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005167MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	05/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FV	c.c	12882	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	FV51JJA00355	Colour	WHITE / BLUE	
Odometer	732379	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	CHAO YANG	7 mm	
L/H Front Tyre	295/80 R22.5	CHAO YANG	7 mm	
R/H Rear Tyre	295/80 R22.5 (D/D)	FIRESTONE	6/6 3/3 mm	
L/H Rear Tyre	295/80 R22.5 (D/D)	FIRESTONE	6/6 3/3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2018	Inspection Date	05/07/2018	
Survey held at	CHEONG CHEONG MOTOR SERVICE PL BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		