

ASS. REC. BY:

REF

CS3/MS918012332/G240302

Special Instruction:

Survivor
Menmen

Guo Quney

ASSIGNMENT (Office)

From (Person)

Katherine Wong

of

MSG

Date/Time:

5/7/18 @ 3:52pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 10164

Insured:

FBC 4093R

at Workshop n/s

Celebrity Auto

Tel:

9022 2411

of

176 Sin Ming Drive # 03-17

Policy No:

MSD/VMFT / 17-982927-WTH

Claim No:

MSC/V/18-000917

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/06/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

12:56pm @ 6/7/18

Person Contacted:

Mr. Leslie

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKN 10164 - X
	FBC 4093 R - CCT/AIG 11026575 / Gpuu DOA: 22/12/2011
19/7/18	After repair \$ 30206

REF:

MS/6

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

celebrity Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SKN 10164

Yr Regn: _____

08 Jan 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Estima

c.c

2362

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

144470

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

AHR20 7042829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

235/45 R18

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

06-07-18

Survey held at

w/s

5:40pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimate repair range \$2000 - \$3000.

RECEIVED 19 JUL 2010

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

2)

☐

Final Report

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$

120

50

10

180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2018		05 Jul 2018 15:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LEK WEI HAO JARREN, ID: S9426796Z		
Main Claimant:	KHOO MIN, ID: S7430726D		
Vehicle Reg. No.:	SKN1016U	Date of Loss:	30/06/2018 00:00 - :59 [101 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-000917	Policy/Cover Note No.:	MSD/VMFT/17-982927-WTT (TP, Fire & Theft) Coverage: 13/05/2017 - 06/09/2018
Vehicle Reg. No. (Insured):	FBC4093R	Policy No. (Claimant):	
		Excess:	
Repairer:	Celebrity Auto - Sin Ming (HQ) 176 SIN MING DRIVE, #03-17, 575721 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/07/2018]		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP agreed & nominated LKK to our SJE, Insured non-reporting. Contact : Mr Leslie Yeo @ 9022 2411, vehicle will be parked at 6th car park.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SKN1016U
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	ESTIMA HYBRID 2.4X A
Chassis No. :	AHR207042829
Propellant :	Petrol-Electric
Engine No. :	2AZH426695
Motor No. :	2JM2AZH426695
Engine Capacity :	2362 cc
Power Rating :	155.0 kW
Maximum Power Output :	110.0 kW (147 bhp)
Maximum Laden Weight :	2355 kg
Unladen Weight :	1970 kg
Year Of Manufacture :	2009
Original Registration Date :	08 Jan 2010
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
Quota Premium :	\$17,889.00
COE Expiry Date :	07 Jan 2020
Road Tax Expiry Date :	07 Jan 2019
PARF Eligibility Expiry Date :	07 Jan 2020
Inspection Due Date :	07 Jan 2019
Intended Transfer Date :	11 Jul 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	
Amount Payable	

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0726D
Vehicle Details	
Vehicle No.:	SKN1016U
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA HYBRID 2.4X A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	2AZH426695
Chassis No.:	AHR207042829
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$46,905.00
Original Registration Date:	08 Jan 2010
First Registration Date:	08 Jan 2010
Transfer Count:	2
Actual ARF Paid:	\$28,143.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2020
PARF Rebate Amount:	\$15,478.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$17,889.00
COE Rebate Amount:	\$2,630.00
Total Rebate Amount:	\$18,108.00

The information contained herein is correct as at 18 Jul 2018

OK

SKN1016U [FBC4093R] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



1/20: **General View**



2/20: **General View**



3/20: **General View**

SKN1016U [FBC4093R] - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



4/20: **General View**



5/20: **General View**



6/20: **General View**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2018		05 Jul 2018 15:52 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEK WEI HAO JARREN , ID: S9426796Z									
Main Claimant: KHOO MIN , ID: S7430726D									
Vehicle Reg. No.: SKN1016U		Date of Loss: 30/06/2018 00:00 - :59 [101 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-000917		Policy/Cover Note No.: MSD/VMFT/17-982927-WTT (TP, Fire & Theft) Coverage: 13/05/2017 - 06/09/2018							
Vehicle Reg. No. (Insured): FBC4093R		Policy No. (Claimant):							
		Excess:							
Repairer: Celebrity Auto - Sin Ming (HQ) 176 SIN MING DRIVE, #03-17, 575721 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 06/07/2018]									
Adj Asg. Remarks: Third Party Pre-Repair Survey. TP agreed & nominated LKK to our SJE. Insured non-reporting. Contact : Mr Leslie Yeo @ 9022 2411, vehicle will be parked at 6th car park.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN1016U (MSC/V/18-000917)
[FBC4093R]
TP
KHOO MIN
Jun 30 2018 12:00AM
[LEK WEI HAO JARREN]
Celebrity Auto - Sin Ming

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/07/18 09:45	General View	Load JPG	<input checked="" type="checkbox"/>
2	10/07/18 09:45	General View	Load JPG	<input checked="" type="checkbox"/>
3	10/07/18 09:45	General View	Load JPG	<input checked="" type="checkbox"/>
4	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
5	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
6	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
7	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
8	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
9	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
10	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
11	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
12	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
13	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
14	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
15	10/07/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
16	10/07/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	10/07/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	10/07/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	10/07/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	10/07/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/07/18 17:29	TP PRI	Load PDF	
2	05/07/18 10:03	TP REPLY & NOMINATED LKK TO BE SJE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012332/GZ4D3E2

Date: 20/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMFT/17-982927-WTT
Claimant Vehicle No :	SKN1016U	Insured Vehicle No :	FBC4093R
Date of Loss:	30/06/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000917

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN1016U		
Make & Model:	TOYOTA ESTIMA, 2.4 E X Hybrid (A)	Engine No:	2AZH426695
Reg. Date:	08/01/2010 (Man. Year: 2009)	Chassis No:	AHR207042829
Colour:	White	Odometer:	144470 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	05/07/2018	
Date Inspected:	06/07/2018	Inspected At: Celebrity Auto - Sin Ming (HQ) 176 SIN MING DRIVE, #03-17 Singapore 575721
Estimated Period of Repair:	0.0 days	

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jul 2018)

Parts: M1-MPV TOYOTA ESTIMA 2.4 E X Hybrid (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKN1016U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >