Munimen stacy!	)	Date/Time: 5/7/180 11-59 am
Estimated Cost: OD / TD / WS / TP RES / OD RI To Inspect Vehicle No:	SGP 4635 A	
of BIK 2 Ke Policy No. P168 0520 Sum Insured:	Twincar Automotive aki Bukit # 01-17/18 Claim No:_	co474022
Make of Veh: (Client's Record)  CA / REV / REP. / REV 24  Date/Time: 10:2 am 66 7	HRS (Up) 715857	D.O.A. 24 06 2018  H.O.D. Endorsement:  Vehicle IN OUT
Date/Time Action/Instruction	SA-X Estimate	4/Kea3 DOA: 9/6/2018

## ASSIGNMENT

From: Date:	Veh No: SGP 4635 A Yr Regn: 2566 / DCC .
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Kin Cento. c.c 1599.
at Workshop m/s	Colour Silves A/C: Insured / Std / NI / NA
of	Sp.Reading 164974. T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: KNAFE22226535 1666
Claims No.	Gen. Cond. Good. Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 205/55R16
(Policy Condition)	R: 205/55F4(,
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYOTYOKO OF Habilead.
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? ; Yes or No	R/Bal. O( mm R/Bal. To( mm
GIA / PR Seen. Consistent? : Yes or No	L/Bal. 06 mm L/Bal. 96 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.L. 17/07/08
Lum Sum: % 3 Val.: Yes or No	Survey held at Twincor-
CA / DEV / DED / 24 HDS	Des. of Damages : Frt / Rear / O/S / N/S (U/C)/ Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OU	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Action / Instruction	COF 5 22 30/1/21
TP AXA. PRS.	COE Expiry: 30/1/21
	V
mv . 701C	
MV: 701C PV: 17.4K	
Nett: 261C.	
18/7/18 BUMIT PRS REPORT	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Add Fe	ee:: Site Insp (\$)s+RSSI
m and the second se	: Interview (\$ ) Photos
Report Format :	: Tech fives (\$ ) Ollers
Lump Sum / LB.I: (\$	; Weekend (\$
	TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat				
FW	SINGAPORE PT	ELTD	Ref : CS/FWD18012	928/Avd3		
	MASEK BOULEVA 01 SUNTEC TOW	ARD ER 4SINGAPORE 038986	Date: 17-07-2018 Code: FWD			
1.		Policy Particu	lars :- OWN DAMAGE			
	Insured Veh.		Veh. Inspected	SLG 4419X		
	Policy No.	PNPV2017-00006429	Coverage (\$)	0.00		
	Claim No.	1201800009007	Excess (\$)	600.00		
	Assign From	MERIMEN (JOSEY LOH)	Assign Date	17/07/2018		
2.		Vehicle Par	ticulars & Condition			
	Make & Model		c.c 0			
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	( <del>-</del> )	Steering			
	Brakes		Modification			
	General					
3.		Cond	itions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		Descrip	tion of Damages			
5.		Gene	ral Information			
	Accident Date	16/07/2018	Inspection Date	17/07/2018		
	Survey held at	DA COTTOS A GRANDO CONTRA DE CONTRA				
5a.			Remarks			
	A)THE MARKET V B)IN ACCORDANG	ALUE IS S\$(EST. AVE				

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Ad) Rpt	Adi Su	bmitted	Ins Auth'ed	Status			
Main	05 Jul 2018		05 Jul 2018 23:59 Assign						ssignment Case	Ė	
	Main	Re	ference		Claim Details		Docume	nts	SI	how All	
CLAIM SU	BFOLDER D	ETAILS		and delivery of the latest		[Create	ed by insurer]	A STATE OF THE PARTY OF T	THE REAL PROPERTY.	CONTRACTOR AND ADDRESS OF THE PARTY OF THE P	
Insured:	TRANS-C	AB SERVICES PT	ELTD. Co. Red	. No.: 2003	03878K Email			90			
Main Claimant:	ISKANDA	AR BIN YUSOFF,			DOG ON, LINE	CENTING	TICHISCAB.COM.	30			
Vehicle Reg No.:	SGP463	5A			Date of Loss	: 24/06/2	018 04:00 - :59				
Claim Type	TP / C04	0474022			Policy/Cover Note No.:	P1680520 (Third Party Only)					
Vehicle Reg No. (Insured):	SHC5549	R			Policy No. (Claimant):						
					Excess:	\$\$5,000					
Repairer:	Twincar	Automotive Pte L	td (Kaki Bukit)	BLK 2 KAKI	BUKIT, #01-17	7/18 KAKI E	BUKIT AUTOHUB,	417921 Kak	i Bukit - Te	el:	
Handling Insurer:	AXA Insu	rance Pte Ltd (H	Q) - Tel: 6338 7	288 [Han	dled by Stacey	Ng - 6880	4351]				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 16/	07/20181				
Driver/Cust dian (Insured):	0	EE WEI (), NRIC			Property and the second		•				
ASSOCIAT	ED MAIL RE	CEIVED						View All	Compose (	Case Ma	
AXA_SG	(05/07/2018)	: New TP Assigni	ment - C04740	22/P16805	520						
	CIATED TAS	SKS <sup>E</sup>				View A	Search Tasks	Create Ne	w Tack	Comple	
ALL ASSO											
Due Date	Priority	Type Task	Group Subi	ect Han		ned By	Completed O				

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIE	7-11-	тетл	10-15	100	т
ACCIE	JEN.	DIA	115		

 Date Of Report
 25/06/2018 10:46

 Date Of Accident
 24/06/2018 04:50

Exact Location Of Accident PIE (CHANGI) BEFORE BEDOK RESERVOIR ROAD EXIT

Country/State of Loss SINGAPORE

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SGP4635A

#### Insured/Policyholder

Name Of Registered Owner ISKANDAR BIN YUSOFF

NRIC No S1718258G Email Address NOEMAIL

 Mobile Phone No
 (LOCAL) +65-92386100

 Alternative Phone No
 OTHERS-92386100

#### Vehicle Particulars

Manufacturer KIA
Model CERATO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

....

NO

LEISURE

If No. Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

#### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy NO

Policy Number 5052450759-06

Cover Note Number

#### Driver

Name of Driver ISKANDAR BIN YUSOFF

 NRIC No
 S1718258G

 Date Of Birth
 28/03/1965

 Occupation
 INDOOR

 Date Of Driving Pass
 03/07/1985

Driving Experience 32 YEARS AND 11 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-92386100

Fax Number

Contact Number OTHERS-92386100

EMail Address NOEMAIL

Address

BLK 55 #03-174 CHAI CHEE DRIVE

Postcode

460055

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-2448999 - FAX NO: 62446558

Was notice of intended Prosecution given?

If Yes, against whom?

#### Circumstances of Accident

Refer to police report

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SHC5549R

Vehicle Make/Model/Colour

**Details Of Properties** 

TAXI

Vehicle Category Name of Driver

WONG CHEE WEI

NRIC/Passport Number

S7341390G

Contact Number

96380537

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 17

#### Sketch Plan Pg. 1

INCOME MOTOR SERVICE C	ENTRE	Report Date & Start Time:	25-06-2018 / 10:43
Report No: MT/	D.O.A: 24-06-2018 Time: 04:50 hrs	Vehicle No. SGP4635A	Reporting Type: —(P

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the malling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

Driver's Signature (if driver is not the policyholder) / Date & Time

- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

25-06-18 / 10:43

(ii) for complying with requirements under any regulations, laws or court orders.


25-06-18 / 10:43

Alan Tang (S098825) Customer Care Executive Motor Service Centre

Witnessed by Reporting Centre Peronnel

Policyholder's Signature / Date & Time

#### Sketch Plan Pg. 2



Refer to police report	

Declaration

I/We declare the foregoing particulars are true in every respect.

25-06-18 / 10:43

25-06-18 / 10:43

Alan Tang (S098825) Customer Care Executive Motor Service Centre

KY

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

#### Police Report Pg. 1





Police Station Of Origin: Bedok South N.P.C 20 Chai Chee Drive SINGAPORE 469045 1 of 3 Report No. T/20180624/2040

Tel No: 1800-2448999

REPORT OF A TRAFFIC ACCIDENT				
	REPORT OF A TRAFFIC ACCIDENT			

Station Diary No.: Date/Time Report Made: Vide Report No .: 24/06/2018 13:57 12 Informant's Particulars Name of Informant: Address: ISKANDAR BIN YUSOFF APT BLK 55 CHAI CHEE DRIVE #03-174 SINGAPORE 460055 ID Type / ID No .: Contact No .: Home/Office: NRIC NO / S1718258G Mobile: 92386100 Nationality: Email: SINGAPORE CITIZEN Sex: Date of Birth: Type of Informant: Age: Male 53 28/03/1965 Driver Race: Language: Institution / School Name: English Malay Occupation: Driving Licence Information: AVIATION REFUELLER Class: 3,4 Date of Expiry:

Concret into	mation of the Accident			
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/06/2018 04:50	Type of Location:
	I ERVOIR ROAD DS CHANGI, BEFORE BI	EDOK RESERVOII	R EXIT. NEAR TO LAN	APOST 396
		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance:

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SGP4635A	Car	KIA	CERATO 1.6M	Silver	Seriously Damaged	0
SHC5549R	TAXI				Slightly Damaged	0

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		
SGP4635A	NTUC Income Insurance Co-Operative Limited	5052450759-06	18/12/2017	17/12/2018		

#### Police Report Pg. 2



Police Station Of Origin: Bedok South N.P.C

20 Chai Chee Drive SINGAPORE 469045

Tel No: 1800-2448999

T/20180624/2040

2 of 3

Report No. T/20180624/2040

#### CONTINUATION OF REPORT

Details of Person	n Involved					
Any Pedestrian In	volved: No					
No. of Pedestrian			Use of Ped	destrian	Cross	ing: NA
Driver						
Name	ISKANDAR BIN YUSOFF			ID No.		S1718258G
Related Vehicle	NIL			Contact No.		92386100
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
	ted Medical Leave	NIL	Degree of	Injury	NIL	
Driver						
Name	WONG CHEE WEI	WONG CHEE WEI		ID No.		S7341390G
Related Vehicle	NIL		Contact No.		96380537	
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc	charge	NIL	
	nted Medical Leave	NIL	Degree o	f Injury	NIL	

#### Brief Details.

On 24/06/18 at about 0450hrs, I was travelling along PIE towards Changi. Just before the exit of Bedok Reservoir Road, near to lamp post 396, there was a taxi, SHC5549R, from 2nd lane suddently hit to the right passenger side of my car. My car had serious damaged on the front bumper and front right passenger side. There was slight damaged on the right side of the other party's car.

I wish to state that I was driving along the third lane at that point of time. Both of us did not suffer any injury. No ambulance was called. However, police was called to attend to the scene. Report no: G/20180624/0078.

That is all.

#### Police Report Pg. 3





Police Station Of Origin: Bedok South N.P.C 20 Chai Chee Drive SING

20 Chai Chee Drive SINGAPORE 469045

Tel No: 1800-2448999

3 of 3 Report No. T/20180624/2040

CONTINUATION OF REPORT

#### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / SI SOO YAN NEE	Signature of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 24/06/2018 13:57
Officer In Charge Of Case: TP / GIT / SI THABAGESH JEYATHESH Contact No. 65476232	Classification Of Case:
Authentication Stamp NP168	

### > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		TO SEE CONTRACT OF THE
Owner ID Type:	Singapore NRIC	
Owner ID:	8258G	
Vehicle Details		NE GITTE SECTION CONTRACTOR OF THE
Vehicle No.:	SGP4635A	
Vehicle to be Exported:	Yes	
Intended De-registration Date:	17 Jul 2018	
Vehicle Make:	KIA	
Vehicle Model:	CERATO 1.6M	
Primary Colour:	Silver	
Manufacturing Year:	2006	
Engine No.:	G4ED6H103988	
Chassis No.:	KNAFE222265351661	
Maximum Power Output:	77.2 kW (103 bhp)	
Open Market Value:	\$11,350.00	
Original Registration Date:	18 Dec 2006	
First Registration Date:	18 Dec 2006	
Transfer Count:	0	
Actual ARF Paid:	\$10,270.00	
Intended PARF Rebate Details		A CONTRACTOR OF THE PARTY OF TH
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	5 To 10 To 1	
PARF Rebate Amount:	\$0.00	
Intended COE Rébate Debails		
COE Expiry Date:	30 Nov 2021	
COE Category:	E - Open Category	
COE Period(Years):	5	
PQP Paid:	\$25,821.00	
COE Rebate Amount:	\$17,400.00	
Total Rebate Amount:	\$17,400.00	


Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jul 2018

## SELL YOUR CAR YOURSE

Get listed until it's sold + we will handle all the paperwork!







Post an Advertisement Sell it vourself! Advertise it at just \$58 until it's SOLD!

\$2500 Downpayment Monthly From \$588 Onwards. Lowest 3.68%P.A@Gv Cars Financing GV Credit Pte Ltd StarAd


v 5 Years Coe Renewal Toyota Altis 1.6A



# Lake View Credit Pte Ltd

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable





Kia Cerato Forte 2.0A SX

\$9,640 /yr

02-Mar-2009

1,998 cc

103,787 km

Sedan

Available

\$14,900

[Drive With Assurance!] Down Payment \$1.9k, Easy Loan Approval With Financing Options! Low Monthly Installment Plan Super Low Mileage Done. All Our Pre-Owned Cars Are Selling At The Most Reasonable Pr...

Posted: 12-Jul-2018 Tags: 2009 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia

Compare [3] 6

Kia Cerato Forte 1.6A SX \$14,000 \$9,860 /yr 09-Mar-2009 1,591 cc

200,000 km

Sedan

Available

## ...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement VNI

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subi	mitted 1	Ins Auth'ed	Pending for Survey Report Cancel Case		
Main	05 Jul 2018		05 Jul 2018 23:59 Edit Adj Rpt	S\$0.00 Edit Estima	ites	S\$0.00 View Rp					vey
	Main	Re	ference		Claim	Details		Document	s	s	how All
CLAIM SU	BFOLDER DI	ETAILS					[Created	by insurer]	NAME OF TAXABLE PARTY.	WAR STATE	
Insured:	TRANS-C	AB SERVICES PT	ELTD, Co. Reg	. No.: 20030	3878K	, Email:	CLAIMS@T	RANSCAB,COM.SC	3		
Main Claimant:		R BIN YUSOFF,									
Vehicle Reg No.:	24/06/2018 04			8 04:00 - :59 ths and <b>6</b> Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / C04	174022	Policy/Cover Note No.: P1680520 (Third Party Only)								
Vehicle Reg No. (Insured):	SHC5549	R				y No. imant):					
					Exce		\$\$5,000.0	Calculation of the Control of the Co			
Repairer:	Twincar	Automotive Pte L	td (Kaki Bukit	BLK 2 KAK	BUKIT	, #01-17/	/18 KAKI BU	IKIT AUTOHUB, 4	17921 Kak	i Bukit - "	Tel:
Handling Insurer:	12.4000000000000000000000000000000000000	rance Pte Ltd (H									
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Ha	ndled by 3	XING GUO	QIANG] [Fin	al Rpt d	ue 16/0	7/2018
Driver/Cust dian (Insured):	WONG CH	EE WEI (), NRIC	: S7341390G,	Tel: +65963	380537						
ASSOCIA	TED MAIL RE	CEIVED						1	/iew All	Compose	Case Mai
<ul> <li>AXA_SG</li> </ul>	(05/07/2018	): New TP Assign	ment - C04740	)22/P1680	520						
ALL ASSO	CIATED TA	sks <sup>=</sup>					View All	Search Tasks	Create N	ew Task	Complet
Due Dat		Type Task	Group Sub	ject Han	dler	Assign	ned By	Completed On	Cre	ated On	Done

#### Claim Documents

\*SGP4635A (C0474022)

[SHC5549R]

TP

ISKANDAR BIN YUSOFF

Jun 24 2018 4:00AM

[TRANS-CAB SERVICES PTE LTD]

Twincar Automotive Pte Ltd

Upl	load Documents Uplo	and Photos Compose New Letter Upload Video Upload Audio	View	View in Brow	1
Pho	otos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/07/18 10:36	General View	0	Load JPG	•
2	18/07/18 10:36	General View	0	Load JPG	•
3	18/07/18 10:36	General View	0	Load JPG	•
4	18/07/18 10:36	General View	0	Load JPG	•
5	18/07/18 10:36	General View	0	Load JPG	•
6	18/07/18 10:36	General View	0	Load JPG	•
7	18/07/18 10:36	General View	0	Load JPG	•
8	18/07/18 10:36	General View	0	Load JPG	•
9	18/07/18 10:36	General View	0	Load JPG	•
10	18/07/18 10:36	General View	0	Load JPG	•
11	18/07/18 10:36	General View	0	Load JPG	•
12	18/07/18 10:36	General View	0	Load JPG	•
13	18/07/18 10:36	General View	0	Load JPG	•
14	18/07/18 10:36	General View	0	Load JPG	•
15	18/07/18 10:36	General View	0	Load JPG	1
16	18/07/18 10:36	General View	0	Load JPG	•
17	18/07/18 10:36	General View	0	Load JPG	•
18	18/07/18 10:36	General View	0	Load JPG	•
19	18/07/18 10:36	General View	0	Load JPG	•
20	18/07/18 10:36	General View	0	Load JPG	•
21	18/07/18 10:36	General View	0	Load JPG	•
22	18/07/18 10:36	General View	0	Load JPG	•
23	18/07/18 10:36	General View	0	Load JPG	•
Doc	cumentation		1 per	page ▼	
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	05/07/18 12:36	EMAIL FROM WORKSHOP	0	Load PDF	
2	05/07/18 12:36	SGP4635A TP GIA	0	Load PDF	
3	05/07/18 12:36	SHC5549R INSD GIA	0	Load PDF	
4	05/07/18 12:41	EMAIL TO WORKSHOP (LIST OF SURVEYOUR)	0	Load PDF	
5	05/07/18 13:29	REPLY FROM WORKSHOP1	0	Load PDF	
6	05/07/18 13:29	REPLY FROM WORKSHP (LIST OF SURVEYOUR)	0	Load PDF	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AXA18012337/AZ4D3S2

Date:

18/07/2018

REFERENCE

Date of Loss:

Handling Insurer:

AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No:

SGP4635A

24/06/2018

Insured Vehicle No:

Nature of Claim:

SHC5549R

TP

C0474022 Claim No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Rea No:

SGP4635A

Make & Model:

KIA CERATO, 1.6 (A)

Engine No: Chassis No: Odometer:

G4ED6H103988

164974 km

KNAFE222265351661

Reg. Date: Colour:

18/12/2006 (Man. Year: 2006)

Silver

Engine Capacity: Market Value/New Car Price: 1599 cc

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/55R16

Rear Tyre Size:

205/55R16

Front Left Side:

Habilead 6 mm

Rear Left Side:

Habilead 6 mm

Front Right Side:

Habilead 6 mm

Rear Right Side:

Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

05/07/2018

Date Inspected:

17/07/2018 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)

BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB

Singapore 417921

Estimated Period of Repair:

0.0 days

XING GUO QIANG Adjuster:

Manager:

Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 18 Jul 2018) Part Source: MRM-SG

KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SGP4635A)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >