

**PROGRESSIVE
AUTOMOTIVE PTE LTD
BLK 3022A UBI ROAD 1
#01-45/46
SINGAPORE 408716
Email: progauto@progauto.
com.sg**

**Claim Reference: TP 0718 - 5133
Assessment Number: PA001567
Version: PROGRESS/1
Date Calculated: 05/07/2018 06:46**

**Full Report - V1
Registration: SLU8645J
Printed: 05/07/2018 13:47**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Wayne Lim	Date of Incident:	03/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	TP 0718 - 5133	Estimated Repair Time:	
Policy Number:	3100025992	Quote Due Date:	
Other Reference:	TP 0718 - 5133	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MAZDA
Model:	5
Sub Model:	BASE MODEL
Model Sheet Number:	I88 01
Registration:	SLU8645J
Registration Month:	December
Registration Year:	2017
VIN Number:	JM6CW1071H0127488
Manufacture Year:	2017
Odometer:	Not Known
Colour:	
Engine Number:	PE10540866
Fuel Level:	%

Model Specs

FROM 12/2017	AIR CONDITIONING
XENON HEADLAMPS	FOG LAMPS
2.0 LTR 106/110KW	AUTO GEARBOX 5 SPEED
TYRES 205/55 VR 16	WHEELS 6.5J X 16 ALU
4-WHEEL ALIGNMENT	GRILLE DARK SILVER
PREPARE OFF VEHICLE	TWO COAT PEARL/MICA

Vehicle Condition



Vehicle Status

Pre-Accident Condition: Steering:	Severity of Impact: Vehicle Status on Inspection:	
Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:	Date of Inspection:	05/07/2018
Tyres Condition: Tread Depth LHF: Tread Depth LHR:	Tread Depth RHF: Tread Depth RHR: Direction of Impact:	
Damage Areas:		

PROGRESSIVE AUTOMOTIVE PTE LTD

Claim Reference: TP 0718 - 5133
Assessment Number: PA001567
Version: PROGRESS/1
Date Calculated: 05/07/2018 06:46

Full Report - V1
Registration: SLU8645J
Printed: 05/07/2018 13:47



Addresses

Repairer

Name : PROGRESSIVE
 Address :
 Post Code :

Cost Summary

Total Labour	\$247.50
Total Paint/Material	\$99.01
Total Parts	\$1,208.65
Excess:	TBA
Grand Total Exc GST:	\$1,555.16
7 % GST:	\$108.86
Grand Total Inc GST:	\$1,664.02

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$45.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
S0419X-R-X	R + R FRONT GRILLE INCLUDES: R + R FRONT BUMPER	5.0	22.50
S0201X-R-X	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS	10.0	45.00

LABOUR COST

Total Work Units	15.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	1.5HRS	\$67.50
Paint Labour	4.0HRS	\$180.00
Total Labour	5.5HRS	\$247.50

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
281	FRONT BUMPER NEW PART PAINT K1R	11.0	
286	TOWING EYE COVER SURFACE PAINT PLAST.	3.0	
741	L/F WING SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	20.0	
	Preparation Main Work Plastic	15.0	
	Preparation Comp. Work Metal	5.0	

PROGRESSIVE AUTOMOTIVE PTE LTD

Claim Reference: TP 0718 - 5133

Full Report - V1

Assessment Number: PA001567

Registration: SLU8645J

Version: PROGRESS/1

Printed: 05/07/2018 13:47

Date Calculated: 05/07/2018 06:46

Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	40.0	
Total Paintwork Labour	4.0HRS	\$180.00
MATERIAL COST - PAINT		Cost Price
New Part Painting - Plastic K1R		\$53.14
Surface-/Blend Paint		\$11.45
Surface Paint Plastic		\$0.37
Material-Const Main Work Plastic		\$25.05
Material-Const Comp. Work Metal		\$9.00
Total Excluding Pearlescent Uplift		\$99.01
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$99.01

PARTS

Guide No.		Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281		1	FRONT BUMPER	CG1650031BBB		0%	960.00*
350		1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	45.00*
317		1	L/F BUMPER BRACKET	C513500U1B		0%	13.00*
433		1	MANUFACTURER BADGE	C29151731		0%	20.00*
318		1	R/F BUMPER BRACKET	C513500T1B		0%	13.00*
f: OEM Parts				Sub Total			\$1,051.00
g: Original				Mark Up From Cost	(15 %)		\$157.65
h: Secondhand				Sundry Parts	(Fixed)		\$0.00
p: Parallel				Total Parts			\$1,208.65
x: Exchange							

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts	\$1,208.65
Labour	
Total Panel/Mechanical	\$67.50
Total Paintwork	\$180.00
Total Labour	\$247.50
Total Paint/Material Costs	\$99.01
Grand Total Excludes GST	\$1,555.16
GST @ 7 %	\$108.86
Grand Total Includes GST	\$1,664.02

Assessment Notes

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/07/2018 15:13
Date Of Accident	03/07/2018 19:00
Exact Location Of Accident	GEYLANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU8645J
Insured/Policyholder	
Name Of Registered Owner	HO MENG HUAT
NRIC No	S1681342G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84888498
Alternative Phone No	OTHERS-84888498

Vehicle Particulars

Manufacturer	MAZDA
Model	5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	3100025992

Driver

Name of Driver	HO MENG HUAT
NRIC No	S1681342G
Date Of Birth	10/10/1965
Occupation	INDOOR
Date Of Driving Pass	21/04/1984
Driving Experience	34 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84888498
Fax Number	
Contact Number	OTHERS-84888498
EMail Address	NOEMAIL

Address	22 JALAN MOLEK
Postcode	399541
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE AUTOMOTIVE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD558G
Vehicle Make/Model/Colour	LEXUS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAXMAN BHATIA
NRIC/Passport Number	S7285130G
Contact Number	91120030
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 4/7/18
Policyholder's Signature

Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/IN No.:

Sketch Plan #2

SKETCH PLAN

		Vehicle No A - SLU 8645 J B - SKD 5586 G
		Legend  
		Vehicle Bike

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/7/18 around 7pm, I was driving along Geylang Road near Lany 27, after signal, after checking no car coming, I changed lane (attach video) and SKD 5586 car into in a high speed without signal and knock into my car (attach front & back video)

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature  Date & Time: 2/7/18 2.01pm	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature  Name: NRIC/FIN No.:
-----------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------