

7/2/01/2002

ASS. REC. BY:

REF: CS/AGI 18012353/R1vd3⁵²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Julie Mangubat

of AGI

Date/Time: 5/7/18 @ 1:23pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP559D

Insured:

SLX 5313X

at Workshop m/s

Accord Auto

Tel:

92710999

of Blk 1009, Bk f Meruh Lane 3 # 01-80

Policy No:

Claim No:

C10001747/AH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/07/2018

10/07/2018 @ morning

CA / REV / REP. / REV 24 HRS

rup?

H.O.D. Endorsement:

Date/Time: 12pm @ 6/7/2018

Person Contacted:

celia

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 559D - X
	SLX 5313X - X
7/8/18	Final fig \$ 7169 confirmed by email (Red 9365.08, 5676)


Surveyor *Rajan*

REF:

54764

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLP 559D
at Workshop m/s Accord Auto
of 1009, Burnt insurance # 01-80
Insured: Ahi / up
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 559D Yr Regn: 2017 / msh
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: MAZDA 3 1.5 G.C. 1456
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: 25756 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 3M6BN24A8H0131439
Gen. Cond: Good ☒ Fair / Poor / Burnt
Steering: ☒ order / Jammed / Leaked / Burnt or
Brake: ☒ order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60R16
R: 1.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
☒ TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>05/07/18</u>		D.O.I. <u>10/02/18</u>
Survey held at <u>ACCORD AUTO</u>		

Des. of Damages: ☒ Fr ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) 7/8 - typist

Report Format :

Lump Sum / I.B.I: (\$) 7169 1/2

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

)

TOTAL

450

Nivitha (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Thursday, 5 July 2018 4:23 PM
To: sur@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM
Cc: Albert Hong
Subject: FW: PRI SLP559D | Claim: C10001747/AH
Attachments: GIA REPORT - SLP559D.PDF

Hi Team

Please assist to survey TP vehicle on a without Prejudice basis.

Thank you,
-Julie

From: Julie Mangubat
Sent: Thursday, 5 July, 2018 4:05 PM
To: Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: FW: PRI SLP559D | Claim: C10001747 , Claimed Policy: P10071887R00 , Policy Holder: Kim Lee Chioh

Hi Ahong

I assigned this case to you.
Need your help to arrange survey please.

Thank you,
-Julie

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Thursday, 5 July, 2018 2:58 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: PRI SLP559D

Dear Officer In Charge,

Kindly arrange survey as above mentioned and please provide us 10 surveyor name list.

Thank you!

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/07/2018 13:07
Date Of Accident	05/07/2018 08:00
Exact Location Of Accident	ALONG KJE TOWARDS PIE TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP559D
Insured/Policyholder	
Name Of Registered Owner	LIM LAY PHENG (LIN LIPING)
NRIC No	S7225476G
Email Address	FELICE_LIM@AIMCHEM.COM.SG
Mobile Phone No	(LOCAL) +65-92958853
Alternative Phone No	OFFICE-92958853

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01015518
Cover Note Number	

Driver

Name of Driver	LIM LAY PHENG (LIN LIPING)
NRIC No	S7225476G
Date Of Birth	23/07/1972
Occupation	INDOOR
Date Of Driving Pass	27/12/2002
Driving Experience	15 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92958853
Fax Number	
Contact Number	OFFICE-92958853
Email Address	FELICE_LIM@AIMCHEM.COM.SG

Address	BLK 339 WOODLANDS AVENUE 1 #04-557
Postcode	730339
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My car was stationary on the extreme right lane along Kje towards pie due to the heavy traffic. suddenly, veh b hit against my rear. the impact push my car forward and hit against veh in front of me. My front and rear was damage and no visible injury involved. It was a chain collision of 6 vehicles.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX5313X
Vehicle Make/Model/Colour	SUBARU/FORESTER 2.0X
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR PARCO
NRIC/Passport Number	G5147364M
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLP3142C
-----------------------------	----------

Vehicle Make/Model/Colour

B.M.W./216D

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHIOH KIM LEE

NRIC/Passport Number

S6918411A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3

Passenger 1

NAME: : PASSENGER 1

GENDER: : FEMALE

Passenger 2

NAME: : PASSENGER 2

GENDER: : FEMALE

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKB1027B

Vehicle Make/Model/Colour

MERCEDES BENZ/C 200 CGI

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN DRIVER

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SLZ2567P

Vehicle Make/Model/Colour

TOYOTA/WISH 1.8 CVT

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN DRIVER

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number

SJD3591B

Vehicle Make/Model/Colour

HONDA/STREAM 1.8X A

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN DRIVER

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purpose(s); and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purpose(s).

VERIFIED BY ALAX MARS
REPORTING OFFICER
Md Sharil

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

My car was stationary on the extreme right lane along Kje towards pie due to the heavy traffic.suddenly, veh b hit against my rear. the impact push my car forward and hit against veh infront of me. My front and rear was damage and no visible injury involved. It was a chain collision of 6 vehicles.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SHARIL BIN SATAR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

5 July 2018 at 10:58 AM

Date/Time:

5 July 2018 at 10:58 AM

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 / 62717433 FAX: 62745715

ESTIMATE REPAIR

Pg 1

Auto & General Insurance (S) Pte Ltd

Date: 6.7.2018

Owner's Name : Lim Lay Pheng

Vehicle No : SLP559D

Claim Type: Third Party Claim

Vehicle Make & Model : Mazda3 5-Door Hatchback 1.5L SP

Chassis No: JM6BN24A8H0131439

Registration Date : 24 May 2017 (YOM 2016) COE Expiry Date 23 May 2027

DOA: 5.7.2018

No	Description	Unit	List (\$)
1	Rear Bumper	1	\$ DE ✓ 950.00
2	Rear Bumper Side Retainer	1	\$ SUC X 71.20
3	Rear Bumper Clips	10	\$ nu - 42.00
4	Rear Bumper Tow Cover	2	\$ SUC X 60.00
5	Rear Bumper Reflector	2	\$ SUC X 100.80
6	Rear Tail Gate	1	\$ repair 1,268.70
7	Rear Tail Gate Inner Compartment Clips	15	\$ nu X 42.00
8	Rear Tail Gate Logo	1	\$ nu ✓ 74.40
9	Rear Tail Gate Logo " Skyativ"	1	\$ nu ✓ 63.60
10	Rear Tail Gate Logo " Mazda 3"	1	\$ nu - 52.40 53.50
11	Reverse Sensor	4	\$ SLU 200 X 775.60 SUC
12	Reverse Sensor Seal	4	\$ nu X 69.20
13	Rear Reinforcement	1	\$ SUC? 537.30
14	Rear End Panel	1	\$ repair 624.70
15	Front Bumper	1	\$ cut ✓ 825.50
16	Front Bumper Side Retainer	2	\$ nu - 37.40
17	Front Bumper Clips	10	\$ nu - 40.00
18	Front Bumper Grille Base	1	\$ cut? 129.00
19	Front Bumper Grille Chrome	2	\$ cut ✓ 365.00
20	Front Bumper Foglamp Garnish	1	\$ X 43.20
21	Front Bumper Foglamp Chrome	2	\$ X 135.40
22	Front Support Panel	2	\$ SUC X 469.70
23	Front Reinforcement Bar	1	\$? 478.80
24	Front Headlamp LH & RH Rthc / LH - X SUC	2	\$? 7,197.20
25	Panel Radiator Grille	1	\$ DE ✓ 338.50

Total (A) : \$ 14,792.60

Less 20% \$ 2,958.52

Total: \$ 11,834.08

No	Description	Unit	List (\$)
	Special Nett		
1	FRONT CAR PLATE NUMBER WITH FRAME	1	\$ su / 35 50.00
2	REAR CAR PLATE NUMBER WITH FRAME	1	\$ svl X 50.00
3	REVERSE SENSOR	SET	\$ 200? / svl 300.00
4	REVERSE SENSOR SEAL	2	\$ nu / 20.00
Total (B) :			\$ 420.00

No	Description	Unit	List (\$)
	Labour		
1	Spray Painting to All Affected Areas	1	\$ 900 / 1,000.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 700 / 1,000.00
3	Check Wiring System & Light	1	\$ 30 / 100.00
4	Anti Rust Treatment	1	\$ 60 / 120.00
5	To Check & Adjust Wheel Aligment	1	\$ n/a X / 100.00
6	To Remove/Refix Inner Compartment & Carpet To Facilitate Repair	1	\$ 60 / 280.00
7	To Remove / Refix / Replace Reverse Camera	1	\$ n/a X / 180.00
8	To Remove / Replace Rear Reverse Sensor	1	\$ 60 / 180.00
9	To Check Water Leaking	1	\$ 30 / 150.00
10	To Remove / Refix / Replace Rear Tail Gate Inner Compartment,Mechemism & Assy To New Tail Gate	1	\$ n/a X / 200.00
11	To Remove / Refix / Replace Reverse Camera	1	\$ reputed X n/a / 180.00
12	To Remove / Refix Rear Windscreen To New Tail Gate	1	\$ n/a X / 220.00
13	Upholstery Details Cleaning	1	\$ n/a X / 220.00
14	Computer Diagnostic	1	\$ 60 / 350.00
	LKK Auto Consultants hence notify the Repairer of the following:		
	• To resurvey before/after spray painting		
	• To display damaged part(s) during resurvey		
	• Parts prices are subject to confirmation		
	• Third party survey is on a "Without Prejudice" basis		
	• No illegal modification(s) is allowed		
	• Supplementary item(s) must be authorised and is subject to final approval from Insurance Company		
	Acknowledged by Repaire		
	Signature:		
	Date:		
	Total (C) :	\$	4,280.00
	Grand Total:	\$	16,534.08

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL 62715133 62717431 FAX 62745715

ESTIMATE REPAIR

Pg 1

Auto & General Insurance (S) Pte Ltd

Date: 6.7.2018

Owner's Name : Lim Lay Pheng

Vehicle No : SLP559D

Claim Type: Third Party Claim

Vehicle Make & Model : Mazda3 5-Door Hatchback 1.5L SP

Chassis No: JM6BN24A8H0131439

Registration Date : 24 May 2017 (YOM 2016) COE Expiry Date 23 May 2027

DOA: 5.7.2018

No.	Description	Unit	Unit Price	Est. Price
1	Rear Bumper	1	\$	DE ✓ 950.00
2	Rear Bumper Side Retainer	1	\$	X 71.20
3	Rear Bumper Clips	10	\$	neu ✓ 42.00
4	Rear Bumper Tow Cover	2	\$	X 60.00
5	Rear Bumper Reflector	2	\$	X 100.80
6	Rear Tail Gate	1	\$	repair 1,268.70
7	Rear Tail Gate Inner Compartment Clips	15	\$	X 42.00
8	Rear Tail Gate Logo	1	\$	neu ✓ 74.40
9	Rear Tail Gate Logo " Skyativ"	1	\$	neu ✓ 63.60
10	Rear Tail Gate Logo " Mazda 3"	1	\$	neu ✓ 53.40
11	Reverse Sensor	4	\$	slu 200 X 775.60
12	Reverse Sensor Seal	4	\$	X 69.20
13	Rear Reinforcement	1	\$? 537.30
14	Rear End Panel	1	\$	repair 624.70
15	Front Bumper	1	\$	cut ✓ 825.50
16	Front Bumper Side Retainer	2	\$	neu ✓ 37.40
17	Front Bumper Clips	10	\$	neu ✓ 40.00
18	Front Bumper Grille Base	1	\$	cut ✓ 129.00
19	Front Bumper Grille Chrome	2	\$	cut ✓ 365.00
20	Front Bumper Foglamp Garnish	1	\$	X 43.20
21	Front Bumper Foglamp Chrome	2	\$	X 135.40
22	Front Support Panel	2	\$	X 469.70
23	Front Reinforcement Bar	1	\$? 478.80
24	Front Headlamp LH & RH	2	\$? 7,197.20
25	Panel Radiator Grille	1	\$	DE ✓ 338.50

Parts \$ 6391.40

17 20% \$ 5113.12

+ SH \$ 55.00

+ Labour \$ 1900.00

\$ 7068.12

Paul
12/07/18

Total (A): \$ 14,792.60

Less 20% \$ 2,958.52

Total: \$ 11,834.08

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 7 August 2018 10:23 AM
To: 'Accord Claims(AV)'
Cc: SUR
Subject: RE: Photos After Repair SLP559D

Dear Celia,

Noted with thanks.

Kindly send Final invoice and all supporting documents to BUDGET DIRECT

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Tuesday, 7 August 2018 9:43 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: Photos After Repair SLP559D

Dear Veron,

Agree on finalize amt \$7,169.00 @ 7 working days.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Tue, Aug 7, 2018 at 9:35 AM, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Celia,

WITHOUT PREJUDICE

Final amount \$7169 @ 7 working days.

Kindly confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>

Sent: Monday, 6 August 2018 1:51 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: Re: Photos After Repair SLP559D

Dear Veron,

Kindly refer headlamp damage photos.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Mon, Aug 6, 2018 at 1:28 PM, Accord Claims(AV) <avclaims@mycarworkshop.com.sg> wrote:

Dear Veron,

Estimate marked re-survey by Rasul on 12.7.2018.

Kindly review and revert us the finalize amount.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Mon, Aug 6, 2018 at 12:24 PM, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Celia,

WITHOUT PREJUDICE

Final amount \$4290.12 @ 7 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Sent: Wednesday, 1 August 2018 4:40 PM
To: SUR <sur@lkkauto.com>
Subject: Fwd: Photos After Repair SLP559D

Dear Veron,

As spoken, kindly refer attached file.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

----- Forwarded message -----

From: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>
Date: Thu, Jul 19, 2018 at 2:49 PM
Subject: Photos After Repair SLP559D
To: "Rasul (LKK Auto)" <rasul@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>

Dear Rasul,

Kindly refer photos after repair as attached file and please finalize.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI18012353/R1vd3s2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 27-08-2018	
			Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 5313X	Veh. Inspected	SLP 559D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001747/AH	Excess (\$)	0.00	
Assign From	JULIE MANGUBAT	Assign Date	05/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN24A8H0131439	Colour	BLACK	
Odometer	25756	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60R16	TOYO	6 mm	
L/H Front Tyre	205/60R16	TOYO	6 mm	
R/H Rear Tyre	205/60R16	TOYO	6 mm	
L/H Rear Tyre	205/60R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/07/2018	Inspection Date	10/07/2018	
Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 559D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	950.00	950.00
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	71.20	-
10	REAR BUMPER CLIPS	NECESSARY	42.00	42.00
2	REAR BUMPER TOW COVER	SERVICEABLE	60.00	-
2	REAR BUMPER REFLECTOR	SERVICEABLE	100.80	-
1	REAR TAIL GATE	TO REPAIR SEE LABOUR	1,268.70	-
15	REAR TAIL GATE INNER COMPARTMENT CLIPS	NOT NECESSARY	42.00	-
1	REAR TAIL GATE LOGO	NECESSARY	74.40	74.40
1	REAR TAIL GATE LOGO "SKYATIV"	NECESSARY	63.60	63.60
1	REAR TAIL GATE LOGO "MAZDA 3"	NECESSARY	53.50	53.50
4	REVERSE SENSOR	SERVICEABLE	775.60	-
4	REVERSE SENSOR SEAL	NOT NECESSARY	69.20	-
1	REAR REINFORCEMENT	SERVICEABLE	537.30	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	624.70	-
1	FRONT BUMPER	CUT	825.50	825.50
2	FRONT BUMPER SIDE RETAINER	NECESSARY	37.40	37.40
10	FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT BUMPER GRILLE BASE	CRACKED	129.00	129.00
2	FRONT BUMPER GRILLE CHROME	CRACKED	365.00	365.00
1	FRONT BUMPER FOGLAMP GARNISH	SERVICEABLE	43.20	-
2	FRONT BUMPER FOGLAMP CHROME	SERVICEABLE	135.40	-
2	FRONT SUPPORT PANEL	SERVICEABLE	469.70	-
1	FRONT REINFORCEMENT BAR	SERVICEABLE	478.80	-
2	FRONT HEADLAMP LH & RH	O/S CRACKED / N/S SERVICEABLE	7,197.20	3,598.60
1	PANEL RADIATOR GRILLE	DEFORMED	338.50	338.50
	LESS 20% DISCOUNT		-2,958.54	-1,303.50
			11,834.16	5,214.00
SPECIAL NETT ITEMS				
1	FRONT CAR PLATE NUMBER WITH FRAME (SN)	SCRATCHED	50.00	35.00
1	REAR CAR PLATE NUMBER WITH FRAME (SN)	SERVICEABLE	50.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	300.00	-

Report Ref No. CS/AGI18012353/R1vd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REVERSE SENSOR SEAL (SN)	NECESSARY	20.00	20.00
			420.00	55.00
	LABOUR			
	SPRAY PAINTING TO ALL AFFECTED AREAS.		1,000.00	900.00
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND RELAIN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR TAIL GATE AND REAR END PANEL.		1,000.00	700.00
	CHECK WIRING SYSTEM & LIGHT.		100.00	30.00
	ANTI RUST TREATMENT.		120.00	60.00
	TO CHECK & ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO REMOVE / REFIX INNER COMPARTMENT & CARPET TO FACILITATE REPAIR.		280.00	60.00
	TO REMOVE / REFIX / REPLACE REVERSE CAMERA.	NOT NECESSARY	360.00	-
	TO REMOVE / REPLACE REAR REVERSE SENSOR.		180.00	60.00
	TO CHECK WATER LEAKING.		150.00	30.00
	TO REMOVE / REFIX / REPLACE REAR TAIL GATE INNER COMPARTMENT, MECHANISM & ASSY TO NEW TAIL GATE.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIX REAR WINDSCREEN TO NEW TAIL GATE.	NOT NECESSARY	220.00	-
	UPHOLSTERY DETAILS CLEANING.	NOT NECESSARY	220.00	-
	COMPUTER DIAGNOSTIC.		350.00	60.00
			4,280.00	1,900.00
GRAND TOTAL			16,534.16	7,169.00
RECOMMENDED COST OF REPAIRS				7,169.00

Report Ref No. CS/AGI18012353/R1vd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.