




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI18012353/R1vd3s2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 27-08-2018		
		Code : AGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 5313X	Veh. Inspected	SLP 559D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001747/AH	Excess (\$)	0.00	
Assign From	JULIE MANGUBAT	Assign Date	05/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN24A8H0131439	Colour	BLACK	
Odometer	25756	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60R16	TOYO	6 mm	
L/H Front Tyre	205/60R16	TOYO	6 mm	
R/H Rear Tyre	205/60R16	TOYO	6 mm	
L/H Rear Tyre	205/60R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/07/2018	Inspection Date	10/07/2018	
Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		