

ASS. REC. BY:

REF: CS/SMO18012365/71sd3<sup>n2</sup> Special Instruction:

Surveyor:

Tawhikh

ASSIGNMENT (Office)

From (Person): Grace Leo

of SMO

Date/Time: 6/7/18 @ 1:39pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SGJ 6925G

Insured:

FBM 9796K

at Workshop m/s

Woon Meng Motor

Tel:

6316 1151

of

50 Bkt Bafok St. 23

Policy No:

Claim No:

CM7D1802872/ACX

Sum Insured:

Excess:

D.O.A.

04/07/18

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time:

1:00pm 06/7/18

Person Contacted:

Ms l/kg

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGJ 6925G - X

FBM 9796K - X

23/07/18

@ 13:45pm revised PA to Grace via email.

Signature

Taufik

REF:

Sampo

# ASSIGNMENT

SGJ 69256

COE 2026 June

From:

Date:

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn: 2006 / Jly

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A/Hs

C.C. 1598

Colour:

Silver.

A/C: Insured / Std / NI / NA

Sp. Reading

196367

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR0557EC107127315

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/7/18 @ 1050

Survey held at

Woon Meiy

Bkt Bkt

Des. of Damages: Frt / Rear / S/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/08/18 Confirmed L/S \$ 1,300/- @ 4 days with Taufik.

( \$1,065.11 Red - 45% )

RECEIVED 29 AUG 2018

Date/Time, File Pass to?

29/08/18

1)

Typist

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) S = RS \$

) Photos

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / L.B. : (\$ 1,300/- L/S )

TOTAL

250



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO18012365/T1sd3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 06-07-2018 Code : SMO	
				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	FBM 9796K	Veh. Inspected	SGJ 6925G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1802872/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	06/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	04/07/2018	Inspection Date		
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1802872/AGC

Date: 23 July 2018

Our Ref: CS/SMO18012365/T1sd3

The Motor Claims Department  
Tenet Sampo Insurance Pte Ltd

**Without Prejudice**

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SGJ 6925G.**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18-07-2018 at the premises of M/s Woon Meng Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,365.11</u> .
Revised Estimate Amount	: S\$ <u>1,326.43</u> .
"Check" Items Amount	: S\$ <u>          </u> .
Market Value	: S\$ <u>          </u> .
LTA Reimbursement Value	: S\$ <u>          </u> .
Nett Value	: S\$ <u>          </u> .

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.  
Repair days: 3 Days

Yours faithfully,  
Mohamad Taufikh  
Automotive Assessor

## Shirley Hiew (LKK Auto)

---

**From:** Heng Sew Sow <woonmeng@singnet.com.sg>  
**Sent:** Wednesday, 29 August 2018 10:56 AM  
**To:** 'Shirley Hiew (LKK Auto)'  
**Cc:** 'Taufikh (LKK Auto)'; sur@lkkauto.com; 'Admin A'  
**Subject:** RE: SGJ6925G ON 04.07.18

Dear Shirley

Accept your offer \$1300.00

Best Regards,  
Heng Sew Sow (Ms)  
Woon Meng Motor Pte Ltd  
Tel: 6316 1131/51  
Fax: 6316 7050

-----Original Message-----

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 29 August 2018 10:42 AM  
**To:** 'Heng Sew Sow' <woonmeng@singnet.com.sg>  
**Cc:** 'Taufikh (LKK Auto)' <taufikh@lkkauto.com>; sur@lkkauto.com; 'Admin A' <admin-a@lkkauto.com>  
**Subject:** RE: SGJ6925G ON 04.07.18

Hi Ms Heng,

Please re-confirmed COR I/s \$1300 , 4 days.

Thank you.  
Best Regards,  
Shirley Hiew | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]  
**Sent:** Thursday, 16 August 2018 10:02 AM  
**To:** 'Heng Sew Sow' <woonmeng@singnet.com.sg>; sur@lkkauto.com; 'Admin A' <admin-a@lkkauto.com>  
**Cc:** 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>  
**Subject:** RE: SGJ6925G ON 04.07.18

Hi Ms Heng,

COR I/s \$1050 , 3 days.

Regards  
Taufikh  
Lkk AUTO

-----Original Message-----

From: Heng Sew Sow [mailto:woonmeng@singnet.com.sg]  
Sent: Saturday, 11 August 2018 1:26 PM  
To: 'Taufikh (LKK Auto)'; sur@lkkauto.com; 'Admin A'  
Subject: SGJ6925G ON 04.07.18

Dear Taufikh

Can we finalise the repair cost

Thank you

Best Regards,  
Heng Sew Sow (Ms)  
Woon Meng Motor Pte Ltd  
Tel: 6316 1131/51  
Fax: 6316 7050

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 23 July 2018 1:45 PM  
**To:** 'Teo, Grace'; assignments@lkkauto.com  
**Cc:** 'Chan, Shu Hui Agnes'; 'Ye, Yong Kang Melvin'; 'SUR'; 'Nivitha (LKK Auto)'  
**Subject:** RE: CMTD1802872/AGC - SUV(LKK)/ & FBM9796K & SGJ6925G ACC ON 04/07/18  
Along Ang Mo Kio Ave 3 Towards Hougang  
**Attachments:** SGJ 6925G - Preli Advise.pdf

Dear Grace,

Enclosed herewith preliminary advice of SGJ 6925G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Friday, 6 July 2018 6:09 PM  
**To:** 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments@lkkauto.com  
**Cc:** 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'SUR' <sur@lkkauto.com>  
**Subject:** RE: CMTD1802872/AGC - SUV(LKK)/ & FBM9796K & SGJ6925G ACC ON 04/07/18 Along Ang Mo Kio Ave 3 Towards Hougang

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [mailto:grace.teo@sompo.com.sg]  
**Sent:** Friday, 6 July 2018 1:39 PM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Woon Meng <woonmeng@singnet.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
**Subject:** CMTD1802872/AGC - SUV(LKK)/ & FBM9796K & SGJ6925G ACC ON 04/07/18 Along Ang Mo Kio Ave 3 Towards Hougang

Our Reference: CMTD1802872/AGC

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Friday, 6 July 2018 1:39 PM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Woon Meng; Chan, Shu Hui Agnes; Ye, Yong Kang Melvin  
**Subject:** CMTD1802872/AGC - SUV(LKK)/ & FBM9796K & SGJ6925G ACC ON 04/07/18  
Along Ang Mo Kio Ave 3 Towards Hougang

Our Reference: CMTD1802872/AGC

Dear LKK AUTO/ MOHD TAUFIKH,

Please make arrangement to conduct the survey for SGJ6925G.

Please be informed that Agnes Chan the handler of this case.

Aside to Agnes,

Please refer to the liability request from Woon Meng Motor Pte Ltd.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy



---

**From:** Woon Meng [mailto:woonmeng@singnet.com.sg]

**Sent:** Friday, July 06, 2018 12:10 PM

**To:** Teo, Grace

**Cc:** Chan, Shu Hui Agnes; Ye, Yong Kang Melvin

**Subject:** RE: CMTD1802872/AGC - PRI(LIA)/ & FBM9796K & SGJ6925G ACC ON 04/07/18 Along Ang Mo Kio Ave 3 Towards Hougang

Dear Grace,

We refer to the matter below for your kind attention.

Please kindly refer to the tick in the table below for our selection.

Thanks & Warmest Regards,



**WOON MENG**

Woon Meng Motor Pte Ltd

Address : 50, Bukit Batok Street 23, #01-06 Midview Building, S(659578)

Tel : 63161131 / 63161151 || Fax : 63167050

---

**From:** Teo, Grace [mailto:grace.teo@sompo.com.sg]

**Sent:** Friday, 6 July 2018 8:57 AM

**To:** Woon Meng <woonmeng@singnet.com.sg>

**Cc:** Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

**Subject:** CMTD1802872/AGC - PRI(LIA)/ & FBM9796K & SGJ6925G ACC ON 04/07/18 Along Ang Mo Kio Ave 3 Towards Hougang

Our Reference : CMTD1802872/AGC

Your Reference: SGJ6925G

**Without Prejudice**

Date: 6<sup>th</sup> July 2018

**Attention:**

**M/S WOON MENG MOTOR**

Dear Ms. Heng,

**ACCIDENT INVOLVING FBM9796K & SGJ6925G ON 04.07.2018**

We refer to your Notice of Accident dated 05/07/2018.

Please be informed that Agnes Chan the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

#### Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	✓
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

--

Aside to Agnes,

Please refer to the liability request from Woon Meng Motor Pte Ltd.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Woon Meng [<mailto:woonmeng@singnet.com.sg>]

**Sent:** Thursday, July 05, 2018 4:34 PM

**To:** Claims - Motor Survey

**Subject:** Accident Involving SGJ6925G & FBM9796K On 04/07/18 Along Ang Mo Kio Ave 3 Towards Hougang

Dear Sir/Madam,

We refer to the above accident for your kind attention.

Kindly be advised that we will be assisting our client, owner of vehicle no: SGJ6925G, to submit a third party claim against your insured vehicle, FBM9796K. We would like to **proceed with direct settlement**.

Please arrange for your surveyor to liaise with us for an inspection of our client's vehicle at your earliest convenience.

Location : 50, Bukit Batok St 23 Midview Building ( S ) 659578 ( Vehicle in )

Warmest Regards,

**Woon Meng Motor Pte Ltd**

Address : 50, Bukit Batok Street 23, #01-06 Midview Building, S(659578)  
Tel: +65 6316 1131 / +65 6316 1151 | Fax: 6316 7050



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/07/2018 13:53
Date Of Accident	04/07/2018 11:20
Exact Location Of Accident	ANG MO KIO AVE 3 TOWARDS HOUGANG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGJ6925G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KONG WEI SING
NRIC No	S7382497D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92712519
Alternative Phone No	OFFICE-92712519
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00292601
Cover Note Number	

### Driver

Name of Driver	KONG WEI SING
NRIC No	S7382497D
Date Of Birth	02/03/1973
Occupation	OUTDOOR
Date Of Driving Pass	29/12/2001
Driving Experience	16 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92712519
Fax Number	
Contact Number	OFFICE-92712519
Email Address	NOEMAIL

Address BLK 450C, BUKIT BATOK WEST AVENUE 6 #09-625  
 Postcode 653450  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 21 BUKIT BATOK EAST AVE 4, POSTCODE: 659840, COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-6659999 - FAX NO: 66655793  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

REFER TO SKETCH PLAN.

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBM9796K  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category MOTORCYCLE  
 Name of Driver GOH TECK ANN  
 NRIC/Passport Number S2145645D  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



*[Signature]*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

( ) Claim Own Damage ( / ) Claim TP ( ) Reporting Only ( ) Claim OD/TP at other workshop

Workshop Name :

SKETCH PLAN



A-5GJ 6925G  
B-FBM 9796K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 4/7/18 at 11:20hrs, I was driving my vehicle along Ang Morkio Ave 3 towards Ploungang. The vehicle in front of me suddenly brake thus, I use emergency brake and the motorcycle FBM 9796K collided onto the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:



# Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578  
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578  
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050  
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523  
( Email Address : woonmeng@singnet.com.sg )  
Co Reg No. 200603678M GST Reg No. 20-0603678M

## Estimate

## TP Claim

To : Sompoo Insurance Singapore Pte Ltd  
Motor Claims Dept

Date : 18 Jul 2018

Dear Sirs :

Fax : 62213302  
62213147

**RE : ESTIMATE COST FOR TOYOTA COROLLA ALTIS 1.6 - SGJ6925G**  
**ACCIDENT INVOLVING SGJ6925G & FBM9796K ON 04/07/2018**

ITEMS	DESCRIPTION	QTY	PRICE
1	Rear bumper.	1pc	\$ 484.90 <i>del</i>
2	Rear bumper retainer @\$88.5ea	2pcs	\$ 177.00 <i>del</i>
3	Rear end panel	1pc	\$ 587.50 <i>Rw</i>
4	Rear bootlid lock.	1pc	\$ 197.41 <i>x nn</i>
			\$ 1,446.81 <i>661.90</i>
	Less 25%		\$ (361.70)
			\$ 1,085.11 <i>496.43</i>
5	Rear sensor.	1pc	\$ 220.00 <i>200 nw</i>
	<b>Labour Charge &amp; Misc</b>		
	To remove, replace, repair & install damaged parts. }		\$ 500.00 ✓
	To R & R wiring and lighting. }		\$ 60.00 <i>30</i>
	To putty & spray painting.		\$ 500.00 <i>,400</i>
			<i>930</i>
<b>Total</b>			<b>\$ 2,365.11</b>

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

- LKK Auto Consultants hence notify**
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Position:

Tan Jiah 97443749  
WP  
3 days  
19/7/18 @ 1050  
1626.43  
Resurvey after repair 4/8/18 @ 1300  
4 days



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18012365/T1sd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 01-09-2018



Code : SMO

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	FBM 9796K	Veh. Inspected	SGJ 6925G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802872/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/07/2018

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107127315	Colour	SILVER
Odometer	196367	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	04/07/2018	Inspection Date	18/07/2018
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 6925G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	484.90	484.90
2	REAR BUMPER RETAINER @\$88.50	NECESSARY	177.00	177.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	587.50	-
1	REAR BOOTLID LOCK	NOT NECESSARY	197.41	-
	LESS 25% DISCOUNT		-361.70	-165.48
			1,085.11	496.42
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR SENSOR (SN)	NOT WORKING	220.00	200.00
			220.00	200.00
	<b><u>LABOUR</u></b>			
	TO REMOVE,REPLACE,REPAIR & INSTALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		500.00	500.00
	TO R&R WIRING AND LIGHTING.		60.00	30.00
	TO PUTTY & SPRAY PAINTING.		500.00	400.00
			1,060.00	930.00
	<b>GRAND TOTAL</b>		<b>2,365.11</b>	<b>1,626.42</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,300.00</b>

Report Ref No. CS/SMO18012365/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.