

ASS. REC. BY:

REF: CS3/MSG18012415/G24d322 Special Instruction:

Survivor  
menimen

Guo Qiang

ASSIGNMENT (Office)

From (Person): Jasmine Lok

of

MSG

Date/Time: 6/7/18 @ 3:44pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCV 6106M

Insured: SKH 6784J

at Workshop n/s ECO Automobile

Tel: 9176 5733

of 13 Kaki Bukit Rd 4 # 03-29

Policy No: 80450449 QMX

Claim No: 563555

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 04/07/2008

CA / REV / REP. / REV 24 HRS <sup>1up</sup>

H.O.D. Endorsement:

Date/Time: 9:48am @ 9/7/18

Person Contacted:

Mr. Alfie

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SCV 6106 M - NA / LPO 8013554/r
	SKH 6784J - X
10/7/18	Discontinued

DOA: 29/04/2008

## ASSIGNMENT

From: \_\_\_\_\_ Date: 9/7/2018

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SCV 6106Mat Workshop m/s Eco Automobileof 13 Kaki Bkt Rd 4 # 03-29

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Mr. Alher 9176 5733

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS up

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SCV6106M Yr Regn: 26 May 2017Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 530i c.c. 1998Colour: Black A/C: Insured / Std / NI / NASp. Reading: 21129 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAJA 520 80 WA 34261Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/35 R19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 09-07-18Survey held at W/SDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 - \$4000

13/7/18 for submit PRS Report

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

120

90

10

180

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9507198-R

**TAX INVOICE**
**JUSEQUITY LAW CORPORATION**  
 171 CHIN SWEE ROAD  
 #02-06 CES CENTRE

SINGAPORE 169877

 INV No. AC1806610  
 INV Date 26/06/2018  
 Reference CS1/LAW18009989/Arbs2  
 Code L053

**PROFESSIONAL SERVICE FEE**

 Vehicle No. SJK 5957E  
 Insured Veh. SGQ 5266U  
 Claim No. JEQ/170536/0617/LHS-PD ml  
 Policy No. CLS.CG.2017.215976.jp  
 Accident Date 25/06/2017  
 Inspection Date

Description	Total
Evaluation	700.00
Subtotal	700.00
GST (7%)	49.00
Grand Total	749.00

We shall be glad if you could forward the payment at your early convenience.

 Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**


NORTH BRANCH

 Date 04 JUL 2018  
 D D M M Y Y

 Pay LKK Auto Consultants Pte Ltd

 Singapore Dollars \$6374.500

Pay-Deefer

S\$

Please sign above the line

**JUSEQUITY LAW CORPORATION**  
 OFFICE'S A/C 2

Cheque No. Bank No. Account No.

1705362097317339652181832900211

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2018		06 Jul 2018 15:44 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>NG WEI SIANG DANNY</b> , ID: NA								
Main Claimant:	<b>TAN YEW KONG</b> , ID: S7029833C								
Vehicle Reg. No.:	<b>SCV6106M</b>	Date of Loss:	04/07/2018 00:00 - :59 [13 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 563555</b>	Policy/Cover Note No.:	80450449QMX (Comprehensive) Coverage: 04/12/2017 - 04/12/2018						
Vehicle Reg. No. (Insured):	<b>SKH6784J</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Eco Automobile Claims And Repair Pte Ltd (HQ)</b> 13 KAKI BUKIT ROAD 4, #03-29, 417807 Kaki Bukit - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 07/07/2018]</b>								
Adj Asg. Remarks:	Third Party Pre-Repair Survey. Insured non-reporting. Contact : Mr Alfie @ 9176 5733								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/07/2018 10:55
Date Of Accident	04/07/2018 19:50
Exact Location Of Accident	BKE TOWARDS WOODLANDS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCV6106M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN YEW KONG
NRIC No	S7029833C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96709770
Alternative Phone No	OTHERS-96709770

### Vehicle Particulars

Manufacturer	BMW
Model	530I LED NAV HUD MSPT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN826994
Cover Note Number	

### Driver

Name of Driver	TAN YEW KONG
NRIC No	S7029833C
Date Of Birth	07/09/1970
Occupation	INDOOR
Date Of Driving Pass	16/10/1989
Driving Experience	28 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96709770
Fax Number	
Contact Number	OTHERS-96709770
Email Address	NOEMAIL

Address	59 CHOA CHU KANG LOOP #08-48 S'PORE 689686
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH6784J
Vehicle Make/Model/Colour	HONDA FIT 1.3G A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: John Tan  
NRIC/FIN No.: S9045678

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04/07/2018 at about 1949hrs, I was travelling along BKE towards Woodlands when the vehicle in front slow down and stop. I slow down and stopped as well. Vehicle B, SKH 6784J, couldn't slow down in time and bang into the rear portion of my vehicle, Vehicle A SCV 6106M.

### DECLARATION

I hereby declare that the foregoing is true and correct to the best of my knowledge.

Signature of Driver  
Date: 04/07/2018

Signature of Witness  
Date: 04/07/2018

Signature of Driver  
Name: JACOB JACOB



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9833C
Vehicle Details	
Vehicle No.:	SCV6106M
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	530I LED NAV HUD MSPT
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	12339936B48B20B
Chassis No.:	WBAJA52080WA34261
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$54,822.00
Original Registration Date:	26 May 2017
First Registration Date:	26 May 2017
Transfer Count:	0
Actual ARF Paid:	\$70,680.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2027
PARF Rebate Amount:	\$53,010.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,406.00
COE Rebate Amount:	\$48,248.00
<b>Total Rebate Amount:</b>	<b>\$101,258.00</b>

The information contained herein is correct as at 12 Jul 2018

OK

### ...CLAIM SUBFOLDER...(Pending for Survey Report)




































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jul 2018		06 Jul 2018 15:44 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>













  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>NG WEI SIANG DANNY</b> , ID: NA									
Main Claimant: <b>TAN YEW KONG</b> , ID: S7029833C									
Vehicle Reg. No.: <b>SCV6106M</b>		Date of Loss: 04/07/2018 00:00 - :59 [13 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 563555</b>		Policy/Cover Note No.: 80450449QMX (Comprehensive) Coverage: 04/12/2017 - 04/12/2018							
Vehicle Reg. No. (Insured): <b>SKH6784J</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Eco Automobile Claims And Repair Pte Ltd (HQ)</b> 13 KAKI BUKIT ROAD 4, #03-29, 417807 Kaki Bukit - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jasmine Lok Kheng Kwei</b> - 6594 2550]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 07/07/2018]									
Adj Asg. Remarks: Third Party Pre-Repair Survey. Insured non-reporting. Contact : Mr Alfie @ 9176 5733									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SCV6106M (563555)  
[SKH6784J]  
TP  
TAN YEW KONG  
Jul 4 2018 12:00AM  
[NG WEI SIANG DANNY]  
Eco Automobile Claims And Repair Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
2	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
3	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
4	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
5	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
6	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
7	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
8	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
9	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
10	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
11	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
12	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
13	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
14	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
15	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
16	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
17	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
18	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
19	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
20	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
21	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
22	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
23	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
24	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
25	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
26	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
27	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
28	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
29	13/07/18 11:45	General View						Load JPG	<input checked="" type="checkbox"/>	
30	13/07/18 11:46	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
31	13/07/18 11:46	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
32	13/07/18 11:46	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
33	13/07/18 11:46	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
34	13/07/18 11:46	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
35	13/07/18 11:46	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
36	13/07/18 11:46	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
37	13/07/18 11:46	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	13/07/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/07/18 11:10	TP PRI	 Load PDF	
2	06/07/18 13:26	EMAIL TP OUR REJECTION & WE NOMINATED LKK TO BE SJE	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012415/GZ4D3E2

Date: 16/07/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80450449QMX

Claimant Vehicle No : SCV6106M

Insured Vehicle No : SKH6784J

Date of Loss: 04/07/2018

Nature of Claim: TP

Claim No: 563555

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SCV6106M

Make &amp; Model: BMW 530I, 2.0 LED NAV (A)

Engine No: 12339936B48B20B

Reg. Date: 26/05/2017 (Man. Year: 2017)

Chassis No: WBAJA52080WA34261

Colour: Black

Odometer: 21129 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 275/35 R19

Rear Tyre Size: 275/35 R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 06/07/2018

Date Inspected: 09/07/2018 Inspected At:

Eco Automobile Claims And Repair Pte Ltd (HQ)

13 KAKI BUKIT ROAD 4, #03-29

Singapore 417807

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2018)
<b>Parts:</b>	143	BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCV6106M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >