

ANS. REC. BY

REP CS/CTI18012416/Ard3

Special Instruction

SWINBUR
Menimen

Adnan

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTI

Date/Time:

6/7/18 @ 3.24pm

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SGL 8527Z

Insured:

SIN 8763L

at Workshop in/:

Z-One Automotive

Tel:

6250 2115

of

1 Kaki Bukit Ave 6 # 01-87 Autobay

Policy No:

DMPCSN 3009 761801

Claim No:

SNM18D03337C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

05/07/2018

CA / REV / REP. / REV 24 HRS

hup?

H.O.D. Endorsement

Date/Time:

9.51am @ 9/7/18

Person Contacted:

Ivonne

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SGL 8527Z - CCG / AIG 12016005 / Usg 24	DOA: 17/8/2012
	SIN 8763L - X	
	Confirm EIS \$2700 @ 5 days	
	(Red: \$2717.48, s.i.)	

ASSIGNMENT

From: _____ Date: 09/07/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGL 85272

at Workshop m/s Zone Automotive

of 1 Kaki Bukit Ave 6 # 01-87 Autobay

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGL85272 Yr Regn: 2006, Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c 1598

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 123238 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MK0532EC10/128054

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/70R17.

R: 185/70R14.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

D.O.I. 09/07/18

Survey held at

2-one

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chrm.

COE Expiry: 28/09/21.

MV: 22K

PV: 17.2K

Nett: 48K

RECEIVED 20 AUG 2018

Date/Time, File Pass to?

☐ : Prel. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS: SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: TP

ump Sum / L.B.I: (\$ 2750)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jul 2018		06 Jul 2018 15:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ALEX TAY , ID: S8601411D								
Main Claimant:	CHUA SIOW LOONG , ID: S7507365H								
Vehicle Reg. No.:	SGL8527Z	Date of Loss:	05/07/2018 07:00 - :59						
Claim Type:	TP / SNM18D03337C02	Policy/Cover Note No.:	DMPCSN3009761801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJN8763L	Policy No. (Claimant):	5094644153						
		Excess:	S\$0.00						
Repairer:	Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/07/2018]								
Driver/Custodian (Insured):	TAN JOANN (29 / Female), NRIC: S8828873D, Tel: +6596284244								
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Date: 06th July 2018

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Email Only

claimsdept@sg.cntaiping.com

Attn: Motor Claims Department

Dear Sirs

**ACCIDENT INVOLVING VEHICLES SGL8527Z & SJN8763L ALONG TPE SLIP ROAD
TOWARDS LOYANG AVE ON 05/07/2018 AT 0745HRS**

We are instructed by **CHUA SIOW LOONG** to notify you of a road traffic accident on 05 July 2018 at 0745hrs along TPE Slip Road towards Loyang Ave involving our customer's vehicle registration number SGL8527Z and vehicle registration number SJN8763L driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report will be forwarded to you once we are in receipt of the same.

As a result of the accident, our customer's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Yvonne Yong

Z-One Automotive Pte Ltd

Tel: 62502115

MSME18087109 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 06/07/2018 12:47
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/07/2018 12:47
 Date Of Accident 05/07/2018 07:45
 Exact Location Of Accident TPE SLIP RD TWDS LOYANG AVE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGL8527Z
Insured/Policyholder
 Name Of Registered Owner CHUA SIOW LOONG
 NRIC No S7507365H
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-97685509
 Alternative Phone No OFFICE-97685509

Vehicle Particulars

Manufacturer TOYOTA
 Model ALTIS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy NO
 Policy Number 5094644153
 Cover Note Number

Driver

Name of Driver SONG BUZHU
 NRIC No S7279829E
 Date Of Birth 23/08/1972
 Occupation INDOOR
 Date Of Driving Pass 27/06/2005
 Driving Experience 13 YEARS AND 0 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-86661675
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 123A RIVERVALE DRIVE #07-135
 Postcode 541123
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - -
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : CHUA CHENGXU
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4629999 - FAX NO: 64628933
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20180706/2008

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJN8763L
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver TAN JANN
 NRIC/Passport Number S8828873D
 Contact Number 96284244
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

SONG BUZHU

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGL8527Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(Policyholder or authorised person)
Date & Time

Reporting Centre's Representative Signature
Name
ID No. / PIN No.

7-ONE

Sketch Plan #2 Pg. 1

SKETCH PLAN

Vehicle A : SGL 8527E

Vehicle B : SJN 8763L

TPE Slip Road Towards Loyang Ave.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

2 Refer to the Police Report T/2018 07 06 / 2008 2

DECLARATION

I/We declare the foregoing particulars are true to the best of my/our knowledge.


 Perpetrator's Signature
 Date & Time


 Officer's Signature
 Date & Time

6/7/18 at 11.25 AM
 Reporting Officer's Signature
 Name
 NRIC No.

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Bukit Timah N.P.C.
1 Duke's Road SINGAPORE 261014
Tel No. 1800 4629899



T/20180705/2008

2 of 4

Report No. T/20180705/2008

CONTINUATION OF REPORT

Passenger			
Name	Chua Cheng Xu Lawrence	ID No.	S9831451Z
Related Vehicle	SGL8527Z (Car)	Contact No.	83662145
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SONG BUZHU	ID No.	S7279829E
Related Vehicle	SGL8527Z (Car)	Contact No.	86661675
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	06/07/2018	Date Discharge	06/07/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	Tan Joann	ID No.	S8828873D
Related Vehicle	SJN8763L (Car)	Contact No.	96284244
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

On 06/07/2018 at about 0745hrs, I was travelling along TPE towards Changi. Subsequently, I exit TPE and proceed along road towards Loyang Ave. As there was heavy traffic, my vehicle was stationary at the intersection of the 2 lane road.

At that time, I was impacted from the rear of the vehicle. I then alighted the vehicle and noticed that the driver of the vehicle was seen taking picture of the accident. As such, I proceed to take picture of the vehicle and exchange particulars and left the scene.

After the accident, I then felt nausea and giddy. As such I proceed to Mount Alvernia Hospital for treatment from 08/07/2018 to 10/07/2018. I wish to state that there is not a car camera inside my vehicle.

Sketch Plan #5 Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Bukit Timah N.P.C.
1 Duke's Road SINGAPORE 268914
Tel No: 1800 4629999



1/20180706/2108

4/1/1

Report No: 1/20180706/2108

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E/
Staff Sgt ONG CHUN KAI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
Sgt ONG SIEU LUI
65478151

Stamp



Signature Of Informant:

Date/Time:
06/07/2018 01:54

Classification Of Case:

SN 170

SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	7365H
Vehicle Details	
Vehicle No.:	SGL8527Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Gold
Manufacturing Year:	2006
Engine No.:	3ZZ4592743
Chassis No.:	MR053ZEC107128054
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,498.00
Original Registration Date:	29 Sep 2006
First Registration Date:	29 Sep 2006
Transfer Count:	0
Actual ARF Paid:	\$17,048.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,670.00
COE Rebate Amount:	\$17,157.00
Total Rebate Amount:	\$17,157.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Jul 2018.

OK



☐ Toyota Corolla Altis 1.6A (COE till 05/2021) \$18,500 \$6,520 /yr 11-May-2006 1,598 cc 206,228 km Sedan Available

Regularly Servicing.

DIRECT OWNER

★ Posted: 16-Jul-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 05/2021) \$18,988 \$6,610 /yr 24-May-2006 1,598 cc 187,400 km Sedan Available

Direct Sale By Car Owner. New Road Tax. Regularly Servicing. Feel Free To Call To Arrange A Test Drive!

DIRECT OWNER

★ Posted: 22-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 05/2021) \$18,500 \$6,430 /yr 26-May-2006 1,598 cc 195,703 km Sedan Available

Direct Sale By Car Owner. Road Tax Expires Nov 2018. Regularly Serviced, Relatively New Tyres. Please Call To Arrange A Test Drive!

DIRECT OWNER

★ Posted: 03-Jul-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Lease a car for peace of mind

No worries over hefty repair costs and depreciation with leasing. Find the list of recommended car leasing companies now.

Find out more!



☐ Toyota Corolla Altis 1.6A (COE till 06/2021) \$21,899 \$7,390 /yr 26-Jun-2006 1,598 cc 128,000 km Sedan Available

\$3000 Down Payment. Low Mileage. Popular Choice For Daily Use! Excellent Fuel Efficiency With Ample Space For Passengers And Boot Storage. Well Maintained By Previous Owner. Clean And Neat Interior! B...

★ Posted: 09-Jun-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 06/2021) \$23,899 \$8,060 /yr 27-Jun-2006 1,598 cc 123,000 km Sedan Available

\$3000 Down Payment. Low Mileage. Popular Choice For Daily Use! Excellent Fuel Efficiency With Ample Space For Passengers And Boot Storage. Well Maintained By Previous Owner. Clean And Neat Interior! B...

★ Posted: 03-Jul-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 06/2021) \$30,800 \$10,370 /yr 29-Jun-2006 1,598 cc - Sedan Available

New Paint And New Leather. Engine And Gearbox In Good Condition. All Our Vehicles Has Undergone A 120 Points Safety Check By Our In House Mechanics With Assessment Report And Come With One Year In Hou...

★ Posted: 29-Jun-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 05/2021) \$20,500 \$7,090 /yr 05-Jul-2006 1,598 cc 74,000 km Sedan Available

1 Owner Only. Very Well Maintained By Previous Owner. Engine And Gearbox Are In Good Condition. Nice Exterior And Interior. Flexible Loan Available. No GST Included. Call Us Now.

★ Posted: 03-Jul-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 11/2021) \$23,900 \$7,060 /yr 28-Nov-2006 1,598 cc - Sedan Available

\$2500 Drive Away. Flexible In-House Loan Packages Available. Very Well Kept. Low Maintenance Cost.

Prime Motor & Leasing

★ Posted: 23-Jun-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 12/2021) \$23,800 \$6,940 /yr 14-Dec-2006 1,598 cc - Sedan Available

Elegant Silver, Flexible In-house Loan Packages Available, Low Maintenance Cost, Low Fuel Consumption, Very Well Maintained.

TS Wheeler Capital Pte Ltd

★ Posted: 22-Jun-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 01/2022) \$24,388 \$6,900 /yr 22-Jan-2007 1,598 cc 138,000 km Sedan Available

Low Mileage. Popular Choice For Daily Use! Excellent Fuel Efficiency With Ample Space For Passengers And Boot Storage. Trusted And Dependable Toyota. \$3000 Drive-Away. Full Loan Available. Call Us Now ...

★ Posted: 27-Jun-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

BOOK FAVORITE HISTORY

Compare

☐ Toyota Corolla Altis 1.6A (COE till 12/2021) \$24,838 \$6,990 /yr 29-Jan-2007 1,598 cc 142,000 km Sedan Available



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg, enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE

Company Registration No. 201118055N

TP China

Service

ESTIMATE

Chua Siow Loong
Blk123A Rivervale Drive #07-135 Singapore
541123

Contact : 86661675 97685509

Code : C101810

Date in : 06/07/2018

Vehicle Num. : SGL8527Z

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053ZEC107126054/3ZZ4592743

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Rear Boot Lid <i>Repair</i>	1	840.00	840.00 ✓
Rear Boot Lid "1.6" Emblem	1	46.00	46.00 ✓
Rear Boot Lid "Altis" Emblem	1	48.00	48.00 ✓
Rear Boot Lid "Corolla" Emblem	1	75.00	75.00 ✓
Rear Boot Lid "E" Emblem	1	30.00	30.00 ✓
Rear Boot Lid "Logo" Emblem	1	58.00	58.00 ✓
Rear Boot Lid "VVTi" Emblem	1	40.00	40.00 ✓
Rear Boot Lid Lock Striker <i>Not in</i>	1	39.90	39.90 ✓
Rear Boot Lid Mechanism Lock <i>Not in</i>	1	101.00	101.00 ✓
Rear Boot Lid Reflector Lamp L/R <i>2 pcs in</i>	2	89.65	179.30 ✓
Rear Boot Lid Rubber Guide Stopper L/R	2	17.00	34.00 ✓
Rear Boot Lid Weather Strip <i>Not in</i>	1	175.00	175.00 ✓
Rear Bumper <i>Deformed</i>	1	495.00	495.00 ✓
Rear Bumper Impact Bracket L/R/H <i>2 Deformed</i>	1	45.00	45.00 ✓
Rear Bumper Side Retainer L/R <i>2 in</i>	2	36.90	73.80 ✓
Rear End Panel <i>Painted</i>	1	700.50	700.50 ✓
Rear End Panel Inner Top Garnish <i>Deformed</i>	1	68.75	68.75 ✓



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Rear End Panel Inner Top Garnish Clips <i>Me</i>	2	9.80	19.60 <i>210</i>
Rear Taillamp Apron Panel L/R <i>2H dented</i>	2	86.45	172.90 <i>+ 8645</i>
Rear Taillamp Apron Panel Rivet L/R <i>Me</i>	2	6.90	13.80 <i>+</i>
Rear Taillamp Clips L/R <i>Me</i>	2	12.10	24.20 <i>2</i>
Rear Taillamp Gasket L/R <i>Me</i>	2	12.00	24.00 <i>0</i>
Rear Taillamp L/R <i>cracked</i>	1	289.55	289.55 <i>2</i>
Rear Taillamp Panel L/R <i>2H Buckled</i>	2	95.00	190.00 <i>95</i>
Subtotal before discount			3,783.30
Percentage discount 25%			945.83
Sub-total 1			2,837.48
Rear Bumper Clips (Set) (SN) <i>Me</i>	1	30.00	30.00 <i>✓</i>
Rear Bumper Reverse Sensor (Set) (SN) <i>Damaged</i>	1	350.00	350.00 <i>200</i>
Subtotal before discount			380.00
Percentage discount 0%			0.00
Sub-total 2			380.00
Parts-total			3,217.48

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	120.00 <i>30</i>
To remove, refix / renew reverse sensor assy and rectify for proper functioning.	80.00 <i>50</i>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80.00 <i>40</i>
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00 <i>700</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800.00 <i>700</i>

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 3406.93
h/s 27K

Adrian Ling
h/s 09/09/18
Mod days: 05



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: [625021115](tel:625021115)/[66342112](tel:66342112) Fax: [66342122](tel:66342122)

Email: service@z-one.com.sg, enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

To apply anti-rust chemical on repaired and replaced panel.	120.00 ✕
Labour Total	2,200.00
Parts & Labour Total	5,417.48































...CLAIM SUBFOLDER...(Pending for Survey Report)
















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jul 2018		06 Jul 2018 15:24 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ALEX TAY , ID: S8601411D								
Main Claimant:	CHUA SIOW LOONG , ID: S7507365H								
Vehicle Reg. No.:	SGL8527Z	Date of Loss:	05/07/2018 07:00 - :59 [141 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03337C02	Policy/Cover Note No.:	DMPCSN3009761801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJN8763L	Policy No. (Claimant):	5094644153						
		Excess:	S\$0.00						
Repairer:	Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/07/2018]								
Driver/Custodian (Insured):	TAN JOANN (29 / Female), NRIC: S8828873D, Tel: +6596284244								
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGL8527Z (SNM18D03337C02)
[SJN8763L]
TP
CHUA SIOW LOONG
Jul 5 2018 7:00AM
[ALEX TAY]
Z-one Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/07/18 12:55	Accident Statement	 Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/07/18 12:54	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	06/07/18 12:54	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	06/07/18 12:54	Driving License [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	06/07/18 12:54	INSURANCE [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	06/07/18 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	06/07/18 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	06/07/18 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	06/07/18 12:54	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	06/07/18 12:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	06/07/18 12:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	06/07/18 12:55	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
19	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/08/18 16:46	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/08/18 16:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/07/18 15:24	PRS	Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
2	06/07/18 15:24	OI GIA	Load PDF	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/07/18 12:52	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	06/07/18 12:52	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	06/07/18 12:53	Sketch Plan #3 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	06/07/18 12:53	Sketch Plan #4 [Linked Accident Report Documents]	Load TIF	
5	06/07/18 12:53	Sketch Plan #5 [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/07/18 12:55	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/07/18 12:54	Identification Card	Load JPG	<input checked="" type="checkbox"/>
2	06/07/18 12:54	Identification Card	Load JPG	<input checked="" type="checkbox"/>
3	06/07/18 12:54	Driving License	Load JPG	<input checked="" type="checkbox"/>
4	06/07/18 12:54	INSURANCE	Load JPG	<input checked="" type="checkbox"/>
5	06/07/18 12:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	06/07/18 12:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	06/07/18 12:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	06/07/18 12:54	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	06/07/18 12:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	06/07/18 12:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	06/07/18 12:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/07/18 12:52	Sketch Plan	Load TIF	
2	06/07/18 12:52	Sketch Plan #2 Click here & type to add comment...	Load TIF	
3	06/07/18 12:53	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>
4	06/07/18 12:53	Sketch Plan #4	Load TIF	
5	06/07/18 12:53	Sketch Plan #5	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18012416/ARD3Q2

Date: 06/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3009761801

Claimant Vehicle
No: SGL8527ZInsured Vehicle
No: SJN8763L

Date of Loss: 05/07/2018

Nature of Claim: TP

Claim
No: SNM18D03337C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGL8527Z**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 Classic (A)

Engine No: 3ZZ4592743

Reg. Date: 29/09/2006 (Man. Year: 2006)

Chassis No: MR053ZEC107128054

Colour: Gold

Odometer: 123238 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,217.47	1,886.94	1,330.53	41.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,520.00	680.00	30.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,417.47	3,406.94	2,010.53	37.11
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	5,417.47	2,700.00	2,717.47	50.16
+ GST 7.00/7.00% (S\$)	379.22	189.00	190.22	50.16
Nett Amount (S\$)	5,796.69	2,889.00	2,907.69	50.16

INSPECTION

Date of Assignment: 06/07/2018

Date Inspected: 09/07/2018 Inspected At:

Z-one Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, Blk D #01-87,
Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Classic (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL8527Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	840.00 FL	*- FL
2	1		*REAR BOOT LID 1.6 EMBLEM	Necessary	46.00 FL	*46.00 FL
3	1		*REAR BOOT LID ALTIS EMBLEM	Necessary	48.00 FL	*48.00 FL
4	1		*REAR BOOT LID COROLLA EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1		*REAR BOOT LID E EMBLEM	Necessary	30.00 FL	*30.00 FL
6	1		*REAR BOOT LID LOGO EMBLEM	Necessary	58.00 FL	*58.00 FL
7	1		*REAR BOOT LID VVTI EMBLEM	Necessary	40.00 FL	*40.00 FL
8	1		*REAR BOOT LID LOCK STRIKER	Not Necessary	39.90 FL	*- FL
9	1		*REAR BOOT LID MECHANISM LOCK	Not Necessary	101.00 FL	*- FL
10	2		*REAR BOOT LID REFLECTOR LAMP L/R	Not Necessary	179.30 FL	*- FL
11	2		*REAR BOOT LID RUBBER GUIDE STOPPER L/R	Not Necessary	34.00 FL	*- FL
12	1		*REAR BOOT LID WEATHER STRIP	Not Necessary	175.00 FL	*- FL
13	1		*REAR BUMPER	Deformed	495.00 FL	*495.00 FL
14	1		*REAR BUMPER IMPACT BRACKET L/R RH	Dented	45.00 FL	*45.00 FL
15	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	73.80 FL	*73.80 FL
16	1		*REAR END PANEL	Dented	700.50 FL	*700.50 FL
17	1		*REAR END PANEL INNER TOP GARNISH	Deformed	68.75 FL	*68.75 FL
18	2		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	19.60 FL	*10.00 FL
19	1		*REAR TAILLAMP APRON PANEL L/R	O/S Dented	172.90 FL	*86.45 FL
20	2		*REAR TAILLAMP APRON PANEL RIVET L/R	Not Necessary	13.80 FL	*- FL
21	2		*REAR TAILLAMP CLIPS L/R	Necessary	24.20 FL	*24.20 FL
22	2		*REAR TAILLAMP GASKET L/R	Necessary	24.00 FL	*24.00 FL
23	1		*REAR TAILLAMP L/R	Cracked	289.55 FL	*289.55 FL
24	1		*REAR TAILLAMP PANEL L/R	O/S Buckled	190.00 FL	*95.00 FL
25	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,163.30	2,439.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	945.83	552.31
Total Parts (\$\$)	3,217.47	1,886.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSE, REPLACE AND /OR REPAIR TO RECTIFY REAR PORTON ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	120.00	30.00
2	TO REMOVE,REFIX /RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	New	80.00	50.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	40.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDEN	New	1,000.00	700.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR -RE CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	700.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	0.00
Gross Labour Cost (\$\$)			2,200.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >