

ASS. REC. BY

REF: CS/CTI18012417 / Gvd3

SULVOR
NUMBER

From (Person)

Guo Chang
Huang-Shiang Yi

ASSIGNMENT (Office)

of CTI

Date/Time: 6/7/18 @ 3:04pm

Estimated Cost:

Bill to:

① OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 629 K

Insured:

at Workshop n/s:

Kah Motor

Tel: 6846 5673 / 8100 6306

of

15 Ubi Road 4

Policy No:

DMPCSN 1669891701

Claim No:

SNM18DD 3338C01

Sum Insured:

Excess:

1BA 1000

Make of Veh:

(Client's Record)

D.O.A

30/06/2018

CA / REV

/ REP. / REV 24 HRS

10/7/18 @ 11am aw

H.O.D. Endorsement:

Date/Time:

9:54am @ 9/7/18

Person Contacted:

Amy chun

Vehicle IN / OUT

Date/Time	Action/Instruction
	(✓) Estimate check consistency of the damages
	Pls note that Ins. with pre-existing Accident on 18/02/18 and rejected OD claim. Refer to both accident Report, Damages at the Rear Bumper.
	SKW 629 K - X
10/7/18	Revert via merimen
11/7/18	@ 1130am Eric call up to cancel garnish assy R, slide door lwr and garnish assy R wheel arch

Xhe.

REF: CTI

6554J

ASSIGNMENT

From: Date: 10072018

Estimated Cost:

① TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 629K

at Workshop m/s: Kah motor

of: 15 Ubi Rd 4

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

TBA

(Client's Record)

Any

Make of Veh: 18-12-2018 got Pre-existing accident

(Policy Condition)

From owner willing

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$110K.

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est Repair: 3.8 days Res: Yes or No

Lump Sum % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKW629K

Vr Regn: 15 Oct 2015

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda odyssey 2356

Colour:

white

A/C Insured / Std / Nil / NA

Sp Reading:

15064

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JHLMRC1890FC203162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

"

BS / DUNLOP / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

10-07-18

Survey held at:

w/s

11:30 AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

11/7/18 Re- seek mandate via merimen

12/7/18 Rere approved \$1796.94 from Susan Teo by merimen

12/7/18 Informed Ary clA ex \$1000 by email

19/7/18 Rere email from shiang yi to 'close the file

20/7/18 Submit preli report

RECEIVED 20 JUL 2018

Date/Time: File Path to:



Preli. Report

If



Final Report

Date/Time: File Path to:

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

220

Transportation:

Site Insp:

Interview:

Tech. Insp:

Weekend:

TOTAL

220

20/7 - typist

Report Format:

merimen

Lump Sum / I.B.I. is

Add Fee:



Site Insp: 15



Interview: 15



Tech. Insp: 15



Weekend: 15

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jul 2018		06 Jul 2018 15:04 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	NG DJONI, ID: S7276554J, Tel: +6581989989, Email: NGDJONI@GMAIL.COM		
Vehicle Reg. No.:	SKW629K	Date of Loss:	30/06/2018 11:00 - 15:59
Claim Type:	OD / SNM18D03338C01	Policy/Cover Note No.:	DMPCSN1669891701 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/07/2018]		
Driver/Custodian:	NG DJONI (46 / Male), NRIC: S7276554J, Tel: +6581989989		
Adj Asg. Remarks:	PLEASE SURVEY INSURED VEHICLE & REVERT AND CHECK THE CONSISTENCY OF THE DAMAGES. PLEASE NOTED THAT INSURED WITH PRE-EXISTING ACCIDENT ON 18/02/2018 AND WE REJECTED THE OWN DAMAGES CLAIM, REFER TO BOTH ACCIDENT REPORT, DAMAGES AT THE REAR BUMPER.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 19 July 2018 12:48 PM
To: 'Hwang Shiang Yi'; Ary Chua
Cc: Liew Thye Wui; SUR
Subject: RE: SKW 629K-DOA: 30/6/2018 (CHINA TAIPING) -SNM18D03338C01/9

Dear Shiang Yi,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hwang Shiang Yi [mailto:shiangyi.hwang@sg.cntaiping.com]
Sent: Thursday, 19 July 2018 12:39 PM
To: Ary Chua <arychua@honda.com.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Liew Thye Wui <twliw@honda.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SKW 629K-DOA: 30/6/2018 (CHINA TAIPING) -SNM18D03338C01/9

Dear Ary,

Noted.

Dear Veron,

Please assist upload your survey fees and close the file.

Thanks & Regards,

Hwang Shiang Yi

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6541

Fax (65) 6224 7175 /62247478

Website :www.sg.cntaiping.com

Email :claimsdept@sg.cntaiping.com

shiangyi.hwang@sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Ary Chua [mailto:arychua@honda.com.sg]

Sent: Thursday, 19 July, 2018 12:26 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Hwang Shiang Yi <shiangyi.hwang@sg.cntaiping.com>; SUR <sur@lkkauto.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>

Subject: RE: SKW 629K-DOA: 30/6/2018 (CHINA TAIPING)

Hi Veron Chen & Shiang Yi,

Kindly Closed this Case OD Claim from China Taiping.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Thursday, 12 July, 2018 12:55 PM

To: Ary Chua <arychua@honda.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: SKW 629K-DOA: 30/6/2018 (CHINA TAIPING)

Dear Ary,

As instructed by our client , please proceed to repair the insured vehicle **SKW 629K** , please refer mark **estimate attached, (Excess \$1000/-)**,

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: mkm118086906 Vehicle Registration No: SKW 629K
Name(as shown in NRIC): Ng Djoni
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No: S7276554J
Address: Blk 260B Sengkang East Way #13-442 S542260
Contact (Tel): — (H/P): 8198 9989
(Email): ngdjoni@gmail.com
Date of Accident: 30/06/2018 Time of Accident: 11:00am
Place of Accident: Car Park 1120A Serangoon Rd
Insurance Company: China Taiping Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Own Damage claim Change it to Reporting Only
& withdraw Own Damage claim from China Taiping
Insurance. Refer to attachment behind page.



Signature of Vehicle Owner / Driver

Date: 19 JUL 2018 @ 10:10am

Date: 19 JUL 2018 @ 11:11 am

To : China Taiping Insurance Pte Ltd

Re : Withdrawal of claim.

Att : Motor Claim Department,

I, Ng Djoni owner of vehicle registration number STW 629K
accident date on 30/06/2018 insured with insurance : China Taiping, policy
number DM PCSN1669891701 hereby, wish to withdraw the claim make earlier
and will pay full amount repair cost by myself.

Regret for any inconvenience caused.

Regards,



Ng Djoni
NRIC: S7076554J



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Ardur Road #15-00 Springvale Tower Singapore 329505
Tel: 6389 6111 Fax: 6222 1033
Website: www.ctaiping.com
Cn Reg No: 2000083842

OUR CLAIM NO : **SNM18D03338/C01**

DATE : **12 JULY 2018**

BY POST

**NG DJONI
BLK 260B SENGKANG EAST WAY
#13-442
SINGAPORE 542260 542260**

Dear Sir/Madam,

POLICY NO : **DMPCSN1669891701**
ACCIDENT INVOLVING : **SKW629K**
DATE OF ACCIDENT : **30 JUNE 2018**

We refer to the above and the own damage claim submitted to our office on **06 JULY 2017**.

We have appointed the following surveyor to survey your vehicle at the following workshop.

SURVEYOR : **LKK AUTO CONSULTANTS PTE LTD**
DISTRIBUTOR : **KAH MOTOR CO SDN BHD**

We wish to inform you that the policy excess is **S\$ 1,000.00** (subject to GST, if applicable).

Please do not hesitate to contact us if you require further clarifications.

Yours sincerely,

**CLAIMS DEPARTMENT
MOTOR DIVISION
DID : 6389 6111
FAX: 6225 5879**

(This is a computer generated letter and no signature is required.)

CC : **SAFE HARBOUR ENSURANCE
(AN0412A)**

Ary Chua

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 12 July, 2018 12:55 PM
To: Ary Chua
Cc: SUR
Subject: SKW 629K-DOA: 30/6/2018 (CHINA TAIPING)
Attachments: MARK ESTIMATE.pdf

Dear Ary,

As instructed by our client , please proceed to repair the insured vehicle **SKW 629K** , please refer **mark estimate attached, (Excess \$1000/-)**,

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 12 July 2018 12:55 PM
To: 'Ary Chua'
Cc: SUR
Subject: SKW 629K-DOA: 30/6/2018 (CHINA TAIPING)
Attachments: MARK ESTIMATE.pdf

Dear Ary,

As instructed by our client , please proceed to repair the insured vehicle **SKW 629K** , please refer mark estimate attached, (Excess \$1000/-),

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKW629K (SNM18D03338C01)**

OD

Jun 30 2018 11:00AM

[NG DJONI]

Kah Motor Co Sdn Bhd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 12/07/2018 09:19 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1796.94) - SKW629K - Claim Handler: Hwang Shiang Yi

Approved:1796.94.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Hwang Shiang Yi	Date: 11 Jul 2018

Preliminary Advice

Vehicle No	: SKW629K	Accident Date	: 30/06/2018
Make	: HONDA ODYSSEY	Policy No.	: DMPCSN1669891701
Assignment Date	: 06/07/2018	Excess	: S\$1,000.00
Date of Inspection	: 10/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,801.82
Revised Amount	:S\$	6,938.86
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,938.86

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	64,694.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,306.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

()

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Hwang Shiang Yi	Date:	10 Jul 2018

Preliminary Advice

Vehicle No	: SKW629K	Accident Date	: 30/06/2018
Make	: HONDA ODYSSEY	Policy No.	: DMPCSN1669891701
Assignment Date	: 06/07/2018	Excess	: S\$0.00
Date of Inspection	: 10/07/2018	Est. Duration of Repair	: 6.00
Inspection At	KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	S\$	13,801.82
Revised Amount	S\$	7,165.43
Check Items (Estimated)	S\$	0.00
Total	S\$	7,165.43

Lump Sum Repair	S\$	
-----------------	-----	--

Total Loss Consideration

New for Old Value	S\$	
Pre-Accident Value	S\$	110,000.00
COE / PARF Rebate	S\$	64,694.00
Salvage Value	S\$	
Margin for Repair	S\$	45,306.00

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle was involved in an accident on 18/2/2018. The damage area is at the same area as this current accident on 30/6/2018. Furthermore , current accident is reported to hit and run.
We suggest to carry out interview/ investigation.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6554J
Vehicle Details	
Vehicle No.:	SKW629K
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K24W71011552
Chassis No.:	JHMRC1890FC203162
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$27,090.00
Original Registration Date:	15 Oct 2015
First Registration Date:	15 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$29,926.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2025
PARF Rebate Amount:	\$22,444.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$42,250.00
Total Rebate Amount:	\$64,694.00

The information contained herein is correct as at 10 Jul 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6554J
Vehicle Details	
Vehicle No.:	SKW629K
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K24W71011552
Chassis No.:	JHMRC1890FC203162
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$27,090.00
Original Registration Date:	15 Oct 2015
First Registration Date:	15 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$29,926.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2025
PARF Rebate Amount:	\$22,444.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$42,250.00
Total Rebate Amount:	\$64,694.00

The information contained herein is correct as at 10 Jul 2018

OK



**SINGAPORE
POLICE FORCE**



F/20180219/2245

1 of 2

POLICE REPORT (NP299)

Report No. F/20180219/2245

Police Station Of Origin
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Date/Time Report Made 19/02/2018 21:45	Vide Report No.	Station Diary No. 175
Name Of Informant CHING AI HOON KAREN	Address APT BLK 260B SENGKANG EAST WAY #13-442 SINGAPORE 542260	
ID Type / ID No. NRIC NO / S7322318J	Contact No. Home/Office	Mobile 91813344
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Admin	Sex Female	Age 44
Institution/School Name	Date of Birth 01/07/1973	Race Chinese
Date/Time Of Incident 18/02/2018 20:00 - 18/02/2018 20:00	Location Of Incident Highway Road from KL back to Singaopre North-South Expressway, Ayer, Keroh 75450 Malaysia MALAYSIA	

Brief details.

On 18/02/2018 at about 2000hrs, I was driving along Malaysia North- South Expressway heading towards Singapore. I was driving bearing plate number SKW 629K along the second lane of the expressway. While I was driving, an unknown vehicle was driving along lane 1. The vehicle suddenly made a slight left turn and hit on the rear right of my vehicle. Subsequently, I slowed down my vehicle at the road shoulder. However, the unknown vehicle did not stop and continued to travel along lane 1. I had

Signature Of Officer Recording The Report: F / Sgt 2 B HEMANRAJ	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 19/02/2018 21:45
Officer In-Charge Of Case: F / Sengkang N.P.C / Sgt 2 NUR AMIRA BINTE ROZIMAN Contact No.: 63438999	Classification Of Case:

Authentication Stamp

h
POLICE

The vehicle was involved in an accident on 18/02/2018 & damage to area is same at the same area as this current accident on 20/02/18. Furthermore, current accident is reported to hit and run. We suggest to carry out interview / investigation.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/07/2018 18:22
Date Of Accident	30/06/2018 11:00
Exact Location Of Accident	CAR PARK 1120A SERAGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW629K
Insured/Policyholder	
Name Of Registered Owner	NG DJONI
NRIC No	S7276554J
Email Address	NGDJONI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81989989
Alternative Phone No	OFFICE-81989989

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 EX-S (RC1) (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1669891701
Cover Note Number	

Driver

Name of Driver	NG DJONI
NRIC No	S7276554J
Date Of Birth	19/05/1972
Occupation	INDOOR
Date Of Driving Pass	14/06/1996
Driving Experience	22 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81989989
Fax Number	
Contact Number	OFFICE-81989989
Email Address	NGDJONI@GMAIL.COM

Address BLK 260B SENGKANG EAST WAY #13-442
Postcode S542260
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name SENGKANG NPC
Police Station Address ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

HIT & RUN CASE. CAR IS PARKING

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Vehicle No

SEW 629K

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

16:28pm Ary
05 JUL 2018
ARY CHUA

Car park 1120A
Serangoon Road

A: SEW 629K
? - Hit & Run

(Please continue in Annex E)

Vehicle No SKW629K

Annex E

Describe Circumstances of the Accident

Refer to Police Report No: T/20180630/2148
Hit & Run case.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

16:28pm 
05 JUL 2018 ARY CHUA

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20180630/2148

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

1 of 3

Report No. T/20180630/2148

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/06/2018 21:15	Vide Report No.:	Station Diary No.: 161
--	------------------	---------------------------

Informant's Particulars

Name of Informant: CHING AI HOON KAREN			Address: APT BLK 260B SENGKANG EAST WAY #13-442 SINGAPORE 542260		
ID Type / ID No.: NRIC NO / S7322318J			Contact No.: Home/Office: Mobile: 91813344		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 44	Date of Birth: 01/07/1973	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: ADMIN			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 30/06/2018 11:00	Type of Location: Car park
Location: Along Road 1 SERANGOON ROAD				
Carpark at 1120A Serangoon Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: unknown				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKW629K	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180630/2148

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 3
Report No. T/20180630/2148

CONTINUATION OF REPORT

Brief Details.

On 30/06/2018 at about 1100hrs, I parked my car bearing SKW629K at the car park. Before I left, everything was in order and intact.

On the same day at about 1140hrs, when I went back I discovered that my car rear right portion was damaged. No one was at scene and I am unsure which car knocked onto my car and caused this damaged.

There is CCTV at the car park exit. I lodge this police report for my insurance claim purposes. That's all.



**SINGAPORE
POLICE FORCE**



T/20180630/2148

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 3

Report No. T/20180630/2148

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 1 LEONG GHUM WAI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

30/06/2018 21:15

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt ESTHER CHONG

Contact No.: 65476368

Classification Of Case:

Authentication Stamp

NP168



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

MX1FE SN
AN0412A
Cov.Type: C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DNPEN1669891701	Engine No : K24W71011552 Chassis No: JHMBCL890FC203162
1. Index Mark and Registration Number of Vehicle	SEWS29K	
2. Name of Policy Holder	NG DJONI	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	15 OCTOBER 2017	NAMED DRIVERS EX SECT. IS\$1,000.00 ADDITIONAL EX OTHER THAN NAMED DRIVERS: EX SECT. I - AGE <= 35.....S\$3,000.00 EX SECT. I - AGE >= 36.....S\$500.00 * AGE AS AT DATE OF ACCIDENT EX ON WINDSCREENS\$100.00
4. Date of Expiry of Insurance	14 OCTOBER 2018	
5. Persons or Classes of Persons entitled to drive *		
(A) THE POLICYHOLDER.		
(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.		
PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.		
6. Limitations as to use: *		
USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING FACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.		
EXCESS WHICHVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS/THEFT) WILL BE DOUBLED. ONE TIME WAIVER OF EXCESS FOR THE FIRST S\$500 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORIZED WORKSHOPS FOR EACH POLICY YEAR.		
HIRE PURCHASE CO. : DBS BANK LTD AS HP OWNER * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned By:

Authorised Officer

Authorised Signatory



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

*Libra = 68411973
11am tomorrow 10/07/2018
Urgent Action!*

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18002769	Page	1
	3 ANSON ROAD #16-00	Date	: 6. Jul 2018		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 6. Jul 2018 10:15:00 AM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	:		
Owner's Name	: NG DJONI	Survey Date	: TUE : +65 6846 5673		
Ins Policy No.	: DMPCSN1669891701	Authorisation Date	: WF : +65 8100 8306		
Date of Accident	: 30/6/2018		Email : ary@honda.com.sg		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 70812						
	POLICY/CLAIMS NO: DMPCSN1669891701						
	OWNER: NG DJONI						
	ACC DATE: 30/06/2018@11.00AM						
	SURVEYED BY:						
	AUTHORIZED ON:						
	REF NO:						
54206	EXTERNAL LABOUR SALES - INS. EXCESS	-1	500.00		-500.00	-35.00	-535.00
			Sum G/L Account		-500.00	-35.00	-535.00
34150-T6A-003	LIGHT ASSY.R.LID / CMA	1	378.60	25	283.95	19.88	303.83
91505-TM8-003	CLIPBUMPER / MC	14	2.00	25	21.00	1.47	22.47
75701-T6A-000	EMBLEMH / MC	1	25.80	25	19.35	1.35	20.70
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE /	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER /	1	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER /	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD / MC	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM /	1	3.60	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5 /	2	8.30	25	12.45	0.87	13.32
76711-T6A-003	CAPPVOT /	1	4.70	25	3.52	0.25	3.77
BO-WS-SEALANT	WINDSCREEN SEALANT (N) /	1	60.00		60.00	4.20	64.20
04715-T6A-900ZZ	FACERR.BUMPER / cut	1	557.20	25	417.90	29.25	447.15
71502-T6A-003ZE	FACERR.BUMPER GARNISH / CMA	1	75.30	25	56.47	3.95	60.42
33505-SLJ-013	REFLECTOR ASSY.RR. / CMA	1	44.50	25	33.37	2.34	35.71
71512-T6A-921ZE	SPOILER ASSY.RR SIDE / cut	1	111.80	25	83.85	5.87	89.72
71593-T6A-003	SPACERRR.BUMPER SIDE / MC	1	18.70	25	14.02	0.96	15.00
75313-T6A-J11ZE	GARNISH ASSY.SLIDE DOOR LWR / cut	1	266.80	25	200.10	14.01	214.11
74410-T6A-J01ZE	GARNISH ASSYR.WHEEL ARCH / cut	1	35.30	25	26.47	1.85	28.32
68100-T6A-Q10ZZ	TAILGATE COMP / Acc	1	1049.80	25	787.35	55.11	842.46
74440-T6A-003	WEATHERSTRIPTAILGATE / X NV	1	115.10	25	86.32	6.04	92.36



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18002769	Page	2
	3 ANSON ROAD #16-00	Date	: 6. Jul 2018		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 6. Jul 2018 10:15:00 AM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	: DID: +65 6846 5673		
Owner's Name	: NG DJONI	Survey Date	: W: +65 8100 6306		
Ins Policy No.	: DMPCSN1669891701	Authorisation Date	: Email: arychua@honda.com.sg		
Date of Accident	: 30/6/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Sum Item					2171.82	152.02	2,323.84
BOSUN	SUNDRIES	1	60.00	20	60.00	4.20	64.20
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	X 1/2	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT	1	100.00	X 1/2	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	140	180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	240.00	140	240.00	16.80	256.80
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00	X 1/2	250.00	17.50	267.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	350.00	300	350.00	24.50	374.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	400.00	350	400.00	28.00	428.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	350	450.00	31.50	481.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	500.00	X 1/2	500.00	35.00	535.00
BKDR22K	STRAIGHTEN ALIGN RR R SLIDING DOOR.	1	550.00	X 1/2	550.00	38.50	588.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	450	650.00	45.50	695.50
BP06R	SPRAY PAINT ON REPAIRED/REPLACED AREAS. (6PX \$450)	1	3150.00	1350	3150.00	220.50	3370.50
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	4800.00	1680	4800.00	336.00	5136.00
Sum Labor					12130.00	849.10	12,979.10

Survey By	Gua Qian - 82880282	10/7/18	Total Amount	13,801.82	966.12	14,767.94
Date & Time	10/7/18		Total (Inclusive of GST)			14,767.94
Excess	TBA					
Status	Not Authorised.					
Signature	Signature					

6 Days. before paint photos.

Printed on 6/7/2018 12:34:58 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

*Urgent Action
Demanding Owner!*

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18002769	Page	1
	3 ANSON ROAD #16-00	Date	: 6. Jul 2018		
	SPRINGLEAF TOWER	Customer No.	: WC008		
	SINGAPORE 079909	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SKW629K	Engine No	: K24W71011552		
Chassis No	: JHMRC1890FC203162	Date Time	: 6. Jul 2018 10:15:00 AM		
Model	: ODYSSEY 2.4 EXV-S 15YM	Surveyor Name	:		
Owner's Name	: NG DJONI	Survey Date	: DID : +65 6846 5673		
Ins Policy No.	: DMPCSN1669891701	Authorisation Date	: HP : +65 8100 6306		
Date of Accident	: 30/6/2018		: Email : arychua@honda.com.sg		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	OWN DAMAGE CLAIMS-J/NO: 70812						
	POLICY/CLAIMS NO: DMPCSN1669891701						
	OWNER: NG DJONI						
	ACC DATE: 30/06/2018@11.00AM						
	SURVEYED BY:						
	AUTHORIZED ON:						
	REF NO:						
54206	EXTERNAL LABOUR SALES - INS. EXCESS	-1	500.00		-500.00	-35.00	-535.00
			Sum G/L Account		-500.00	-35.00	-535.00
34150-T6A-003	LIGHT ASSY.R.LID <i>MC</i>	1	378.60	25	283.95	19.86	303.83
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
75701-T6A-000	EMBLEM.H <i>NN</i>	1	25.80	25	19.35	1.35	20.70
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>NN</i>	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGRR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
16-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD <i>NN</i>	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A.WINDSHIELD DAM	1	3.60	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD.5X5	2	8.30	25	12.45	0.87	13.32
76711-T6A-003	CAPPVOT	1	4.70	25	3.52	0.25	3.77
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
04715-T6A-900ZZ	FACERR.BUMPER <i>CRA</i>	1	557.20	25	417.90	29.25	447.15
71502-T6A-003ZE	FACER.RR.BUMPER GARNISH	1	75.30	25	56.47	3.95	60.42
33505-SLJ-013	REFLECTOR ASSY.RR <i>NN</i>	1	44.50	25	33.37	2.34	35.71
71512-T6A-921ZE	SPOILER ASSY.RR.SIDE <i>MC</i>	1	111.60	25	83.85	5.87	89.72
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
75313-T6A-J11ZE	GARNISH ASSY.SLIDE DOOR LWR <i>inconsistent</i>	1	256.80	25	200.10	14.01	214.11
74410-T6A-J01ZE	GARNISH ASSY.WHEEL ARCH <i>inconsistent</i>	1	35.30	25	26.47	1.85	28.32
68100-T6A-Q10ZZ	TAILGATE COMP	1	1049.80	25	787.35	55.11	842.46
74440-T6A-003	WEATHERSTRIPTAILGATE <i>NN</i>	1	115.10	25	86.32	6.04	92.36



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 96203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1360G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SKW629K
Chassis No : JHMRC1890FC203162
Model : ODYSSEY 2.4 EXV-S 15YM
Owner's Name : NG DJONI
Ins Policy No. : DMPCSN1669891701
Date of Accident : 30/6/2018

Document No. : SQT18002769
Date : 6. Jul 2018
Customer No. : WC008
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24W71011552
Date | Time : 6. Jul 2018 10:15:00 AM
Surveyor Name :
Survey Date :
Authorisation Date :
DID : +65 6846 5673
HF : +65 8100 6306
Email : arychua@honda.com.sg

Page 2

Date of Accident : 30/6/2018							
Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Sum Item					2171.82	152.02	2323.84
BOSUN	SUNDRIES	1	60.00 20		60.00	4.20	64.20
BOBC	BODY UNDERSIDE COATING (N)	1	100.00 X		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00 X		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 X		180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	240.00 140		240.00	16.80	256.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00 X		250.00	17.50	267.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION1	1	350.00 X		350.00	24.50	374.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00 X		350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	400.00 X		400.00	28.00	428.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00 X		450.00	31.50	481.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	500.00 X		500.00	35.00	535.00
BKDR22K	STRAIGHTEN ALIGN RR R SLIDING DOOR.	1	550.00 X		550.00	38.50	588.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00 X		650.00	45.50	695.50
06R	SPRAY PAINT ON REPAIRED/REPLACED AREAS. (6PX \$450)	1	3150.00 450		3150.00	220.50	3370.50
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	4800.00 560		4800.00	336.00	5136.00
Sum Labor					12130.00	849.10	12979.10

03 days

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 13,801.82 966.12 14,767.94
Total (Inclusive of GST) 14,767.94

Printed on 6/7/2018 12:34:58 PM

* This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

* The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jul 2018		06 Jul 2018 15:04 Edit Adj Rpt	S\$6,938.93 Edit Estimates	S\$6,938.93 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NG DJONI , ID: S7276554J, Tel: +6581989989, Email: NGDJONI@GMAIL.COM									
Vehicle Reg. No.: SKW629K		Date of Loss: 30/06/2018 11:00 - :59 32 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D03338C01		Policy/Cover Note No.: DMPCSN1669891701 (Comprehensive)							
		Excess: S\$1,000.00							
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/07/2018]									
Driver/Custodian: NG DJONI (46 / Male), NRIC: S7276554J, Tel: +6581989989									
Adj Asg. Remarks: PLEASE SURVEY INSURED VEHICLE & REVERT AND CHECK THE CONSISTENCY OF THE DAMAGES. PLEASE NOTED THAT INSURED WITH PRE-EXISTING ACCIDENT ON 18/02/2018 AND WE REJECTED THE OWN DAMAGES CLAIM. REFER TO BOTH ACCIDENT REPORT, DAMAGES AT THE REAR BUMPER.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (12/07/2018): Alert - Adj Mandate Approved (S\$1796.94) - SKW629K - Claim Handler: Hwang Shiang...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW629K (SNM18D03338C01)





























OD

Jun 30 2018 11:00AM









[NG DJONI]

Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	05/07/18 18:33	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/07/18 12:51	Adjuster Immediate Advice		Load HTM	
2	11/07/18 11:56	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	05/07/18 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	05/07/18 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	05/07/18 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	05/07/18 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	05/07/18 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	05/07/18 18:33	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/07/18 10:05	General View		Load PDF	
2	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
3	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
4	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
5	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
6	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
7	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
8	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
9	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
10	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
11	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
12	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
13	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
14	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
15	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
16	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
17	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
18	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
19	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
20	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
21	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
22	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
23	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>
24	14/07/18 21:32	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
25	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/07/18 21:32	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/07/18 14:59	ESTIMATE	 Load PDF	
2	06/07/18 15:00	SAS REPORT FOR ACCIDENT 18/02/2018	 Load PDF	
3	11/07/18 14:09	Revised Estimate	 Load PDF	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 18:32	Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/07/18 10:51	MARK ESTIMATE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 18:33	Accident Statement	 Load HTM	
2	19/07/18 12:12	Addendum Sheet	 Load TIF	
3	19/07/18 12:17	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 18:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	05/07/18 18:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	05/07/18 18:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	05/07/18 18:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	05/07/18 18:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	05/07/18 18:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 18:32	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118012417/GVD3E2

Date: 01/08/2018

REFERENCE

Insured/Claimant: NG DJONI Policy No: DMPCSN1669891701
Date of Loss: 30/06/2018 Nature of Claim: OD Claim No: SNM18D03338C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW629K**
Make & Model: HONDA ODYSSEY, 2.4 EX-S (RC1) (A) Engine No: K24W71011552
Reg. Date: 15/10/2015 (Man. Year: 2015) Chassis No: JHMRC1890FC203162
Colour: White Odometer: 15064 km
Engine Capacity: 2356 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,231.82	1,878.93	352.89	15.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,070.00	5,060.00	7,010.00	58.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,301.82	6,938.93	7,362.89	51.48
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	13,301.82	5,938.93	7,362.89	55.35
+ GST 7.00/7.00% (S\$)	931.13	415.73	515.40	55.35
Nett Amount (S\$)	14,232.95	6,354.66	7,878.29	55.35

INSPECTION

Date of Assignment: 06/07/2018
Date Inspected: 10/07/2018 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2018)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 EX-S (RC1) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW629K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LIGHT ASSYR.LID	Cracked	283.95 FS	*283.95 FS
2	14		*CLIPBUMPER	Necessary	21.00 FS	*21.00 FS
3	1		*EMBLEMH	Necessary	19.35 FS	*19.35 FS
4	2		*MOLDINGRR.WINDSHIELD SIDE	Necessary	26.40 FS	*26.40 FS
5	1		*MOLDINGRR.WINDSHIELD CORNER	Necessary	12.45 FS	*12.45 FS
6	1		*MOLDINGL.RR.WINDSHIELD CORNER	Necessary	12.45 FS	*12.45 FS
7	1		*SPACERRR.W/SHIELD (4PCS)	Necessary	11.70 FS	*11.70 FS
8	1		*RUBBER A WINDSHIELD DAM	Necessary	2.70 FS	*2.70 FS
9	1		*DAMPER STD 5X5 (2PCS)	Necessary	12.45 FS	*12.45 FS
10	1		*CAPPIVOT	Necessary	3.52 FS	*3.52 FS
11	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
12	1		*FACERR.BUMPER	Cut	417.90 FS	*417.90 FS
13	1		*FACERR.BUMPER GARNISH	Cracked	56.47 FS	*56.47 FS
14	1		*REFLECTOR ASSYR.RR	Cracked	33.37 FS	*33.37 FS
15	1		*SPOILER ASSYR.RR.SIDE	Cut	83.85 FS	*83.85 FS
16	1		*SPACERRR.BUMPER SIDE	Necessary	14.02 FS	*14.02 FS
17	1		*GARNISH ASSYR.SLIDE DOOR LWR	Not Necessary	200.10 FS	*- FS
18	1		*GARNISH ASSYR.WHEEL ARCH	Not Necessary	26.47 FS	*- FS
19	1		*TAILGATE COMP	Buckled	787.35 FS	*787.35 FS
20	1		*WEATHERSTRIPTAILGATE	Not Necessary	86.32 FS	*- FS
21	1		*SUNDRIES	Necessary	60.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,231.82	1,878.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY UNDERSIDE COATING	New	100.00	0.00
2	BODY JOINT SEALANT	New	100.00	0.00
3	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	180.00	140.00
4	REMOVE & INSTALL REVERSE SENSOR	New	240.00	140.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	0.00
6	REMOVE& INSTALL REVERSE CAMERA & CALIBRATION	New	350.00	300.00
7	REMOVE & INSTALL RR WINDSCREEN	New	350.00	300.00
8	RESET VEHICLE SMART KEY ACCESS / ENTRY SYSTEM	New	400.00	350.00
9	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	350.00
10	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	500.00	0.00
11	STRAIGHTEN ALIGN RR R SLIDING DOOR	New	550.00	0.00
12	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	650.00	450.00
13	SPRAY PAINT ON REPAIRED / REPLACED AREAS (6PX \$450)	New	3,150.00	1,350.00
14	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	4,800.00	1,680.00
Gross Labour Cost (\$\$)			12,070.00	5,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >