

ASS. REC. BY:

REF: CS3/FCI18612441/624d3⁵² Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

CWS

Eileen Lee

of

FCI

Date/Time: 9/7/2018 @ 2.54pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

CB 62712

Insured:

SHA 5968A

at Workshop m/s

MSM Logistic

Tel:

94866649 / 91074212

of

Blk 160 Sin Ming Drive #03-08

Policy No:

Claim No:

D18005245 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 05/07/2018

(Client's Record)

11/07/2018 @ 2pm - 4pm

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

3:02pm @ 9/7/18

Person Contacted:

Mr. Siao

Vehicle IN/OUT

Date/Time

Action/Instruction (·X) Estimate

CB 62712-X

SHA 5968A-X.

74 Sungai Kadut St 1 (Ah Liang)

After repair: 19/7/2018

/13) wef

REC. BY:

REF: FCI

1128G

ASSIGNMENT

From: _____ Date: 11/07/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: CB 62712

at Workshop m/s MSM Logistics

of BIK 160 Sin Ming Drive # 03-08

Insured: 01-12

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

2pm - 4pm

Make of Veh: _____

Mr. Siew @ 91074212

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$100k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1wp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: CB 62712 Yr Regn: 30 Dec 2005

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit RK117ISRDEA c.c. 7545

Colour: blue & white A/C: Insured / Std / NI / NA

Sp. Reading: 410158 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RK117IB 20077

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/70R 22.5 6

R: 11 (b)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

AEOLUS

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6/6 mm

L/Bal. 6/6 mm

D.O.A.

D.O.I. 11-07-18

Survey held at

w/s

3:40pm

Des. of Damages (Fr) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$8000 per year.

 $8000/12 \times 89 = 59333$

COE: 45k.

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS3/FCI18012441/Gz4d3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-07-2018



Code : FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 5968A	Veh. Inspected	CB 6271Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18005245MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	09/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/07/2018	Inspection Date
Survey held at	160 SIN MING DRIVE #03-08	
Repairer	MSM LOGISTICS PTE LTD	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

MOTOR SURVEY ASSIGNMENT

Date	06-07-2018	Our Ref No. D18005245MFSH
Accident Date	05-07-2018	Claim Type. Third Party
Insured Vehicle	SHA5968A	Third Party Vehicle. CB6271Z
Survey Location	BLK 160 SIN MING DRIVE SIN MING AUTOCITY#03-08	
Contact Person.	MR.SIEW - 94866649/91074212	
Contact No.	94866649/ 94866649	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MSM LOGISTIC PTE LTD	Attention. NIL
Cc : TP Solicitor	RIAZ LLC	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242133)



PRI Documents



Close



PRI Header Details

Claim No	D18005245MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & RIAZ LLC
Workshop Name	MSM LOGISTIC PTE LTD (Contact Person : MR.SIEW - 94866649/91074212)	Survey Location & Contact Details	BLK 160 SIN MING DRIVE SIN MING AUTOCITY#03-08 Mobile: 94866649 , Phone: 94866649 , Fax: 0 EmailId: RIAZ@JUSTICE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA5968A	TP Vehicle No	CB6271Z
PRI Recieved Date	06-07-2018 08:32:48 PM	Surveyor Appointed Date	09-07-2018 02:53:13 PM	Surveyor Accept Date	09-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1128G
Vehicle Details	
Vehicle No.:	CB6271Z
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	RK117JSRDEA
Primary Colour:	White
Manufacturing Year:	2004
Engine No.:	6D16972323
Chassis No.:	RK117JB20077
Maximum Power Output:	-
Open Market Value:	\$79,808.00
Original Registration Date:	30 Dec 2005
First Registration Date:	30 Dec 2005
Transfer Count:	0
Actual ARF Paid:	\$3,991.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 18 Jul 2018

OK



PRE-REPAIR INSPECTION REPORT				
FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI18012441/Gz4d3s2		
36 ROBINSON ROAD		Date: 17-08-2018		
#16-01 CITY HOUSESINGAPORE 068877		Code: FCI2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHA 5968A	Veh. Inspected	CB 6271Z	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005245MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	09/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI RK117JSRDEA	c.c	7545	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	RK117JB20077	Colour	BLUE / WHITE	
Odometer	410158 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	AEOLUS	6 mm	
L/H Front Tyre	275/70 R22.5	AEOLUS	6 mm	
R/H Rear Tyre	275/70 R22.5 (D)	AEOLUS	6/6 mm	
L/H Rear Tyre	275/70 R22.5 (D)	AEOLUS	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5. General Information				
Accident Date	05/07/2018	Inspect Date / Time	11/07/2018 (03:40 PM)	
Survey held at	160 SIN MING DRIVE #03-08			
Repairer	MSM LOGISTICS PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE:\$100,000.00				

Report Ref No. CS3/FCI18012441/Gz4d3s2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or sort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.