

INS. CASE OWNER:

CC 4 / AIG1801 2508, K job 9

LKK:
IDAC:

Surveyor:

PSC

DOI:

ASSIGNMENT

11/7/18

Date / Time:

9/7/18

Registered in Merimen:

10/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLS 7NK

Claim No.:

52196149054

Name of Insured:

LEOW MIAU YI

Policy No.:

17004776E

Insured Tel No.:

HP: 96712277

Make / Model:

Andi

Excess Sec II : \$S

D.O.A.:

6/7/18

Place of Accident:

P16 2MPS UHMB1

Is driver the owner?

YES / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final? Yes/No

SJU 6415T



INSRS:
WSP:
Tel:
Liability:
RMKS:

Hwa Seng



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
12/7/18	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	12-7-18 JOY
	After call Itr to OI:	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>
	After call Itr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	ITA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	\$S		days) Reduction:	% Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 7-3-19	Confirm with: H. 1500		Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.:	27	If NO or B 28, Ass. Lia:
Repair Cost:	\$S 2,550.xx			
Loss of Rental (LOR):	\$S	days)		
Loss of Use (LOU):	\$S 360 (560 = 6 days)			
Loss of Income (LOI):	\$S - (5 x days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>				[Tick only one]
GIA/LTA Search:	\$S 7.45			
Medical:	\$S -			
Disbursement:	\$S -	(e.g. Tow/ Independent)		1) Claim status: Normal/Reject/Private Settle
Legal Cost:	\$S -			2) Report Format:
Total:	\$S 2,917.45	Global Sum \$S:	2,900	3) Survey fee:
FINAL PAYMENT	Date/Time:	Confirm with:		Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$S 2,900.x	Name 1:	HWA SENG SPRAY PAINTING CO.	
Payee 2: (Strike if N.A.)	\$S x	Name 2:	x	
Payee 3: (Strike if N.A.)	\$S	Name 3:		

ASS. REC. BY:

REF: 110/

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Hwa Bay

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$17k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: od Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: STU 6415T Yr Regn: 12, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____
Make: NIS Lario c.c. 1498

Colour: n. Black A/C: Insured / Std / NI / NA

Sp. Reading: 8558 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: JN1BAAG118 0021823

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 185/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 6/7/18 D.O.I. 11/7/18

Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
FRONT O/S

The UIC / Chasals frame / Body Structure affected due to collision.

Date / Time Action / Instruction
12/7 File pass to Catherine

\$2,550

R (\$1,700.14 / 40%)

Date/Time, File Pass to?

: Prell. Report

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ - RS - SI

Fines

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18012508/jb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 10-07-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLS 721K	Veh. Inspected	SJU 6415T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/07/2018	Inspection Date	
Survey held at	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

HWA SENG SPRAY PAINTING COMPANY
 160 Sin Ming Drive, #05-11,
 Sin Ming AutoCity
 Singapore 575722
 (Registration no :095744/00B)
 Tel : 64533100, Fax 62669932

Date of Accident : 08/07/2018
 Your Insured Vehicle
 No : SLS 721K

Estimate repair cost to NISSAN LATIO reg no : SJU 6415 T

Nett Item

1pc rear bumper	SS	CNT	532.40	—
1pc rear bumper o/s retainer		DIT	36.00	—
1pc o/s/r panel air duct		SW	55.30	X
1pc o/s taillamp		SL	279.00	X
1pc o/s/r panel		R1	1004.70	—
1pc o/s/r panel inner shield		CNT	115.00	—
			2022.40	
			2022.40	
	Less 10%		202.24	
			1820.16	
<u>Labour & misc charges</u>				
Panel knocking			1000.00	700
Spray painting			750.00	600
Labour to remove and install rear windscreen			180.00	120
Sealant and clip			60.00	✓
1pc windscreen moulding			100.00	—
Wire checking			40.00	20
Labour to remove and install petrol tank			150.00	60
Tuff kote			150.00	30
			4250.16	

10%

HWA SENG SPRAY PAINTING COMPANY
 I, the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Not authorized
 L/S by ?
 Resurvey After Paint
 6 days

Date: 14/07/2018

Teo Zhi Xiang, Darren
160 Sin Ming Drive
#05-11 Sin Ming Auto City
Singapore 575722

Attn: Motor Claim Department

Your Ref:

AI& Asia Pacific Insurance Pre. Ltd
AI& Building
78 Shenton Way
#09-16, Singapore 079120

Dear Sirs/Madam,

DIRECT SETTLEMENT

Accident on 06/07/2018 involving Vehicle No. SSU 6415T & SLS721K
At P.T.E

I/We refer to my/our letter date

Arising out of the above accident, as a assessment on the damaged to my/our Vehicle No. SSU 6415T was being conducted by your appointed panel surveyor.

Due to the negligence/fault of your insured/driver of Vehicle No. SLS721K. I/We am/are now claiming against you for the repair and other consequential suffered by me/us.

For the purpose of a amicable settlement. I/We quantified my/our claim as follows:-

a) Cost of repair at	S\$ 2,550.00
b) Loss of use for <u>6</u> days at rate of (<u>\$60 per day</u>)	S\$ 360.00
c) Police/ROV Fee	S\$
d) Others <u>LTA Search Fee</u>	S\$ 7.45

Total Cost

S\$ 2,917.45

I/We enclose herewith copies of all relevant documents for your perusal.

Kindly also direct all correspondence or liase with my Repairer's Messrs Hwa Seng Spray Painting Co. relating to the said accident without any further reference to me/us.

Thanking you and awaiting your favourable response.

Yours Faithfully

x



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18012509/Kjb3

12 JULY 2018

LEOW MING YI
23 CHENG SOON GARDEN
SINGAPORE 599801

Dear Sir/Madam,

ACCIDENT INVOLVING SLS 721K AND SJU 6415T ON 6/7/18

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.


Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Joy Irene

Case Handler

DID: 6841 2409

FAX: 6741 4108

Email: joyirene@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


LETTER OF AUTHORIZATION

To Whom It May Concern

Accident on 06/07/2018 involving SJU 6415T and SLS721K
along PIE

I/We Teo Zhi Xiang, Darren NRIC No. S 87 01520C
of Horizon Green, 46 Thomson Walk, Singapore 574497
Owner of Motor Vehicle Registration No. SJU 6415T insured by _____
of EQ Insurance Company Ltd under Policy No. DMPPH218-003123
do hereby authorize M/s Hwa Seng Spray Painting Co.
as my/our representative with full authority to write, negotiate and settle claim
for damages on my/our behalf against the owner and/or driver of
Motor Vehicle No. SLS721K in regard to the abovementioned accident.

I/We also consent to the agreed settlement sum be made in favour of my/our
representative, M/s Hwa Seng Spray Painting Co. and
the said payment be forwarded to them to be construed as full and final discharge of
my/our claim.



Owner Signature & Company Stamp

Date: 19/07/2018

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, HWA SENG SPRAY PAINTING CO. ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,900.00 (Global Sum)(All-in) for vehicle no. SJU 6415T that was damaged pursuant to the accident which occurred on 06/07/2018 (date) along PIE (location) involving vehicle no/s SLS 721K. This is pursuant to the inspection conducted on 11/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TEO ZHI XIANG DARREN (ZHANG ZHIXIANG) ("the third party claimant") of vehicle no. SJU 6415T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJU 6415T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of 03 (month) 2019 (year)



KSL

Signed by appointed surveyor



Signed by "the workshop" (with chop)

HWA SENG SPRAY PAINTING CO.

160 Sin Ming Drive, #05-11, Sin Ming Autocity
 Singapore 575722
 Tel No. : 64533100 Fax No. : 62669932
 Buss. Reg. No. : 095744/00B

Final Repair Bill : H00030

TEO ZHI XIANG, DARREN
 HORIZON GREEN, 48 THOMSON WALK
 574497

Attention : Motor Claim Department
 Contact : 87372510

Date : 18/07/2018
 Vehicle Num. : SJU 8415 T
 Make/Model : NISSAN LATIO
 Chassis/Eng# :
 Accident Date : 06/07/2018
 Claim No. :
 Reference :
 Policy No. :-

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		2,550.00
		On lump sum basis repair inclusive of spare parts, panel knocking, spray paint and misc charges		
		Labour Total S\$:		2,550.00

E. & O.E.

Total S\$: 2,550.00


 for HWA SENG SPRAY PAINTING CO.

Subject: Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-180709-000604

From: LTA-VTL@lta.gov.sg

To: hsh.painter@yahoo.com

Date: Monday, July 9, 2018, 10:44:08 AM GMT+8

**Notification of Successful Vehicle Insurance Search for
Receipt No.: ITNET-00000-180709-000604**

Dear Sir/Madam

We wish to inform you that your transaction on "Enquire Vehicle Insurance Particulars" performed on 09 Jul 2018 was successful and the Receipt No. is ITNET-00000-180709-000604.

2. The details of the search results are as follow:

Vehicle No.	Search Date	Search Time	Search Result
SLS721K	08 Jul 2018	17:20:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

3. Please contact our customer service officers at tel : 1800-CALL LTA (1800-2255 582) should you require further assistance.
4. Please do not reply to this auto-generated e-mail. If you have any feedback, please go to www.lta.gov.sg/feedback. You can also visit www.onemotoring.com.sg for more information.
5. Thank you.

If you are not the intended recipient of this communication, please delete it.

As it may contain confidential or official information, do not retain it or disclose the contents to any person as it may be an offence under the Official Secrets Act.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018 Edit Reg		11 Jul 2018 00:00 Edit Adj Rpt	S\$2,550.00 Edit Estimates	S\$2,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEOW MING YI , ID: S8628388C								
Main Claimant:	TEO ZHI XIANG DARREN (ZHANG ZHIXIANG) , ID: S8701520C								
Vehicle Reg. No.:	SJU6415T	Date of Loss:	06/07/2018 17:00 - :59 [102 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5211959490SG	Policy/Cover Note No.:	1700047764 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLS721K	Policy No. (Claimant):	DMPPHQ18-003123						
		Excess:							
Repairer:	Hwa Seng Spray Painting Co (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU6415T (5211959490SG)
[SLS721K]

TP

TEO ZHI XIANG DARREN (ZHANG ZHIXIANG)

Jul 6 2018 5:00PM

[LEOW MING YI]

Hwa Seng Spray Painting Co

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	11/07/18 16:51	Accident Statement From:OO - Reg. No: SLS721K, Claimant: LEOW MING YI							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
2	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
3	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
4	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
5	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
6	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
7	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
8	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
9	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
10	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
11	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
12	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
13	07/03/19 14:08	General View							Load JPG	<input checked="" type="checkbox"/>	
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	10/07/18 14:09	EMAIL FROM AIG DD 09072018							Load PDF		
2	10/07/18 14:09	TP EST & GIA REPORT							Load PDF		
3	12/07/18 17:29	TP ESTIMATE- MARKED							Load PDF		
4	13/03/19 16:33	WORKSHOP INVOICE							Load PDF		
5	13/03/19 16:33	AUTHORISATION TO ACT FORM							Load PDF		
6	13/03/19 16:33	Release Voucher							Load PDF		
7	13/03/19 16:33	LTA SEARCH							Load PDF		
8	13/03/19 16:33	LETTER TO OI							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLS721K (Insd veh)	Model:	NISSAN LATIO 1.5 L (A)
	SJU6415T (TP veh)		
Date of Accident:	06/07/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	4,250.16
Final Repair Cost	:	\$	2,900.00
Loss of Use	:	\$	6.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	2,900.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hwa Seng Spray Painting Co.	: \$	2,900.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

13 Mar
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18012508/KJB3Q2
Date: 13/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700047764
Claimant Vehicle No : SJU6415T	Insured Vehicle No :	SLS721K
Date of Loss: 06/07/2018	Nature of Claim:	TP
	Claim No:	5211959490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU6415T	Engine No:	HR15125752B
Make & Model:	NISSAN LATIO, 1.5 L (A)	Chassis No:	JN1BAAC11Z0021823
Reg. Date:	21/12/2009 (Man. Year: 2009)	Odometer:	85588 km
Colour:	Metallic Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,980.16	1,679.29	300.87	15.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,530.00	740.00	32.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,250.16	3,209.29	1,040.87	24.49
Approved Total (Overridden) (S\$)		2,550.00		
Nett Amount (S\$)	4,250.16	2,550.00	1,700.16	40.00
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,917.45		
Global Sum Settlement (S\$)		2,900.00		

INSPECTION

Date of Assignment:	09/07/2018	
Date Inspected:	11/07/2018 Inspected At:	Hwa Seng Spray Painting Co (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING

AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	532.40 FL	*532.40 FL
2	1		*REAR BUMPER O/S RETAINER	Distorted	36.00 FL	*36.00 FL
3	1		*O/S/R PANEL AIR DUCT	Serviceable	55.30 FL	*- FL
4	1		*O/S TAILLAMP	Serviceable	279.00 FL	*- FL
5	1		*O/S/R PANEL	Bent	1,004.70 FL	*1,004.70 FL
6	1		*O/S/R PANEL INNER SHIELD	Cracked	115.00 FL	*115.00 FL
7	1		*SEALANT AND CLIP	Necessary	60.00 FS	*60.00 FS
8	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,182.40	1,848.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	202.24	168.81
Total Parts (\$\$)	1,980.16	1,679.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	700.00
2	SPRAY PAINTING	New	750.00	600.00
3	LABOUR TO REMOVE AND INSTALL REAR WINDSCREEN	New	180.00	120.00
4	WIRE CHECKING	New	40.00	20.00
5	LABOUR TO REMOVE AND INSTALL PETROL TANK	New	150.00	60.00
6	TUFF KOTE	New	150.00	30.00
Gross Labour Cost (S\$)			2,270.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >