

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305185257
Date : 09.01.18
Time of Fax: _____

Via Fax : EMAIL
Your Insured: SLK 38Y
Date of Acc : 08.01.18

Attn: Motor Claims Department

AXA

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

A-4980U

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

→ • Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811	} Fax no. 6546 8156
• Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
• Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
• Chiang Liat Choon	Tel: 6214 8314 or HP:	
• Larry Ng Nyuk Phin	Tel: 6214 8316 or HP: !	
• Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Jumani

for Vice President
Crash Repairs & Claims Recovery

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305185257

CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 CUSTOMER NO 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 L (R) (O) (P)	REGN NO. SHA4980U	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 08.07.2018 10:00
	YR OF MANU. 19.05.2016	TARGET DATE
	CHASSIS CODE RMHLB41UMGU089725	COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 08.07.2018

NATURE: 3P 08.07.18

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

to:

Vehicle No.:

File No.:

SHA4980U

JU AXA

Vehicle No.:

SHA4980U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 4980U

DATE 9/7/2018 13:39

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender (RH)			\$ 593.00	
	Front Fender Shield (RH)			\$ 86.00	
	Front Fender Retainer			\$ 9.20	
	SUB TOTAL			\$ 688.20	
	LESS 20%			\$ 137.64	
	DISCOUNTED TOTAL			\$ 550.56	
	Front Fender Advertisement Logo (RH)			\$ 100.00	Nett
				\$ 100.00	
	Labour Charge				
	Panel Beating			\$ 560.00	
	Spray Painting Charge-Fender/Bumper			\$ 500.00	
	Tuff Kote			\$ 50.00	
	TOTAL LABOUR			\$ 1,110.00	
	ESTIMATE TOTAL			\$ 1,760.56	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/07/2018 10:26
Date Of Accident	08/07/2018 10:50
Exact Location Of Accident	HOLIDAY INN EXPRESS LOBBY DRIVE WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4980U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH

Cover Note Number

Driver

Name of Driver	YEE SECK LIONG
NRIC No	S1234302G
Date Of Birth	02/09/1957
Occupation	OUTDOOR
Date Of Driving Pass	03/03/1977
Driving Experience	41 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96369282
Fax Number	
Contact Number	
Email Address	ERICYSL@GMAIL.COM

Address 117B 11-68 RIVERVALE DRIVE
 Postcode 542117
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE (70 reverse)
 Weather Conditions CLEAR
 Road Surface DRY
Other Information
 Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLK36Y
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TAY
 NRIC/Passport Number
 Contact Number 96626646
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage LEFT REAR

No. Of Passenger (Including Driver) .

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/7/2018 at about 1050 hrs, I vehicle A was
 at the Holiday Inn Express Katoomba lobby way loading
 her luggage. Vehicle B reverse and bump onto right front
 portion. No one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)

8/7/18
 Jackson Hong
 COO

Reporting Centre Personnel's Signature
 Name:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

8/9/18
Jackson Hong
CSO

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: