

23/02/2012

ASS. REC. BY:

REF: CS3/SMD18012545/624652

Special Instruction:

Surveyor

GR

ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 10072018 11:30am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 767X Insured: PC 2767C

at Workshop m/s A-Tec Automotiv Tel: 6384 5206

of 8 Kaki Bukit Ave 4 #105-27

Policy No: Claim No: CMTD 1807924 / THE

Sum Insured: Excess:

Make of Veh: D.O.A. 09072018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement:

Date/Time: 10072018 11:52am Person Contacted: Peggy Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLK 767X - X
	PC 2767C - X
11/3/18	dismantled

PRG
xnd
Bimms

REF: SMO

C 303R

ASSIGNMENT

(2018)
07 Nov 2008

From: _____ Date: _____
Estimated Cost: _____
OD / DWS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s A-Tec
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLK 7627X Yr Regn: 07 Nov 2008
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Fit C.C. 1339
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 224051 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: GE 61095459
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD Rim or
Tyre Size: F: 185/65 R14
R: v

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	<input checked="" type="radio"/>

Bal. or Market Value: \$9000
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or LINGLONG
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 10-07-18
Survey held at w/s 3:30pm
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$3000 - \$4000</u>
<u>13/7/18</u>	<u>Submit PRS report.</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____

Date/Time, File Return to?
1)
2)

Resurvey No. of Trip: _____

Report Format :

Lump Sum / I.B.f: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
_____ S+RS, _____ SI	
Photos	
Others	
TOTAL	

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 10 July, 2018 11:30 AM
To: Margaret Lim; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Pte Ltd A-Tec Automotive; Danny Lim; Aaron; pri@satwantlaw.com; Choo, Thelma; Ye, Yong Kang Melvin
Subject: CMTD1802924/THE - SUV(LKK)/ Accident involving PC2767C & SLK7627X on 09/07/2018 (Our File Ref: PD/DL/1801215 (ml))
Attachments: Accident Statement - SLK7627X.PDF

Our Reference : CMTD1802924/THE
Your Reference: PD/DL/1801215 (ml)

Without Prejudice

EMAIL ONLY

Date: 10th July 2018

Attention:
M/S SATWANT & ASSOCIATES

Dear Margaret,

ACCIDENT INVOLVING PC2767C & SLK7627X ON 09.07.2018

We refer to your email reply of instant.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Margaret Lim [mailto:MargaretLim@satwantlaw.com.sg]

Sent: Tuesday, July 10, 2018 11:24 AM

To: Teo, Grace

Cc: Pte Ltd A-Tec Automotive; Danny Lim; Aaron; pri@satwantlaw.com; Choo, Thelma; Ye, Yong Kang Melvin

Subject: Re: CMTD1802924/THE - PRI/ Accident involving PC2767C & SLK7627X on 09/07/2018 (Our File Ref: PD/DL/1801215 (ml))

WITHOUT PREJUDICE

Hi Grace,

We have instructions to reject your surveyors and propose to engage a surveyor from the list below:-

1. Chang Fuh Keong, Dave
2. Lee Kok Weng
3. Lim Yong Tian, Sebastian
4. Ong Ah Keng, Kent
5. Ong Poh Meng
6. Cheong Kim Hin, Alan
7. Ananda K Biswas Marc

Kindly see our attached letter and the workshop details as below:-

Workshop Name: A-Tec Automotive Pte Ltd
Address: 8 Kaki Bukit Ave 4 #05-27 Premier (S) 415875
Contact Person: Peggie Woo
Contact No.: 6384 5206

Kindly liaise directly with the workshop for the PRS on an urgent basis. Thank you.

Thank you & Best Regards
Margaret Lim (Branch Office)
Secretary

For and on behalf of

SATWANT & ASSOCIATES

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Branch Office: 450 Lorong 6 Toa Payoh #02-03 Harsing Centre Singapore 319394 | tel: 6221 6114 | fax: 6266 6925

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at [margaretlim@satwantlaw.com.sg] and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses. We take no responsibility for any loss or damage, whether caused by our own negligence or not, that results from a computer virus or a defect in the transmission of this email or any attached file

From: Teo, Grace <grace.teo@sompo.com.sg>

Sent: Tuesday, July 10, 2018 11:12:21 AM

To: Margaret Lim

Cc: Pte Ltd A-Tec Automotive; Danny Lim; Aaron; pri@satwantlaw.com; Choo, Thelma; Ye, Yong Kang Melvin

Subject: CMTD1802924/THE - PRI/ Accident involving PC2767C & SLK7627X on 09/07/2018 (Our File Ref: PD/DL/1801215 (ml))

Our Reference : CMTD1802924/THE

Your Reference: PD/DL/1801215 (ml)

Without Prejudice

EMAIL ONLY

Date: 10th July 2018

Attention:

M/S SATWANT & ASSOCIATES

Dear Margaret,

ACCIDENT INVOLVING PC2767C & SLK7627X ON 09.07.2018

We refer to your Notice of Accident dated 09/07/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	

		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Margaret Lim [mailto:MargaretLim@satwantlaw.com.sg]

Sent: Monday, July 09, 2018 6:02 PM

To: Claims - Motor Survey

Cc: Pte Ltd A-Tec Automotive; Danny Lim; Aaron; pri@satwantlaw.com

Subject: Urgent - Accident involving SLK7627X & PC2767C on 09/07/2018 (Our File Ref: PD/DL/1801215 (ml))

Importance: High

WITHOUT PREJUDICE

Dear Sir/Madam,

Please see attached our PRS notification letter for your urgent attention.

Thank you & Best Regards
Margaret Lim (Branch Office)
Secretary

For and on behalf of

SATWANT & ASSOCIATES

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Branch Office: 450 Lorong 6 Toa Payoh #02-03 Hersing Centre Singapore 319394 | tel: 6221 6114 | fax: 6266 6925

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at margaretlim@satwantlaw.com.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses. We take no responsibility for any loss or damage, whether caused by our own negligence or not, that results from a computer virus or a defect in the transmission of this email or any attached file

Satwant & Associates

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Conveyancing: Blk 186 Toa Payoh Central #02-420, Singapore 310186 | tel: 6635 7493 | fax: 6635 7494

The information contained in this communication is confidential and may be legally privileged. It is intended solely for the use of the individual or entity to whom it is addressed and others authorised to receive it. If you are not the intended recipient you are hereby notified that any disclosure, copying, distribution or taking any action with respect to the content of this information is strictly prohibited and may be unlawful, and kindly inform the sender via email or call SATWANT & ASSOCIATES at (65) 6 2999 470 immediately and destroy all copies. SATWANT & ASSOCIATES is neither liable for the proper and complete transmission of the information contained in this communication nor for any delay in its receipt.

Satwant & Associates

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Conveyancing: Blk 186 Toa Payoh Central #02-420, Singapore 310186 | tel: 6635 7493 | fax: 6635 7494

The information contained in this communication is confidential and may be legally privileged. It is intended solely for the use of the individual or entity to whom it is addressed and others authorised to receive it. If you are not the intended recipient you are hereby notified that any disclosure, copying, distribution or taking any action with respect to the content of this information is strictly prohibited and may be unlawful, and kindly inform the sender via email or call SATWANT & ASSOCIATES at (65) 6 2999 470 immediately and destroy all copies. SATWANT & ASSOCIATES is neither liable for the proper and complete transmission of the information contained in this communication nor for any delay in its receipt.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/07/2018 11:34
Date Of Accident	09/07/2018 14:00
Exact Location Of Accident	ALONG RD 1 CHANGI RD NEAR TO STILL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK7627X
Insured/Policyholder	
Name Of Registered Owner	DREAM CARZ LEASING PTE LTD
Co Reg No	20143303R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63845206
Vehicle Particulars	
Manufacturer	HONDA
Model	FIT-1.3 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5098634822
Cover Note Number	
Driver	
Name of Driver	CHUA KOK SENG
NRIC No	S1294203F
Date Of Birth	04/11/1958
Occupation	OUTDOOR
Date Of Driving Pass	13/10/2001
Driving Experience	16 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92263610
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHUA KOK SENG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLK7627X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name RIKE JULIANTI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLK7627X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?


Address

Postcode

Accident Sketch Plan Pg. 1

SKETCH PLAN

Road 1 Changi Road Near To Still Road.



(A) SLK 7127X
(B) PC 2767C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the Police Report No : T/20180709/2100

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time


Driver's Signature

(If driver is not the policyholder)

Date & Time

IDAC KAKI BUKIT (VAC),
23 KAKI BUKIT AVE 4

Reporting Singapore 415933
Name: Tel: 67416697
NRIC/IN No: Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180709/2100

Police Station Of Origin:
Kampong Ubi NPP
9 Eunus Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

2 of 3

Report No. T/20180709/2100

CONTINUATION OF REPORT

Driver			
Name	CHUA KOK SENG	ID No.	S1294203F
Related Vehicle	SLK7627X (Car)	Contact No.	92263610
Hospital/Clinic	CRESCENT CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	09/07/2018	Date Discharge	09/07/2018
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Passenger			
Name	RIKE JULIANTI	ID No.	B1803709
Related Vehicle	SLK7627X (Car)	Contact No.	83170869
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	09/07/2018	Date Discharge	09/07/2018
No. of Days granted Medical Leave	02	Degree of Injury	NIL

Brief Details.

On the above mentioned date time and place, I was driving my vehicle registration plate number SLK7627X along Changi Road on the most left hand. The car in front of me stopped as there was a minor jam on the road. I then applied my brakes and came to a complete stop. Out of a sudden, I felt a huge impact from the rear of my vehicle. I realized that another vehicle bearing registration plate number PG2767C collided onto the rear of my vehicle. No police or ambulance came to our scene. Both parties exchanged particulars and we left. I went to see a doctor and was given a total of three days of medical certificate. My passenger was given a total of 2 days of medical certificate.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3037R
Vehicle Details	
Vehicle No.:	SLK7627X
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3 A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A4105447
Chassis No.:	GE61095459
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,046.00
Original Registration Date:	07 Nov 2008
First Registration Date:	07 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$12,046.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2018
PARF Rebate Amount:	\$6,023.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,455.00
COE Rebate Amount:	\$332.00
Total Rebate Amount:	\$6,355.00
Message	
Transfer of ownership or de-registration is not allowed for this vehicle.	

The information contained herein is correct as at 12 Jul 2018

OK




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO18012545/Gz4bs2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date:	16-07-2018
		Code:	SMO
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	PC 2767C	Veh. Inspected	SLK 7627X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802924/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	10/07/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GE61095459	Colour	RED
Odometer	224051 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65R14	LING LONG	6 mm
L/H Front Tyre	185/65R14	LING LONG	6 mm
R/H Rear Tyre	185/65R14	LING LONG	6 mm
L/H Rear Tyre	185/65R14	LING LONG	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	09/07/2018	Inspect Date / Time	10/07/2018 (03:30 PM)
Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/SMO18012545/Gz4bs2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.