

ASS. REC. BY:

REF: CS/FCL18012551/Uvbnz | Special Instruction:

Surveyor: \_\_\_\_\_ ASSIGNMENT (Office)

From (Person): WS KURENE JEAN of FCL Date/Time: 10072018 223pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 7258L Insured: SHD 8577D

at Workshop m/s Ethoz Tel: 9698 1309

of 22 Tampines St 92

Policy No: \_\_\_\_\_ Claim No: D18 004453 MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 01062018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP. H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 10072018 304pm Person Contacted: Subelmi Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLN 7258L - X</u>
	<u>SHD 8577D - CG3/AL6/8020426 / mlub3</u> <span style="float: right;"><u>DA: 030218</u></span>
<u>25/7/18</u>	<u>Email preli revised to FCL</u>

SYDNEY

REF: FO

### ASSIGNMENT

From: \_\_\_\_\_ Date: 24/7/18

Estimated Cost: \_\_\_\_\_

OD / (P) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLN 7258L

at Workshop n/s: Ethos

of: 27 Tampines St 92

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GA / PR Seen: 2 Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLN 7258L Yr Regn: 5/17

Type: (M) Caf / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Toyota Corolla Altis G.C. 15-88

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 8300 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53REH104560323

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>1/6/18</u>		D.O.I. <u>24/7/18</u>	

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time      Action / Instruction

24/7/18      confirm panel by \$840.00 with AH Kei

(Red 4126.90, 8370)

RECEIVED 25 JUL 2018

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) 25/7 - typist

Report Format: CWS

Lump Sum / I.B.I. (\$) 840.00

Days Of Repair: 2

Resurvey No. of Trip: -

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: 135

Transportation: 50

Photos: 15

Others: \_\_\_\_\_

TOTAL: 200



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004453MFSH

Our ref: CS/FCI18012551/Uvb

DATE: 25/7/2018

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 7258L**


We thank for your instruction on 10/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/7/2018 at the premises of M/s ETHOZ GROUP LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,966.90
Revised Estimate Amount	: S\$840.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the n/s rear portion.



Comments/Present Status:  
Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	04-06-2018	<b>Our Ref No.</b> D18004453MFSH
<b>Accident Date</b>	01-06-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD8527D	<b>Third Party Vehicle.</b> SLN7258L
<b>Survey Location</b>	22 TAMPINES ST 92	
<b>Contact Person.</b>	SUHELMI SUHARMAN	
<b>Contact No.</b>	66547607/ 96981309	<b>Fax No.</b> 66547648
<b>Survey Type</b>	WITHOUT PREJUDICE: PENDING ID'S VF TO DETERMINE LIABILITY	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	ETHOZ GROUP LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	LURENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 25 July 2018 10:06 AM  
**To:** 'Claim Workflow System'  
**Cc:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18004453MFSH/1, SLN 7258L  
**Attachments:** SLN 7258L PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLN 7258L  
Date of survey: 24/7/2018  
Number of days :2 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 10 July 2018 3:08 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18004453MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 10 July, 2018 2:23 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [LURENEJAW@MSFIRSTCAPITAL.COM.SG](mailto:LURENEJAW@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004453MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3943G
<b>Vehicle Details</b>	
Vehicle No.:	SLN7258L
Vehicle to be Exported:	No
Intended De-registration Date:	24 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY339935
Chassis No.:	MR053REH104560323
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	16 May 2017
First Registration Date:	16 May 2017
Transfer Count:	0
Actual ARF Paid:	\$19,990.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 May 2027
PARF Rebate Amount:	\$14,992.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$45,589.00
<b>Total Rebate Amount:</b>	<b>\$60,581.00</b>

The information contained herein is correct as at 24 Jul 2018

OK

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 22 TAMPINES ST 92 (S  
528876)

Ng Boon Kai  
CLAIM DEPARTMENT  
DID : 6654\_7617  
FAX :

Date : 04/06/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

**ESTIMATION**

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000072

Accident Date : 01/06/2018

Vehicle No : SLN-7258-L

Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)

**ESTIMATED REPAIR COST DETAILS**

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<b>List Item</b>			
1	REAR DOOR LH <i>✓</i>	1,398.50	<i>✓</i>
1	REAR DOOR HINGE LH UPPER <i>✓✓</i>	101.40	<i>✓</i>
1	REAR DOOR HINGE LH LOWER <i>✓✓</i>	101.40	<i>✓</i>
1	REAR DOOR LOCK LH <i>✓✓</i>	562.40	<i>✓</i>
1	REAR DOOR WEATHERSTRIPE L/H <i>✓✓</i>	193.00	<i>✓</i>
1	REAR DOOR STICKER LH <i>✓✓</i>	92.50	<i>✓</i>
1	REAR FENDER LH <i>✓</i>	RESTORE	<i>✓</i>

Date : 04/06/2018

To : MS FIRST CAPITAL INSURANCE LIMITED

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000072

Accident Date : 01/06/2018

Vehicle No : SLN-7258-L

Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	<b>Sub Total</b>	<b>2449.20</b>	
	<b>Discount 25% On Parts</b>	<b>(612.30)</b>	
	<b>Special Nett Item</b>		
1	REAR SPORT RIM LH <i>^</i>	600.00	<i>X</i>
	<b>Sub Total</b>	<b>600.00</b>	
	<b>Labour &amp; Misc</b>		
	LABOUR TO FACILIATE REPAIR	1,000.00	<i>300</i>
	LABOUR TO SPRAY PAINT AFFECTED AREAS	1,200.00	<i>480</i>
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	<i>1 hr</i> 30.00	<i>X</i>
	TO RUST PROOF AFFECTED AREA	<i>1 hr</i> 70.00	<i>X</i>

Date : 04/06/2018  
 To : MS FIRST CAPITAL INSURANCE LIMITED  
 Attn : Motor Claim Department

**ESTIMATION**  
 FAX :

Owner : ETHOZ Group Ltd  
 : SOMPO INSURANCE SINGAPORE PTE. LTD.  
 Certificate No : D17MTRENT000072      Accident Date : 01/06/2018  
 Vehicle No : SLN-7258-L      Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)

**ESTIMATED REPAIR COST DETAILS**      Excess : 0.00      Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO CONDUCT ALL COMPUTERISED WHEEL ALIGNMENT	80.00	60
	TO REMOVE & REFIT REAR DOOR COMPONENT	11 150.00	X
	<b>Sub Total</b>	<b>2530.00</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

7128840 4,966.90

Remarks: not authorized

**SUB TOTAL**  
**GST 7.0 %**      347.68  
**TOTAL**      5,314.58

Surveyor's name: Marcus Loh  
 Principal's name: ETHOZ Group Ltd  
 Survey Date & Time: \_\_\_\_\_

*take photo after repair  
 2 day. 24/7/18*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012551/Uvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 8527D	Veh. Inspected	SLN 7258L
Policy No.		Coverage (\$)	0.00
Claim No.	D18004453MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	10/07/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH104560323	Colour	GREY
Odometer	83500	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	MICHELIN	6 mm
L/H Front Tyre	215/45 R17	MICHELIN	6 mm
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/06/2018	Inspection Date	24/07/2018
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 7258L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,398.50	-
1	REAR DOOR HINGE LH UPPER	NOT NECESSARY	101.40	-
1	REAR DOOR HINGE LH LOWER	NOT NECESSARY	101.40	-
1	REAR DOOR LOCK LH	NOT NECESSARY	562.40	-
1	REAR DOOR WEATHERSTRIPE L/H	NOT NECESSARY	193.00	-
1	REAR DOOR STICKER LH	NOT NECESSARY	92.50	-
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-612.30	-
			1,836.90	-
<b>SPECIAL NETT ITEMS</b>				
1	REAR SPORT RIM LH (SN)	TO REPAIR SEE LABOUR	600.00	-
			600.00	-
<b>LABOUR</b>				
	LABOUR TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF REAR DOOR LH,REAR FENDER LH AND REAR SPORT RIM LH.		1,000.00	300.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS.		1,200.00	480.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.	NOT NECESSARY	30.00	-
	TO RUST PROOF AFFECTED AREA.	NOT NECESSARY	70.00	-
	TO CONDUCT ALL COMPUTERISED WHEEL ALIGMENT.		80.00	60.00
	TO REMOVE & REFIT REAR DOOR COMPONENT.	NOT NECESSARY	150.00	-
	-		-	-
	-		-	-
	-		-	-
			2,530.00	840.00
<b>GRAND TOTAL</b>			<b>4,966.90</b>	<b>840.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>840.00</b>

Report Ref No. CS/FCI18012551/Uvbn2



Report Ref No. CS/FCI18012551/Uvbn2

A handwritten signature in black ink, appearing to read 'Chua Kang Seng'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.