

22/03/2002

ASS. REC. BY:

REF:

CS/MS(180)2553/Tisbet

Special Instruction:

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSLH

Date/Time:

10/7/2018 1256pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGZ 8505M

Insured:

SJL 1896T

at Workshop m/s

Motorway Car Care

Tel:

~~6571 1635~~ 6571 9625

of

10914 Lower Delta Rd

Policy No:

SX40110179mpa

Claim No:

562436

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23062018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp.

11.07.2018 @ 10am

H.O.D. Endorsement:

Date/Time:

10/7/2018 4:06pm

Person Contacted:

~~Yann~~ Aineel

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGZ 8505M - CCA / AXA 11004978 / R/Lcl

DA: 13032011

SJL 1896T - CVI / VAL 1801222 / Bg

DA: 30062018

13/07/18

@ 13:42 p.m. revised IA to Catherine Thia sh. x via merimen.

ASS. REC. BY: Tanjin

REF: MSIG

ASSIGNMENT

From: 11/7/2018
Estimated Cost: 11/7/2018

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SGZ 8505Mat Workshop m/s Motorway Car Careof 1094 Lower Delta Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) 10am

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 925K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGZ 8505M CofE 2022 NA

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axi C.C. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 200/43 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NZE14160472.94Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: N/S / S/Rim / STD A/Rim orTyre Size: F: 185/70R14R: ~ ~BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or WestlakeFront 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 11/7/18Survey held at Motorway

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/04/19 Confirmed HS \$1,500/- @ 3 days with Tanjin
(+ \$3,200/- Red - 68%)

RECEIVED 23 APR 2018

Date/Time, File Pass to?

23/4/19☐ : Prel. Report☒ : Final Report

Date/Time, File Return to?

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 150

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

10160

Report Format :

ump Sum / I.B.I: (\$ 1,500/- HS)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018		10 Jul 2018 12:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by insurer]																					
Insured:	SUBBARAYALU RAVI, ID: S7561568Z, Tel: +6591017689																							
Main Claimant:	MOTORWAY CAR RENTALS PTE LTD, Co. Reg. No.: 199902927C																							
Vehicle Reg. No.:	SGZ8505M	Date of Loss:	23/06/2018 22:00 - :59 [127 Months and 3 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 562436	Policy/Cover Note No.:	S29041017SMA (Comprehensive) Coverage: 18/11/2017 - 17/11/2018																					
Vehicle Reg. No. (Insured):	SJL1896T	Policy No. (Claimant):																						
		Excess:	S\$500.00																					
Repairer:	Motorway Car Care Centre Pte Ltd - Lower Delta (HQ) 1094 LOWER DELTA ROAD, 169205 Bukit Merah - Tel:																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/07/2018]																							
Driver/Custodian (Insured):	MANICKAVASAGAM LATCHOUMY (), NRIC: S7662274D, Tel: +6591017689																							
Adj Asg. Remarks:	Please survey the vehicle today. thank you.																							
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail																					
There are no mail for this case.																								
ALL ASSOCIATED TASKS																								
<div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2927C
Vehicle Details	
Vehicle No.:	SGZ8505M
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Beige
Manufacturing Year:	2007
Engine No.:	1NZC711930
Chassis No.:	NZE1416047694
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$13,350.00
Original Registration Date:	20 Nov 2007
First Registration Date:	20 Nov 2007
Transfer Count:	0
Actual ARF Paid:	\$14,685.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$18,279.00
Total Rebate Amount:	\$18,279.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Jul 2018

OK

toyota axio Price Range Depreciation > 10 year(s) of Vehicle Type Search

Advanced Search

Home » Used Cars » Guan Motor Trading » Toyota Corolla Axio 1.5A X (COE till 11/2022)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Toyota Corolla Axio 1.5A X (COE till 11/2022)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$25,800
Depreciation	\$5,880 /yr
Reg Date	27-Dec-2007 (4yrs 4mths 18days COE left)
Manufactured	2007
Mileage	130,000 km (12.3k /yr)
Transmission	Auto
Engine Cap	1,496 cc
Road Tax	\$750 /yr
Power	81.0 kW (108 bhp) View specs of the Toyota Corolla Axio (2007-2012)
Curb Weight	1,130 kg
Features	Powerful And Fuel Efficient 16V DOHC VVT-i E Throttle Engine, CVT Auto Transmission, ABS, Dual SRS Airbags.
Accessories	Sports Rims, Leather Seats, DVD Audio System, Reverse Sensors, Solar Film, Retractable Side Mirrors.
Description	Down Payment As Low As \$3k. Loan Up To 90%. High Approval Rate. High Trade In. All Vehicles Are Inspected By Our Professional Workshop And Come With 1 Year Engine And Gearbox Protection Shield. Please Call Or SMS Now For Enquiries And Viewing Appointment.
COE	\$20,997
OMV	\$11,758
ARF	\$12,934
Dereg Value	\$18,431 as of today (orange)
No. of Owners	1
Type of Veh	Mid-Size Sedan
Category	COE Car
Availability	Available

Add to Shortlist Add to Compare Add a Note

Posted on: 07-Jul-2018 | Last Updated on: 07-Jul-2018

Tags: Toyota Corolla, 2007 Toyota Corolla, Toyota, Corolla, Used Toyota

Upfront Payment [» more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$7,740 (change)	Maximum 70% Loan
1st Instalment	\$404	
Total Upfront Payment	\$8,169 (excluding insurance)	

Estimates based on 70% loan at 3.75% interest rate. Check with seller for exact figure.

Items for Toyota Corolla

[» View All](#)

 Magnetic Sun Shade \$90	 Chrome Door Handle \$70
 Front Grill \$380	 Fog Light \$228
 Angel Eyes Head Light \$85	 Bridged Carplate For Sale \$3,588

Showing 6 out of 272 suitable items for Toyota Corolla [View All](#)

Alliance Auto Pte Ltd is a specialist workshop for Toyota cars.



Seller Information

Company	Guan Motor Trading <ul style="list-style-type: none">dealer's priority24-vehicle 23 vehicles available
Address	61 Ubi Avenue 2 #02-11/#04-12 Search cars nearby this location
Location	Automobile Megamart
Office No	67433291
Contact Person(s)	Kai 82001060 Kenneth 96999979 Sharon Tay 91391181 Priscilla Cha 96363049

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Recommended for you



Embrace your individuality with the BMW X3



Five car insurance claim mistakes to avoid



Ready for an electrified automotive future



How the new VES affects you as a car buyer



The Toyota Corolla Altis moves a step up



Toyota Corolla Axio

Compare

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport /Company Cert No.:	199902927C
Owner ID Type:	Company
Owner Name:	MOTORWAY CAR RENTALS PTE LTD
Registered Address:	1094 LOWER DELTA ROAD MOTORWAY BUILDING SINGAPORE 169205
Mailing Address:	-
Birth Date:	-

Vehicle Particulars

Vehicle No.:	SGZ8505M
Previous Vehicle No.:	-
Effective Date of Ownership:	20 Nov 2007
Original Regn Date:	20 Nov 2007
Registration Date:	20 Nov 2007
Year of Manufacture:	2007
Vehicle Type:	Private Hire (Self-Drive) Motor Car
Vehicle Scheme:	-
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Beige
Secondary Colour:	-
Passenger Capacity:	4
Chassis No.:	NZE1416047694
Engine No.:	1NZC711930
Engine Capacity /Power Rating:	1496 cc / -
Maximum Power Output:	81.0 kW (108 bhp)
Propellant:	Petrol

Shirley Hiew (LKK Auto)

From: Tew Ai Nee <ainee@motorway.com.sg>
Sent: Monday, 22 April 2019 2:31 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'SUR'
Subject: RE: Request for Finalise SGZ8505M

Dear Shirley

Confirm the COR.
Please advise LOD need to send your side or MSIG?

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, April 22, 2019 12:01 PM
To: 'Tew Ai Nee'
Cc: SUR
Subject: RE: Request for Finalise SGZ8505M

Dear Ai Nee,

Please confirm final fig \$ 1,500.00 (lump sum) @ 3 days of repairs.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tew Ai Nee [mailto:ainee@motorway.com.sg]
Sent: Thursday, 18 April 2019 3:06 PM
To: sur@lkkauto.com
Subject: Request for Finalise SGZ8505M

Dear All,

Can we finalize?
Attach after paint photos

Best Regards,

Annie Tew

Motor Claims

Claims Department / Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road

Motorway Building, Singapore 169205

DID: 6571 9625 Fax: 6273 5535

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 13 Jul 2018

Preliminary Advice

Insured Vehicle No	: SJL1896T	Accident Date	: 23/06/2018
TP Vehicle No	: SGZ8505M	Assignment Date	: 10/07/2018
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 3 days
Date of Inspection	: 11/07/2018		
Inspection At	: Motorway Car Care Centre Pte Ltd - Lower Delta (HQ) 1094 LOWER DELTA ROAD Singapore 169205		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,700.00
Revised Amount	:S\$	2,330.00
Check Items (Estimated)	:S\$	790.00
Total	:S\$	3,120.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/06/2018 13:35
Date Of Accident	23/06/2018 22:30
Exact Location Of Accident	BLK 171A MSCP (TPTPM3) LORONG 1 TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGZ8505M
Insured/Policyholder	
Name Of Registered Owner	MOTORWAY CAR RENTALS PTE LTD
Co Reg No	199902927C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64682200

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5093337471
Cover Note Number	

Driver

Name of Driver	ANTHONY CHEONG YONG MENG
NRIC No	S1686117J
Date Of Birth	28/07/1965
Occupation	INDOOR
Date Of Driving Pass	12/03/1984
Driving Experience	34 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94350322
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 173 LORONG 1 TOA PAYOH #03-1260
Postcode	310173
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL1896T
Vehicle Make/Model/Colour	HONDA JAZZ
Details Of Properties	VEH.B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	91017689
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

stationary parked & no driver in car.
 Veh. B (SJL1896T) hit onto Veh. A frt
 left & admitted fault.
 * Pls find Attached Note fr. Veh. B
 Driver * .

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Signature of Motorway Car Rental

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Car Incident

Unfortunately my car met with the
incident in the car parking and it hit
your car. Sorry for what had happened
to you due to our mistake.
Could you please contact me in the
below contact no

Subbarajulu Ravi
173 Lorong 1 Tok Payoh
#06 - 1272

91017689, 66490665

My Veh. No is STL 1896 T.

MSIG Insurance (Singapore)

4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

ATTN : MOTOR CLAIMS DEPARTMENT

ESTIMATE

VEHICLE NO. : **SGZ8505M**
CHASSIS NO : NZE1416047694
MAKE / MODEL : TOYOTA COROLLA AXIO 1.5X A
DATE OF ACCIDENT : 23rd JUNE 2018 @ 1030hrs

MSIG INSURED VEHICLE NUMBER : SJL1896T

<u>PARTS DISCRPTION</u>	<u>QTY</u>	<u>Cost Price</u>	<u>Total Cost Price</u>
FRONT BUMPER	1	\$ 650.00	\$ <i>del</i> 650.00
FRONT BUMPER CLIPS	1 SET	\$ 35.00	\$ <i>ner</i> 35.00
FRONT BUMPER SIDE RETAINER	1	\$ 75.00	\$ <i>ner</i> 75.00
FRONT LEFT HEADLIGHT	1	\$ 790.00	\$ <i>un</i> 790.00
FRONT LEFT FENDER	1	\$ 870.00	\$ <i>bt</i> 870.00
FRONT LEFT TYRE RIM	1	\$ 480.00	\$ <i>Rp</i> 480.00

Total Parts \$ 2,900.00

25% 1630 1222.50

LABOUR CHARGES

TO SPRAY PAINT ON THE AFFECTED AREAS
TO REPAIR, REMOVE & REPLACE ALL THE DAMAGE ITEMS

	\$ 600.00	<i>400</i>
	\$ 1,200.00	<i>300</i>
Total Labour	<u>\$ 1,800.00</u>	<i>700</i>

Sub Total **\$ 4,700.00**

Prepared By : -

Lynn Ahmad

Motorway Car Care Centre Pte Ltd
TEL: 6571 9625 FAX : 6278 5535
EMAIL: lynn@motorway.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749 1922.50
wp' 41581500
11/7/18 @ 1015
sur@lkkauto.com
3 days
Resurvey after repair
Lumpsum
16/7/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jun 2018		10 Jul 2018 12:56 Edit Adj Rpt	S\$1,500.00 Edit Estimates	S\$1,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SUBBARAYALU RAVI , ID: S7561568Z, Tel: +6591017689									
Main Claimant: MOTORWAY CAR RENTALS PTE LTD , Co. Reg. No.: 199902927C									
Vehicle Reg. No.:	SGZ8505M	Date of Loss:	23/06/2018 22:00 - :59 [127 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 562436	Policy/Cover Note No.:	S29041017SMA (Comprehensive) Coverage: 18/11/2017 - 17/11/2018						
Vehicle Reg. No. (Insured):	SJL1896T	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer: Motorway Car Care Centre Pte Ltd - Lower Delta (HQ) 1094 LOWER DELTA ROAD, 169205 Bukit Merah - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/08/2018]									
Driver/Custodian (Insured): MANICKAVASAGAM LATCHOUMY () , NRIC: S7662274D, Tel: +6591017689 Email:									
Adj Asg. Remarks: Please survey the vehicle today. thank you.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGZ8505M (562436)

[SJL1896T]



































TP

MOTORWAY CAR RENTALS PTE LTD

Jun 23 2018 10:00PM

[SUBBARAYALU RAVI]

Motorway Car Care Centre Pte Ltd - Lower Delta

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	10/07/18 11:38	Accident Statement From:OD - Reg. No: SJL1896T, Claimant: SUBBARAYALU RAVI						Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	13/07/18 13:42	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	13/07/18 13:57	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
2	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
3	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
4	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
5	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
6	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
7	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
8	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
9	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
10	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
11	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
12	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
13	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
14	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
15	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
16	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
17	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
18	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
19	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
20	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
21	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
22	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
23	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
24	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
25	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
26	13/07/18 13:57	General View						Load JPG	<input checked="" type="checkbox"/>	
27	22/04/19 12:04	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
28	22/04/19 12:04	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
29	22/04/19 12:04	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
30	22/04/19 12:04	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
31	22/04/19 12:04	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
32	22/04/19 12:04	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/18 11:40	SGZ8505M E-FILE REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012553/T1SBE2

Date: 30/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S29041017SMA

Claimant Vehicle No : SGZ8505M

Insured Vehicle No : SJL1896T

Date of Loss: 23/06/2018

Nature of Claim: TP

Claim No: 562436

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGZ8505M

Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A)

Engine No: 1NZC711930

Reg. Date: 20/11/2007 (Man. Year: 2007)

Chassis No: NZE1416047694

Colour: Beige

Odometer: 200143 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,900.00	1,222.50	1,677.50	57.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	700.00	1,100.00	61.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,700.00	1,922.50	2,777.50	59.10
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	4,700.00	1,500.00	3,200.00	68.09
+ GST 7.00/7.00% (S\$)	329.00	105.00	224.00	68.09
Nett Amount (S\$)	5,029.00	1,605.00	3,424.00	68.09

INSPECTION

Date of Assignment: 10/07/2018

Date Inspected: 11/07/2018 Inspected At:

Motorway Car Care Centre Pte Ltd - Lower Delta (HQ)
1094 LOWER DELTA ROAD
Singapore 169205

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Apr 2019)
Parts: 143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGZ8505M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	650.00 F	*650.00 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	Necessary	75.00 F	*75.00 FL
4	1		*FRONT LEFT HEADLIGHT	Not Necessary	790.00 F	*- FL
5	1		*FRONT LEFT FENDER	Bent	870.00 F	*870.00 FL
6	1		*FRONT LEFT TYRE RIM	Repair	480.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,900.00	1,630.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	407.50
Total Parts (\$\$)	2,900.00	1,222.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	400.00
2	TO REPAIR, REMOVE & REPLACE ALL THE DAMAGE ITEMS	New	1,200.00	300.00
Gross Labour Cost (S\$)			1,800.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >