

Surveyor: Menmen ASSIGNMENT (Office)From (Person): Kok Ming Shao of MSCH Date/Time: 10/7/2018 4:11pm

Estimated Cost: _____ Bill to: _____

OD / (P) WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLN 880K Insured: WC 82493at Workshop m/s Fastech Tel: 6746 5445of Blk 1 Kaki Bukit Ave 6 #01-46

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06/7/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wp 11/7/2018 @ 11am H.O.D. Endorsement: _____Date/Time: 10/7/2018 4:40pm Person Contacted: Nancy Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 880K - x
	WC 82493 - x
26/7	Revert via menmen

(08/11/13) wef

AGS. REC. BY:

REF: MSIG

ASSIGNMENT

From: _____ Date: 11/7/2018

Estimated Cost: _____

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 880K

at Workshop m/s Fastech-Auto

of Blk 1, Kaki Bukit Ave 6 #01-46

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 82k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up LTA 69104

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKN 880K

Yr Regn: 11/12

Type: ☒ M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or ☒ CA /

Make: BMW 520 c.c. 1997

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 112335 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W3A XG 12040DX5172

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil (S/Rim) / STD A/Rim or

Tyre Size: F: 255/35R20

R: 255/30R220

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 6/7/18

D.O.I. 11/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4 yrs. 4 mths. exp 14 have video. mirror (51167322504)

15/10/18 4/5 \$1500 confirmed with AIA (Red: 1772.84' 54%)

RECEIVED 16 OCT 2018

Date/Time, File Pass to?

☐

: Prel. Report

1) 16/10 Typist

☒

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

10

160

Report Format :

Lump Sum / I.B.I. (\$ 1500/-)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Koh Ming Shao

Date: 26 Jul 2018

Preliminary Advice

Insured Vehicle No	: WC8249J	Accident Date	: 06/07/2018
TP Vehicle No	: SLN880K	Assignment Date	: 10/07/2018
Make	: BMW 116D	Est. Duration of Repair	: 2.00
Date of Inspection	: 11/07/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,272.84
Revised Amount	:S\$	2,085.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,085.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018		10 Jul 2018 16:11 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Alliance Concrete Singapore Pte. Ltd., Co. Reg. No.: 20056266D		
Main Claimant:	SEE WOON SIANG, ID: S8034255A		
Vehicle Reg. No.:	SLN880K	Date of Loss:	06/07/2018 08:00 - :59 [67 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	Coverage: 01/07/2018 - 30/06/2019
Vehicle Reg. No. (Insured):	WC8249J	Policy No. (Claimant):	
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Koh Ming Shao - 6594 2546]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/07/2018]		
Adj Asg. Remarks:	OI not reported SJE agree - LKK Contact : Nancy Lam at 6746 5405		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/07/2018 16:45
Date Of Accident	06/07/2018 08:10
Exact Location Of Accident	ALONG ECP
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN880K
Insured/Policyholder	
Name Of Registered Owner	SEE WOON SIANG
NRIC No	S8034255A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91913686
Alternative Phone No	OTHERS-91913686
Vehicle Particulars	
Manufacturer	BMW
Model	116D-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27428561 SMP
Cover Note Number	
Driver	
Name of Driver	SEE WOON SIANG
NRIC No	S8034255A
Date Of Birth	06/11/1980
Occupation	INDOOR
Date Of Driving Pass	01/09/1999
Driving Experience	18 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91913686
Fax Number	
Contact Number	OTHERS-91913686
Email Address	NOEMAIL

Address	BLK 137 SIMEI STREET 1 #09-102
Postcode	520137
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN WAN XIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK POLICE DIVISIONAL HQ (G DIVISION)
Police Station Address	ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2440000 - FAX NO: 64443009
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.G/20180706/7041

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC8249J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 415933

Reporting Centre Telephone: 67492305
Name: Fax: 67492305
NRIC/FIN No: Email: vackb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refw to the police report 6/20180706/704

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 415933

Reporting Centre Person's Signature
Name: Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg
NRIC/FIN No:

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



G/20180706/7041

1 of 3

POLICE REPORT (NP299)

Police Station Of Origin
Bedok Police Divisional HQ
30 Bedok North Road SINGAPORE 469676
Tel No:1800-2440000

Report No. G/20180706/7041

Date/Time Report Made 06/07/2018 23:01	Vide Report No.	Station Diary No.
Name Of Informant SEE WOON SIANG RON	Address APT BLK 137 SIMEI STREET 1 #09-102 SINGAPORE 520137	
ID Type / ID No. NRIC NO / S8034255A	Contact No. Home/Office:	Mobile: 91913686
Nationality SINGAPORE CITIZEN	Email Address seeron19@gmail.com	
Occupation TRANSPORTATION LOGISTIC	Sex Male	Age 37
Institution/School Name	Date of Birth 06/11/1980	Race Chinese
Date/Time Of Incident 06/07/2018 08:07 - 06/07/2018 08:07	Location Of Incident Rochor flyover exit from East Coast Park (ECP) Expressway.	

Brief details.

Debris fallen from Cement mixer truck (WC8249J) and hit onto right side of my car (SLN880K). Alliance Concrete (932) is the name of the truck company indicated on the vehicle. As a result, my side mirror fold suffered deep scratches as well as my side mirror cover. Upon impact, the debris further disintegrated and smaller debris scattered and scratched my right front and rear doors. No exchange of both drivers' particulars were made as it was unsafe for me to stop on the flyover ramp which is going downhill and due to the then traffic condition. I have great concern over such unsafe practice from this truck company

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 06/07/2018 23:01
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



G/20180706/7041

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20180706/7041

as the consequence would have been worse if I had over-reacted and over-steer which could caused an accident affecting others and my own personal safety. The event was captured on my in-car camera and photos were taken after i stopped my car safely in my office carpark which is less than 15mins distance after the incident. I would like to hear from this company to seek compensation to the damages to my car as a result of their unsafe act. I hope that the relevant authorities are able to look into this matter to avoid greater consequence if this is to happen to a motorcyclist who is more vulnerable to this kind of impact. Good if I can receive feedback from the relevant authorities and hope for a safer road in Singapore.

Subjects Involved			
Victim			
Person Name	SEE WOON SIANG RON		
ID Type	NRIC NO	ID No	S8034255A
Gender	Male	Age	37
Race	Chinese	Language	English
Occupation	TRANSPORTATION LOGISTIC		Address Type
Address	APT BLK 137 SIMEI STREET 1		Mobile No
	#09-102 SINGAPORE 520137		91913686
Is Informant A	Yes		
Victim?			
Person Name	Tan Wan Xin		
ID Type	NRIC NO	ID No	S8977203F
Gender	Female	Age	29
Race	Chinese	Language	Chinese

Signature Of Officer Recording The Report:	Signature Of Informant:
Not applicable	The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter:	Date/Time:
Not applicable	06/07/2018 23:01
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	



**SINGAPORE
POLICE FORCE**



G/20180706/7041

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20180706/7041

Address Type	HDB / HUDC	Address	APT BLK 137 Simei Street 1 #09-102 SINGAPORE 520137
Mobile No	97708438	Relation To Informant	fiancée
Person Name	SEE WOON SIANG RON (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 06/07/2018 23:01
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4255A

Vehicle Details

Vehicle No.: SLN880K
Vehicle to be Exported: No
Intended De-registration Date: 11 Jul 2018
Vehicle Make: B.M.W.
Vehicle Model: 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour: Blue
Manufacturing Year: 2012
Engine No.: B0890329N20B20B
Chassis No.: WBAXG12040DX51721
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$40,484.00
Original Registration Date: 30 Nov 2012
First Registration Date: 30 Nov 2012
Transfer Count: 0
Actual ARF Paid: \$40,484.00 20242

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Nov 2022
PARF Rebate Amount: \$28,338.00

Intended COE Rebate Details

COE Expiry Date: 29 Nov 2022
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$93,004.00
COE Rebate Amount: \$40,766.00
Total Rebate Amount: \$69,104.00

The information contained herein is correct as at 11 Jul 2018

OK

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

not authorized
the plate after repair
11/7/18
2dy.
4/5 \$ 1500

Estimate :

Date : 11.07.2018

Vehicle Num : SLN880K

Make/Model : BMW 535

Chassis/Engine no :

Accident Date : 06.07.2018

Claim No :

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc Front door wing mirror RH

873.00

List item total :

Discount 10 % :

Damaged part	1,047.60
\$	1,047.60
\$	104.76
\$	942.84

Nett Item:

1 set Front door wing mirror cover (carbon)

450

\$ 450	650.00
\$	650.00

Labour Change

To diagnostic wing mirror programming

To renew the above mention parts

To respray painting on RH front & rear door, fender etc.

\$ 150	200.00
\$	280.00
\$ 500	1,200.00
\$	1,680.00

1885.7

E & O . E

Total Amount : \$ 3,272.84

FASTECH AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012557/UTBN2
Date: 17/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29088496MKF
Claimant Vehicle No :	SLN880K	Insured Vehicle No :	WC8249J
Date of Loss:	06/07/2018	Nature of Claim:	TP
		Claim No:	564748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN880K	Engine No:	B0890329N20B20B
Make & Model:	BMW 116D, 1.5 (A)	Chassis No:	WBAXG12040DX51721
Reg. Date:	30/11/2012 (Man. Year: 2012)	Odometer:	112335 km
Colour:	Blue		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 ZR20	Rear Tyre Size:	285/30 ZR20
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,592.84	1,235.70	357.14	22.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	650.00	1,030.00	61.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,272.84	1,885.70	1,387.14	42.38
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	3,272.84	1,500.00	1,772.84	54.17
+ GST 7.00/7.00% (S\$)	229.10	105.00	124.10	54.17
Nett Amount (S\$)	3,501.94	1,605.00	1,896.94	54.17

INSPECTION

Date of Assignment:	10/07/2018	
Date Inspected:	11/07/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2018)
Parts: 144	BMW 116D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN880K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR WING MIRROR RH	Damaged/Cut	1,047.60 FL	*873.00 FL
2	1	*SET FRONT DOOR WING MIRROR COVER (CARBON)	Grazed	650.00 FS	*450.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.					
Sub Total (S\$)				1,697.60	1,323.00
- List Item Discount on L Items 10.00/10.00% (S\$)				104.76	87.30
Total Parts (S\$)				1,592.84	1,235.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW THE ABOVE MENTION PARTS }	New	280.00	150.00
2	TO DIAGNOSTIC WING MIRROR PROGRAMMING }	New	200.00	-
3	TO RESPRAY PAINTING ON RH FRONT DOOR & REAR DOOR,FENDER ETC	New	1,200.00	500.00
Gross Labour Cost (\$\$)			1,680.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >